

# Release Notes for Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version (1.0.2.17-1.0.0.39)

## Contents

This document includes the following topics:

- [Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version, 1.0.2.17, page 2](#)
- [Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version, 1.0.2.16, page 2](#)
- [Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version, 1.0.2.15, page 3](#)
- [Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version, 1.0.2.14, page 3](#)
- [Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version, 1.0.2.8, page 4](#)
- [Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version, 1.0.2.8, page 4](#)
- [Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version 1.0.1.4, page 6](#)
- [Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version 1.0.0.39, page 7](#)
- [Related Information, page 8](#)

# Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version, 1.0.2.17

## Aug 2019

These release notes describe the known issues in the Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points firmware version 1.0.2.17.

## Resolved Issues

The following issue has been fixed in the firmware version 1.0.2.17:

Ref Number	Description
CSCvq31943	<b>Symptom:</b> Evaluation of WAP131 for TCP SACK vulnerabilities.

# Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version, 1.0.2.16

## January 2019

These release notes describe the known issues in the Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points firmware version 1.0.2.16.

## Software Component Update

- Openssl upgrade to version 1.0.2l
- NTP update to version 4.2.8p10

## Resolved Issues

The following issue has been fixed in firmware version 1.0.2.17:

- Security Enhancements

## Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version, 1.0.2.15

### December 2017

These release notes describe the known issues in the Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points firmware version 1.0.2.15.

### Resolved Issues

The following issue has been fixed in the firmware version 1.0.2.15

Ref Number	Description
CSCvf96801	<b>Symptom:</b> Key Reinstallation attacks against WPA protocol.

### Known Issues

The following table lists the known issues in firmware version 1.0.2.15:

Ref Number	Description
CSCuv04511	The IGMP Packets/Data statistics always shows 0. <b>Workaround</b> None.

## Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version, 1.0.2.14

### August 2017

These release notes describe the known issues in the Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points firmware version 1.0.2.14.

### Resolved Issues

The following issues have been fixed in the firmware version 1.0.2.14:

Ref Number	Description
CSCvf57848	<b>Symptom:</b> WAP131/WAP351: Security Vulnerability “Cross-Site Scripting” Attack.
CSCur36577	<b>Symptom:</b> Some characters of the cluster location are dropped when you set the Cluster Location settings through the Setup Wizard.
CSCuq49207	<b>Symptom:</b> The WDS bridge is established between two units in different channels.
CSCur51986)	<b>Symptom:</b> The port status of the VLAN cannot return to its default status after the VLAN ID (except VLAN 1) is deleted.
CSCuu69519	<b>Symptom:</b> Away Timeout GUI issue.

### Known Issues

The following table lists the known issues in firmware version 1.0.2.14:

Ref Number	Description
CSCuv04511	The IGMP Packets/Data statistics always shows 0. <b>Workaround</b> None.

## Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version, 1.0.2.8

### December 2016

These release notes describe the known issues in the Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points firmware version 1.0.2.8.

## New Features and Enhancements

- Updated Japanese Online Help page.

## Resolved Issues

The following issues have been fixed in the firmware version 1.0.2.8:

Ref Number	Description
CSCvc33119	<b>Symptom:</b> Fix Android device DHCP failure when associating WAP351 using WPS2-AES only.
CSCvb91702	<b>Symptom:</b> WAP5GHz radio failed and became inactive after injecting HTTP/HTTPS traffic simultaneously.

## Known Issues

The following table lists the known issues in firmware version 1.0.2.8:

Ref Number	Description
CSCuv04511	The IGMP Packets/Data statistics always shows 0. <b>Workaround</b> None.

# Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version, 1.0.2.2

## June 2016

These release notes describe the known issues in the Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points firmware version 1.0.2.2.

## New Features and Enhancements

- Added Japanese support and localized GUI.
- Upgraded OpenSSL to 1.0.2d and added TLSv1.2 support.

### Resolved Issues in 1.0.1.4 Release

The following issues have been fixed in the firmware version 1.0.1.4:

Ref Number	Description
CSCur36577	<b>Symptom:</b> Some characters of the cluster location are dropped when you set the Cluster Location settings through the Setup Wizard.
CSCuq49207	<b>Symptom:</b> The WDS bridge is established between two units in different channels.
CSCur51986	<b>Symptom:</b> The port status of the VLAN cannot return to its default status after the VLAN ID (except VLAN 1) is deleted.
CSCuu69519	<b>Symptom:</b> Away Timeout GUI issue.

### Known Issues

The following table lists the known issues in firmware version 1.0.2.2:

Ref Number	Description
CSCuv04511	The IGMP Packets/Data statistics always shows 0. <b>Workaround</b> None.

## Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version 1.0.1.4

### October 2015

These release notes describe the known issues in the Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points firmware version 1.0.1.4.

### New Features and Enhancements

- LLDP
- Band Steering

- IGMP Snooping
- Cluster Plus (Single IP Management, Clustering Firmware Upgrade)

## Resolved Issues

The following issues have been fixed in the firmware version 1.0.1.4:

Ref Number	Description
CSCur36577	<b>Symptom:</b> Some characters of the cluster location are dropped when you set the Cluster Location settings through the Setup Wizard.
CSCuq49207	<b>Symptom:</b> The WDS bridge is established between two units in different channels.
CSCur51986	<b>Symptom:</b> The port status of the VLAN cannot return to its default status after the VLAN ID (except VLAN 1) is deleted.
CSCuu69519	<b>Symptom:</b> Away Timeout GUI issue.

## Known Issues

The following table lists the known issues in firmware version 1.0.1.4:

Ref Number	Description
CSCuv04511	The IGMP Packets/Data statistics always shows 0. <b>Workaround</b> None.

# Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points Firmware Version 1.0.0.39

## November 2014

These release notes describe the known issues in the Cisco WAP131 and WAP351 Wireless-N Dual Radio Access Points firmware version 1.0.0.39.

### Known Issues

The following table lists the known issues in firmware version 1.0.0.39:

Ref Number	Description
CSCur36577	<p>Some characters of the cluster location are dropped when you set the Cluster Location settings through the Setup Wizard.</p> <p><b>Workaround</b> Only use normal characters to define the Cluster Location settings through the Setup Wizard.</p>
CSCuq49207	<p>The WDS bridge is established between two units in different channels.</p> <p><b>Workaround</b> Set up the WDS bridge in the same channel.</p>
CSCur51986	<p>The port status of the VLAN cannot return to its default status after the VLAN ID (except VLAN 1) is deleted.</p> <p><b>Workaround</b> None.</p>

### Related Information

Support	
Cisco Support Community	<a href="http://www.cisco.com/go/smallbizsupport">www.cisco.com/go/smallbizsupport</a>
Cisco Support and Resources	<a href="http://www.cisco.com/go/smallbizhelp">www.cisco.com/go/smallbizhelp</a>
Phone Support Contacts	<a href="http://www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html">www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html</a>
Cisco Firmware Downloads	<a href="http://www.cisco.com/go/smallbizfirmware">www.cisco.com/go/smallbizfirmware</a> Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	<a href="http://www.cisco.com/go/smallbiz_opensource_request">www.cisco.com/go/smallbiz_opensource_request</a>
Cisco Partner Central (Partner Login Required)	<a href="http://www.cisco.com/web/partners/sell/smb">www.cisco.com/web/partners/sell/smb</a>



### Product Documentation

Cisco WAP131 and WAP351	<a href="http://www.cisco.com/go/100_wap_resources">www.cisco.com/go/100_wap_resources</a> <a href="http://www.cisco.com/go/300_wap_resources">www.cisco.com/go/300_wap_resources</a>
Regulatory Compliance and Safety Information	<a href="http://www.cisco.com/en/US/docs/switches/lan/csb_switching_general/rcsi/Switch_ClassA_RCSI.pdf">www.cisco.com/en/US/docs/switches/lan/csb_switching_general/rcsi/Switch_ClassA_RCSI.pdf</a>
Warranty Information	<a href="http://www.cisco.com/go/warranty">www.cisco.com/go/warranty</a>

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2020 Cisco Systems, Inc. All rights reserved.