

# Ascertain ASA Smart Licensing Failures Due to Certificate Issues

## Contents

[Introduction](#)

[Prerequisites](#)

[Requirements](#)

[Components Used](#)

[Background Information](#)

[Problem](#)

[Syslogs and Debug Output](#)

[Solution](#)

[Verify](#)

[Root CA Certificate Change - October 2018](#)

[4100/9300 Platforms Running ASA](#)

[Resolution Steps](#)

[ASA Software Installations That Require Federal Information Processing Standards \(FIPS\) Compliance](#)

[Related Information](#)

## Introduction

This document describes how to ascertain ASA Smart Licensing failures that are due to a certificate handshake failure.

## Prerequisites

## Requirements

There are no specific requirements for this document.

## Components Used

This document is not restricted to specific software and hardware versions.

The information in this document was created from the devices in a specific lab environment. All of the devices used in this document started with a cleared (default) configuration. If your network is live, ensure that you understand the potential impact of any command.

## Background Information

This document describes how to address a change that occurred on March 2016 and October 2018, in which web servers that host tools.cisco.com were migrated to a different root Certificate Authority (CA) certificate. After that migration, some ASA (Adaptive Security Appliance) devices fail to connect to the Smart Software Licensing Portal (which is hosted on tools.cisco.com) when they register an ID token or while they attempt to renew current authorizations. This was determined to be a certificate-related issue. Specifically, the new certificate that is presented to the ASA is signed by a different Intermediate CA than the ASA expects and has preloaded.

# Problem

When an attempt is made to register an ASA v to the Smart Software Licensing Portal, the registration fails with a connection or communication failure. The **show license registration** and **call-home test profile license** commands show these outputs.

```
<#root>
```

```
ASAv#
```

```
show license registration
```

```
Registration Status: Retry In Progress.
Registration Start Time: Mar 22 13:25:46 2016 UTC
Registration Status: Retry In Progress.
Registration Start Time: Mar 22 13:25:46 2016 UTC
Last Retry Start Time: Mar 22 13:26:32 2016 UTC.
Next Scheduled Retry Time: Mar 22 13:45:31 2016 UTC.
Number of Retries: 1.
Last License Server response time: Mar 22 13:26:32 2016 UTC.
Last License Server response message:
```

```
Communication message send response error
```

```
<#root>
```

```
ASAv#
```

```
call-home test profile License
```

```
INFO: Sending test message to DDCEService
ERROR: Failed:
```

```
CONNECT_FAILED(35)
```

However, the ASA v can resolve tools.cisco.com and connect on TCP port 443 with a TCP ping.

## Syslogs and Debug Output

Syslog output on the ASA v after an attempted registration can show this:

```
<#root>
```

```
%ASA-3-717009: Certificate validation failed. No suitable trustpoints found to validate
certificate serial number: 250CE8E030612E9F2B89F7058FD, subject name:
cn=VeriSign Class 3 Public Primary Certification Authority - G5,ou=(c) 2006 VeriSign\, Inc.
- For authorized use only,ou=VeriSign Trust Network,o=VeriSign\, Inc.,c=US, issuer name:
ou=Class 3 Public Primary Certification Authority,o=VeriSign\, Inc.,c=US .
```

```
%ASA-3-717009: Certificate validation failed. No suitable trustpoints found to validate
certificate serial number: 513FB9743870B73440418699FF, subject name:
```

```
cn=Symantec Class 3 Secure Server CA - G4
```

```
,ou=Symantec Trust Network,o=Symantec
Corporation,c=US, issuer name: cn=VeriSign Class 3 Public Primary Certification Authority
```

- G5,ou=(c) 2006 VeriSign\, Inc. - For authorized use only,ou=VeriSign Trust Network,  
o=VeriSign\, Inc.,c=US .

For further information, run these debug commands while you attempt another registration. Secure Socket Layer errors are seen.

```
debug license 255
debug license agent all
debug call-home all
debug ssl 255
```

Specifically, this message is seen as part of that output:

```
error:14090086:SSL routines:SSL3_GET_SERVER_CERTIFICATE:certificate verify
failed@s3_clnt.c:1492
```

In the default ASAv configuration, there is a trustpoint called `_SmartCallHome_ServerCA` that has a certificate loaded and issued to the subject name "cn=Verisign Class 3 Secure Server CA - G3".

<#root>

ASAv#

```
show crypto ca certificate
```

CA Certificate

```
Status: Available
Certificate Serial Number: 6ecc7aa5a7032009b8cebc2d491
Certificate Usage: General Purpose
Public Key Type: RSA (2048 bits)
Signature Algorithm: SHA1 with RSA Encryption
Issuer Name:
  cn=VeriSign Class 3 Public Primary Certification Authority - G5
  ou=(c) 2006 VeriSign\, Inc. - For authorized use only
  ou=VeriSign Trust Network
  o=VeriSign\, Inc.
  c=US
Subject Name:
```

```
  cn=VeriSign Class 3 Secure Server CA - G3
```

```
  ou=Terms of use at https:// verisign /rpa (c)10
  ou=VeriSign Trust Network
  o=VeriSign\, Inc.
  c=US
```

OCSP AIA:

```
  URL: http://ocsp verisign
```

CRL Distribution Points:

```
  [1] http://crl verisign/pca3-g5.crl
```

Validity Date:

```
  start date: 00:00:00 UTC Feb 8 2010
  end   date: 23:59:59 UTC Feb 7 2020
```

Associated Trustpoints: \_SmartCallHome\_ServerCA

However, in the the previous syslogs, the ASA indicates that it gets a certificate from the Smart Software Licensing Portal signed by an intermediate called "cn=Symantec Class 3 Secure Server CA - G4".

---

**Note:** The subject names are similar, but have two differences; Verisign vs. Symantec at the beginning and G3 vs. G4 at the end.

---

## Solution

The ASAv needs to download a trustpool that contains the proper intermediate and/or root certificates in order to validate the chain.

In Version 9.5.2 and later, the ASAv has the trustpool configured to auto-import at 10:00 PM device local time:

```
<#root>
```

```
ASAv#
```

```
sh run crypto ca trustpool
```

```
crypto ca trustpool policy
```

```
  auto-import
```

```
ASAv#
```

```
  sh run all crypto ca trustpool
```

```
crypto ca trustpool policy
```

```
  revocation-check none
```

```
  crl cache-time 60
```

```
  crl enforcenextupdate
```

```
  auto-import
```

```
  auto-import url http://www.cisco.com/security/pki/trs/ios_core.p7b
```

```
  auto-import time 22:00:00
```

If this is an initial installation, and Domain Name System (DNS) lookups and Internet connectivity have not been up at that time yet, then the auto-import has not succeeded and needs to be completed manually.

On older versions, such as 9.4.x, the trustpool auto-import is not configured on the device and needs to be imported manually.

On any version, this command imports the trustpool and relevant certificates:

```
<#root>
```

```
ASAv#
```

```
crypto ca trustpool import url http://www.cisco.com/security/pki/trs/ios_core.p7b
```

```
Root file signature verified.
```

```
You are about to update the current trusted certificate pool
with the 17145 byte file at http://www.cisco.com/security/pki/trs/ios_core.p7b
Do you want to continue? (y/n)
Trustpool import:
  attempted: 14
  installed: 14
  duplicates: 0
  expired: 0
  failed: 0
```

## Verify

Once the trustpool is imported either by the manual command or it is after 10:00 PM local time, this command verifies that there are installed certificates in the trustpool:

```
<#root>

ASAv#

show crypto ca trustpool policy
14 trustpool certificates installed

Trustpool auto import statistics:
  Last import result: FAILED
  Next scheduled import at 22:00:00 UTC Wed Mar 23 2016

Trustpool Policy
  Trustpool revocation checking is disabled
  CRL cache time: 60 seconds
  CRL next update field: required and enforced
  Automatic import of trustpool certificates is enabled
  Automatic import URL: http://www.cisco.com/security/pki/trs/ios_core.p7b
  Download time: 22:00:00
  Policy Overrides:
    None configured
```

---

**Note:** In the previous output the last auto-update import failed since DNS was not operational the last time it attempted automatically, so it still shows the last auto-import result as failed. However, a manual trustpool update was run and did successfully update the trustpool (which is why it shows 14 certificates installed).

---

After the trustpool is installed, the token registration command can be run again in order to register the ASAv with the Smart Software Licensing Portal.

```
<#root>

ASAv#

license smart register idtoken id_token force
```

If the ASAv was already registered to the Smart Software Licensing Portal, but authorization renewals failed, those can also be attempted manually.

```
<#root>
```

```
ASAv#
```

```
license smart renew auth
```

## Root CA Certificate Change - October 2018

The root CA certificate for tools.cisco.com was changed on Friday, October 5th, 2018.

The currently deployed ASAvâ€™s version 9.6(2) and later and Firepower 2100â€™s running ASA cannot be affected by this change if communication to [http://www.cisco.com/security/pki/trs/ios\\_core.p7b](http://www.cisco.com/security/pki/trs/ios_core.p7b) is not allowed. There is a certificate auto-import feature that is enabled by default on all ASA Smart Licensed platforms mentioned before. The output of `show crypto ca trustpool` contains the Quovaadis Root CA 2â€™ certificate:

### CA Certificate

```
Fingerprint: 5e397bddf8baec82e9ac62ba0c54002b  
Issuer Name:  
  cn=QuoVadis Root CA 2  
  o=QuoVadis Limited  
  c=BM  
Subject Name:  
  cn=QuoVadis Root CA 2  
  o=QuoVadis Limited  
  c=BM
```

For new deployments, you can issue the `crypto ca trustpool import default` command and download the default Cisco cert bundle that contains the Quovaadis cert. If that doesnâ€™t work you can install the cert manually:

```
asa(config)# crypto ca trustpoint QuoVadisRootCA2  
asa(config-ca-trustpoint)# enrollment terminal  
asa(config-ca-trustpoint)# crl configure  
asav(config-ca-crl)# crypto ca authenticate QuoVadisRootCA2  
Enter the base 64 encoded CA certificate.  
End with the word "quit" on a line by itself  
  
-----BEGIN CERTIFICATE-----  
MIIFtzCCA5+gAwIBAgICBQkwdQYJKoZIhvcNAQEFBQAwRTElMAkGA1UEBhMCQk0x  
GTAXBgNVBAoTEFF1b1ZlZGlzIEExpbWl0ZWQxGzAZBgNVBAMTElF1b1ZlZGlzIFJv  
b3QgQ0EgMjAeFw0wNjExMjQzMDBaFw0zMTExMjQzMDIzMDAUMzNaMEUxCzAJBgNV  
BAYTAKJNMWk0YzIwMjQzMDBaFw0zMTExMjQzMDIzMDAUMzNaMEUxCzAJBgNV  
YWRpcyBSb290IENBIDlwggIiMA0GCSqGSIb3DQEBAQUAA4ICDwAwggIKAoICAQCa  
GMpL1A0ALa8DKYrWd4HIrkwZhr0In6spRlXzL4GtMh6QRr+jhiYaHv5+HBg6XJxg  
Fyo6dIMzMH1hVBHL7avg5tKifvVrbxi3Cgst/ek+7wrGsxDp3MJGF/hd/aTa/55J  
WpzmM+Yk1vc/ulsrHHo1wtZn/qtmUIttKGAr79dgw8eTvI02kfN/+NsRE8Scd3bB  
rrcCaoF6qUWD4gXmuVbBlDePSHFjIuwXZQeVikvfj8ZaCuWw419eaxGrDPmF60Tp  
+ARz8un+XJiM9X0va7R+zdRcAitMOeGylZUtQofX1b0QQ7dsE/He3fbE+Ik/0XX1  
ksOR1YqI0JDs3G3eicJlcZaLDQP9nL9bFqyS2+r+eXyt66/3FsvbzSUr5R/7mp/i  
Ucw6UwxI5g69ybr2B1LmEROfcmMDBOAEInisgQLodKcfts1WzVb1JdxnwQ5hYIiz  
PtGo/KPaHbDRsSNU30R2be1B2MGyIrZTHN81Hdyhdyox5C315eXby0D/5YDXC20g
```

```
/z0hD7osFRXq17PSorW+8oyWHhqPHWykYTe5hnMz15eWniN9ggRMgeKh0bpnX5UH
oycR7hYQe7xFSkyyBNKr79X9DFHOUGoIMfmR2gyPZFwDwzqLID9ujWc90tb+fVuI
yV77zGHcizN300QyNQLiBJIWENieJ0f70yHj+OsdWwIDAQABo4GwMIGtMA8GA1Ud
EwEB/wQFMAMBAf8wCwYDVR0PBAQDAgEGMB0GA1UdDgQWBQahGK8SEwzJQTU7tD2
A8QZRTGUazBuBgNVHSMZzBlgBQahGK8SEwzJQTU7tD2A8QZRTGUa6FJpEcwRTEL
MAKGA1UEBhMCQk0xGTAXBgNVBAoTEFFf1b1ZhZGlzIEExpbWl0ZWQxGzAZBgNVBAMT
ElF1b1ZhZGlzIFJvb3QgQ0EgMoICBQkwDQYJKoZIhvcNAQEFBQADggIBAD4KfK2f
BluornFdLwUvZ+YTRYPENvbzWCYMDbVHZF34tHLJRqUDGCdViXh9duqWNIAXINzn
g/iN/Ae42l9NLmeyhP3ZRPx3UIHmFLTJDQtyU/h2BwdBR5YM++CCJpNVjP4iH2Bl
fF/nJrP3MpCYUNQ3cVX2kiF495V5+vgtJodmVjB3pjd4M1IQWK4/YY7yarHvGH5K
WwPKjaJW1acvvFYfzbnB4vsKqBUsfU16Y8Zs10Q80m/DSHcK+JDSV6IZUaUt10Ha
B0+pUNqQjZRG4T7w1P0QADj10+hA4bRuVhogzG9Yje0uRY/W6ZM/57Es3zrWIoZc
hLsib9D45MY56QSIpM0661V6bYcZJPVsAfV417CUw+v90m/xd2gNNWQjrLhVoQPR
TUIZ3Ph1WVaj+ahJefivDrkRoHy3au000LYmYjgahwz46P0u05B/B5EqHdZ+XIWD
mbA4CD/pXvk1B+TJYm5Xf6dQlfe6yJvmjqIBxdZmv3lh8zwc4bmCXF2gw+nYSL0Z
ohEUGW6yhhtoPkg3Goi3XZZenMfvJ2II4pEZXLxId26F0KC13GBUzGpn/Z9Yr9y
4a0THcyKJloJONDO1w2AFrR4pTqHTI2KpdVGl/IsELm8VCLAAVBpQ570su9t+0za
8e0x79+Rj1QqCyXBjhnEUhAFZdWCE0rCMc0u
-----END CERTIFICATE-----
```

quit

```
INFO: Certificate has the following attributes:
Fingerprint:      5e397bdd f8baec82 e9ac62ba 0c54002b
Do you accept this certificate? [yes/no]: yes
```

Trustpoint CA certificate accepted.

% Certificate successfully imported

## 4100/9300 Platforms Running ASA

This issue has affected some 4100/9300s in the field that are running ASA which relies on Firepower eXtensible Operating System (FXOS) to provide Smart Licensing information:

Affected unit:

<#root>

```
FP9300-1-A-A-A /license # show license all
```

```
Smart Licensing Status
```

```
=====
```

```
Smart Licensing is ENABLED
```

```
Registration:
```

```
Status: REGISTERED
```

```
Smart Account: TAC Cisco Systems, Inc.
```

```
Virtual Account: CALO
```

```
Export-Controlled Functionality: Allowed
```

```
Initial Registration: SUCCEEDED on Jul 01 18:37:38 2018 UTC
```

```
Last Renewal Attempt: FAILED on Oct 09 17:32:59 2018 UTC
```

```
Failure reason: Failed to authenticate server
```

## Resolution Steps

To resolve, you need to create a new trustpoint and enter the certificate data in FXOS:

```
<#root>
```

```
FPR-2-A /license # scope security
FPR-2-A /security # enter trustpoint QuoVadisRootCA2
FPR-2-A /security/trustpoint* # set certchain
Enter lines one at a time. Enter ENDOFBUF to finish. Press ^C to abort.
Trustpoint Certificate Chain: (THIS PART NEEDS TO BE COPY/PASTED)
>
```

```
-----BEGIN CERTIFICATE-----
MIIFtzCCA5+gAwIBAgICBQkwDQYJKoZIhvcNAQEFBQAwRTElMAkGA1UEBhMCk0x
GTAXBgNVBAoTEFF1b1ZlZGlzIExpbnWl0ZWQxGzAZBgNVBAMTElF1b1ZlZGlzIFJv
b3QgQ0EgMjAeFw0wNjExMjQxODIzMDBaFw0zMTExMjQxODIzMDZNaMEUxCzAJBgNV
BAYTAKJNMRkwFwYDVQQKEwBRdW9WYWRpcyBMaW1pdGVkMRswGQYDVQQDEwJRdW9W
YWRpcyBSb290IENBIDwggIiMA0GCSqGSIb3DQEBAQUAA4ICDwAwggIKAoICAQCa
GMpL1A0ALa8DKYrWd4HlRkZhr0In6spRIXzL4GtMh6QRr+jhiYaHv5+HBg6XJxg
Fyo6dIMzMH1hVBHL7avg5tKifvVrbxi3Cgst/ek+7wrGsxDp3MJGF/hd/aTa/55J
WpzmM+Yk1vc/ulsrHHo1wtZn/qtmUIttKGA79dgw8eTvI02kfn/+NsRE8Scd3bB
rrcCaoF6qUWD4gXmuVbBlDePSHFjIuwXZQeVikvfj8ZaCuWw419eaxGrDPmF60Tp
+ARz8un+XJiM9X0va7R+zdRcAitMOeGylZUtQofX1b0QQ7dsE/He3fbE+Ik/0XX1
ksOR1YqI0JDs3G3eicJlcZaLDQP9nL9bFqyS2+r+eXyt66/3FsvbzSUR5R/7mp/i
Ucw6UwxI5g69ybr2B1LmEROfcmMDBOENisgGQLodKcfts1WzVb1JdxnwQ5hYIiz
PtGo/KPaHbDRsSNU30R2be1B2MGyIrZTHN81Hdyhdyox5C315eXby0D/5YDXC20g
/z0hD7osFRXq17PSorw+8oyWHhQPHWykYTe5hnMz15eWniN9gqRMgeKh0bpnX5UH
oycR7hYQe7xFSkyyBNKr79X9DFHOUGoIMfmR2gyPZFwDwzqLID9ujWc90tb+fVuI
yV77zGHcizN300QyNq1iBJIWENieJ0f70yHj+0sdWwIDAQBo4GwMIgTMA8GA1Ud
EwEB/wQFMAMBAf8wCwYDVR0PBAQDAgEGMB0GA1UdDgQWBBAhGK8SEwzJQTU7tD2
A8QZrtGUazBuBgNVHSMZzBlGqahGK8SEwzJQTU7tD2A8QZrtGUa6FJpEcwRTEL
MAkGA1UEBhMCk0xGTAXBgNVBAoTEFF1b1ZlZGlzIExpbnWl0ZWQxGzAZBgNVBAMT
ElF1b1ZlZGlzIFJvbnWl0ZWQxGzAZBgNVBAMTElF1b1ZlZGlzIFJvbnWl0ZWQxGz
BluornFdLwUvZ+YTRYPENvbzWcYMDbVHZF34tHLJRqUDGCdViXh9duqWNIAXINzn
g/iN/Ae4219NLmeyhP3ZRPx3UIHmFLTJDQTYU/h2BwdBR5YM++CCJpNVjP4iH2Bl
fF/nJrP3MpCYUNQ3cVX2kiF495V5+vgtJodmVjB3pjd4M1IQWk4/YY7yarHvGH5K
WWPKjaJw1acvvFYfzznB4vsKqBusfU16Y8Zs10Q80m/DSHck+JDSV6IZUaUt10Ha
B0+pUNqQjZRG4T7w1P0QADj10+hA4bRuVhogzG9Yje0uRY/W6ZM/57Es3zrWIozc
hLsib9D45MY56QSIPM0661V6bYCZJPVsAfv417CUw+v90m/xd2gNNWQjrLhVoQPR
TUIZ3Ph1WVaj+ahJefivDrkRoHy3au000LYmYjgahwz46P0u05B/B5EqHdZ+XIWD
mbA4CD/pXvk1B+TJm5Xf6dQlfe6yJvmjqIBxdZmv31h8zwc4bmCXF2gw+nYSL0Z
ohEUGW6yhhtoPkg3Goi3XZZenMfvJ2II4pEZXNLxId26F0KC13GBUZGpn/Z9Yr9y
4a0THcyKJloJONDO1w2AFrR4pTqHTI2KpdVGl/IsELm8VCLAAVBpQ570su9t+0za
8e0x79+Rj1QqCyXBjhnEUhAFZdwCEOrCMc0u
-----END CERTIFICATE-----
>ENDOFBUF
```

<---manually type this on a new line after the ----END OF CERTIFICATE---- line and press ENTER

Next, commit the change and then renew the license:

```
FPR-2-A /security/trustpoint* # comm
FPR-2-A /security/trustpoint # scope license
FPR-2-A /license # scope licdebug
FPR-2-A /license/licdebug # renew
```



You must now verify that the licensing has been renewed:

<#root>

FP9300-1-A-A-A /license/licdebug # show license all

Smart Licensing Status  
=====

Smart Licensing is ENABLED

Registration:

Status: REGISTERED  
Smart Account: TAC Cisco Systems, Inc.  
Virtual Account: CALO  
Export-Controlled Functionality: Allowed  
Initial Registration: SUCCEEDED on Jul 01 18:37:38 2018 UTC  
**Last Renewal Attempt: SUCCEEDED on Oct 09 17:39:07 2018 UTC**  
  
Next Renewal Attempt: Apr 07 17:39:08 2019 UTC  
Registration Expires: Oct 09 17:33:07 2019 UTC

License Authorization:

Status: AUTHORIZED on Oct 09 17:39:12 2018 UTC  
Last Communication Attempt: SUCCESS on Oct 09 17:39:12 2018 UTC  
Next Communication Attempt: Nov 08 17:39:12 2018 UTC  
Communication Deadline: Jan 07 17:33:11 2019 UTC

## ASA Software Installations That Require Federal Information Processing Standards (FIPS) Compliance

For ASA-based platforms that require FIPS compliance, the import of the QuoVadis Root CA 2 certificate can fail for nonconformance to signature cryptographic requirements and this message can be displayed:

Do you accept this certificate? [yes/no]: yes

Trustpoint CA certificate is not FIPS compliant.  
% Error in saving certificate: status = FAIL

As a workaround for FIPS compliant ASA installations, import the HydrantID SSL ICA G2 intermediate certificate. The HydrantID SSL ICA G2 certificate is shown next and complies with sha256WithRSAEncryption signature algorithm requirements, refer to the documentation shown on this article in order to load the certificate based on your platform:

-----BEGIN CERTIFICATE-----

MIIGxDCCBKyGAWIBAgIUdRcWd4PQQ361VsNXlG5FY7jr06wwDQYJKoZIhvcNAQEL  
BQAwRTElMAkGA1UEBhMCQk0xGTAXBgNVBAoTEFF1b1ZlZGlzIEVxpbl0ZWQxGzAZ

BgNVBAMTElF1b1ZhZGlzIFJvb3QgQ0EgMjAeFw0xMzEyMTcxNDI1MTBaFw0yMzEy  
MTcxNDI1MTBaMF4xCzAJBgNVBAYTA1VTMTAwLgYDVQKKEydIeWRyYW50SUQgKEF2  
YWxhbmNoZSBDbG91ZCBDb3Jwb3JhdGlvbikxHTAbBgNVBAMTFEh5ZHZHbnRJRjCBT  
U0wgSUNBIEcyMIICIjANBgkqhkiG9w0BAQEFAAOCAg8AMIICCGKCAgEA9p1Z0A9+  
H+tgdlN+STF7bd0xvn0ERYyjo8ZbKumzigNePSwbQYVWuso76GI843yjaX2rhn0+  
Jt0NVJM41jVctf9qwaCVduR7CEi0qJgpAUJyZUuB9IpFWF1Kz1403Leh6URRZ43  
RzHaRmNtzkxttGBU0tAg+i10uwiGAo9VQLgdONlqQFcrbp97/f08ZiQiPrbhLxCZ  
fXkYi3mktZVRFKXG62FHAuH1sLDXCKba3avDcUR7ykG4ZXcmp6k114UKa8JHOHPE  
NYyr0R6oHELOGZMox1nQcFwuYMX9sJdAUU/9SQVXYA6u6YtxlpZiC8qhXM1IE00T  
Q9+q5ppffSUDMC4V/5IF5A6snKVP78M8qd/RMVswcjmUMEnov+wykwCbDLD+IREm  
A57XX+HojN+8XFTL9Jwge3z3ZlMwL7E54W3cI7f6cx05DVwoKxkdk2jRIg37oqS1  
SU3z/bA9UXjHcT1/6BoLho2p9rWm6o1jANPeQuLHyGJ3hc19N8nDo2IATp70k1GP  
kd1qhIgrdkki7gBpanMOK98hKMPdQgs+NY4DkaMJqfrHzWR/CYkdyUCivFaepaFS  
K78+jVu1oCM0F0nucPXL2fQa3VQn+69+7mA324frjwZj9NzrHjd0a5UP7waPpd9W  
2jZoj4b+g+l+XU1SQ+9DWiuZtvfDW++k0BMCAwEAAa0CAZEwggGNMBIGA1UdEwEB  
/wQIMAYBAf8CAQAwEAYDVR0gBHEwZAIIBgZngQwBAGewCAYGZ4EMAQICMA4GDCsG  
AQQBvlgAAmQBAjBjBgwrbgEEAb5YAA0HBAAwOTA3BggrBgEFBQcCARYraHR0cDov  
L3d3dy5oeWRyYW50aWQuY29tL3N1cHBvcnQvcmlvbm3NpdG9yeTBjYBggrBgEFBQcB  
AQRmMGQwKgYIKwYBBQUHAGGhmdHA6Ly9vY3NwLnF1b3ZhZGlzZ2xvYmFsLmNvb  
bTA2BggrBgEFBQcAwYqAHR0cDovL3RydXN0LnF1b3ZhZGlzZ2xvYmFsLmNvbS9x  
dnJjYTIuY3J0MA4GA1UdDwEB/wQEAwIBBjAfBgNVHSMEGDAWgBQahGK8SEwzJQTU  
7tD2A8QZrTGUazA5BgNVHR8EMjAwMC6gLKAqhiodHRwOi8vY3JsLnF1b3ZhZGlz  
Z2xvYmFsLmNvbS9xdnJjYTIuY3JsMB0GA1UdDgQWBBSYarYtLr+nqp/299YJr9WL  
V/mKtzANBgkqhkiG9w0BAQsFAAOCAgEAlraik8EDDUkpAnIOaj09/r4dpj/Zry76  
6SH1oYPo7eTGzpdanPMeGMuSmwdjUkFUPALuWwkaDERfz9xdyFL3N8CRg9mQhdtT  
3aWQUv/iyXULXT87EgL3b8zzf8fhTS7r654m9WM2W7pFqfimx9qAlFe9XcV1ZrUu  
9hph+/MfWMrUju+VPL5U7hZvUpq66mS3BaN15rsXv2+Vw6kQsQC/82iJLHvtYVL/  
LwbNio18CsinDeyRE0J9wlyDqzcg5rhD0rtX4JEmBzq8yBRvHIB/023o/vIO5oxh  
83Hic/2Xgwkfs1DKS3/z5nTzhsUipCpwn6nHp6gmA8JBXoU1KQz4eYHJCq/ZyC+  
BuY2vHpNx6101J5dmy7ps7J7d6mZXzguP3DQN84hjtJfWJPqdf+/9RgLriXeFTqwe  
snxbk2FsPhwxhiNOH98GSZVvG02v10uHLVaf9B+puYpoUiEqgm1WG5mWW1PxHstu  
Ew9jBMcJ6wjQc8He9rSUMrhBr0HyhckdC99RgEvpCZpV2XL4nPPrTI2ki/c9xQb9  
kmhVGonSXY5aP+hDC+Ht+bxmc4wN5x+vB02hak8Hh8jIUSTRx0sRfJozU0R9ysyP  
EZAHFZ3Zivg2BaD4t0IS08/T2FDjG7PNUv0tgPAOKw2t94B+1evrSUhqJDU0Wf9c  
9vkaKoPvX4w=  
-----END CERTIFICATE-----

## Related Information

- [Cisco Technical Support & Downloads](#)