

Upgrade Software on Catalyst 9800 with N+1 Rolling AP Upgrade

Contents

[Introduction](#)

[Prerequisites](#)

[Requirements](#)

[Components Used](#)

[Background Information](#)

[WorkFlow](#)

[Rolling AP Upgrade Algorithm](#)

[1.Candidate AP Set Selection](#)

[2.Client Steering](#)

[3. AP Re-load and Re-join](#)

[Restrictions](#)

[Topology](#)

[Configuration](#)

[From GUI](#)

[From CLI](#)

[Verify](#)

[On Source WLC](#)

[On Destination WLC](#)

Introduction

This document describes how to perform an N+1 hitless software upgrade on Catalyst 9800 series Wireless LAN controllers.

Prerequisites

Requirements

Cisco recommends that you have knowledge of these topics:

- Catalyst 9800 Wireless LAN Controllers and AP (Cisco IOS® and ClickOS) platforms
- Catalyst 9800 Wireless LAN Controllers software feature sets

Components Used

The information provided in this document is based on the these software and hardware components.

- Catalyst C9800-40 and C9800-L-F-K9 wireless LAN Controllers
- Click OS and Cisco IOS® APs

The information in this document was created from the devices in a specific lab environment. All of the devices used in this document started with a cleared (default) configuration. If your network is live, ensure that you understand the potential impact of any command.

Background Information

The current CAPWAP implementation requires the WLC and the AP to be on the same software version. Therefore, a WLC upgrade is followed by APs upgrade which causes an inevitable network outage. With the current implementation, it is impossible to upgrade the WLC without scheduled downtime.

Hitless upgrade leverages the concept of N+1 high availability with a spare WLC (already upgraded to the target version) to upgrade the CAPWAP infrastructure. The APs are then upgraded in a staggered fashion, and they use the Rolling AP upgrade feature, which avoids network disruption and does not allow all the APs upgrade at once. This ensures that the clients are serviced by the neighbor APs while one of the APs undergoes the upgrade process.

WorkFlow

1. Upgrade the spare WLC to the target version.
2. Establish a mobility tunnel between the production WLC and the spare one.
3. Initiate the upgrade on the production controller with the **install add file** command.
4. Pre-download the APs.
5. Move the APs to the destination controller (spare WLC). APs are upgraded in a staggered fashion with the Rolling AP upgrade algorithm.
6. Once all the APs move to the spare WLC in multiple iterations activate the target image on production WLC.
7. The production WLC reloads for the new image to take effect.
8. Move all the APs back to the production controller.

Rolling AP Upgrade Algorithm

The algorithm works in three stages.

1. Candidate AP Set Selection

First, a set of candidates are selected based on nearby APs information. Rolling AP Upgrade algorithm selects the configured percentage of APs to be upgraded in each iteration while it maintains RF coverage

For wireless client service, coverage maintenance is important and hence, it takes precedence over selection of the required number of APs. Therefore,

For P = 25%, expected number of iterations for all APs to upgrade ~ 6

For P = 15%, expected number of iterations for all APs to upgrade ~ 12

For P = 5%, expected number of iterations for all APs to upgrade ~ 22

2. Client Steering

Clients on the candidate APs are steered to APs which are not in the candidate list before the candidate APs are rebooted. If the clients still persist on the candidate APs, they are sent a de-authentication frame and the AP reloads with the new image.

3. AP Re-load and Re-join

Past the client steering stage, the AP is reloaded with the new image.

At this point, a 3-minute timer is started for the APs to join back. When this timer expires, all candidate APs are checked and marked for the WLC they have connected to (self or the peer).


If at least 90% of the candidate APs have joined back, the iteration is concluded. If not, 3 minutes window is extended and the check is repeated for two more times until the count hits at least 90%.

At the end of the third try, the iteration is concluded anyway and the next iteration is initiated. Hence, each iteration lasts for, at most, 10 minutes.

Restrictions

- Non-client serving APs (like the ones that work in the monitor, sniffer mode) are upgraded in one go before the rest of the procedure starts.
- Mesh APs are not supported by rolling AP Upgrade. If the deployment has mesh APs, they are upgraded in one shot and at the end of all iterations.
- 16.10 only had a CLI option to configure.
- AP needs to be registered before GUI shows up the option to enable a hitless upgrade.
- The hitless upgrade is not supported by the controller running in BUNDLE mode.


Topology



Configuration

From GUI

 **Note:** From 16.11 onwards, the GUI option for N+1 hitless upgrade is only available when an AP is

 registered to the controller.

1. Establish the mobility tunnel between the controllers.

Configuration > Wireless > Mobility

Global Configuration Peer Configuration

Mobility Peer Configuration


+ Add

- Delete

MAC Address	IP Address	Public IP	Group Name	Multicast IPv4	Multicast IPv6	Status	MTU	SSC Hash	Data Link Encryption
04e8-8062-dc8b	10.106.36.110	N/A	default	0.0.0.0	::	N/A	N/A		N/A
<input type="checkbox"/>	0478-9b3c-4ecb	10.106.36.78	10.106.36.78	default	0.0.0.0	::	Up	1085	Disabled

1 - 2 of 2 items

2. Initiate the upgrade on the controller. Enable the hitless upgrade option as well. Optionally, enable **Fallback after upgrade** so that the APs move back to the parent controller (without a swap and reset) after activation of the new image and reloading of the parent controller.

 **Note:** Before this step, ensure that the destination WLC is already upgraded to the target code.

Software Upgrade

SMU

Upgrade Mode

INSTALL

Current Mode (until next reload): INSTALL

APSP

Transport Type

FTP

APDP

Server IP Address (IPv4/IPv6)*

[REDACTED]

FTP Username*

tftpuser

FTP Password*

.....

File Path*

C9800-40-universalk9_wlc.17.01.01s.SP

Hitless Software Upgrade

Enable Hitless Upgrade



Fallback after Upgrade



Controller IP Address (IPv4/IPv6)

10.106.36.78

Controller Name*

9800-L

Download & Install


3. Once all the stages are done, WLC prompts for a reload.

Status

- ✓ Download Image/Package
 - 📄 C9800-40-universalk9_wlc.17.01.01s.SPA.bin
- ✓ Install Image/Package
- ✓ AP Image Predownload
- ✓ AP Image Upgrade and Move
- 🔄 Install Activate and Commit...

[📄 Show Logs](#)

[📄 AP Upgrade Statistics](#)



From CLI

1. Establish the mobility tunnel between the controllers.

```
<#root>
```

```
9800-40(config)#wireless mobility group member mac-address d478.9b3c.4ecb ip 10.106.36.78 public-ip 10.106.36.78
```

```
9800-L(config)#wireless mobility group member mac-address d4e8.80b2.dc8b ip 10.106.36.110 public-ip 10.106.36.110
```

2. Initiate the upgrade on the controller.

```
<#root>
```

```
9800-40#install add file flash:C9800-40-universalk9_wlc.17.01.01s.SPA.bin
```

Once the installation is successful, the new image is in an inactive state.

```
<#root>
```

```
9800-40#show install summary
```

```
[ Chassis 1 ] Installed Package(s) Information:
```

```
State (St): I - Inactive, U - Activated & Uncommitted,
```

```
C - Activated & Committed, D - Deactivated & Uncommitted
```

```
-----  
Type St Filename/Version  
-----
```

```
IMG I 17.1.1s.0.351
```

```
IMG C 16.12.2s.0.47  
-----
```

```
Auto abort timer: inactive  
-----
```

3. Initiate the pre-download on APs to load the new image as the backup on the APs.

```
<#root>
```

```
9800-40#ap image predownload
```

In order to check the status of pre-download, use this command.

```
<#root>
```

```
9800-40#show ap image
```

```
Total number of APs: 5
```

```
Number of APs
```

```
Initiated : 0
```

```
Predownloading : 1
```

```
Completed predownloading : 3
```

Not Supported	:	0		
Failed to Predownload	:	0		
Predownload in progress	:	Yes		
AP Name		Primary Image	Backup Image	Predownload Status

AP3800		16.12.2.132	17.1.1.29	Complete
3800-2		16.12.2.132	17.1.1.29	Complete
4800-1		16.12.2.132	17.1.1.29	Complete
3702I-2		16.12.2.132	0.0.0.0	Predownloading

4. Optionally, if you are required to configure the percentage of APs to be upgraded per iteration, this command can be used. The default value is 15.

```
<#root>
```

```
9800-40(config)#ap upgrade staggered ?
 15      15 percent APs per iteration
 25      25 percent APs per iteration
 5       5 percent APs per iteration
one-shot All APs in one shot, no staggering
```

5. Once the pre-download is complete on all the APs, move the APs to the spare controller that runs on the updated code.

```
<#root>
```

```
9800-40#ap image upgrade destination 9800-L 10.106.36.78 fallback
```

This command moves the APs to the specified destination WLC with a **swap** and **reset** command. **Swap** command interchanges the AP image so that the target code is marked as the primary image for the APs, whereas, **reset** command reloads the AP. It is assumed that the destination WLC is on the same version as the APs backup image.

Optionally, you can use the fallback keyword to enable **Fallback after Upgrade** option so that the APs move back to the parent controller (without a swap and reset) after activation of the new image and reloading of the source controller.

6. Once all the APs have moved to the destination controller, activate the image on the source WLC.

On Destination WLC, verify if all the APs have moved successfully.

```
<#root>
```

```
9800-L#show ap upgrade
AP upgrade is complete, fallback awaited
Fallback type: Fallback only
From version: 16.12.2.132
```


To version: 17.1.1.29

Started at: 04/13/2020 02:32:09 UTC

Configured percentage: N/A

Percentage complete: 100

End time: 04/13/2020 02:56:09 UTC

Progress Report

Iterations

Iteration	Start time	End time	AP count
0	04/13/2020 02:32:09 UTC	04/13/2020 02:32:09 UTC	1
1	04/13/2020 02:32:09 UTC	04/13/2020 02:38:09 UTC	1
2	04/13/2020 02:38:09 UTC	04/13/2020 02:44:09 UTC	1
3	04/13/2020 02:44:09 UTC	04/13/2020 02:47:09 UTC	1
4	04/13/2020 02:47:09 UTC	04/13/2020 02:56:09 UTC	1

Upgraded

Number of APs: 5

AP Name	Radio MAC	Iteration	Status	Site
AP3800	1880.9021.e0e0	0	Joined	default-s
3800-2	1880.9021.e280	1	Joined	default-s
9130-1	04eb.409f.9760	2	Joined	default-s
4800-1	dc8c.3746.b0e0	3	Joined	default-s
3702I-2	fc5b.39f1.c7e0	4	Joined	Unknown

In Progress

Number of APs: 0

AP Name	Radio MAC
---------	-----------

Remaining

Number of APs: 0

AP Name	Radio MAC
---------	-----------

APs not handled by Rolling AP Upgrade

AP Name	Radio MAC	Status	Reason for not handling by Ro
---------	-----------	--------	-------------------------------

On Source WLC, activate the **image**. Type **yes** to all the prompts. Once the install is complete, the controller proceeds to reload.

<#root>

9800-40#install activate

install_add_activate_commit: Activating PACKAGE

These packages shall be activated:

/bootflash/C9800-L-rpboot.17.01.01s.SPA.pkg

/bootflash/C9800-L-mono-universalk9_wlc.17.01.01s.SPA.pkg


/bootflash/C9800-L-hw-programmables.17.01.01s.SPA.pkg

```
This operation requires a reload of the system. Do you want to proceed? [y/n]y
--- Starting Activate ---
Performing Activate on all members
  [1] Activate package(s) on chassis 1
  [1] Finished Activate on chassis 1
Checking status of Activate on [1]
Activate: Passed on [1]
Finished Activate
```

Post-reload, commit the image with this command.

```
<#root>
9800-40#install commit
```

7. If you have not enabled **Fallback after Upgrade** option (as mentioned in Step 5) use this command on destination WLC to move back the APs to the source WLC, once the source WLC is upgraded to the latest code.

 **Note:** Use this command on destination WLC, only if **Fallback after upgrade** (in step 5) option was not enabled while the hitless upgrade is initiated.

On source WLC:

```
<#root>
9800-40#show version | i Version
Cisco IOS XE Software,
Version 17.01.01s
Cisco IOS Software [Amsterdam], C9800 Software (C9800_IOSXE-K9), Version 17.1.1s, RELEASE SOFTWARE (fc4
```

On Destination WLC:

```
<#root>
9800-I#ap image move destination 9800-40 10.106.36.110
```

This command moves the APs back to the source WLC without a **swap** and **reset** command.

8. All the APs join back the source WLC and the latest image must be in a committed state.

```
9800-40#show install summary
[ Chassis 1/R0 ] Installed Package(s) Information:
State (St): I - Inactive, U - Activated & Uncommitted,
```

C - Activated & Committed, D - Deactivated & Uncommitted

```
-----  
Type St  Filename/Version  
-----
```

```
IMG  C   17.1.1s.0.351  
-----
```

```
Auto abort timer: inactive  
-----
```

```
9800-40#show ap summary  
Number of APs: 5
```

AP Name	Slots	AP Model	Ethernet MAC	Radio MAC	Location
9130-1	2	9130AXI	04eb.409e.2620	04eb.409f.9760	default location
AP3800	2	3802I	a023.9fae.f48a	1880.9021.e0e0	default location
3800-2	2	3802I	a023.9fae.f4a4	1880.9021.e280	default location
4800-1	3	4800	dc8c.370e.b2da	dc8c.3746.b0e0	default location
3702I-2	2	3702I	fc5b.39d9.f4b4	fc5b.39f1.c7e0	default location

Verify

- Ensure that the WLC runs in INSTALL mode. The hitless upgrade is not supported in the BUNDLE mode.

```
<#root>
```

```
9800-40#show version | i mode
```

```
Installation mode is INSTALL
```

- The mobility tunnel between the controllers must be UP.

```
<#root>
```

```
9800-40#show wireless mobility summary
```

```
Mobility Summary
```

```
Wireless Management VLAN: 36  
Wireless Management IP Address: 10.106.36.110  
Wireless Management IPv6 Address:  
Mobility Control Message DSCP Value: 48  
Mobility Keepalive Interval/Count: 10/3  
Mobility Group Name: default  
Mobility Multicast Ipv4 address: 0.0.0.0  
Mobility Multicast Ipv6 address: ::  
Mobility MAC Address: d4e8.80b2.dc8b  
Mobility Domain Identifier: 0x34ac
```

```
Controllers configured in the Mobility Domain:
```

IP	Public Ip	MAC Address	Group Name	Multicast IPv4	Multicast IPv6
----	-----------	-------------	------------	----------------	----------------

```

10.106.36.110    N/A                d4e8.80b2.dc8b    default    0.0.0.0    ::
10.106.36.78    10.106.36.78        d478.9b3c.4ecb    default    0.0.0.0    ::

```

- In order to monitor the AP upgrade, use these commands.

On Source WLC

<#root>

```

9800-40#show ap upgrade
AP upgrade is in progress

```

Fallback type: Fallback only

From version: 16.12.2.132

To version: 17.1.1.29

Started at: 04/12/2020 21:02:09 India

Configured percentage: 15

Percentage complete: 80

Expected time of completion: 04/12/2020 22:22:09 India

Progress Report

Iterations

Iteration	Start time	End time	AP count
0	04/12/2020 21:02:09 India	04/12/2020 21:02:09 India	1
1	04/12/2020 21:02:09 India	04/12/2020 21:08:09 India	1
2	04/12/2020 21:08:09 India	04/12/2020 21:14:09 India	1
3	04/12/2020 21:14:09 India	04/12/2020 21:17:09 India	1
4	04/12/2020 21:17:09 India	ONGOING	1

Upgraded

Number of APs: 4

AP Name	Radio MAC	Iteration	Status	Site
AP3800	1880.9021.e0e0	0	Joined Member	default-s
3800-2	1880.9021.e280	1	Joined Member	default-s
9130-1	04eb.409f.9760	2	Joined Member	default-s
4800-1	dc8c.3746.b0e0	3	Joined Member	default-s

In Progress

Number of APs: 1

AP Name	Radio MAC
3702I-2	fc5b.39f1.c7e0

Remaining

Number of APs: 0

AP Name	Radio MAC
---------	-----------

APs not handled by Rolling AP Upgrade

AP Name	Radio MAC	Status	Reason for not handling by Ro
---------	-----------	--------	-------------------------------

On Destination WLC

9800-L#show ap upgrade
AP upgrade is in progress

Fallback type: Fallback only

From version: 16.12.2.132
To version: 17.1.1.29

Started at: 04/13/2020 02:32:09 UTC
Configured percentage: N/A
Percentage complete: 80
Expected time of completion: 04/13/2020 03:52:09 UTC

Progress Report

Iterations

Iteration	Start time	End time	AP count
0	04/13/2020 02:32:09 UTC	04/13/2020 02:32:09 UTC	1
1	04/13/2020 02:32:09 UTC	04/13/2020 02:38:09 UTC	1
2	04/13/2020 02:38:09 UTC	04/13/2020 02:44:09 UTC	1
3	04/13/2020 02:44:09 UTC	04/13/2020 02:47:09 UTC	1
4	04/13/2020 02:47:09 UTC	ONGOING	0

Upgraded

Number of APs: 4

AP Name	Radio MAC	Iteration	Status	Site
AP3800	1880.9021.e0e0	0	Joined	default-s
3800-2	1880.9021.e280	1	Joined	default-s
9130-1	04eb.409f.9760	2	Joined	default-s
4800-1	dc8c.3746.b0e0	3	Joined	default-s

In Progress

Number of APs: 1

AP Name	Radio MAC
3702I-2	fc5b.39f1.c7e0

Remaining

Number of APs: 0

AP Name	Radio MAC
---------	-----------

APs not handled by Rolling AP Upgrade

```

-----
AP Name                               Radio MAC                               Status                               Reason for not handling by Rol
-----

```

<#root>

9800-L#show ap upgrade summary

```

Report Name                               Start time
-----
AP_upgrade_from_9800-40_13320202329      04/13/2020 02:32:09 UTC

```

9800-L#show ap upgrade name AP_upgrade_from_9800-40_13320202329

AP upgrade is in progress

Fallback type: Fallback only

From version: 16.12.2.132

To version: 17.1.1.29

Started at: 04/13/2020 02:32:09 UTC

Configured percentage: N/A

Percentage complete: 60

Expected time of completion: 04/13/2020 03:52:09 UTC

Progress Report

Iterations

```

Iteration                               Start time                               End time                               AP count
-----
0                                         04/13/2020 02:32:09 UTC                 04/13/2020 02:32:09 UTC                 1
1                                         04/13/2020 02:32:09 UTC                 04/13/2020 02:38:09 UTC                 1
2                                         04/13/2020 02:38:09 UTC                 04/13/2020 02:44:09 UTC                 1
3                                         04/13/2020 02:44:09 UTC                 ONGOING                                  0

```

Upgraded

Number of APs: 3

```

AP Name                               Radio MAC                               Iteration                               Status                               Site
-----
AP3800                               1880.9021.e0e0                           0                                         Joined                               default-s
3800-2                               1880.9021.e280                           1                                         Joined                               default-s
9130-1                               04eb.409f.9760                           2                                         Joined                               default-s

```

In Progress

Number of APs: 1

```

AP Name                               Radio MAC
-----
4800-1                               dc8c.3746.b0e0

```

Remaining

Number of APs: 0

```

AP Name                               Radio MAC
-----

```

APs not handled by Rolling AP Upgrade

