



Release Notes for Cisco cBR Series Converged Broadband Routers for Cisco IOS-XE Release 3.18S

Last Modified: 2017-04-21

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
<http://www.cisco.com>
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 527-0883



CONTENTS

CHAPTER 1

Introduction 1

System Requirements 1

Memory Requirements 1

Hardware Supported 2

Determining the Software Version 2

Microcode Software 3

Cisco IOS-XE Release 3.18.3aSP 3

Cisco IOS-XE Release 3.18.2aSP 3

Cisco IOS-XE Release 3.18.1aSP 4

Cisco IOS-XE Release 3.18.1SP 5

Cisco IOS-XE Release 3.18.0SP 6

Cisco IOS-XE Release 3.18.1S 6

Cisco IOS-XE Release 3.18.0Sa 6

Cisco IOS-XE Release 3.18.0S 6

Cisco IOS-XE Release 3.17.1S 6

Cisco IOS-XE Release 3.16.2S 7

Cisco IOS-XE Release 3.17.0S 7

Cisco IOS-XE Release 3.16.1S 7

Cisco IOS-XE Release 3.16.0S 7

Cisco IOS-XE Release 3.15.0S 8

Feature Support 9

New and Changed Information 9

New Firmware Features in Cisco IOS-XE Release 3.18.3aSP 9

New Firmware Features in Cisco IOS-XE Release 3.18.2aSP 9

New Firmware Features in Cisco IOS-XE Release 3.18.1aSP 10

| | |
|--|----|
| New Firmware Features in Cisco IOS-XE Release 3.18.1SP | 10 |
| New Firmware Features in Cisco IOS-XE Release 3.18.0SP | 10 |
| New Firmware Features in Cisco IOS-XE Release 3.18.1S | 10 |
| New Firmware Features in Cisco IOS-XE Release 3.18.0Sa | 10 |
| New Firmware Features in Cisco IOS-XE Release 3.18.0S | 10 |
| Upstream DOCSIS 3.1 PHY Module | 10 |
| New Firmware Features in Cisco IOS-XE Release 3.17 0S | 10 |
| New Hardware Features in Cisco IOS-XE Release 3.18.3aSP | 10 |
| New Hardware Features in Cisco IOS-XE Release 3.18.2aSP | 10 |
| New Hardware Features in Cisco IOS-XE Release 3.18.1aSP | 11 |
| New Hardware Features in Cisco IOS-XE Release 3.18.1SP | 11 |
| New Hardware Features in Cisco IOS-XE Release 3.18.0SP | 11 |
| New Hardware Features in Cisco IOS-XE Release 3.18.1S | 11 |
| New Hardware Features in Cisco IOS-XE Release 3.18.0Sa | 11 |
| New Hardware Features in Cisco IOS-XE Release 3.18.0S | 11 |
| Cisco cBR DOCSIS 3.1 Upstream PHY Module | 11 |
| New Hardware Features in Cisco IOS-XE Release 3.17.1S | 11 |
| New Hardware Features in Cisco IOS-XE Release 3.16.2S | 11 |
| New Hardware Features in Cisco IOS-XE Release 3.17 0S | 11 |
| Sup-60 Productization | 11 |
| Single Downstream PHY Module Line Card Configuration Support | 12 |
| New Hardware Features in Cisco IOS-XE Release 3.16.1S | 12 |
| New Hardware Features in Cisco IOS-XE Release 3.16.0S | 12 |
| CBR-CCAP-SUP-60G | 12 |
| Downstream DOCSIS 3.1 PHY Module | 12 |
| New Hardware Features in Cisco IOS-XE Release 3.15.1S | 12 |
| New Hardware Features in Cisco IOS-XE Release 3.15.0S | 13 |
| New Software Features in Cisco IOS-XE Release 3.18.3aSP | 13 |
| New Software Features in Cisco IOS-XE Release 3.18.2aSP | 13 |
| New Software Features in Cisco IOS-XE Release 3.18.1aSP | 13 |
| New Software Features in Cisco IOS-XE Release 3.18.1SP | 13 |
| MAC Filtering | 13 |
| AES-128 for non-MTC DOCSIS3.0 Cable Modem | 13 |
| DOCSIS 3.1 Downstream OFDMA Guardband Enhancements | 14 |

| | |
|--|----|
| New Software Features in Cisco IOS-XE Release 3.18.0SP | 14 |
| DOCSIS 3.1 2000 Bytes Data PDUs | 14 |
| DOCSIS 3.1 Adaptive CIR, Fair EIR (ACFE) | 14 |
| DOCSIS 3.1 BPI Authorization Changes | 14 |
| DOCSIS 3.1 DS: Commanded Power for US SC-QAMs | 14 |
| DOCSIS 3.1 DS LCHA HA | 15 |
| DOCSIS 3.1 DS LCPR | 15 |
| DOCSIS 3.1 DS Profile Selection | 15 |
| DOCSIS 3.1 DS SUP HA | 15 |
| DOCSIS 3.1 Interop with Intel Puma7 based CM | 15 |
| DOCSIS 3.1 OFDM Channel Licensing | 16 |
| DOCSIS 3.1 Path Selection | 16 |
| DOCSIS 3.1 Protocol Enable or Disable | 16 |
| DOCSIS 3.1 QoS | 16 |
| DOCSIS 3.1 SGAC | 16 |
| Full Spectrum 108-1218 MHz Support | 17 |
| IPv6 DQoS Lite | 17 |
| Lawful Intercept- Overlapping Taps and Redundant MDs | 17 |
| MTPS Pass-Through | 17 |
| OFDM Channel Support for All Ports | 17 |
| QAM Replication | 18 |
| Show Patch Info in One CLI | 18 |
| Switched Digital Video | 18 |
| UCD TLV for Device Type (Ranging Hold Off) | 18 |
| Video ISSU Improvement | 18 |
| New Software Features in Cisco IOS-XE Release 3.18.1S | 19 |
| New Software Features in Cisco IOS-XE Release 3.18.0Sa | 19 |
| Using VRF for Video Session Traffic | 19 |
| New Software Features in Cisco IOS-XE Release 3.18.0S | 19 |
| Video Services Provisioning Model | 19 |
| Video Virtual Carrier Group and Virtual Edge Input | 19 |
| Advanced Video MPEG Features | 20 |
| Important Notes | 20 |
| PME Video On Demand | 20 |

| | |
|---|----|
| Video QAM Replication | 21 |
| PowerKEY Video On Demand | 21 |
| Video Encryption | 21 |
| Table Based Configuration | 22 |
| PacketCable and PacketCable Multimedia Multicast | 22 |
| Physical to Virtual Binding | 22 |
| Online Offline Diagnostics | 23 |
| Voice over IPv6 | 23 |
| Cable Line Card Process Restart on Crash | 23 |
| BSoD VLAN Redundancy | 23 |
| L2VPN Over Port-Channel | 24 |
| Energy Management | 24 |
| Show Command to display SF Counts | 24 |
| Service Distribution Group | 25 |
| Video QAM Carriers | 25 |
| Management IP Interface | 25 |
| Logical Edge Devices | 26 |
| Global Video Configuration | 26 |
| D6 Discovery Protocol | 26 |
| Cisco Smart Licensing for Video | 27 |
| New Software Features in Cisco IOS-XE Release 3.17.1S | 27 |
| New Software Features in Cisco IOS-XE Release 3.16.2S | 27 |
| New Software Features in Cisco IOS-XE Release 3.17.0S | 27 |
| MPLS QoS via TLV for non-L2VPN | 27 |
| Service Flow Priority in Downstream Extended Header | 27 |
| Configuring UCSB Required Attribute | 27 |
| IPDR CM-STATUS-2008 | 28 |
| Service Group Profile Based Configuration | 28 |
| Subscriber Traffic Management | 28 |
| New Software Features in Cisco IOS-XE Release 3.16.1S | 29 |
| New Software Features in Cisco IOS-XE Release 3.16.0S | 29 |
| Battery Backup 1x1 Mode | 29 |
| Downstream and Upstream JIB Partial Reset | 29 |
| N+1 Line Card Redundancy | 29 |

| | |
|--|----|
| Cable IOSd Restart | 30 |
| US Channel Scaling from 64 to 96 channels | 30 |
| RP only ISSU | 30 |
| Service Group Admission Control | 30 |
| New Software Features in Cisco IOS-XE Release 3.15.1S | 31 |
| New Software Features in Cisco IOS-XE Release 3.15.0S | 31 |
| Modified Software Features in Cisco IOS-XE Release 3.18.3aSP | 35 |
| Modified Software Features in Cisco IOS-XE Release 3.18.2aSP | 35 |
| Modified Software Features in Cisco IOS-XE Release 3.18.1aSP | 36 |
| Modified Software Features in Cisco IOS-XE Release 3.18.1SP | 36 |
| DOCSIS 3.1 Downstream OFDM Graceful Profile Assignment | 36 |
| Usage-Based Billing | 36 |
| show cable modem summary sen | 36 |
| show cable modem service-flow | 36 |
| Enhanced Cable modem provisioning | 36 |
| Modified Software Features in Cisco IOS-XE Release 3.18.0SP | 37 |
| Modified Software Features in Cisco IOS-XE Release 3.18.1S | 37 |
| Modified Software Features in Cisco IOS-XE Release 3.18.0Sa | 37 |
| Modified Software Features in Cisco IOS-XE Release 3.18.0S | 37 |
| 16 US per MAC Domain | 37 |
| SNMP Cache Engine Enhancement | 37 |
| Configurable Burst mode MER | 37 |
| Three Step Dynamic Modulation | 37 |
| Modified Software Features in Cisco IOS-XE Release 3.17.1S | 38 |
| Modified Software Features in Cisco IOS-XE Release 3.16.2S | 38 |
| Modified Software Features in Cisco IOS-XE Release 3.17.0S | 38 |
| Smart Licensing Enforcement | 38 |
| Adaptive CIR, Fair EIR | 38 |
| ISSU with N+1 | 38 |
| Upstream Bonding Support for D-PON | 39 |
| Dynamic Downstream DOCSIS 3.0 Load Balancing | 39 |
| Priority Queues | 39 |
| Flexible Bandwidth Allocation | 40 |
| Cable Line Card Upstream Scheduler Process Restart | 40 |

| | |
|---|----|
| Modified Software Features in Cisco IOS-XE Release 3.16.1S | 40 |
| Modified Software Features in Cisco IOS-XE Release 3.16.0S | 40 |
| Downstream DOCSIS 3.1 PHY Module Upgrade | 40 |
| MIBs | 40 |
| New and Changed MIB Information in Cisco IOS-XE Release 3.18.3aSP | 41 |
| New and Changed MIB Information in Cisco IOS-XE Release 3.18.2aSP | 41 |
| New and Changed MIB Information in Cisco IOS-XE Release 3.18.1aSP | 41 |
| New and Changed MIB Information in Cisco IOS-XE Release 3.18.1SP | 41 |
| New and Changed MIB Information in Cisco IOS-XE Release 3.18.0SP | 41 |
| New and Changed MIB Information in Cisco IOS-XE Release 3.18.1S | 41 |
| New and Changed MIB Information in Cisco IOS-XE Release 3.18.0Sa | 41 |
| New and Changed MIB Information in Cisco IOS-XE Release 3.18.0S | 41 |
| New and Changed MIB Information in Cisco IOS-XE Release 3.17.1S | 42 |
| New and Changed MIB Information in Cisco IOS-XE Release 3.16.2S | 42 |
| New and Changed MIB Information in Cisco IOS-XE Release 3.17.0S | 42 |
| New and Changed MIB Information in Cisco IOS-XE Release 3.16.0S | 42 |
| Important Notes for Cisco IOS-XE Release 3S | 42 |
| Important Notes for Cisco IOS-XE Release 3.18.0SP | 42 |
| Important Notes for Cisco IOS-XE Release 3.18.0S | 42 |
| Important Notes for Cisco IOS-XE Release 3.16.0S | 42 |
| Important Notes for Cisco IOS-XE Release 3.15.0S | 43 |
| Cisco IOS-XE Release 3S Image Upgrade Best Practice Manual of Procedure | 43 |
| Obtaining Documentation and Submitting a Service Request | 43 |

CHAPTER 2
Caveat List 45

| | |
|---|----|
| Cisco Bug Search | 46 |
| Important Software Upgrade | 47 |
| Open Caveats - Cisco IOS-XE Release 3.18.3bSP | 47 |
| Resolved Caveats—Cisco IOS-XE Release 3.18.3bSP | 49 |
| Open Caveats—Cisco IOS-XE Release 3.18.3aSP | 49 |
| Resolved Caveats—Cisco IOS-XE Release 3.18.3aSP | 51 |
| Open Caveats—Cisco IOS-XE Release 3.18.2aSP | 52 |
| Resolved Caveats—Cisco IOS-XE Release 3.18.2aSP | 55 |
| Open Caveats—Cisco IOS-XE Release 3.18.1aSP | 57 |

Resolved Caveats—Cisco IOS-XE Release 3.18.1aSP 59

Open Caveats—Cisco IOS-XE Release 3.18.1SP 59

Resolved Caveats—Cisco IOS-XE Release 3.18.1SP 61

Open Caveats—Cisco IOS-XE Release 3.18.0SP 63

Resolved Caveats—Cisco IOS-XE Release 3.18.0SP 64

Open Caveats—Cisco IOS-XE Release 3.18.1S 69

Resolved Caveats—Cisco IOS-XE Release 3.18.1S 69

Open Caveats—Cisco IOS-XE Release 3.18.0Sa 71

Resolved Caveats—Cisco IOS-XE Release 3.18.0Sa 71

Open Caveats—Cisco IOS-XE Release 3.18.0S 72

Resolved Caveats—Cisco IOS-XE Release 3.18.0S 73

Open Caveats—Cisco IOS-XE Release 3.17.1S 74

Resolved Caveats—Cisco IOS-XE Release 3.17.1S 75

Open Caveats—Cisco IOS-XE Release 3.16.7S 76

Resolved Caveats—Cisco IOS-XE Release 3.16.7S 76

Open Caveats—Cisco IOS-XE Release 3.16.2S 77

Resolved Caveats—Cisco IOS-XE Release 3.16.2S 79

Open Caveats—Cisco IOS-XE Release 3.17.0S 83

Resolved Caveats—Cisco IOS-XE Release 3.17.0S 84

Open Caveats—Cisco IOS-XE Release 3.16.1S 90

Resolved Caveats—Cisco IOS-XE Release 3.16.1S 93

Open Caveats—Cisco IOS-XE Release 3.16.0S 96

Resolved Caveats—Cisco IOS-XE Release 3.16.0S 96

Open Caveats—Cisco IOS-XE Release 3.15.1S 98

Resolved Caveats—Cisco IOS-XE Release 3.15.1S 98

Open Caveats—Cisco IOS-XE Release 3.15.0S 99

Resolved Caveats—Cisco IOS-XE Release 3.15.0S 101



CHAPTER 1

Introduction

This release notes contain information about downloading and installing Cisco IOS-XE Release 3S. It also provides new and changed information, hardware support, limitations and restrictions, and caveats for Cisco IOS-XE Release 3S.

We recommend that you view the field notices for this release to see if your software or hardware platforms are affected. If you have an account on Cisco.com, you can find field notices at http://www.cisco.com/en/US/customer/support/tsd_products_field_notice_summary.html.

If you do not have a Cisco.com login account, you can find field notices at http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html.



Note Cisco IOS-XE Release 3S is generally available for field deployment. However, we recommend that you validate and qualify Cisco IOS-XE Release 3S in a limited field trial with your specific network configuration requirements in order to ensure a smoother, faster, and successful field deployment.

This chapter includes the following sections:

- [System Requirements, on page 1](#)
- [New and Changed Information, on page 9](#)
- [MIBs, on page 40](#)
- [Important Notes for Cisco IOS-XE Release 3S, on page 42](#)
- [Cisco IOS-XE Release 3S Image Upgrade Best Practice Manual of Procedure, on page 43](#)
- [Obtaining Documentation and Submitting a Service Request, on page 43](#)

System Requirements

These sections describe the system requirements for Cisco IOS-XE Release 3S:

Memory Requirements

This section describes the memory requirements for Cisco IOS-XE Release 3S.

The following table displays the memory recommendations for the Cisco cBR Series Converged Broadband Routers with Cisco IOS-XE Release 3S feature sets.

Table 1: Memory Recommendations for the Cisco cBR Series Converged Broadband Routers

| Feature Set | Cisco cBR Route Processor | Software Image | RecommendedFlash Memory | RecommendedDRAM Memory | RunsFrom |
|--------------------------|-------------------------------|---|-------------------------|------------------------|------------|
| CISCO IOS-XE universalk9 | Cisco cBR8 (CBR) Processor | cbrsup-universalk9.03.15.00.S.155-2.S-std.SPA.bin | 8G | 48G | Bootflash: |
| CISCO IOS-XE CLC K9 | Cisco cBR8 (CYLONS) Processor | cbrsup-universalk9.03.15.00.S.155-2.S-std.SPA.bin | 8G | 16G | Supervisor |

Hardware Supported

For detailed information about the hardware supported in Cisco IOS-XE Release 3S, see:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/installation/guide/b_cbr_how_and_what_to_order.html.



Note The Cisco cBR chassis must house line cards with either Downstream DOCSIS 3.0 PHY modules or Downstream DOCSIS 3.1 PHY modules. Mixed configuration is not supported.

Determining the Software Version

To determine the version of the Cisco IOS-XE software running on your Cisco cBR Series Converged Broadband Routers, log in to the router and enter the **show version** EXEC command:

```
Router# show version
Cisco IOS XE Software, Version 03.15.00.S - Standard Support Release
Cisco IOS Software, cBR Software (X86_64_LINUX_IOSD-UNIVERSALK9-M), Version 15.5(2)S,
RELEASE SOFTWARE (fc3)
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2015 by Cisco Systems, Inc.
Compiled Sun 22-Mar-15 03:32 by mcpre
Cisco IOS-XE software, Copyright (c) 2005-2015 by cisco Systems, Inc. All rights reserved.
Certain components of Cisco IOS-XE software are licensed under the GNU General Public
License ("GPL") Version 2.0. The software code licensed under GPL Version 2.0 is free
software that comes with ABSOLUTELY NO WARRANTY. You can redistribute and/or modify such
GPL code under the terms of GPL Version 2.0. For more details, see the documentation or
"License Notice" file accompanying the IOS-XE software, or the applicable URL provided on
the flyer accompanying the IOS-XE software.
ROM: IOS-XE ROMMON
Tmaker uptime is 3 hours, 23 minutes
Uptime for this control processor is 3 hours, 26 minutes
System returned to ROM by reload
System restarted at 20:19:18 PST Wed Mar 25 2015
System image file is "bootflash:cbrsup-universalk9.03.15.00.S.155-2.S-std.SPA.bin"
Last reload reason: redundancy force-switchover
This product contains cryptographic features and is subject to United States and local
country laws governing import, export, transfer and use. Delivery of Cisco cryptographic
products does not imply third-party authority to import, export, distribute or use encryption.
Importers, exporters, distributors and users are responsible for compliance with U.S. and
local country laws. By using this product you agree to comply with applicable laws and
```

regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at:
<http://www.cisco.com/wwl/export/crypto/tool/stqrg.html>

If you require further assistance please contact us by sending email to export@cisco.com.

cisco cBR1013 (CBR) processor (revision CBR) with 10483520K/6147K bytes of memory.
 Processor board ID FXS181902A9
 16 Gigabit Ethernet interfaces
 32768K bytes of non-volatile configuration memory.
 50331648K bytes of physical memory.
 7739391K bytes of eUSB flash at bootflash:.
 97620247K bytes of SATA hard disk at harddisk:.
 Configuration register is 0x1820

Microcode Software

This section describes microcode software that is supported for the Cisco cBR Series Converged Broadband Routers.

For more information on the upgrade procedures, see the [Upgrade Guides](#).

Cisco IOS-XE Release 3.18.3aSP

There are no new microcode versions for Cisco IOS-XE Release 3.18.3aSP. Use the minimum required versions and upgrade methods for Cisco IOS-XE Release 3.18.2aSP described below.

Cisco IOS-XE Release 3.18.2aSP

Table 2: Downstream Module Firmware Version Supported in Cisco IOS-XE Release 3.18.2aSP

| Component | Programmable Device | Existing Versions (In Field) | Minimum Required Version (With IOS-XE 3.18.2aSP) |
|--------------------------|---------------------|---|--|
| Gemini-2 LC ¹ | Apollo Version | 44147 44141 4413D 44131 31030 | 44148 |

¹ CBR-D31-DS-MOD

Cisco IOS-XE Release 3.18.2aSP Upgrade Package:
[cbrsup-rp-programmable-firmware.156-2.r.SP2-ext.01.SPA.pkg](#)

Cisco IOS-XE Release 3.18.1aSP

Table 3: Downstream Module Firmware Versions Supported in Cisco IOS-XE Release 3.18.1aSP

| Component | Programmable Device | Existing Versions (In Field) | Minimum Required Version(s) (With IOS-XE 3.18.1aSP) |
|--------------------------|-------------------------|--------------------------------------|--|
| CBR-CCAP-SUP-160G | CPLD version | 16012711 15091511 14121111 | 16012711 or 15091511 |
| CBR-CCAP-SUP-160G | Rommon version | 15.5(3r)S 15.5(2r)S1 15.5(2r)S | 15.5(3r)S |
| CBR-CCAP-LC-40G | Rommon version | 2011.03.13 2011.03.12 | 2011.03.13 |
| CBR-CCAP-LC-40G | PSOC 0 version | v4.6 v4.3 | v4.6 |
| CBR-CCAP-LC-40G | PSOC 1 version | v4.6 v4.3 | v4.6 |
| Gemini-1 LC ² | MicroController Version | 1000c 10008 10005 10006 | 1000e |
| Gemini-2 LC ³ | MicroController Version | 30013 30010 2.000c 2.000a | 30016 |
| Gemini-2 LC ⁴ | Apollo Version | 44141 4413D 44131 31030 | 44147 |

² CBR-D30-DS-MOD

³ CBR-D31-DS-MOD

⁴ CBR-D31-DS-MOD

Cisco IOS-XE Release 3.18.1aSP Upgrade Package:
[cbrsup-rp-programmable-firmware.156-2.r.SP1-ext.01.SPA.pkg](#)

Cisco IOS-XE Release 3.18.1SP

Table 4: Downstream Module Firmware Versions Supported in Cisco IOS-XE Release 3.18.1SP

| Component | Programmable Device | Existing Versions (In Field) | Minimum Required Version(s) (With IOS-XE 3.18.1SP) |
|--------------------------|-------------------------|--------------------------------------|---|
| CBR-CCAP-SUP-160G | CPLD version | 16012711 15091511 14121111 | 16012711 or 15091511 |
| CBR-CCAP-SUP-160G | Rommon version | 15.5(3r)S 15.5(2r)S1 15.5(2r)S | 15.5(3r)S |
| CBR-CCAP-LC-40G | Rommon version | 2011.03.13 2011.03.12 | 2011.03.13 |
| CBR-CCAP-LC-40G | PSOC 0 version | v4.6 v4.3 | v4.6 |
| CBR-CCAP-LC-40G | PSOC 1 version | v4.6 v4.3 | v4.6 |
| Gemini-1 LC ⁵ | MicroController Version | 1000c 10008 10005 10006 | 1000e |
| Gemini-2 LC ⁶ | MicroController Version | 30013 30010 2.000c 2.000a | 30016 |
| Gemini-2 LC ⁷ | Apollo Version | 44141 4413D 44131 31030 | 44147 |

- ⁵ CBR-D30-DS-MOD
- ⁶ CBR-D31-DS-MOD
- ⁷ CBR-D31-DS-MOD

Cisco IOS-XE Release 3.18.1SP Upgrade Package:
[cbrsup-rp-programmable-firmware.156-2.r.SP1-ext.01.SPA.pkg](#)

Cisco IOS-XE Release 3.18.0SP

Starting from Cisco IOS-XE Release 3.18.0SP, Docsis 3.1 downstream module firmware can only be upgraded via firmware upgrade package using upgrade hw-programmable command. The table below lists the newer version number of Docsis 3.1 downstream module firmware in Cisco IOS-XE Release 3.18.0SP.

Table 5: Firmware Packages and Versions Supported in Cisco IOS-XE Release 3.18.0SP

| Component | Programmable Device | Existing Versions (In Field) | New Version (With IOS-XE 3.18.0SP) | Upgrade Package |
|----------------|-----------------------|------------------------------|------------------------------------|---|
| CBR-D31-DS-MOD | MicroController Image | 3.13 | 3.13 | cbrsup-rp-programmable-firmware.156-2.r.SP-ext.01.SPA |
| | DS PHY FPGA | 4.413D | 4.4141 | |

Cisco IOS-XE Release 3.18.1S

Starting from Cisco IOS-XE Release 3.18.1S, Docsis 3.0 and Docsis 3.1 downstream module firmware can only be upgraded via firmware upgrade package using upgrade hw-programmable command. The table below lists the newer version number of Docsis 3.1 downstream module firmware in Cisco IOS-XE Release 3.18.1S.

Table 6: Downstream Module Firmware Versions Supported in Cisco IOS-XE Release 3.18.1S

| Component | Programmable Device | Existing Versions (In Field) | New Version (With IOS-XE 3.18.1S) | Upgrade Package |
|----------------|-----------------------|------------------------------|-----------------------------------|---|
| CBR-D31-DS-MOD | MicroController Image | 3.10 | 3.13 | cbrsup-rp-programmable-firmware.156-2.r.S1-ext.01.SPA.p |
| | DS PHY FPGA | 4.4131 | 4.413D | |

Cisco IOS-XE Release 3.18.0Sa

There are no new firmware changes in Cisco IOS-XE Release 3.18.0Sa.

Cisco IOS-XE Release 3.18.0S

There are no new firmware changes in Cisco IOS-XE Release 3.18.0S.

Cisco IOS-XE Release 3.17.1S

There are no new firmware changes in Cisco IOS-XE Release 3.17.1S.

Cisco IOS-XE Release 3.16.2S

There are no new firmware changes in Cisco IOS-XE Release 3.16.2S.

Cisco IOS-XE Release 3.17.0S

If you are upgrading the programmable devices listed in the table below, please download the firmware packages from the [Cisco software download](#) site. For Cisco IOS-XE Release 3.17.0S, microcode upgrade is optional. The firmware packages listed in the following table are backward compatible with the older image.

Table 7: Firmware Packages and Versions Supported in Cisco IOS-XE Release 3.17.0S

| Programmable Device | Existing Versions (In Field) | New Version (With IOS-XE 3.17.0S) | Upgrade Method |
|---------------------|---------------------------------|--------------------------------------|--|
| ROMMON | 15.5(2r)S1 | 15.5(3r)S | HW-Prog-Pkg: cbrsub-rp-hw-programmable-firmware.156-1.r.S1-std.01.SPA.pkg |
| Uboot | 3.12 | 3.13 | HW-Prog-Pkg: cbrsub-rp-hw-programmable-firmware.156-1.r.S1-std.02.SPA.pkg |

Cisco IOS-XE Release 3.16.1S

When Cisco IOS-XE Release 3.16.1S first loads, it will auto-upgrade the Docsis 3.0 and Docsis 3.1 downstream module firmware to a newer version. The table below lists the newer version number of Docsis 3.0 and Docsis 3.1 downstream module firmware in Cisco IOS-XE Release 3.16.1S.

Table 8: Downstream Module Firmware Versions Supported in Cisco IOS-XE Release 3.16.1S

| Component | Programmable Device | Existing Versions (In Field) | New Version (With IOS-XE 3.16.1S) |
|----------------|-----------------------|---------------------------------|--------------------------------------|
| CBR-D30-DS-MOD | MicroController Image | 1.8 | 1.C |
| | DS PHY FPGA | 2F | 2F |
| CBR-D31-DS-MOD | MicroController Image | 2.A | 2.C |
| | DS PHY FPGA | 3.8 | 3.103 |

Cisco IOS-XE Release 3.16.0S

If you are upgrading the programmable devices listed in the table below, please download the firmware packages from the [Cisco software download](#) site.

Table 9: Firmware Packages and Versions Supported in Cisco IOS-XE Release 3.16.0S

| Programmable Device | Existing Versions (In Field) | New Version (With IOS-XE 3.16.0S) | Upgrade Method |
|---------------------|------------------------------|-----------------------------------|--|
| ROMMON | 15.5(2r)S | 15.5(2r)S1 | HW-Prog-Pkg: cbrsup-rp-hw-programmable-firmware.155-3.r.S3-ext.01.SPA.pkg |
| Fan-Tray firmware | 1.4 | 1.6 | HW-Prog-Pkg: cbrsup-rp-hw-programmable-firmware.155-3.r.S3-ext.02.SPA.pkg |
| CLC CPLD (Daggits) | 0x1C(v28) | 0x21(v33) | HW-Prog-Pkg: cbrsup-rp-hw-programmable-firmware.155-3.r.S3-ext.03.SPA.pkg |
| CLC PSOC | 4.3 | 4.6 | HW-Prog-Pkg: cbrsup-rp-hw-programmable-firmware.155-3.r.S3-ext.04.SPA.pkg |
| SUP CPLD (Viper) | 0x14121111 | 0x15091511 | HW-Prog-Pkg: cbrsup-rp-hw-programmable-firmware.155-3.r.S3-ext.05.SPA.pkg |

Cisco IOS-XE Release 3.15.0S

Table 10: Microcode Software Supported in Cisco IOS-XE Release 3S

| Component | Version |
|---------------------|--------------------|
| ROMMON | 15.5(2r)S |
| Supervisor CPLD | 0x14121111 |
| CLC bootloader | 2011.03.12 |
| CLC CPLD | 0x1C (v28) |
| Supervisor PIC CPLD | 0x14071504(v0.130) |
| RF-PIC Firmware | 0x73E(v7.62) |
| Fan-Tray Firmware | v1.4 |
| Supervisor DC CPLD | 0x14072207 |
| Supervisor CPLD SO | 0x14091201 |
| Supervisor CPLD SIO | 0x14092901 |
| Supervisor PSOC1 | v4.0.9 |
| Supervisor PSOC2 | v4.0.8 |

| Component | Version |
|----------------------|---------|
| Supervisor PSOC3 | v4.1.0 |
| Supervisor PSOC4 | v4.0.6 |
| Supervisor DC PSOC1 | v4.0.8 |
| Supervisor DC PSOC2 | v4.0.5 |
| Supervisor PIC PSOC1 | v2.0.6 |
| Supervisor PIC PSOC2 | v2.0.6 |
| CLC PSOC1 | v4.2 |
| CLC PSOC2 | v4.2 |

Feature Support

Cisco IOS-XE software is packaged in feature sets that consist of software images that support specific platforms. The feature sets available for a specific platform depend on which Cisco IOS-XE software images are included in a release. Each feature set contains a specific set of Cisco IOS-XE features.



Caution

Cisco IOS-XE images with strong encryption (including, but not limited to 168-bit [3DES] data encryption feature sets) are subject to U.S. government export controls and have limited distribution. Strong encryption images to be installed outside the United States are likely to require an export license. Customer orders may be denied or subject to delay because of U.S. government regulations. When applicable, the purchaser or user must obtain local import and use authorizations for all encryption strengths. Please contact your sales representative or distributor for more information, or send an e-mail to export@cisco.com.

New and Changed Information

The following sections list the new hardware and software features supported on the Cisco cBR Series Converged Broadband Routers in Cisco IOS-XE Release 3S:

New Firmware Features in Cisco IOS-XE Release 3.18.3aSP

There are no new firmware features in Cisco IOS-XE 3.18.3aSP.

New Firmware Features in Cisco IOS-XE Release 3.18.2aSP

There are no new firmware features in Cisco IOS-XE 3.18.2aSP.

New Firmware Features in Cisco IOS-XE Release 3.18.1aSP

There are no new firmware features in Cisco IOS-XE Release 3.18.1aSP.

New Firmware Features in Cisco IOS-XE Release 3.18.1SP

There are no new firmware features in Cisco IOS-XE Release 3.18.1SP.

New Firmware Features in Cisco IOS-XE Release 3.18.0SP

There are no new firmware features in Cisco IOS-XE Release 3.18.0SP

New Firmware Features in Cisco IOS-XE Release 3.18.1S

There are no new firmware features in Cisco IOS-XE Release 3.18.1S.

New Firmware Features in Cisco IOS-XE Release 3.18.0Sa

There are no new firmware features in Cisco IOS-XE Release 3.18.0Sa.

New Firmware Features in Cisco IOS-XE Release 3.18.0S

Upstream DOCSIS 3.1 PHY Module

The Upstream DOCSIS 3.1 PHY, a plug-and-play module, provides the hardware support for enabling DOCSIS 3.1 features in the Cisco cBR router.

For more information about this feature, see the following URL:

<http://www.cisco.com/c/en/us/td/docs/cable/cbr/Cisco-cBR/index.html>

New Firmware Features in Cisco IOS-XE Release 3.17 0S

- SSD (hard disk) access in ROMMON is supported.
- HA PLL chip on the newly shipped line card is supported.

New Hardware Features in Cisco IOS-XE Release 3.18.3aSP

There are no new hardware features in Cisco IOS-XE Release 3.18.3aSP.

New Hardware Features in Cisco IOS-XE Release 3.18.2aSP

There are no new hardware features in Cisco IOS-XE Release 3.18.2aSP.

New Hardware Features in Cisco IOS-XE Release 3.18.1aSP

There are no new hardware features in Cisco IOS-XE Release 3.18.1aSP.

New Hardware Features in Cisco IOS-XE Release 3.18.1SP

There are no new hardware features in Cisco IOS-XE Release 3.18.1SP.

New Hardware Features in Cisco IOS-XE Release 3.18.0SP

There are no new hardware features in Cisco IOS-XE Release 3.18.0SP.

New Hardware Features in Cisco IOS-XE Release 3.18.1S

There are no new hardware features in Cisco IOS-XE Release 3.18.1S.

New Hardware Features in Cisco IOS-XE Release 3.18.0Sa

There are no new hardware features in Cisco IOS-XE Release 3.18.0Sa.

New Hardware Features in Cisco IOS-XE Release 3.18.0S

Cisco cBR DOCSIS 3.1 Upstream PHY Module

Effective with Cisco IOS-XE Release 3.18.0S, the Cisco cBR router supports the Cisco Upstream D3.1 PHY module (PID: CBR-D31-US-MOD).

For more information about this feature, see the following URL:

<http://www.cisco.com/c/en/us/td/docs/cable/cbr/Cisco-cBR/index.html>

New Hardware Features in Cisco IOS-XE Release 3.17.1S

There are no new hardware features in Cisco IOS-XE Release 3.17.1S.

New Hardware Features in Cisco IOS-XE Release 3.16.2S

There are no new hardware features in Cisco IOS-XE Release 3.16.2S.

New Hardware Features in Cisco IOS-XE Release 3.17 0S

Sup-60 Productization

Effective with Cisco IOS-XE Release 3.17.0S, CBR-CCAP-SUP-60G supports 8 cable line cards. The total traffic rate is limited to 60Gbps, the total number of downstream service flow is limited to 72268, and downstream unicast low-latency flow does not count against the limits.

For more information about this feature, see the following URL:

<http://www.cisco.com/c/en/us/td/docs/cable/cbr/Cisco-cBR/index.html>

Single Downstream PHY Module Line Card Configuration Support

The system sends warning message when Downstream PHY module version is inconsistent.

For more information about this feature, see the following URL:

<http://www.cisco.com/c/en/us/td/docs/cable/cbr/cisco-cbr/index.html>

New Hardware Features in Cisco IOS-XE Release 3.16.1S

There are no new hardware features in Cisco IOS-XE Release 3.16.1S.

New Hardware Features in Cisco IOS-XE Release 3.16.0S

CBR-CCAP-SUP-60G

The Supervisor card with 60 Gbps forwarding capacity (PID CBR-CCAP-SUP-60G) is introduced on the Cisco cBR-8 router. This Supervisor card supports a maximum of four interface cards, working in 3+1 protection mode, on the Cisco cBR-8 router.



Note The Cisco cBR-8 router does not support redundancy if different Supervisor cards are installed in the chassis. We recommend that you install the Supervisor cards with the same capacity in a Cisco cBR-8 router.

This Supervisor card supports a maximum of 72268 downstream unicast flows or 88268 downstream modular quality of service (MQoS) flows. The maximum number of downstream unicast and MQoS flows supported is 88268.

The output of the **show inventory** command was modified.

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/installation/guide/b_cbr_overview.html

Downstream DOCSIS 3.1 PHY Module

The Downstream DOCSIS 3.1 PHY, a plug-and-play module, provides the hardware support for enabling DOCSIS 3.1 features in the Cisco cBR router.

For more information about this feature, see the following URL:

<http://www.cisco.com/c/en/us/td/docs/cable/cbr/cisco-cbr/index.html>

New Hardware Features in Cisco IOS-XE Release 3.15.1S

There are no new hardware features in Cisco IOS-XE Release 3.15.1S.

New Hardware Features in Cisco IOS-XE Release 3.15.0S

This is the first release of the Cisco cBR Series Converged Broadband Routers and its FRUs.

For more information about the new hardware feature, see:

<http://www.cisco.com/c/en/us/td/docs/cable/cbr/cisco-cbr/index.html>

New Software Features in Cisco IOS-XE Release 3.18.3aSP

There are no new software features in Cisco IOS-XE Release 3.18.3aSP.

New Software Features in Cisco IOS-XE Release 3.18.2aSP

There are no new software features in Cisco IOS-XE Release 3.18.2aSP.



Note ISSU from Cisco IOS XE 3.18.0SP to Cisco IOS XE 3.18.2aSP with OFDM channels, might not recover channel operation after a linecard switchover. ISSU from Cisco IOS XE 3.18.1aSP to Cisco IOS XE 3.18.2aSP has no limitations.

New Software Features in Cisco IOS-XE Release 3.18.1aSP

There are no new software features in Cisco IOS-XE Release 3.18.1aSP.

New Software Features in Cisco IOS-XE Release 3.18.1SP

MAC Filtering

This feature enables/disables MAC address filter on the backhaul interface. It supports 32 unicast filter entries per interface.

For more information, see:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cmts_sec_and_cable_mon_features_cbr/mac_filtering.html

AES-128 for non-MTC DOCSIS3.0 Cable Modem

This feature allows DOCSIS3.0 cable modem working on non-MTC mode to use AES-128 as BPI encryption Algorithms. It also allows DOCSIS3.0 cable modem to use AES-128 as encryption algorithms when EAE is enabled.

For more information, see:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cmts_sec_and_cable_mon_features_cbr/cable_duplicate_map_address_reject.html

DOCSIS 3.1 Downstream OFDMA Guardband Enhancements

This feature allows user to configure the guard band of an OFDM channel.

For more information, see:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer2_docsis31/ofdm_channel_configuration.html

New Software Features in Cisco IOS-XE Release 3.18.0SP

DOCSIS 3.1 2000 Bytes Data PDUs

Cisco cBR-8 router supports 2000 bytes layer 2 MTU and 1982 bytes layer 3 MTU in Cisco IOS-XE 3.18.0SP release.

For more information about this feature, see the following URLs:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_layer2_layer3_vpn/2vpn_support_on_cable.html#con_1056996

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer3_config/virtual_interface_bundling.html#con_1065039

DOCSIS 3.1 Adaptive CIR, Fair EIR (ACFE)

DOCSIS 3.1 introduces the following new modes for higher throughput and higher spectral efficiency while still allowing backward compatibility to DOCSIS 3.0:

- OFDM channel
- OFDM channel rate
- Interface bandwidth

The following commands were modified:

- **show interface {wideband-cable | modular-cable | integrated-cable}**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cmts_quality_of_services/fairness_across_docsis_interfaces.html

DOCSIS 3.1 BPI Authorization Changes

A new security specification is introduced for DOCSIS 3.1. A new certificate public key infrastructure (PKI) is defined, that strengthens the security of cable modem authentication and secures software download features. The following features are supported:

- Support for 256-bit encrypted authentication key.
- Support for 2048-bit encrypted RSA public key.
- Certificates use RSA3 signature algorithm with a SHA-256 hash [FIPS 180-4] (vs D3.0 SHA-1).

DOCSIS 3.1 DS: Commanded Power for US SC-QAMs

Commanded Power for upstream SC-QAMs supports a new method during ranging, to dynamically set the transmit power level of a DOCSIS 3.1 cable modem. The following command displays the new DOCSIS 3.1 Commanded Power levels per upstream:

- **show cable modem**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer2_docsis31/docsis_31_commanded_power_for_upstream_sc_qam.html

DOCSIS 3.1 DS LCHA HA

Line Card High Availability (LCHA) for D3.1 DS features with LCHA feature parity to Cisco IOS-XE 3.18.0S Release has been introduced. There are dependencies on cable modem (CM) firmware performance, so some D3.1 cable modems may fall offline or come up in partial mode due to known CM issues. The Cisco cBR Converged Broadband Routers Series attempt to reset D3.1 CMs that are not w-online after linecard switchover.

DOCSIS 3.1 DS LCPR

Cable Line Card Process Restart (LCPR) support (both CLC IOSd and cdman) for D3.1 DS features with LCPR feature parity to Cisco IOS-XE 3.18.0S Release has been introduced.

DOCSIS 3.1 DS Profile Selection

DOCSIS 3.1 introduces the concept of downstream profiles for OFDM channels. A profile is a list of modulation orders that are defined for each of the subcarriers within an OFDM channel. The CMTS can define multiple profiles for use in an OFDM channel, where the profiles differ in the modulation orders assigned to each subcarrier. The CMTS can assign different profiles for different groups of CMs. To enable or configure profile selection feature, following commands were introduced or modified:

- **cable downstream ofdm-flow-to-profile**
- **cable downstream ofdm-prof-mgmt exempt-sc-pct**
- **cable downstream ofdm-prof-mgmt mer-margin-qdb**
- **cable downstream ofdm-prof-mgmt prof-dwngrd-auto**
- **cable downstream ofdm-prof-mgmt recommend-profile-age**
- **cable downstream ofdm-prof-mgmt rxmer-poll-interval**
- **cable downstream ofdm-prof-mgmt unfit-profile-age**
- **show controller integrated-cable**
- **show cable modem phy ofdm-profile**
- **show cable modem prof-mgmt**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer2_docsis31/docsis_31_downstream_profile_selection.html

For more information on commands, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cmts/cmd_ref/b_cmts_cable_cmd_ref.html

DOCSIS 3.1 DS SUP HA

Support for D3.1 DS features with SUP HA feature parity to Cisco IOS-XE 3.18.0S has been introduced.

DOCSIS 3.1 Interop with Intel Puma7 based CM

The cBR8 D3.1 DS features have gone through interoperability testing with both Broadcom 3390 based D3.1 CMs and Intel Puma7 based D3.1 CMs. Both are supported for D3.1 DS operation with Cisco cBR Converged Broadband Routers Series.

DOCSIS 3.1 OFDM Channel Licensing

The DOCSIS 3.1 license scheme provides support to identify the DOCSIS 3.1 channels and their widths. The DOCSIS 3.1 entitlement is DOCSIS 3.1 Downstream Channel License.

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_sw_config_features/cisco_smart_licensing.html

DOCSIS 3.1 Path Selection

RCC template, RCC management, and path selection is enhanced to support OFDM downstream channels and OFDMA upstream channels. RCC/TCS decision process is enhanced to include OFDM and OFDMA channels. Path selection is integrate with the new simplified RCC encoding process and enables the assignment of downstream Profiles. The following commands are introduced:

- **show cable modem path-sel**
- **clear cable modem path-sel**
- **show cable mac-domain rcc simplified**

The following command is updated:

- **show cable mac-domain rcc**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cmts/cmd_ref/b_cmts_cable_cmd_ref.html

DOCSIS 3.1 Protocol Enable or Disable

This feature allows the user to enable and disable the DOCSIS 3.1 mode on a cable modem. By default, the DOCSIS 3.1 mode is enabled. If the user does not want to support the DOCSIS 3.1 cable modem, the DOCSIS 3.1 mode can be disabled on a MAC domain. Then the DOCSIS 3.1 cable modem will connect in DOCSIS 3.0 mode. The following command is introduced:

- **cable d31-mode**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cmts/cmd_ref/b_cmts_cable_cmd_ref.html

DOCSIS 3.1 QoS

DOCSIS 3.1 defines the framework for QoS The aggregation could be per subscriber or based on traffic type, for example; video or data. The following commands were modified:

- **show cable acfe interface**
- **show cable admission-control**
- **show interface wideband-cable**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cmts_quality_of_services/fairness_across_docsis_interfaces.html

DOCSIS 3.1 SGAC

Effective from 3.18.0SP Release, for DOCSIS 3.1, if bonding group contains an OFDM channel, the bonding group's total bandwidth that can be reserved (its capacity), is calculated using the least efficient OFDM profile it can use.

Full Spectrum 108-1218 MHz Support

An OFDM channel can be configured within the frequency range of 108 - 1218 MHz.

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer2_docsis31/ofdm_channel_configuration.html

IPv6 DQoS Lite

IPv6 DQoSLite is a modem centric solution without notion of gates, to validate and deliver residential voice services over IPv6 to reclaim IPv4 address space.

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_pktcbl_pktcblmm/packetcable_and_packetcable_multimedia.html

Lawful Intercept- Overlapping Taps and Redundant MDs

The Cisco cBR Series Converged Broadband Routers supports replicating Lawful Intercept (LI) packets to multiple Mediation Devices (MDs). To use this feature, multiple identical taps are configured.

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cmts_sec_and_cable_mon_features_cbr/lawful_intercept_architecture.html

MTPS Pass-Through

Switched digital video (SDV) sessions are typically multicast STPS remap type. The Cisco CBR-8 router also supports multicast MTPS pass-through and data-piping session types.

OFDM Channel Support for All Ports

DOCSIS 3.1 introduces modes for higher throughput and higher spectral efficiency while still allowing backward compatibility to DOCSIS 3.0. OFDM Channel support includes 1 OFDM channel per port with channel bandwidth from 24 MHz to 192 MHz. The following commands are introduced:

- **cable downstream ofdm-modulation-profile**
 - **assign**
 - **description (config-ofdm-mod-prof)**
 - **start-frequency**
 - **subcarrier-spacing**
 - **width**
- **show cable ofdm-modulation-profiles**
- **cable downstream ofdm-chan-profile**
 - **cyclic-prefix**
 - **description (config-ofdm-chan-prof)**
 - **interleaver-depth**
 - **pilot-scaling**
 - **profile-control**
 - **profile-data**
 - **profile-ncp**
 - **roll-off**

- **show cable ofdm-chan-profiles**
- **max-ofdm-spectrum**
- **ofdm-freq-excl-band**
- **ofdm channel-profile**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer2_docsis31/ofdm_channel_configuration.html

QAM Replication

Multicast sessions can be replicated from one port to other ports on the same line card and/ or across line cards.

Show Patch Info in One CLI

Effective from 3.18.0SP Release, the show platform software patch info command is used to determine the detailed patch information for all the FRUs. The following command was modified:

- **show platform software patch info**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cmts/cmd_ref/b_cmts_cable_cmd_ref.html

Switched Digital Video

The Switched Digital Video (SDV) services are supported for the MPEG video subsystem on the Cisco cBR-8 router. It consists of Multicast IP Packet based video streams that are managed as "Video Sessions". The Cisco cBR-8 router supports both Any Source Multicast (ASM) and Source Specific Multicast (SSM) sessions.

The following commands were introduced or modified:

- **multicast-uplink** interface-name
- **multicast-label** label
- **session** session-name
- **rf-channel** number
- **show cable video session logical-edge-device**

For more information, see the Switched Digital Video feature guide at:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_video_features/switched_digital_video.html

UCD TLV for Device Type (Ranging Hold Off)

The cable modem steering feature helps to redirect or steer cable modems to multiple CMTS routers using downstream frequency overrides. A configurable string is used to bond the cable modem to the proper CMTS. Once the bonding is done, the CMTS can move the cable modem within itself for load balancing.

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer2_docsis30/b_cbr_layer2_docsis_chapter_010010.html

Video ISSU Improvement

The ISSU process performance is improved, time consumed is much less, and the secondary linecard is reloaded for upgrade at first.

New Software Features in Cisco IOS-XE Release 3.18.1S

There are no new software features in Cisco IOS-XE Release 3.18.1S.

New Software Features in Cisco IOS-XE Release 3.18.0Sa

Using VRF for Video Session Traffic

Effective with Cisco IOS-XE release 3.18.0Sa, the **virtual-edge-input** CLI command now supports using a VRF for video session traffic.

For more information, see *Video Virtual Carrier Group and Virtual Edge Input* section at:

https://www.cisco.com/en/US/d/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/virtual_carrier_group_and_virtual_edge_input_configuration.html

New Software Features in Cisco IOS-XE Release 3.18.0S

Video Services Provisioning Model

The Cisco cBR-8 router offers the next generation CCAP platform supporting converged CMTS and EQAM functionality. The redesigned video data model supports the creation of virtual edge devices within the platform. This data model simplifies the provisioning procedure and enables seamless migration to virtualized video service management in the future. The video provisioning constructs of the new data model provide hardware abstraction and divides services into virtual edge devices for easier provisioning at scale. It also provides isolation between the service applications at the software layer. A bind-operation connects these constructs to the physical resources.

For more information, see the *Video Services Provisioning Model* guide at:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/video_services_provisioning_model.html

Video Virtual Carrier Group and Virtual Edge Input

A Virtual Carrier Group (VCG) is a collection of virtual QAM carriers (RF channels) provisioned on a Logical Edge Device (LED). A Virtual Edge Input (VEI) is a customer assigned IP address that is used, from the Head End, as a destination IP address for unicast video IP packets.

The following commands were introduced:

- **virtual-carrier-group**
- **virtual-edge-input-ip**
- **Encrypt**
- **service-type**
- **rf-channel**
- **show cable video virtual-carrier-group**
- **logical-edge-device**
- **protocol**

- **virtual-edge-input-ip**
- **vcg**
- **active**
- **show cable video logical-edge-device**

For more information about this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/virtual_carrier_group_and_virtual_edge_input_configuration.html

Advanced Video MPEG Features

Cisco cBR Series Converged Broadband Router supports these video features for the MPTS pass-through video sessions: Reserved Output PID Range, PID Filtering, and Program Filtering.

The following commands were introduced:

- **reserve-pid-range**
- **filter pid vcg**
- **ip**
- **pid**
- **filter program vcg**
- **program**
- **show cable video session logical-edge-id**

For more information about this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/advanced_video_mpeg_features.html

Important Notes

For more information about the important notes for Management IP Interface and Virtual Routing Interface, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/important_notes.html

PME Video On Demand

The VoD Privacy Mode Encryption system integrates the encrypted VoD content within a ARRIS digital cable headend. The Cisco CBR-8 and CEM provides encryption for the content received from the VoD system.

The following commands were introduced:

- **protocol table-based**
- **show cable video session logical-edge-device id**
- **show controllers integrated-cable**
- **show interfaces tenGigabitEthernet**

For more information on this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_video_features/table_based_video_and_vpme_encryption.html

Video QAM Replication

The Video QAM replication feature allows video carriers to be replicated to support service group alignment between DOCSIS and Video service groups. This feature is internal to the cBR-8 and replaces the need for external splitters, allowing content to be replicated across multiple ports on a line card.

The following commands were introduced:

- **controller Integrated-Cable**
- **type**
- **scrambler**
- **encrypt**
- **show cable video encryption linecard**

For more information on this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_video_features/replication.html

PowerKEY Video On Demand

PowerKEY Video On Demand is the video content that is chosen by the subscriber and streamed specifically to the subscriber. The content is encrypted using PowerKEY conditional access through a video session that is created on the Cisco cBR-8 specifically for each request.

The following commands were introduced:

- **show cable video encryption linecard**
- **virtual carrier group**
- **virtual edge input**
- **show cable video virtual-carrier-group name**
- **service-distribution-group**
- **onid**
- **logical-edge-device**
- **show cable video logical-edge-device name**
- **show cable video logical-edge-device id**
- **show cable video gqi connections**
- **show cable video session logical-edge-device id**
- **show cable video session logical-edge-device name**
- **show cable video output-port**
- **show cable video scg logical-edge-device id**
- **show cable video scg id**

For more information on this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_video_features/powerkey_vod.html

Video Encryption

The Cisco cBR-8 provides encryption for Video On Demand (VoD) sessions to address security concerns. The encrypted sessions can be created on any QAM carriers on a linecard.

The following commands were introduced:

- **encryption**

- **ca-system**
- **scrambler**
- **encrypt**
- **show cable video encryption linecard**
- **pme vodsid**
- **pme cem**
- **pme mgmt-ip**
- **show cable video encryption pme status**
- **show cable video encryption pme version**
- **show cable video encryption pme linecard**

For more information on this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/encryption.html

Table Based Configuration

The Table-based video session configurations can be performed for a range or an individual session under each Quadrature Amplitude Modulation (QAM) carrier that is being assigned to a table-based Logical Edge Device (LED).

The following commands were introduced:

- **table based**
- **session**
- **start-udp-port**
- **num-sessions-per-qam**
- **processing-type**
- **start-program**
- **bitrate**
- **jitter**
- **show cable video logical-edge-device**
- **show cable video vei-bundle all**

For more information on this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/table_based_configuration.html

PacketCable and PacketCable Multimedia Multicast

The PacketCable and PacketCable Multimedia feature provides support for multicast transmission.

The following command is implemented on Cisco cBR Series Converged Broadband Routers:

- **cable multicast source**

For more information, see the cable multicast source command at the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cmts/cmd_ref/b_cmts_cable_cmd_ref/b_cmts_cable_cmd_ref_chapter_0101.html#wp1998501503

Physical to Virtual Binding

The Virtual Carrier Group (VCG) is bound to a Service Distribution Group (SDG) using a bind command (bind-vcg). This connects the virtual carriers to the physical ports listed in the SDG.

The following command was introduced:

- **bind-veg**

For more information about this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/physical_to_virtual_binding.html

Online Offline Diagnostics

Online Offline Diagnostics (OOD) Field Diagnostics feature allows the customer to test and verify hardware-related issues on a line card deployed in the field. The test results can be used to verify whether a line card is fault and troubleshoot network issues.

The following commands were introduced:

- **request platform hardware diagnostic load**
- **request platform hardware diagnostic unload**
- **show platform hardware diagnostic status**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cisco_cmts_networkmgmt_trblshng_cbr/online_offline_diagnostics.html

Voice over IPv6

Effective with Cisco IOS-XE release 3.18.0S, Voice over IPv6 is supported on Cisco cBR-8 routers. PacketCable Multimedia needs to be enabled before using this feature.

The following commands were supported:

- **show cable modem ipv6**
- **show packetcable gate ipv6**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer3_config/ipv6_on_cable.html

Cable Line Card Process Restart on Crash

The SNMP Background Synchronization features provides periodic background synchronization of DOCSIS MIB data from line card to Supervisor in order to improve the performance of the SNMP polling of these MIB tables.

The following commands were introduced:

- **show platform software ios socket statistics**
- **show cable bgsync sync-info cable**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cisco_cmts_networkmgmt_trblshng_cbr/snmp_background_synchronization.html

BSoD VLAN Redundancy

BSoD VLAN redundancy feature is introduced to configure a backup Network System Interface (NSI) interface and a default primary interface for dot1q L2VPN. When the primary NSI interface goes down, the backup NSI interface takes over and the traffic flows through the second interface.

The following commands were introduced:

- **cable l2-vpn dot1q-nsi-redundancy force-switchover**
- **show cable l2-vpn dot1q-nsi-redundancy**

For more information about this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_layer2_layer3_vpn/l2vpn_support_on_cable.html

To configure dot1q L2VPN backup WAN interface for TLS, see the following URL:

<http://www.cisco.com/c/en/us/td/docs/cable/cmts/feature/tls-cmts.html#wp1075949>

L2VPN Over Port-Channel

The Layer 2 VPN (L2VPN) over port-channel feature supports IEEE 802.1Q (dot1q) L2VPN WAN interface port-channel. Using this feature, you can configure the dot1q L2VPN traffic to pass through port-channel uplink.

The following commands were introduced:

- **cable l2-vpn-service xconnect nsi dot1q interface port-channel**
- **cable dot1q-vc-map port-channel**

For more information, see the L2VPN Over Port-Channel chapter at the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_layer2_layer3_vpn.html

Energy Management

Data-over-Cable Service Interface Specifications (DOCSIS) cable modems (CM) and CMTS support a low power energy mode referred to as the Energy Management (EM) 1x1 mode. During idle times, when the data rate demand of a user is met by the available capacity on a single upstream and downstream channel pair to which it is assigned, the CM switches to the Energy Management 1x1 mode. When the CM requires a higher data rate than that can be reliably provided on the single channel pair, the CMTS instructs the CM to return to the larger transmit and receive channel set.

The following commands were introduced:

- **cable reduction-mode energy-management enable**
- **cable reduction-mode energy-management dynamic-channel-percent**
- **cable reduction-mode energy-management process-queue-size**
- **cable reduction-mode energy-management ranging-init-technique**
- **show cable modem reduction-mode energy-management-param**
- **show cable modem reduction-mode energy-management-mode**
- **show cable modem reduction-mode energy-management-status**

For more information, see the Energy Management Mode chapter at the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer2_docsis30.html

Show Command to display SF Counts

Displays system level service flow and downstream classifier summary and detailed information per line card basis.

The following commands were introduced:

- **show cable service-flow summary**
- **show cable service-flow summary detail**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cmts/cmd_ref/b_cmts_cable_cmd_ref/b_cmts_cable_cmd_ref_chapter_01111.html

Service Distribution Group

The Service Distribution Group (SDG) is a collection of one or more RF ports and defines the physical slot/bay/port to be used in a video service.

The following commands were introduced:

- **service-distribution-group**
- **show cable video service-distribution-group all**
- **psi-interval**
- **onid**

For more information about this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/service_distribution_group.html

Video QAM Carriers

For video provisioning, the carriers must be of type “video” in the controller integrated-cable configuration.

The following commands were introduced:

- **rf-channel**
- **type**
- **start-frequency**
- **rf-output**
- **power-adjust**
- **qam-profile**

For more information about this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/video_qam_carriers.html

Management IP Interface

The management interface is used for the video control plane messages, such as session creation and deletion, between the LED and the external Edge Resource Manager (ERM) server.

The following commands were introduced:

- **interface VirtualPortGroup**
- **show run interface VirtualPortGroup**
- **mgmt-interface VirtualPortGroup**
- **show run | in mgmt-intf**
- **show interfaces VirtualPortGroup**
- **show ip interface brief | in VirtualPortGroup**
- **show ip route | in**
- **sh run | begin logical-edge-device test**
- **show arp | in VirtualPortGroup**

For more information about this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/management_ip_interface.html

Logical Edge Devices

A Logical Edge Device (LED) is a virtual edge device within the cBR-8 and can be provisioned for static or dynamic sessions.

The following commands were introduced:

- **logical-edge-device**
- **virtual-edge-input input-port-number**
- **vcg**
- **keepalive retry interval**
- **reset interval**
- **show cable video logical-edge-device id**

For more information about this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/logical_edge_devices.html

Global Video Configuration

For provisioning video services you can perform some global configurations. These configurations have some default values. If you do not choose to change those, the default values are used. The following sections describe the procedures for global configurations.

The following commands were introduced:

- **default-onid**
- **default-psi-interval**
- **timeout init-session**
- **timeout idle-session**
- **timeout off-session**

For more information about this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/global_video_configuration.html

D6 Discovery Protocol

The D6 discovery protocol is part of the Comcast Next Generation on Demand (NGOD) specification. This protocol helps in advertising the video QAM carrier information like frequency, modulation mode, annex, and edge input for the video traffic such as IP address, group name, maximum bandwidth, and so on, to an Edge Resource Manager (ERM). The D6 discovery protocol also sends unique structured names (topological location information) for each edge input or carrier output. From these structured names, and input and RF port numbers, the ERM can infer the topological network location of both the QAM streaming input port (IP) and RF output port (MPEG).

For more information about this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_video_features/d6_discovery_protocol.html

Cisco Smart Licensing for Video

The Cisco Smart Licensing for Video on the Cisco cBR router leverages existing Cisco cBR Smart Licensing framework that includes Call Home and SLA capabilities. For more information, see the *Cisco Smart Licensing for Video* guide at:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_config_prov_construct/cisco_smart_licensing_for_video.html

New Software Features in Cisco IOS-XE Release 3.17.1S

There are no new software features in Cisco IOS-XE Release 3.17.1S

New Software Features in Cisco IOS-XE Release 3.16.2S

There are no new software features in Cisco IOS-XE Release 3.16.2S.

New Software Features in Cisco IOS-XE Release 3.17.0S

MPLS QoS via TLV for non-L2VPN

The MPLS QoS via TLV for non-L2VPN Service Flow feature allows to mark TC bits for MPLS L3VPN imposition packets and classify downstream packets based on TC bits of MPLS disposition packets, using vendor-specific TLVs.

The following commands were introduced:

- **show platform hardware qfp active feature docsis mpls tc-precfy db**
- **show platform hardware qfp active cable us-mpls-tc**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_layer2_layer3_vpn/mpls_qos_tlv_non_l2vpn_service_flow.html

Service Flow Priority in Downstream Extended Header

The service flow priority in downstream extended header feature is supported on Cisco cBR-8 Converged Broadband Router. The purpose of the feature is to be able to reflect the traffic priority of downstream packets into the DOCSIS extended header.

The following commands were introduced or modified:

- **cable service flow priority**
- **show cable modem**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer2_docsis/docsis_3_downstream_bonding.html

Configuring UCSB Required Attribute

If the CM configuration file has TLV 43.9.3 (CM upstream required attribute mask) configured and bonded bit is set to 1, then the modem comes UB-online on a MAC domain basis. If the CM configuration file has no TLV 43.9.3 or the bonded bit is not set to 1, then the modem comes online with a single upstream channel on a MAC domain basis.

You can configure the required CM attribute on UCSB using the following command:

- **cable mtc-mode required-attribute**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cmts/config_guide/b_cmts_ds_us_features/b_cmts_ds_us_features_chapter_010010.html

IPDR CM-STATUS-2008

The IPDR CM-STATUS 2008 version is introduced for forward compatibility to support old IPDR collectors. In the IPDR CM-STATUS 2008 version, the CmtsRcsId and CmtsTcsId objects are 16 bits in length whereas in the CM-STATUS version both these objects are 32 bits in length. The CmtsRcsId object in the CM-STATUS-2008 version returns the lower 16 bits of value from the CM-STATUS version. But, the CmtsTcsId object returns the same value for both the CM-STATUS-2008 and CM-STATUS version since the value does not exceed 16 bits in both the schemas.

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cisco_cmts_networkmgmt_trblshting_cbr.html

Service Group Profile Based Configuration

To simplify and speed up the process of configuring the physical and logical interfaces required to deploy the Cisco cBR router quickly, a service group (SG) profile based approach is adopted.

To configure the interfaces and quickly operationalize the Cisco cBR router, a set of common profiles are created and configured into global service group profiles. These global service group profiles may be applied to fiber node interfaces along with a mapping of the service group interfaces to the physical interfaces.

The following commands were introduced or modified:

- **cable profile service-group**
- **cable fiber-node**
- **Show cable fiber-node**
- **Show cable modem fiber-node mac-domain**
- **Show cable mac-domain fiber-node**
- **Show cable profile**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer2_docsis30.html

Subscriber Traffic Management

The Subscriber Traffic Management (STM) feature allows a service provider to configure a maximum bandwidth threshold over a fixed period for a specific service class (or quality of service [QoS] profile). The subscribers who exceed this configured threshold can then be identified and allocated reduced QoS. STM works as a low-CPU alternative to Network-Based Application Recognition (NBAR) and access control lists (ACLs). You can configure the STM feature on the Cisco CMTS routers using the following command:

- **cable qos enforce-rule**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cmts/config_guide/b_cmts_Quality_Service_Features.html

New Software Features in Cisco IOS-XE Release 3.16.1S

There are no new Software features in Cisco IOS-XE Release 3.16.1S.

New Software Features in Cisco IOS-XE Release 3.16.0S

Battery Backup 1x1 Mode

Cisco CMTS supports downgrading the channel bonding for cable modems and media terminal adapters (MTAs) in battery backup mode. When this feature is enabled and the cable modem enters the battery backup mode, channel bonding is downgraded to one downstream and one upstream channels (battery backup 1x1 mode). This feature reduces the power usage when the cable modem is running on battery backup. When the cable modem returns to the AC power mode, the channel bonding is returned to its original configuration.

The following commands were introduced:

- **cable reduction-mode mta-battery**
- **show cable modem reduction-mode mta-battery**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer2_docsis/downgrading_channel_bonding_battery_mode.html

Downstream and Upstream JIB Partial Reset

The fatal interrupts received from the hardware components on the line cards result in reset and reload of the line cards, which triggers switchover and partial system downtime. The Downstream and Upstream JIB Partial Reset feature significantly reduces this recovery time.

N+1 Line Card Redundancy

The line cards support high availability with redundancy schemes. Line card redundancy can help limit customer premises equipment (CPE) downtime by enabling robust automatic switchover and recovery in the event that there is a localized system failure. The Cisco cBR-8 router supports N+1 redundancy scheme for line cards. A single RF Protect PIC can be configured as a secondary card for multiple RF Through PICs (primary cards).

The following commands were introduced or modified:

- **class**
- **description**
- **linecard-group**
- **member slot**
- **redundancy**
- **redundancy linecard-group switchover from slot**
- **revertive**
- **show lcha logging level**
- **show lcha rfs**
- **show redundancy linecard**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_sw_config_features/line_card_redundancy.html

Cable IOSd Restart

When an upgrade is done to a package or sub-package, the RF line card must be rebooted. The time taken for the package upgrade on N number of active RF line cards, the total number of reboots would be 2xN. This is time-consuming and may affect services on the rebooting RF line cards. The Cable IOSd Restart feature or Line Card Process Restart (LCPR) supports the restart of specific processes without service disruption and simplified package upgrade without LCHA based reboot.

The following command was introduced:

- **request platform software process restart**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_sw_config_features/consolidated_packages_and_subpackages_management.html

US Channel Scaling from 64 to 96 channels

Effective with Cisco IOS-XE Release 3.16.0S, 96 upstream channels are supported on each line card in the Cisco cBR-8 routers.

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer2_docsis/docsis_interface_fn_configuration.html

RP only ISSU

Effective with Cisco IOS-XE Release 3.16.0S, Cisco cBR-8 Routers support In-Service Software Upgrades (ISSU) for redundant platforms. The ISSU process allows software to be updated or otherwise modified while packet forwarding continues with minimal interruption.

The following commands were introduced:

- **request platform software package install rp**
- **request platform software package install node**
- **request platform software package expand**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cmts_ha_features_cbr/cisco_ios_xe_in_service_software_upgrade_process.html

Service Group Admission Control

Service Group Admission Control (SGAC) is a mechanism that gracefully manages service group based admission requests when one or more resources are not available to process and support the incoming service request.

The following commands were introduced:

- **admission-control application-type**
- **cable application-type**
- **show cable admission-control**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cmts_quality_of_services/Service_Group_Admission_Control.html

New Software Features in Cisco IOS-XE Release 3.15.1S

There are no new Software features in Cisco IOS-XE Release 3.15.1S.

New Software Features in Cisco IOS-XE Release 3.15.0S

The following table lists the features supported on Cisco cBR Series Converged Broadband Routers in Cisco IOS-XE Release 3.15.0S.

Table 11: Supported Features

| Cisco IOS-XE Release | Supported Features |
|----------------------|---|
| 3.15.0S | <ul style="list-style-type: none"> • 16x4 CM support • 4293 IP-MIB (IPv6 only) and RFC 4292 IP-FORWARD-MIB (IPv6 only) • ACL IPV4 for cBR • ACL IPV6 for cBR • Adaptive CIR and Fair EIR • Add Channel Interface for physical RF channel • Advanced Mode DSG with MIB Support • Alarm Filtering Support in the Cisco Entity Alarm MIB • Allow Dynamic SF For L2VPN Provisioned Modems • ARP Filter for CBR • ATOM on CBR • Automatic Initial Ranging Insertion Interval for CBR8 • Basic cBR-8 Sup HA • Bundle Flood for cBR (Infrastructure) • Cable Duplicate-MAC Reject • Cable Lease Query IPV6 and IPV4 for cBR • cable logging layer2events • cable modem remote-query enhancements • Cable Source Verify and Source Address Verification IPV6 and IPV6 for cBR • CBR8 DTI Client • CBR8 Platform (Infrastructure) • cbr8 ROMMON field Upgrade • Cisco Express Forwarding - SNMP CEF-MIB Support • Cisco Extension to the Interfaces MIB (CISCO-IF-EXTENTION-MIB) • Cisco Memory Pool Mib • Cisco SYSLOG Mib • CISCO-BULK-FILE-MIB enhancements • CISCO-CABLE-AVAILABILITY-MIB • CISCO-CABLE-SPECTRUM-MIB for CBR • CISCO-CABLE-WIDEBAND-MIB • CISCO-CDP-MIB |

| Cisco IOS-XE Release | Supported Features |
|----------------------|--|
| 3.15.0S | <ul style="list-style-type: none"> • CISCO-CONFIG-COPY-MIB: FTP and RCP support • CISCO-CONFIG-COPY-MIB: Secure Copy Support • CISCO-DOCS-EXT-MIB for CBR • CISCO-DOCS-REMOTE-QUERY-MIB for CBR • CISCO-ENHANCED-MEMPOOL-MIB • CISCO-ENTITY-EXT-MIB test for cBR • CISCO-ENTITY-FRU-CONTROL-MIB enhancement for • CISCO-ENTITY-SENSOR-MIB Enhancement • CISCO-IP-URPF-MIB Support • CISCO-PROCESS-MIB on CBR Line Cards • CISCO-QINQ-VLAN-MIB • CISCO-RF-MIB (REVISION) • CLAB-TOPO-MIB • CM VRF Steering • CMTS static CPE • Configurable DFO Retry Count • Control Point Discovery • D3.0 Load Balancing • Database Library for Converged Broadband Router cBR (Infrastructure) • Default DOCSIS 1.0 ToS Overwrite • DHCPv6 Relay - MPLS VPN Support • Differential DHCP GiAddr Assignment per device type • DOCS-CABLE-DEVICE-MIB for CBR8 • DOCS-DIAG-MIB for CBR • DOCS-DRF-MIB For CBR • DOCS-IF3-MIB for CBR • DOCS-IFEXT-MIB for CBR8 • DOCS-IF-MIB for CBR • DOCSIS 1.0 CM Concatonation Disable • DOCSIS 2.0 • DOCSIS 2.0 Load Balancing • DOCSIS 3.0 BPI+ policy enforcement • DOCSIS 3.0 CM Registration (Infrastructure) • DOCSIS 3.0 Downstream Bonding Protocol |

| Cisco IOS-XE Release | Supported Features |
|----------------------|---|
| 3.15.0S | <ul style="list-style-type: none"> • DOCSIS 3.0 Downstream Bonding Protocol • DOCSIS 3.0 Downstream Channel Bonding • DOCSIS Admission Control • DOCSIS Baseline Privacy • DOCSIS Classifiers • DOCSIS DSX Support (Infrastructure) • DOCSIS High Power USCB CM Capability • DOCSIS MAP Replication • DOCSIS Packet Filtering • DOCSIS Service Class Feature • DOCS-MCAST-MIB • DOCS-MCAST-MIB • DOCS-QOS3-MIB for CBR • DOCS-SUBMGT3-MIB • DOCS-SUBMGT-MIB • Downstream Channel Management Module • Dynamic Bandwidth Sharing • Dynamic Bonding Change • Dynamic Cable Helper Address Selection • Dynamic Channel Change • Dynamic Message Integrity Check (DMIC) • EIGRP MIB • Embedded Event Manager (EEM) 4.0 • Entity MIB for cBR • Environment Monitoring Daemon for cBR8 (Infrastructure) • EtherChannel Support on CBR8 • Event MIB and Expression MIB Enhancements • Extended Message Integrity Check (EMIC) • Facility-Alarm Command • FileType support in CISCO-FLASH-MIB • FN-SG(fibre node and SG management) • Fully supported L3-mobility solution for CBR • Generic Routing Encapsulation (GRE) • GRE IPv6 Tunnels • High Speed Data QOS for CBR |

| Cisco IOS-XE Release | Supported Features |
|----------------------|---|
| 3.15.0S | <ul style="list-style-type: none"> • HotIce CLI • IGMP MIB Support Enhancements for SNMP • Ingress noise cancellation for CBR8 • Input MQC on cable interfaces • Inter-area MPLS TE Tunnel Support On CMTS • Interfaces MIB: SNMP context based access • IPDR for CBR8 • IPSLA for CBR • IP-TUNNEL-MIB • IPv6 Device Class Identification • IPv6 eRouter Support • IPv6 Policy-Based Routing • IPv6 Prefix Delegation Support on CMTS • IPv6 QoS: (Quality of Service) • IPv6 SISF (Internet Protocol Version 6) • IPv6/IPv4/Dual stack CPE for cBR • IPv6: 6PE & 6VPE • L2VPN PW redundancy on CMTS • Map Advance for CBR8 • MD(Mac-Domain interface func) • Modular Ranging (Infrastructure) • MPLS P2P L2VPN support over DOCSIS, on cBR-8 • MPLS VPLS support over DOCSIS, on cBR • Multicast on CBR • Multicast VPN and DOCSIS 3.0 Multicast QoS support • Netflow on CBR8 • NTP MIB • OIR for Cable Line cards on cBR8 • Onboard Failure Logging • OSPF MIB Support of RFC 1850 and Latest Extensions • OSPFv3 MIB • Packetcable Multimedia for cbr • PacketCable Support on cBR • Per Downstream Static Multicast • PING MIB |

| Cisco IOS-XE Release | Supported Features |
|----------------------|--|
| 3.15.0S | <ul style="list-style-type: none"> • Policy Based Routing • PROCESS-MIB for CBR • Punt-Path Rate Limiting • RCC Template • SAMIS Inactive service flow, and Channel Utilization Interval CLI • SAMIS Source Address Management • Secure Boot Support • Security Features For CBR8 • Service Class Relay Agent Option • SII - Service Independent Intercept • SII Routed CPE Support • Smart Call Home for CBR • SMART license for cBR • Smart Licensing PRE-HA • SNMP Notification Logging • SNMP support for virtual interface for CBR8 • SNMPv2C • SNMPv3 Community MIB Support • Source Specific Multicast (SSM) • Sub Packaging • Subinterfaces for CBR8 • Subscriber management for cBR • TCP MIB for RFC4022 support • TLV63 Support • Upstream Buffer Control • Upstream Channel Bonding • Upstream drop classifier • Upstream Peak Rate • US WFQ • VDOC scaling and advanced feature support • VDOC: Robustness, Scalability & Debugability • Voice MGPI support • Voice support over D3.0 MTA • Voltage table support for CISCO-ENVMON-MIB • Wideband Modem Resiliency |

Modified Software Features in Cisco IOS-XE Release 3.18.3aSP

There are no modified software features in Cisco IOS-XE Release 3.18.3aSP.

Modified Software Features in Cisco IOS-XE Release 3.18.2aSP

There are no modified software features in Cisco IOS-XE Release 3.18.2aSP.

Modified Software Features in Cisco IOS-XE Release 3.18.1aSP

There are no modified software features in Cisco IOS-XE Release 3.18.1aSP.

Modified Software Features in Cisco IOS-XE Release 3.18.1SP

DOCSIS 3.1 Downstream OFDM Graceful Profile Assignment

This feature dynamically adjusts downstream data profile for each cable modem.

For more information, see:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer2_docsis31_downstream_profile_selection.html

Usage-Based Billing

This feature enables IPDR to automatically generate sflogs during a line card switchover or a line card process restart.

For more information, see Usage-Based Billing (SAMIS) guide at:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cisco_cmts_networkmgmt_trblshtng_cbr/usage_based_billing_samis.html

show cable modem summary scn

The feature enables the user to get the details of the total number of users on each node using the **show cable modem summary** command on the Cisco cBR-8 router.

For more information, see the Cisco CMTS Cable Command Reference:

http://www.cisco.com/c/en/us/td/docs/cable/cmts/cmd_ref/b_cmts_cable_cmd_ref/b_cmts_cable_cmd_ref_chapter_01111.html

show cable modem service-flow

The feature enables the user to get more details of the active cable filter group for the cable modem using the **show cable modem service-flow verbose** command on the Cisco cBR-8 router.

For more information, see the Cisco CMTS Cable Command Reference:

http://www.cisco.com/c/en/us/td/docs/cable/cmts/cmd_ref/b_cmts_cable_cmd_ref/b_cmts_cable_cmd_ref_chapter_01111.html

Enhanced Cable modem provisioning

The following commands were introduced for enhancing cable modem provisioning:

- **clear cable modem device-class**
- **show cable modem wideband**
- **show cable modem docsis device-class**
- **show cable modem wideband**

Modified Software Features in Cisco IOS-XE Release 3.18.0SP

There are no modified software features in Cisco IOS-XE Release 3.18.0SP.

Modified Software Features in Cisco IOS-XE Release 3.18.1S

There are no modified software features in Cisco IOS-XE Release 3.18.1S.

Modified Software Features in Cisco IOS-XE Release 3.18.0Sa

There are no modified software features in Cisco IOS-XE Release 3.18.0Sa.

Modified Software Features in Cisco IOS-XE Release 3.18.0S

16 US per MAC Domain

Starting from Cisco IOS-XE 3.18.0S release, maximum of 16 upstream channels can be configured for each MAC Domain, which are divided into two groups:

- Group 1: upstream channel 0-7
- Group 2: upstream channel 8-15

An upstream bonding-group should include all the upstream channels either from Group 1 or Group 2 only.

For more information about this feature, see the following URL:

https://www.cisco.com/c/en/us/td/docs/cable/cmts/cmd_ref/b_cmts_cable_cmd_ref/b_cmts_cable_cmd_ref_chapter_01001.html#wp2533370910

SNMP Cache Engine Enhancement

Cisco IOS-XE Release 3.18.0S introduces SNMP multiple buffer which can improve the SNMP performance under multiple SNMP sessions.

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cisco_cmts_networkmgmt_trblshing_cbr/snmp_engine_enhancement.html

Configurable Burst mode MER

The configurable data-burst mode feature provides support to loop all the upstream bonding modems for global time interval.

The following command is modified on Cisco cBR Series Converged Broadband Routers:

- **cable upstream resiliency**

For more information about this feature, see the Configuring Cable Upstream Resiliency section at the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cmts/config_guide/b_cmts_ds_us_features/b_cmts_ds_us_features_chapter_010010.html#task_1182573

Three Step Dynamic Modulation

The criteria for switching modulation profiles is modified to determine whether it should switch from the primary modulation to the secondary modulation profile or to the tertiary modulation profile.

For more information about this feature, see the Spectrum Management and Advanced Spectrum Management for the Cisco CMTS chapter at the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cmts/config_guide/b_cmts_ds_us_features/b_cmts_ds_us_features_chapter_01111.html

Modified Software Features in Cisco IOS-XE Release 3.17.1S

There are no modified software features in Cisco IOS-XE Release 3.17.1S.

Modified Software Features in Cisco IOS-XE Release 3.16.2S

There are no modified software features in Cisco IOS-XE Release 3.16.2S.

Modified Software Features in Cisco IOS-XE Release 3.17.0S

Smart Licensing Enforcement

If the Cisco products stop communicating with the Cisco Cloud License Service for 90 days, the cable interfaces in the Cisco products will be locked, which means you can no longer enable/disable the cable interfaces.

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_sw_config_features/cisco_smart_licensing.html

Adaptive CIR, Fair EIR

When multiple bonding groups sharing the RF-channel bandwidth and the current bonding group's guaranteed bandwidth is insufficient, On-demand CIR Acquisition feature can “borrow” neighbor bonding group's non-reserved guaranteed bandwidth for current bonding group's CIR. Fairness Across DOCSIS Interfaces feature use the weight value of the aggregated active flow count, that is EIR demand, to periodically re-balance the reservable bandwidth. So that the service flows with the same weight in different bonding groups will have roughly the same throughput.

The following commands were modified:

- **show cable acfe summary**
- **show controllers integrated-cable acfe cluster**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cmts_quality_of_services/fairness_across_docsis_interfaces.html

ISSU with N+1

Cisco cBR-8 Routers support the In-Service Software Upgrades (ISSU) for redundant platforms. The ISSU process allows software to be updated or otherwise modified while packet forwarding continues with the benefit of LCHA. ISSU supports two different software upgrade modes: Consolidated package mode and Subpackages mode.

The following commands were modified:

- **request platform software package install rp**
- **request platform software package install node**
- **request platform software package expand**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cmts_ha_features_cbr/cisco_ios_xe_in_service_software_upgrade_process.html

Upstream Bonding Support for D-PON

Upstream bonding support for D-PON is enabled on a MAC domain basis on the Cisco cBR Series Converged Broadband Routers. By default, upstream bonding support for D-PON is disabled. In addition, the USCB can support a maximum of 4 US channels in RFOG MAC domain in the following combination:

- US0
- US0, US1
- US0, US1, US2
- US0, US1, US2, US3

You can configure upstream bonding support for D-PON using the following command:

- **cable upstream dpon**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cmts/config_guide/b_cisco_cmts_scg/b_cisco_cmts_scg_chapter_011000.html

Dynamic Downstream DOCSIS 3.0 Load Balancing

The existing load balancing (LB) feature is enhanced to cope with the increase in the number of downstream and upstream channels by multi service operators (MSO) and wider deployment of 16-channel, 24-channel and multiple downstream channel cable modems (CMs). The enhancements include:

- Utilization based dynamic downstream LB for DOCSIS 3.0
- Support for DOCSIS 3.0 LB statistics
- Enable or disable DOCSIS 3.0 LB feature

The following commands were introduced:

- **cable load-balance docsis30-enable dynamic downstream**
- **cable load-balance docsis20-enable**
- **cable load-balance docsis30-enable static**
- **show cable load-balance docsis-group rfch-util**
- **show cable load-balance docsis-group load wideband**
- **show cable load-balance docsis-group modem-list wideband**
- **show cable load-balance docsis-group statistics wideband**
- **show cable load-balance docsis-group target wideband**

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_layer2_docsis/docsis_load_balancing_movement.html

Priority Queues

All low latency flows on a DOCSIS downstream are aggregated to the single priority queue.

For more information about this feature, see the following URL:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cmts_quality_of_services/docsis_wfq_scheduler.html

Flexible Bandwidth Allocation

To address the issue of restricted bandwidth allocation for different application types, admission control can be applied for both normal priority and emergency voice flows. This is done by extending the threshold and assigning a group of application types in a fiber node. Each downstream service flow continues to be categorized to a single application type. However, the one-to-one mapping between an application type and a threshold no longer exists. Each configured threshold and its associated group of application types can thus be treated as a constraint. A service flow categorized to a certain application type must pass all the constraints associated with that application type.

The following command was modified:

- **admission-control application-type**

For more information, see the *Service Group Admission Control* feature guide at:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cmts_quality_of_services/Service_Group_Admission_Control.html

Cable Line Card Upstream Scheduler Process Restart

The Cable Line Card process restart feature eliminates service disruption, loss of modem configuration data, and time consumption in rebooting the line cards and other components.

For more information, see the *Consolidated Packages and SubPackages Management* feature guide at:

http://www.cisco.com/c/en/us/td/docs/cable/cbr/configuration/guide/b_cbr_basic_sw_config_features/consolidated_packages_and_subpackages_management.html

Modified Software Features in Cisco IOS-XE Release 3.16.1S

There are no modified Software features in Cisco IOS-XE Release 3.16.1S.

Modified Software Features in Cisco IOS-XE Release 3.16.0S

Downstream DOCSIS 3.1 PHY Module Upgrade

The Downstream DOCSIS 3.1 PHY module on the RF line card may be upgraded from downstream DOCSIS 3.0 module to downstream DOCSIS 3.1 module. Alternatively, the installed RF line card in the Cisco cBR chassis may be replaced with another RF line card that has the downstream DOCSIS 3.1 modules already installed. The upgrade is required to provide DOCSIS 3.1 readiness to the Cisco cBR router. This hardware upgrade requires that the RF line card, on which the downstream PHY module was upgraded, be reloaded using the following command:

- **hw-module slot reload**

For more information about this feature, see the following URL:

<http://www.cisco.com/c/en/us/td/doc/cable/cbr/Cisco-cBR/index.html>

MIBs

To locate and download MIBs for selected platforms, Cisco IOS-XE releases, and feature sets, use Cisco MIB Locator found at the following URL:

<http://tools.cisco.com/ITDIT/MIBS/servlet/index>

To access Cisco MIB Locator, you must have an account on Cisco.com. If you have forgotten or lost your account information, send a blank e-mail to cco-locksmith@cisco.com. An automatic check verifies that your e-mail address is registered with Cisco.com. If the check is successful, account details with a new random password is e-mailed to you. Qualified users can establish an account on Cisco.com by following the directions found at this URL:

<http://tools.cisco.com/RPF/register/register.do>

New and Changed MIB Information in Cisco IOS-XE Release 3.18.3aSP

There are no new and changed MIB information in Cisco IOS-XE Release 3.18.3aSP

New and Changed MIB Information in Cisco IOS-XE Release 3.18.2aSP

There are no new or changed MIB information in Cisco IOS-XE Release 3.18.2aSP.

New and Changed MIB Information in Cisco IOS-XE Release 3.18.1aSP

There are no new or changed MIB information in Cisco IOS-XE Release 3.18.1aSP.

New and Changed MIB Information in Cisco IOS-XE Release 3.18.1SP

There are no new or changed MIB information in Cisco IOS-XE Release 3.18.1SP.

New and Changed MIB Information in Cisco IOS-XE Release 3.18.0SP

The following MIB was added in Cisco IOS-XE Release 3.18.0SP:

- DOCS-IF31-MIB

New and Changed MIB Information in Cisco IOS-XE Release 3.18.1S

There are no new and changed MIB information in Cisco IOS-XE Release 3.18.1S.

New and Changed MIB Information in Cisco IOS-XE Release 3.18.0Sa

There are no new and changed MIB information in Cisco IOS-XE Release 3.18.0Sa.

New and Changed MIB Information in Cisco IOS-XE Release 3.18.0S

The following MIBs were added in Cisco IOS-XE Release 3.18.0S:

- SCTE-HMS-MPEG-MIB
- SCTE-HMS-QAM-MIB

New and Changed MIB Information in Cisco IOS-XE Release 3.17.1S

There are no new and changed MIB information in Cisco IOS-XE Release 3.17.1S.

New and Changed MIB Information in Cisco IOS-XE Release 3.16.2S

There are no new and changed MIB information in Cisco IOS-XE Release 3.16.2S.

New and Changed MIB Information in Cisco IOS-XE Release 3.17.0S

The following MIBs were changed in Cisco IOS-XE Release 3.17.0S:

- get the whole table-MIB
- get each entry-MIB
- CISCO-CABLE-QOS-MONITOR-MIB
- DOSCIS-QOS-MIB

New and Changed MIB Information in Cisco IOS-XE Release 3.16.0S

The following MIB was changed in Cisco IOS-XE Release 3.16.0S:

- Entity-MIB

Important Notes for Cisco IOS-XE Release 3S

Important Notes for Cisco IOS-XE Release 3.18.0SP

- Load Balancing is not supported on DOCSIS 3.1 cable modems.
- It is recommended to use only technique zero to move cable modem from one MAC domain to the other. Avoid using DCC to move cable modem with non-zero ranging technique within a MAC-domain.

Important Notes for Cisco IOS-XE Release 3.18.0S

- Effective with Cisco IOS-XE Release 3.18.0S, a warning message is displayed when you configure a value greater than the maximum value specified by the DRFI in the **base-channel-power** *value* command.
- Effective with Cisco IOS-XE Release 3.18.0S, the **ARP-filter drops** field is also displayed as output for the **show plat hard qfp active infra punt summary** command.

Important Notes for Cisco IOS-XE Release 3.16.0S

- Effective with Cisco IOS-XE Release 3.16.0S, do not configure the **logging event link-status** command until the system is in the stable state.

Important Notes for Cisco IOS-XE Release 3.15.0S

- Effective with Cisco IOS-XE Release 3.15.0S, **cable l2-vpn xconnect backup force-switchover** command is modified as **xconnect backup force-switchover**.
- Effective with Cisco IOS-XE Release 3.15.0S, to turn *fragment-threshold* to default value (2,000 bytes), use **no** form of the **cable upstream n fragment-force [fragment-threshold [number-of-fragments]]** command.
- Effective with Cisco IOS-XE Release 3.15.0S, for **cable service flow activity-timeout** command, the default timeout length for a DOCSIS 1.0+ cable service flow is 0 seconds.
- Effective with Cisco IOS-XE Release 3.15.0S, the **show interface cable { slot /subslot /cable-interface-index } modem** command displays the number of **Active Modems** and **Total active devices** also.
- Effective with Cisco IOS-XE Release 3.15.0S, the **show cable modem vendor** command does not display **Timing Offset** column.
- Effective with Cisco IOS-XE Release 3.15.0S, the **show cable load-balance docsis-group** command does not display the **Flows** column (number of service flows currently active on the cable interface).

Cisco IOS-XE Release 3S Image Upgrade Best Practice Manual of Procedure

See the [Upgrading the Cisco cBR Series Converged Broadband Routers for Cisco IOS XE Release 3.18SP](#) guide.

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see [What's New in Cisco Product Documentation](#) .

To receive new and revised Cisco technical content directly to your desktop, you can subscribe to the [What's New in Cisco Product Documentation RSS feed](#) . The RSS feeds are a free service.



CHAPTER 2

Caveat List

This chapter describes open severity 1 and 2 caveats and select severity 3 caveats:

- The “Open Caveats” sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.

The bug IDs are sorted alphanumerically.



Note The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- [Cisco Bug Search](#), on page 46
- [Important Software Upgrade](#), on page 47
- [Open Caveats - Cisco IOS-XE Release 3.18.3bSP](#), on page 47
- [Resolved Caveats—Cisco IOS-XE Release 3.18.3bSP](#), on page 49
- [Open Caveats—Cisco IOS-XE Release 3.18.3aSP](#), on page 49
- [Resolved Caveats—Cisco IOS-XE Release 3.18.3aSP](#), on page 51
- [Open Caveats—Cisco IOS-XE Release 3.18.2aSP](#), on page 52
- [Resolved Caveats—Cisco IOS-XE Release 3.18.2aSP](#), on page 55
- [Open Caveats—Cisco IOS-XE Release 3.18.1aSP](#), on page 57
- [Resolved Caveats—Cisco IOS-XE Release 3.18.1aSP](#), on page 59
- [Open Caveats—Cisco IOS-XE Release 3.18.1SP](#), on page 59
- [Resolved Caveats—Cisco IOS-XE Release 3.18.1SP](#), on page 61
- [Open Caveats—Cisco IOS-XE Release 3.18.0SP](#), on page 63
- [Resolved Caveats—Cisco IOS-XE Release 3.18.0SP](#), on page 64
- [Open Caveats—Cisco IOS-XE Release 3.18.1S](#), on page 69
- [Resolved Caveats—Cisco IOS-XE Release 3.18.1S](#), on page 69
- [Open Caveats—Cisco IOS-XE Release 3.18.0Sa](#), on page 71
- [Resolved Caveats—Cisco IOS-XE Release 3.18.0Sa](#), on page 71
- [Open Caveats—Cisco IOS-XE Release 3.18.0S](#), on page 72
- [Resolved Caveats—Cisco IOS-XE Release 3.18.0S](#), on page 73
- [Open Caveats—Cisco IOS-XE Release 3.17.1S](#), on page 74
- [Resolved Caveats—Cisco IOS-XE Release 3.17.1S](#), on page 75

- [Open Caveats—Cisco IOS-XE Release 3.16.7S, on page 76](#)
- [Resolved Caveats—Cisco IOS-XE Release 3.16.7S, on page 76](#)
- [Open Caveats—Cisco IOS-XE Release 3.16.2S, on page 77](#)
- [Resolved Caveats—Cisco IOS-XE Release 3.16.2S, on page 79](#)
- [Open Caveats—Cisco IOS-XE Release 3.17.0S, on page 83](#)
- [Resolved Caveats—Cisco IOS-XE Release 3.17.0S, on page 84](#)
- [Open Caveats—Cisco IOS-XE Release 3.16.1S, on page 90](#)
- [Resolved Caveats—Cisco IOS-XE Release 3.16.1S, on page 93](#)
- [Open Caveats—Cisco IOS-XE Release 3.16.0S, on page 96](#)
- [Resolved Caveats—Cisco IOS-XE Release 3.16.0S, on page 96](#)
- [Open Caveats—Cisco IOS-XE Release 3.15.1S, on page 98](#)
- [Resolved Caveats—Cisco IOS-XE Release 3.15.1S, on page 98](#)
- [Open Caveats—Cisco IOS-XE Release 3.15.0S, on page 99](#)
- [Resolved Caveats—Cisco IOS-XE Release 3.15.0S, on page 101](#)

Cisco Bug Search

Use the [Cisco Bug Search Tool](#) to access open and resolved bugs for a release.

The tool allows you to search for a specific bug ID, or for all bugs specific to a product and a release.

You can filter the search results by last modified date, bug status (open, resolved), severity, rating, and support cases.

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see [What's New in Cisco Product Documentation](#).

To receive new and revised Cisco technical content directly to your desktop, you can subscribe to the [What's New in Cisco Product Documentation RSS feed](#). The RSS feeds are a free service.

Important Software Upgrade

| Problem | Condition | Solution |
|--|---|---|
| CSCux46368- Modems offline on CLC after CDMINFRA CDM_PT_FPA_TEST SANITY TEST FAILED | A Cisco cBR-8 router running one of the following releases: <ul style="list-style-type: none"> • Cisco IOS-XE Release 3.16.1S / Cisco IOS Release 15.5(3)S1 • Cisco IOS-XE Release 3.17.0S / Cisco IOS Release 15.6(1)S | Upgrade to one of the following releases: <ul style="list-style-type: none"> • Cisco IOS-XE Release 3.16.2S / Cisco IOS Release 15.5(3)S2 • Cisco IOS-XE Release 3.17.1S / Cisco IOS Release 15.6(1)S1 • Cisco IOS-XE Release 3.18.0S / Cisco IOS Release 15.6(2)S and later releases <p>If the problem persists, perform the workaround provided at:</p> <p>https://tools.cisco.com/bugsearch/bug/CSCux46368/</p> |

Open Caveats - Cisco IOS-XE Release 3.18.3bSP

| Caveat ID Number | Description |
|----------------------------|--|
| CSCva18706 | cBR-8: show cable calls skips Cable0/0/0 |
| CSCvb85260 | CM reset does not clear tag after config is modified |
| CSCvd19728 | EM modem offline and DBG doesn't free after SUP switch over from Standby to Active card. |
| CSCvd29978 | Many Tracebacks of Duplicated DSID detected. |
| CSCvb97854 | CBR-4-BADTXOFFSET: Bad timing offset 20548 detected for cable modem |
| CSCvd94426 | cBR8 CDM_RT crashed @ubr_ump_rtt_handle_dev_event after shut the mac-domain |
| CSCvd25745 | CGD association is incorrect after default MD & LCSW |
| CSCux28031 | CNR decreased a lot after sent traffic |
| CSCva77731 | D31: OFDM down with width as 148Mhz with user picked PLC |
| CSCva48237 | D31: OFDM wideband status down if OFDM channel width x(ex: 103-Mhz) |
| CSCvb68603 | DS-JIB Non-Critical [PHY0_XFI01:High-Pri:xfi1 lost block lock tdiff |
| CSCva52480 | Incorrect DS License consumed count after SUP SO |
| CSCvb98095 | Shut/no shut Controller followed by shut/no shut ofdm causes OFDM to be down in scm wideband res |
| CSCvc66320 | Threshold configuration under upstream controller is partially duplicated. |

| Caveat ID Number | Description |
|----------------------------|--|
| CSCvb50464 | IPv6 echo request packets go into l3 inject and get skipped for address resolution |
| CSCvd28724 | 03.18.00a.S - Wideband interfaces not added in RCC list |
| CSCvb54886 | cdxCmtsMtcCmTotal uses incorrect TCS id/ cdxCmtsUsecbSfPri not accounting single channel CMs |
| CSCuv30942 | CM offline after A/C power up, if use cross-controller RBG enter 1x1 battery mode |
| CSCvb32272 | DOCS-LOADBAL3-MIB showing wrong value for D2.0 modems |
| CSCva25857 | docsIf31CmtsCmRegStatusDsProfileIdList value become empty after LCHA |
| CSCvc71104 | Primary channel MDD is not transmitted under rare condition |
| CSCut58615 | Ranging Status showing STA when the modem is offline |
| CSCvb03115 | ubr_ucm_get_registered_card() Err and traceback |
| CSCvc06297 | Patch upgrade with LCHA method didn't support rollback |
| CSCva94951 | Cable modem IPv6 address out-of-sync between SUP and CLC |
| CSCuv25680 | SUP crashed @ ubr_subdb_display_subscriber_db |
| CSCve73353 | "hw-module slot r1 start" does not work. |
| CSCvc88451 | CBR-LC-8D31-16U31 linecard crashed due to corrupted pointer to Packet buffer,memory corruption |
| CSCvf27415 | cBR8 "show harddisk: all:" command output incomplete/cut-off before displaying all files |
| CSCvd02176 | CmtsMdIfIndex field not match with CmtsMdIfName after LCSO |
| CSCuz98369 | Incorrect "Power Not Enough" alarm |
| CSCvc93861 | New active LC was reset after LC revert back 1 minute later |
| CSCva39199 | no msg after LC crash due to several continuous IOS/IOSDB restart |
| CSCva32978 | Secondary LC version incorrect after doing ISSU rollback |
| CSCvd10399 | ServiceFlowChSet field in STOP record of US SF changed after clc-iosd restart or lcsd. |
| CSCvc10140 | show platform diag not display Power-Supply version |
| CSCuz83612 | standby SUP's protection LC's OPF stay in drain mode after remove LCRED |
| CSCva37561 | TenGigabit ports under SUP association is missing in EntityAliasmib. |
| CSCvf33535 | PSIT:Session create configs with vei_bundle getting removed on reloading cbr-8 with inactive LED |

| Caveat ID Number | Description |
|----------------------------|--|
| CSCvf06562 | Input version mismatch occurs during source switch |

Resolved Caveats—Cisco IOS-XE Release 3.18.3bSP

| Caveat ID Number | Description |
|----------------------------|--|
| CSCub50530 | OSPF session is taking ~20mins to come up on SVI |
| CSCve75818 | ASR1k crashes due to SNMP polling |
| CSCvg07169 | D6 Update attribute Total Bandwidth = 37901kbps is incorrect. |
| CSCvg01774 | OSPF SPPF: when seg area is disabled and enabled, mapping server EPL entries not re-generated. |

Open Caveats—Cisco IOS-XE Release 3.18.3aSP

| Caveat ID Number | Description |
|----------------------------|--|
| CSCva18706 | cBR-8: show cable calls skips Cable0/0/0 |
| CSCvb85260 | CM reset does not clear tag after config is modified |
| CSCvd19728 | EM modem offline and DBG doesn't free after SUP switch over from Standby to Active card. |
| CSCvd29978 | Many Tracebacks of Duplicated DSID detected. |
| CSCvb97854 | CBR-4-BADTXOFFSET: Bad timing offset 20548 detected for cable modem |
| CSCvf51151 | cbr8 - LC reload upon SUP failover due to "card is not fully ready" |
| CSCvd94426 | cBR8 CDM_RT crashed @ubr_ump_rtt_handle_dev_event after shut the mac-domain |
| CSCvd25745 | CGD association is incorrect after default MD & LCSW |
| CSCux28031 | CNR decreased a lot after sent traffic |
| CSCva77731 | D31: OFDM down with width as 148Mhz with user picked PLC |
| CSCva48237 | D31: OFDM wideband status down if OFDM channel width x(ex: 103-Mhz) |
| CSCvb68603 | DS-JIB Non-Critical [PHY0_XFI01:High-Pri:xfi1 lost block lock tdiff |
| CSCva52480 | Incorrect DS License consumed count after SUP SO |
| CSCvb98095 | Shut/no shut Controller followed by shut/no shut ofdm causes OFDM to be down in scm wideband rcs |

| Caveat ID Number | Description |
|----------------------------|--|
| CSCvc66320 | Threshold configuration under upstream controller is partially duplicated. |
| CSCvb50464 | IPv6 echo request packets go into I3 inject and get skipped for address resolution |
| CSCvd28724 | 03.18.00a.S - Wideband interfaces not added in RCC list |
| CSCvb54886 | cdxCmtsMtcCmTotal uses incorrect TCS id/ cdxCmtsUscbSfPri not accounting single channel CMs |
| CSCuv30942 | CM offline after A/C power up, if use cross-controller RBG enter 1x1 battery mode |
| CSCvb32272 | DOCS-LOADBAL3-MIB showing wrong value for D2.0 modems |
| CSCva25857 | docsIf31CmtsCmRegStatusDsProfileIdList value become empty after LCHA |
| CSCvc71104 | Primary channel MDD is not transmitted under rare condition |
| CSCut58615 | Ranging Status showing STA when the modem is offline |
| CSCvb03115 | ubr_ucm_get_registered_card() Err and traceback |
| CSCvc06297 | Patch upgrade with LCHA method didn't support rollback |
| CSCva94951 | Cable modem IPv6 address out-of-sync between SUP and CLC |
| CSCuv25680 | SUP crashed @ ubr_subdb_display_subscriber_db |
| CSCve73353 | "hw-module slot r1 start" does not work. |
| CSCvc88451 | CBR-LC-8D31-16U31 linecard crashed due to corrupted pointer to Packet buffer,memory corruption |
| CSCvf27415 | cBR8 "show harddisk: all:" command output incomplete/cut-off before displaying all files |
| CSCvd02176 | CmtsMdIfIndex field not match with CmtsMdIfName after LCSD |
| CSCuz98369 | Incorrect "Power Not Enough" alarm |
| CSCvc93861 | New active LC was reset after LC revert back 1 minute later |
| CSCva39199 | no msg after LC crash due to several continuous IOS/IOSDB restart |
| CSCva32978 | Secondary LC version incorrect after doing ISSU rollback |
| CSCvd10399 | ServiceFlowChSet field in STOP record of US SF changed after clc-iosd restart or lcso. |
| CSCvc10140 | show platform diag not display Power-Supply version |
| CSCuz83612 | standby SUP's protection LC's OPF stay in drain mode after remove LCRED |
| CSCva37561 | TenGigabit ports under SUP association is missing in EntityAliasMIB. |

| Caveat ID Number | Description |
|----------------------------|--|
| CSCve00370 | Multicast Source-Switch skipping some Active Sources |
| CSCvf33535 | PSIT:Session create configs with vei_bundle getting removed on reloading cbr-8 with inactive LED |
| CSCvf40730 | cBR-8 line card reloads in sleep system call |
| CSCvf06562 | Input version mismatch occurs during source switch |

Resolved Caveats—Cisco IOS-XE Release 3.18.3aSP

| Caveat ID Number | Description |
|-----------------------------|---|
| CSCve17659 | CLC reset @ cmts_lb_cm_us_chans_in_group when shut the US channel |
| CSCve54739 | when LB trigger DFO on D1.0 QoS provision modems, the target is "/0" |
| CSCva84690 | "Failed to find free freq block!" message on standby RP |
| CSCve09340 | cBR8 linecard cdman restart @ ubrcce_cdm_infra_handle_hwevent |
| CSCve28505 | cdman: US-PHY PHY6 ch:1 rx intUsProcFlow isr |
| CSCve38317 | show cable hop missed poll percent and average% showing incorrect values in adv spectrum management |
| CSCvf42321 | cBR: cpp crash due to DPE0_CPE_CSR32_DPE_CPE_ERR_LEAF_INT__INT_CPE_M40A_ACC_ERR |
| CSCCuy48322 | Could not set value for mib ccqmEnfRuleViolateNotifEnable with OpsConfig |
| CSCvd98223 | "cable upstream balance-scheduling" is configured, but "us_balance:OFF" |
| CSCva21658 | cbr8 - service flow state are pro for certain modems |
| CSCve58503 | Mismatch with CM primary wideband interface and CM DS SF forwarding interface |
| CSCve19262 | Modems unpingable with Invalid HWflow ID after DS Resiliency events |
| CSCve55144 | RNG-RSP status cancel send to quickly with pre-eq active |
| CSCve72030 | VOIP Jitter is bigger than 5ms when configure 43 UGS with modulation profile 24 |
| CSCve05401 | BPI index mismatch causing CM L3 fail after LCHA |
| CSCvc84902 | cBR-8 supervisor reloads due to a freed chunk access during glean processing |
| CSCve77989 | cBR8 - Downstream L2VPN Dot1Q packets dropped |
| CSCve08617 | CBR8 line card CBR-LC-8D31-16U30 crash at process_tek_req_attribute |

| Caveat ID Number | Description |
|----------------------------|---|
| CSCVf10719 | cBR8 linecard reload caused by show cable privacy hotlist cm command |
| CSCVf28887 | CBR8 Misreports In/Out Octet Counters on Etherchannel Subinterfaces |
| CSCVf96094 | Modem stuck in init(io). Some DHCP packets are encrypted when sent from CBR8 to CM |
| CSCVe39863 | Rogue NA messages are corrupting ipv6 neighbor table. |
| CSCVe49908 | SNMP get cdxCmtsCmMaxCpeNumber return wrong value |
| CSCVe95162 | SUP crash while copying file via tftp |
| CSCVe77132 | Cisco IOS XE Software for cBR-8 Routers Line Card Console Access Vulnerability |
| CSCVe32926 | Unable to get compMemPoolEntry after SUP switchover |
| CSCVc06362 | cBR8 - 3.18.0SP - Add show cable video session all and summary commands |
| CSCVe24538 | multicast video ASM delay upto 60 sec |
| CSCVf57004 | PSIT: Bulk sync failure due to PRC mismatch after changing the slot from primary to secondary |
| CSCVf70287 | Secondary GQI connection failure msg floods LED log |
| CSCVe87567 | SUP reload while deleting session when LED debug enabled |
| CSCVe15082 | VSRM Zone Config causes LED & VSRM out-of-sync issue |
| CSCVg07169 | D6 Update attribute Total Bandwidth = 37901kbps is incorrect |
| CSCVd34382 | PSIT: Invalid video operation ADD_SES Session error message after doing LCPR |
| CSCVe02766 | Some sessions go to off state after vidman LCPR |
| CSCVe67523 | VOD UDP sessions corruption |

Open Caveats—Cisco IOS-XE Release 3.18.2aSP

| Caveat ID Number | Description |
|----------------------------|---|
| CSCVa18706 | Cisco cBR-8: show cable calls skips Cable0/0/0. |
| CSCVd91139 | Cisco cBR-8: BitTorrent packet getting stuck in the bundle interface. |
| CSCVb85260 | CM reset does not clear tag after config is modified. |
| CSCVd19728 | EM modem offline and DBG do not free after SUP switch over from Standby to Active card. |

| Caveat ID Number | Description |
|----------------------------|---|
| CSCvd29978 | Many Tracebacks of Duplicated DSID detected. |
| CSCvb97854 | CBR-4-BADTXOFFSET: Bad timing offset 20548 detected for cable modem. |
| CSCvd25745 | CGD association is incorrect after default MD & LCSW. |
| CSCux28031 | CNR decreased a lot after sent traffic. |
| CSCva77731 | D31: OFDM down with width as 148MHz with user picked PLC. |
| CSCva48237 | D31: OFDM wideband status down if OFDM channel width x(ex: 103-Mhz). |
| CSCvb68603 | DS-JIB Non-Critical [PHY0_XFI01:High-Pri:xfi1 lost block lock tdiff. |
| CSCva10909 | Failure case is not handled properly due to missing fw in the pkg. |
| CSCva52480 | Incorrect DS License consumed count after SUP SO. |
| CSCvc82872 | OFDM Channel unable to send low-prio traffic after ofdm config change. |
| CSCvb98095 | Shut or no shut Controller followed by shut or no shut ofdm causes OFDM to be down in scm wideband res. |
| CSCvc66320 | Threshold configuration under upstream controller is partially duplicated. |
| CSCvd32726 | Cisco cBR8/3.18.1SP: Burst of modems causing stuck objects on given LC. |
| CSCvb50464 | IPv6 echo request packets go into I3 inject and get skipped for address resolution. |
| CSCvd28724 | Cisco IOS XE 03.18.00a.S - Wideband interfaces not added in RCC list. |
| CSCvd98496 | Cable modem went p-online after LCHA. |
| CSCvb54886 | cdxCmtsMtcCmTotal uses incorrect TCS id/ cdxCmtsUscbSfPri not accounting single channel CMs. |
| CSCuv30942 | CM offline after A/C power-up, if use cross-controller DBG, enter 1x1. |
| CSCvb32272 | DOCS-LOADBAL3-MIB showing wrong value for D2.0 modems. |

| Caveat ID Number | Description |
|----------------------------|--|
| CSCvc71104 | Primary Channel MDD is Not Transmitted. |
| CSCut58615 | Ranging Status showing STA when the modem is offline. |
| CSCvc06297 | Patch upgrade with LCHA method did not support rollback. |
| CSCva94951 | Cisco cBR-8: Cable modem IPv6 address out-of-sync between SUP and CLC. |
| CSCvc84902 | Cisco cBR-8 supervisor crash due to freed chunk access during glean processing. |
| CSCvd67080 | L2VPN dot1q traffic sometimes will loss after LCHA. |
| CSCuv25680 | SUP crashed @ ubr_subdb_display_subscriber_db. |
| CSCvd17185 | With 64k modems, standby SUP fails to bootup after reload. |
| CSCvc88451 | CBR-LC-8D31-16U31 linecard crashed due to corrupted pointer to Packet buffer, memory corruption. |
| CSCvd02176 | CmtsMdlfIndex field does not match with CmtsMdlfName after LCSO. |
| CSCuz98369 | Incorrect "Power Not Enough" alarm. |
| CSCvc93861 | New active LC was reset after LC revert 1 minute later. |
| CSCva39199 | No msg after LC crash due to several continuous IOS/IOSDB restarts. |
| CSCva32978 | Secondary LC version incorrect after doing ISSU rollback. |
| CSCvc10140 | Show platform diag not display Power-Supply version. |
| CSCuz83612 | Standby SUP's protection LC's OPF stay in drain mode after remove LCRED. |
| CSCva37561 | TenGigabit ports under SUP association are missing in EntityAliasesmib. |
| CSCve02766 | Some sessions go to off state after vidman LCPR. |
| CSCve06350 | Smart licensing traps are not generated on Cisco IOS XE Everest 16.5.1 and Cisco IOS XE 3.18.2aSP. |

Resolved Caveats—Cisco IOS-XE Release 3.18.2aSP

| Caveat ID Number | Description |
|----------------------------|---|
| CSCvc81242 | 10K and Cisco cBR-8 behave differently for IPDR Code. |
| CSCvc51364 | 'Logging event link-status global' config will ignore 'no loggin event link-status' on WB interfaces. |
| CSCvc59793 | Cisco IOS XE 3.18SP - All the modems connected to one line card of a Cisco cBR-8 dropped offline. |
| CSCvc12937 | Cisco cBR-8 Upstream Spectrum reporting is not accurate and displays artifacts from aliasing. |
| CSCvc27210 | Cisco cBR-8: CLC crash on CMTS MAC Parser process. |
| CSCvd29099 | Cisco cBR-8 shows increased jitter on UGS. |
| CSCvd02953 | Cisco cBR-8 shows increased latency for traffic on UGS. |
| CSCvc09109 | D31: Ranging Deadlock due to Pwr Adj Request Beyond Upper Limit. |
| CSCvc06802 | DSJIB BG has wrong JIB channels after multiple controller shut/no shut with video config changes. |
| CSCvb39445 | Gemini1 DSJIB-3-CRIT_REC_INT; replication chan is invalid after upgrade. |
| CSCva16840 | OFDM configuration rejected on G2 after upgrade from G1. |
| CSCvc09005 | OFDM down with subcarrier spacing 25Khz and roll-off as 256. |
| CSCva62309 | Tracebacks@dmp resource pool BG-Pool 32-Chan tmp_ptr not in pool [0 512]. |
| CSCvc36914 | Wrong US Channel utilization in "show controllers cx/y/z upstream". |
| CSCvd42561 | %CPPOSLIB-3-ERROR_NOTIFY: CLC4: cpp_cp: cpp_cp encountered an error. |
| CSCva13481 | fman object download failure; lots of tracebacks and error messages. |
| CSCvb67308 | Traceback@cpp_vbuginf_flags_error after show pl ha qf ac infra punt st. |

| Caveat ID Number | Description |
|----------------------------|--|
| CSCvb38611 | UNIX-EXT-SIGNAL: Segmentation fault(11), Process = CMTS submgmt process. |
| CSCva19771 | Cisco cable/cBR-8 docsIfCmtsCmStatusInetAddress is returning wrong value. |
| CSCvb71506 | Cisco cBR-8 Error Message observed during Cable LC switchover. |
| CSCvc98395 | Cisco cBR-8: cable cm-status not working after reload. |
| CSCvc32010 | Cisco cBR-8 does not do ofdm profile recommendation for channel widths less than 79 MHz. |
| CSCvd30132 | Cisco cBR-8: Traffic counters are not increasing in wideband interfaces. |
| CSCvc08946 | Cisco cBR-8: CABLE_IPCCL_LIB-5-SVC_LOW_WATERMARK. |
| CSCvc35190 | Cisco cBR-8: some DS channels are marked as impaired during DS path selection. |
| CSCvd48695 | cdxCmtsUscbSfPri should return "0" if no service flows exist on USCB. |
| CSCvc55488 | DOCS-IF31-MIB docsIf31CmtsCmRegStatusDsProfileIdList not reporting all 3.1 Profiles. |
| CSCvc19665 | Downstream RF-Channel utilization flatlines at 94% - ccwbRFChannelUtilization. |
| CSCvc65483 | OFDM profiles in DBC-REQ are the same profiles that were sent in REG-RSP-MP. |
| CSCvb59310 | Seeing levels 10 db hot after adding patch. |
| CSCvc62294 | Secondary LC cannot bootup after reset under 7+1 with over 60K CM. |
| CSCvc85324 | Cisco cBR-8 not passing COS for L2VPN dot1q. |
| CSCvb14695 | Interface bundle showing negative input queue "Input queue: -735". |
| CSCvc35255 | Losing startup-config after writing the nvram:/docsBpi2_mib via SNMP set. |
| CSCvc32015 | SUP Crashed due to IPv6 list freed during v6list removing. |

| Caveat ID Number | Description |
|----------------------------|---|
| CSCvc84996 | Cisco cBR-8 Line Card reloads when Broadcast MPTS session becomes active. |
| CSCvc81434 | Cisco cBR-8 loses audio for live Switched Digital Video (SDV) session. |
| CSCvc30168 | CDMAN-0-LOW_FPA_FATAL LC reset - free buffers low, video top user. |
| CSCva87804 | PSIT:cdman DS-JIB Non-Critical"Double encryption error on pipe" on boot. |
| CSCva25240 | Modems reboot after configure init-tech 2 under mac-domain. |

Open Caveats—Cisco IOS-XE Release 3.18.1aSP

| Caveat ID Number | Description |
|----------------------------|--|
| CSCva18706 | cBR-8: show cable calls skips Cable0/0/0 |
| CSCvb21924 | D3.0 static LB not balanced when threshold is 1 |
| CSCvc12772 | Smart Licensing - dropping registration |
| CSCvb47794 | with 21056 multicast sessions configured, reload TB, fman_fp_image crash |
| CSCvb97854 | CBR-4-BADTXOFFSET: Bad timing offset 20548 detected for cable modem |
| CSCvc12937 | cbr-8 Upstream Spectrum reporting is not accurate and displays artifacts from aliasing |
| CSCvc27210 | cBR-8:CLC crash on CMTS MAC Parser process |
| CSCvc09109 | D31: Ranging Deadlock due to Pwr Adj Request Beyond Upper Limit |
| CSCva77731 | D31: OFDM down with width as 148Mhz with user picked PLC |
| CSCva48237 | D31: OFDM wideband status down if OFDM channel width x(ex: 103-Mhz) |
| CSCvb68603 | DS-JIB Non-Critical [PHY0_XFI01:High-Pri:xfi1 lost block lock tdiff |
| CSCva10909 | failure case is not handled properly due to missing fw in the pkg |
| CSCvb39445 | Gemini1 DSJIB-3-CRIT_REC_INT;replication chan is invalid after upgrade |
| CSCva52480 | Incorrect DS License consumed count after SUP SO |
| CSCva16840 | OFDM configuration rejected on G2 after upgrade from G1 |
| CSCvc09005 | OFDM down with subcarrier spacing 25Khz and roll-off as 256 |

| Caveat ID Number | Description |
|------------------|--|
| CSCvb98095 | Shut/no shut Controller followed by shut/no shut ofdm causes OFDM to be down in scm wideband res |
| CSCva62309 | Tracebacks@dmp resource pool BG-Pool 32-Chan tmp_ptr not in pool [0 512] |
| CSCva50633 | CFD: Cylons Watch Dog Timeout Failure detected on multiple customer |
| CSCvc22184 | BQS Interrupt QSM_CSR32_QSM_LOGIC_ERR_LEAF_INT__INT_INCORRECT_POP_STATUS_ERR1 |
| CSCvc21981 | One-way Audio - Dead Air for voice calls on the cbr8 |
| CSCvb67308 | Traceback@cpp_vbuginf_flags_error after show pl ha qf ac infra punt st |
| CSCva19771 | cable/cBR8 docsIfCmtsCmStatusInetAddress is returning wrong value |
| CSCvb71506 | CBR-8 Error Message observed during Cable LC switchover |
| CSCvc32010 | cbr8 does not do ofdm profile recommendation for channel widths less than 79 MHz |
| CSCvc08946 | CBR8: CABLE_IPCCL_LIB-5-SVC_LOW_WATERMARK: |
| CSCvc35190 | cbr8: some DS channels are marked as impaired during DS path selection |
| CSCvb54886 | cdxCmtsMtcCmTotal uses incorrect TCS id/ cdxCmtsUscbSfPri not accounting single channel CMs |
| CSCuv30942 | CM offline after A/C power up, if use cross-controller DBG enter 1x1 |
| CSCvb32272 | DOCS-LOADBAL3-MIB showing wrong value for D2.0 modems |
| CSCvb79025 | OFDM channel goes missing from RCC resulting in low D3.1 speeds |
| CSCut58615 | Ranging Status showing STA when the modem is offline |
| CSCvb59310 | Seeing levels 10 db hot after adding patch: |
| CSCvc06297 | Patch upgrade with LCHA method didn't support rollback |
| CSCva94951 | Battlestar: Cable modem IPv6 address out-of-sync between SUP and CLC |
| CSCvb14695 | Interface bundle showing negative input queue "Input queue: -735" |
| CSCvb50464 | IPv6 echo request packets go into I3 inject and get skipped for address resolution |
| CSCvc35255 | Losing startup-config after writing the nvram:/docsBpi2_mib via SNMP set |
| CSCuu48273 | %EVENTLIB-3-TIMEHOG and traceback when boot up |
| CSCuz98369 | Incorrect "Power Not Enough" alarm |
| CSCva39199 | no msg after LC crash due to several continous IOS/IOSDB restart |
| CSCvc17049 | Redundancy- Standby Console Lock |

| Caveat ID Number | Description |
|----------------------------|---|
| CSCva32978 | Secondary LC version incorrect after doing ISSU rollback |
| CSCvc10140 | show platform diag not display Power-Supply version |
| CSCuz83612 | standby SUP's protection LC's OPF stay in drain mode after remove LCRED |
| CSCva37561 | TenGigabit ports under SUP association is missing in EntityAliasmb. |

Resolved Caveats—Cisco IOS-XE Release 3.18.1aSP

| Caveat ID Number | Description |
|----------------------------|---|
| CSCvc31986 | after repeatedly shut/shut OFDM channel without proper delay, scm prof-mgmt crashes the CLC |
| CSCvc31899 | CLC Crash During IOSd Cmd Pwr Neq Calculation |
| CSCvb84601 | BPI encryption missing after LCHA |

Open Caveats—Cisco IOS-XE Release 3.18.1SP

| Caveat ID Number | Description |
|----------------------------|---|
| CSCva18706 | cBR-8: show cable calls skips Cable0/0/0 |
| CSCvb21924 | D3.0 static LB not balanced when threshold is 1 |
| CSCvc12772 | Smart Licensing - dropping registration |
| CSCvb47794 | with 21056 multicast sessions configured, reload TB, fman_fp_image crash |
| CSCvb97854 | CBR-4-BADTXOFFSET: Bad timing offset 20548 detected for cable modem |
| CSCvc12937 | cbr-8 Upstream Spectrum reporting is not accurate and displays artifacts from aliasing |
| CSCvb92900 | cBR8 LC After Uncorrectable ECC Errors in Gemini RLDRAM no Auto Restart / Failover: CMs Offline |
| CSCva77731 | D31: OFDM down with width as 148Mhz with user picked PLC |
| CSCva48237 | D31: OFDM wideband status down if OFDM channel width x(ex: 103-Mhz) |
| CSCvb68603 | DS-JIB Non-Critical [PHY0_XFI01:High-Pri:xfi1 lost block lock tdiff |
| CSCvb39445 | Gemini1 DSJIB-3-CRIT_REC_INT;replication chan is invalid after upgrade |
| CSCva52480 | Incorrect DS License consumed count after SUP SO |
| CSCva16840 | OFDM configuration rejected on G2 after upgrade from G1 |

| Caveat ID Number | Description |
|----------------------------|---|
| CSCva62309 | Tracebacks@dmp resource pool BG-Pool 32-Chan tmp_ptr not in pool [0 512] |
| CSCvc22184 | BQS Interrupt QSM_CSR32_QSM_LOGIC_ERR_LEAF_INT__INT_INCORRECT_POP_STATUS_ERR1 |
| CSCvc21981 | One-way Audio - Dead Air for voice calls on the cbr8 |
| CSCvb67308 | Traceback@cpp_vbuginf_flags_error after show pl ha qf ac infra punt st |
| CSCvc31986 | after repeatedly shut/shut OFDM channel without proper delay, scm prof-mgmt crashes the CLC |
| CSCva19771 | cable/cBR8 docsIfCmtsCmStatusInetAddress is returning wrong value |
| CSCvb71506 | CBR-8 Error Message observed during Cable LC switchover |
| CSCvc08946 | CBR8: CABLE_IPCCL_LIB-5-SVC_LOW_WATERMARK: |
| CSCvb54886 | cdxCmtsMtcCmTotal uses incorrect TCS id/ cdxCmtsUscbSfPri not accounting single channel CMs |
| CSCvc31899 | CLC Crash During IOSd Cmd Pwr Neq Calculation |
| CSCuv30942 | CM offline after A/C power up, if use cross-controller DBG enter 1x1 |
| CSCvb32272 | DOCS-LOADBAL3-MIB showing wrong value for D2.0 modems |
| CSCvb79025 | OFDM channel goes missing from RCC resulting in low D3.1 speeds |
| CSCvb59310 | Seeing levels 10 db hot after adding patch: |
| CSCvb84601 | BPI encryption missing after LCHA |
| CSCvc06297 | Patch upgrade with LCHA method didn't support rollback |
| CSCva94951 | Battlestar: Cable modem IPv6 address out-of-sync between SUP and CLC |
| CSCvb14695 | Interface bundle showing negative input queue "Input queue: -735" |
| CSCvb50464 | IPv6 echo request packets go into I3 inject and get skipped for address resolution |
| CSCuu48273 | %EVENTLIB-3-TIMEHOG and traceback when boot up |
| CSCuz98369 | Incorrect "Power Not Enough" alarm |
| CSCva39199 | no msg after LC crash due to several continuous IOS/IOSDB restart |
| CSCva32978 | Secondary LC version incorrect after doing ISSU rollback |
| CSCuz83612 | standby SUP's protection LC's OPF stay in drain mode after remove LCRED |
| CSCva37561 | TenGigabit ports under SUP association is missing in EntityAliasMIB. |

Resolved Caveats—Cisco IOS-XE Release 3.18.1SP

| Caveat ID Number | Description |
|----------------------------|--|
| CSCva42614 | LCHA license disappears with pre-provisioned line card |
| CSCva07373 | LCHA reporting wrong license information |
| CSCva42580 | US licenses consumed with pre-provisioned LC |
| CSCva58505 | Cable Monitor config that is applied does not match the cli config. |
| CSCva61353 | cBR8: show cable card x/y us-mac config not returning correct value |
| CSCva60391 | CLC crash @ Process=cBR CLI Transfer IPC Show Process during "show tech" |
| CSCva58205 | D3.1 CMs p-online post LCHA after ofdm chan-prof change on all ctrlrs |
| CSCva02675 | D3.1 modem p-online on hybrid WB interface and ping fail |
| CSCvb79058 | D3.1 modems show N/A for current data profile resulting in low speeds |
| CSCvb66487 | D31 CM goes to p-online due to OFDM down after LCSO with BW change above 96MHz |
| CSCva82604 | DS jib partial reset and cdman crash during AnnexB and AnnexC testing |
| CSCvb07277 | JIB4US Partial Reset and recovery modems not pingable |
| CSCva63833 | Line card crash after repeated LCPR stress test |
| CSCva97648 | Modems transmitting 2dB higher on Leoben3 |
| CSCvb78656 | OFDM channel not function after sub package installs and LC SO |
| CSCvb98465 | SIGALARM found on infra_stats_cache_enc_ack during ISSU from 318SP ES to 318.1SP |
| CSCva38424 | CBR-8 SUP Modems offline due to %FMFP-3-OBJ_DWNLD_TO_CPP_FAILED: qos hqf: |
| CSCuz98057 | MLACP interface flap test at peer resulted in CPP_STUCK |
| CSCva47433 | 1x1 BM doesn't work due to wrong cm-status flag in MDD after LCPR |
| CSCva82119 | cbr8 3.18SP CMTS should not allow to configure OFDM channels as primary |
| CSCvb05507 | D31: Add 1002MHZ To DS Upper Band Edge Support Mask |
| CSCuz62815 | line vty are added automatically |
| CSCvb92235 | Mismatched WB RCC detection and recovering after LCHA/LCPR |
| CSCva63910 | scm vendor does not include vendor info for all CMs |

| Caveat ID Number | Description |
|----------------------------|--|
| CSCvb19276 | US Bonded Modem does not recover from partial mode after LCSO and revert |
| CSCva57001 | cbr8_ISSU: consolidated mode can't work properly. |
| CSCva90326 | BSOD: MPLS PW CktID assignment overlap causing VCs to be down |
| CSCvb40290 | CBR8 - ucode crash with cable_output_qos_prepare |
| CSCva58284 | CBR8 input queue stuck on tengig, Triggered by IPv6 nd queue packet |
| CSCva58124 | D31: exempt subcarrier config does not affect the profile order |
| CSCva84605 | EROUTER appears as MTA |
| CSCva87095 | One way voice issue occurs while doing on-net call |
| CSCvb17352 | sup crash when doing IPv4 DHCP transaction for CPE |
| CSCvb69550 | [cBR] DHCP renew failed if "giaddr-as-server-id" flag enabled on server |
| CSCvb37852 | 3.18.0SP ipdr sflog sup ha support |
| CSCva77912 | 3.18.0SP snmp-server enable traps hccp-failover rfs witch-polling |
| CSCvb45600 | Bad RF PIC result in SNMP-3-INPUT_QFULL_ERR on LC after revert back |
| CSCvb31704 | Caprica top interrupt disabled after multiple cdman restart |
| CSCvb73491 | cBR-8 May See "SUP_dSUM" Alerts w/ Value of 190-199. Threshold Needs to be Adjusted to >200. |
| CSCvb14655 | cBR8 CLC Crashinfo Thread ID: CDM_PKTIO_08 Exception:Segmentation Fault |
| CSCva18734 | cBR8 Show Tech Missing show logging onboard uptime latest for slots 6-9 |
| CSCva62789 | cBR8 showing up as cBR1013 |
| CSCuz89734 | cylons line card i2c communication lost after bootup |
| CSCva65152 | IPC memory may be double freed |
| CSCvb81157 | ISSU upgrade error after patch upgrade w/o SUP reload |
| CSCva76742 | Patch upgrade failed due to LCSO cmd rejected |
| CSCvb82866 | Patch with ISSU LCHA way will fail with DOCSIS_CFG_DNLD |
| CSCvb17509 | queue stuck, CM not pingable or can't online after LCHA |
| CSCuy84933 | sh hw-module subslot x/y transceiver 0 status has no output |
| CSCva41315 | Software crash brought down CLC on CBR8 |
| CSCvb77445 | The cdman crash is happened immediately after patch upgrade trigger cdman restart. |

| Caveat ID Number | Description |
|----------------------------|--|
| CSCva58189 | 2nd Sup flooded w/ASSERT:"Unable to allocate memory" w/extended src loss |
| CSCva84873 | Add encryption support for H.265 Ultra HD video and data components |
| CSCva18487 | Database mismatch Btwn LC & SUP on creating cloned sessions on 2nd LED |
| CSCuz23330 | Delay in getting PAT in the Output |
| CSCux90140 | DS-JIB Non-Critical Pktp Video P0-0:Low-Pri:Video sync byte err |
| CSCvb95374 | mpegInputProgNo table returns no value |

Open Caveats—Cisco IOS-XE Release 3.18.0SP

| Identifier | Description |
|----------------------------|--|
| CSCuz83612 | standby SUP's protection LC's OPF stay in drain mode after remove LCRED |
| CSCva31952 | SUP crashed due to stack is exhausted |
| CSCva37561 | TenGigabit ports under SUP association is missing in EntityAliasmb. |
| CSCva58189 | 2nd Sup flooded w/ASSERT:"Unable to allocate memory" w/extended src loss |
| CSCva18487 | Database mismatch Btwn LC & SUP on creating cloned sessions on 2nd LED |
| CSCva30314 | PSIT:All the multicast sessions removed after removal of VEI from LED |
| CSCva32796 | Traceback observed after multiple line card high availability (LCHAs) |
| CSCva58725 | Dynamic changes to IP bundle may cause some sess goes off at max scale |
| CSCva25240 | Modems reboot after configure init-tech 2 under mac-domain |
| CSCva18706 | cBR-8: show cable calls skips Cable0/0/0 |
| CSCuz91599 | D3.0 CMs r not load balanced as expected when D3.1 CMs are on same MDs |
| CSCva42614 | LCHA license disappears with pre-provisioned line card |
| CSCva32064 | Base-Power-Level not changing on the LC of the CBR8 |
| CSCva58505 | Cable Monitor config that is applied does not match the cli config. |
| CSCux28031 | CNR decreased a lot after sent traffic |
| CSCuy88599 | D3 modems on a CBR cannot be pinged via IPv6 after adding 4 DS Channels |
| CSCva58205 | D3.1 CMs p-online post LCHA after ofdm chan-prof change on all ctrlrs |
| CSCuy91688 | Gemini1 DSJIB-3-CRIT_REC_INT;replication chan is invalid after upgrade |

| Identifier | Description |
|------------|--|
| CSCva16840 | OFDM configuration rejected on G2 after upgrade from G1 |
| CSCva36353 | cpp traceback like "CST: %CPPOSLIB-3-ERROR_NOTIFY: " |
| CSCva25646 | Multicast DP queue length is fixed as 64, bad tolerance for burst |
| CSCva47433 | 1x1 BM doesn't work due to wrong cm-status flag in MDD after LCPR |
| CSCva19771 | cable/cBR8 doesIfCmtsCmStatusInetAddress is returning wrong value |
| CSCva21658 | cbr8 - 3.17.1 IP Ping loss for certain modems |
| CSCuv30942 | CM offline after A/C power up, if use cross-controller DBG enter 1x1 |
| CSCva57001 | cbr8_ISSU: consolidated mode can't work properly. |
| CSCva58284 | CBR8 input queue stuck |
| CSCuv53754 | cBR ROMON - Read access failing on 2GB USB drives |
| CSCva04729 | CBR-8: Te4/1/6's output counter value is wrong |
| CSCuz98369 | Incorrect "Power Not Enough" alarm |
| CSCva39199 | no msg after LC crash due to several continuous IOS/IOSDB restart |
| CSCva32978 | Secondary LC version incorrect after doing ISSU rollback |
| CSCva41315 | Software crash brought down CLC on CBR8 |
| CSCva48237 | D31: OFDM wideband status down if OFDM channel width x(ex: 103-Mhz) |

Resolved Caveats—Cisco IOS-XE Release 3.18.0SP

| Identifier | Description |
|------------|--|
| CSCux98336 | apps_pktcbl_delete_gate_ie() disables interrupts for too long |
| CSCux23893 | cBR8 - DHCP circuit-id field is empty Option 82 Suboption 1 |
| CSCuy60207 | CBR8 sec LC crash at Pktcbl LCHA process |
| CSCuz48578 | DQoS-lite DS traffic forwarding and low latency queuing |
| CSCuy67782 | DSG IGMP Static Group Mroute Missing on new Bundle Activation |
| CSCva13034 | EDVA device classification breaks filter group functionality |
| CSCuy46851 | EM:CLI cannot clear energy mode events correctly. |
| CSCuz55251 | Error message CBR-3-DYN_SRV_IPC_SEND_FAILURE happens during LCHA |

| Identifier | Description |
|----------------------------|--|
| CSCuy52701 | traceback & static route missed after SSO with QRG modification |
| CSCuz53661 | LB weight incorrect after LCSO |
| CSCuz60069 | LC crash@ lb_get_us_pending for policy us-across-ds |
| CSCuz71261 | observed DSG_INFO_DB_LOOKUP_FAILURE error message after config replace. |
| CSCux83175 | PRE_REG_DSID null cause CM reject(na) |
| CSCuy82052 | show cable modem commands display incorrectly after modem enter EM mode. |
| CSCuz00215 | SUP card crash at Process = SVC_0 RX IOSD-CC-6 |
| CSCuz42461 | SUP IOSd crash with multicast leave |
| CSCuz63886 | when CM recover from p-online to WB, the SF does not recover to WB |
| CSCuy22380 | "Failed to find free freq block!" message on standby RP |
| CSCva21576 | cBR8 - 3.17.1 - LC crash on ubr_specsvl_get_cm_cnr |
| CSCuy36957 | cBR:Unconfigured RF ports not configureable after Gemini 2 module upg |
| CSCuy59360 | cm can be seen on offline status @md shutdown @supha |
| CSCuz05968 | cmtsChannelUtilization for DS is not consistent with util-interval value |
| CSCux24459 | DS-JIB 2 Enq:High-Pri:detect if BG has channel greater than 383 |
| CSCuz50518 | DS-JIB Non-Critical [Enq:Low-Pri:one interrupt signal for both pipes |
| CSCuv04305 | Enq:Low-Pri:one interrupt signal for both pipes, when IPH header says BG |
| CSCuz57637 | fix frequency shown wrong when show cable spect-group on cylon |
| CSCuz43219 | Getting parser error if removing unconfigured rf-ch from controller |
| CSCuy94845 | HW-ID and BG Pool details missing from show command post LCHA |
| CSCux55969 | Incorrect "MPEG Mbps" in "show controller <ds-controller> counters" |
| CSCuw89169 | Interface keep in down status after shut & no shut controller then supha |
| CSCuy85297 | Leoben VGAs: CM went offline on an entire MD after LCSO or Revert |
| CSCuy40470 | Leoben3 "Failed to read ACT2, USPHY OFDMA cap on slot 3" on standby SUP |
| CSCuy94430 | mixed PHY info 'show cable card' & bundled ver cleanup & XFI dump |
| CSCuy61540 | Modem IP ping fail due to zero US hw-flow after LCRP and CDMAN PR |
| CSCuy34498 | Multiple US channels went down after the SUP SO (Reason: UMP Failure) |
| CSCuy10043 | NET-Claro CM connectivity issues, CPP queue stuck/Raider2.x.10 |

| Identifier | Description |
|------------|--|
| CSCuz63420 | RAPTOR_MAC_INGRESS_QOS_LO_INTERRUPT: pb_if_err after unshut TenG in PC |
| CSCuy51863 | Shut Controller, SUP-HA, unshut controller - several DS in DOWN State |
| CSCva17171 | Statistics on US port incorrect when using Leoben 3 |
| CSCuz72187 | SUP and LC out of sync if Gemini on the protect card goes into bad state |
| CSCuz55482 | Symbol Rate is not correct after shut/no shut us-channel |
| CSCuy14893 | The output of cable monitor CLI is confusing after LCSO |
| CSCux78899 | Traceback@ubr_dmp_flow_releas when clear cable modem |
| CSCuz51129 | CBR SUP crash on ubr_dp_cm_qos_match_test |
| CSCuz77441 | CBR8 sbrl drops showing on the protect card when in STBY state |
| CSCuy31792 | cBR8 Subscribers are not able to get the IP address through DHCP relay |
| CSCuz17361 | cBR8: ping from console to subscriber-side device must bypass SBRL |
| CSCux93745 | cBR8: support more DS flows per-CM for ubr10k parity |
| CSCuy37158 | Detect stuck CPP client on cbr8 |
| CSCuy77823 | DS queue count failed to decrement after DSC |
| CSCuz48100 | Flex920: nile_efp_db_iterate_all Continuous Crash on latest |
| CSCuz56738 | IPv6 3.0 modems and STB not pingable after sup switchover |
| CSCuy47771 | PPRL: change cBR8 default punt-policer settings |
| CSCux08040 | queue stuck after DS resiliency/recover, cause CM in init(o)/init(t) |
| CSCuy81512 | 3.0 modems are in p-online(pt) after LCSO on CBR8 |
| CSCuy95431 | cBR - rf-chans wrongly marked as unsuable prevent CM to go W-Online |
| CSCuy39767 | cBR8 cable modem counters remain at zero SUPHA |
| CSCuy47866 | cBR8 D3.0 WB Cable Modems reject(na) |
| CSCuz14807 | CBR8 support for separate cm-onoff notification traps and informs. |
| CSCuz87223 | cBR8/3.16.1 : LC crash in cmts_print_modem_verbose_ds |
| CSCuy33796 | CBR8: "cable rcv-control verbose" no longer active after LCHA or SUP SO |
| CSCuz45964 | CBR8: docsIf3DsChSetChList incomplete for first MAC domain (Cable 0/0/0) |
| CSCva51691 | cbr8: protect card mem leak on "docsis cm chunk" |
| CSCuz11642 | cBR8: US Equalizer is Not Set to 8 taps Using TDMA-ATDMA Mixed Mode |

| Identifier | Description |
|----------------------------|--|
| CSCuy42258 | cdxCmtsMtcCmTable: mib get value is different with ubr10k |
| CSCuy73578 | cm offline after LCHA when there are two WB interface with same rf-chan |
| CSCuz29867 | CM-ST AUS TLVs are missing in MDD after LCPR |
| CSCuy50690 | DSC failed and CIR value not recovered to previous value |
| CSCuv29290 | FN failed to generate interface when adding and removing mac domain |
| CSCux78524 | For MGPI of 2, the UGS throughput is low when using Arris CM820 CM's |
| CSCuy70127 | MDD stops sending when DS removed from MD |
| CSCuy85188 | modems become offline after deleting the service flow then iosd restart |
| CSCuu16786 | Non-zero Queue-indicator bit statistics reported for non-UGS flows |
| CSCuz75271 | Some modems from vendor Netgear and Moto cannot 8-ch w-online |
| CSCva26768 | Stale RCC with the outdate info stayed on LC when RP generate new RCC |
| CSCuz83132 | Stale RCC wrongly marks all channels primary capable |
| CSCuy50511 | SUP crash@be_ubr_mbrgrp_rfids_count |
| CSCva05701 | SUP crashed @ SVC_0 RX IOSD-CC-9 process during sh/no shut of mac-domain |
| CSCuy90274 | Supervisor Reload After Executing 'show cable l2-vpn dot1q-vc-map vpn #' |
| CSCux05429 | Battlestar: CBR-8 ARP entries timed out and deleted on standby SUP |
| CSCuy96787 | CBR8 3.17.0S Zero MAC address for x.x.x.x in ARP cache |
| CSCuz38651 | CBR8 : IPv6 CPE become unpingable after ND resolution fails |
| CSCuy33886 | CBR8: SNMP query returns wrong value for BPI encryption |
| CSCuy06815 | cm can't be online with ipv4 in vrf when leak cnr grt to vrf |
| CSCuz46011 | CMTS submgmt process crash |
| CSCuz34011 | CPE overlap IP issue when in VRF using TLV 43 option |
| CSCur82415 | CPP traceback and unable to setup dot1q L2VPN after LI configured |
| CSCuy57024 | DHCP packets not being relayed on dot1q encaps subinterfaces |
| CSCuy54004 | Dual stack provisioning mode orphans IP address |
| CSCuy78428 | ipv6 l3 ds inject not trigger v6 lq |
| CSCuw93287 | lla address not released after GUA lease timeout in hostdb |
| CSCuy33093 | MIB value in docsSubMgtCpeControlTable is not update |

| Identifier | Description |
|------------|---|
| CSCuy99888 | no output with sh cable l2-vpn xcon dot1q customer +second vpnid |
| CSCux43524 | snmp performance is low for cdxCmtsCmStatusDMICEntry |
| CSCuz61514 | "clc-pic 1/1" disappear in " show inventory" when OIR slot 0/1 |
| CSCuz49046 | %CBR_SPA-7-RAPTOR_INTERRUPT_ENABLE: CLC4: iomd: ipv4_hdr_checksum_err |
| CSCuy97233 | Bad RF PIC causing other PIC cards could not up |
| CSCva10588 | cable/cBR8 Upstream SNR value is not reported after IOS upgrade |
| CSCuy88230 | Caprica FPGA isr stop working after LCHA |
| CSCuv87705 | CBR-8 : 'show software authenticity' should indicate Secure Boot |
| CSCuz87007 | CBR-8-CCAP-CHASS/cBR-CCAP-LC-40G/"facility alarm "clear fail |
| CSCuy73678 | CMRP-3-WANPLL_SETUP errmsg prints when cbr boot up |
| CSCuy54609 | CST: The PEM/FM idprom could be read, but is corrupt in slot P10 |
| CSCuz51334 | Intermittent bcm3142 init failed with R2 image at high temperature |
| CSCuy00928 | IPDR generates double records on SF schema scaling testing |
| CSCux41734 | LC bootup after soft reload in dispite of in-sufficient power |
| CSCuy72534 | lpr config: "default lcha-preferred" results in "no lcha-preferred" |
| CSCuz55239 | Protected LC all modems re-online after supha |
| CSCux11278 | RAPTOR_ESI_PCIE_LO_INTERRUPT: LOCAL RAPTOR, LOCAL PCIE IF, tx_terr_drp |
| CSCuy42577 | snmp cache: polling docsIf3CmtsCmRegStatusEntry.16 error |
| CSCux46066 | stby SUP got reset and cmand core file generated after SUP SO |
| CSCuz55436 | SUP/RF PIC is out of service after chassis power down and up |
| CSCuz88537 | WAN interfaces became admin shutdown after 2 times SUP-HA via OIR |
| CSCuz41142 | parse error log observed when type "mgmt-intf VirtualPortGroup 0" twice |
| CSCuy64215 | PSIT: adding vei in one LED makes session active in another LED |
| CSCuy43167 | Changing Default ONID , moves some of the active sessions to Pending |
| CSCuz34817 | Identical Session names on the same QAM is not disallowed |
| CSCuz48205 | PME Sessions go pending for successive remove/add of LED or Sessions |
| CSCuz78277 | Sessions not getting created with veg name of 32 characters |
| CSCuz57812 | Bad checksum of UDP stream w/ vei-bundle configured |

| Identifier | Description |
|----------------------------|---|
| CSCux88801 | Input Session Discontinuity Error goes up with HA test cases |
| CSCuy41562 | Some sessions go OFF state after removing vei-bundle for 8064 sessions. |
| CSCuy55789 | Some sessions going OFF on adding bundle in 8960/8064 session |
| CSCuy30325 | US DOCSIS packet outage after restart vidman process |
| CSCva49171 | Video QAM consumes DOCSIS 3.0 Downstream License |
| CSCuy11118 | dsgIfDownVendorParamId configuration not synced to protect LC |
| CSCuy61879 | Some STB can't receive dsg traffic after upgrade 3gsap to 6gsap |
| CSCuy97717 | LC may crash when CM flaps during 'show interface cable X/X/X modem' |
| CSCux57314 | Online CM marked CM offline in remote-query and not polled |
| CSCuy99728 | Pegasus TCAM core voltage adjustment |

Open Caveats—Cisco IOS-XE Release 3.18.1S

| Identifier | Description |
|----------------------------|--|
| CSCva31072 | Static Route copied to Startup Config |
| CSCva21576 | cBR8 - 3.17.1 - LC crash on ubr_specsvl_get_cm_cnr |
| CSCuy31792 | cBR8 Subscribers are not able to get the IP address through DHCP relay |
| CSCva21658 | cbr8 - 3.17.1 IP Ping loss for certain modems |
| CSCuz83132 | Stale RCC wrongly marks all channels primary capable |
| CSCuz92412 | vcms_proxy process starts before cdman process causing linecard crash |

Resolved Caveats—Cisco IOS-XE Release 3.18.1S

| Identifier | Description |
|----------------------------|--|
| CSCuy60207 | CBR8 sec LC crash at Pktcbl LCHA process |
| CSCva13034 | EDVA device classification breaks filter group functionality |
| CSCuz53661 | LB weight incorrect after LCSO |
| CSCux83175 | PRE_REG_DSID null cause CM reject(na) |
| CSCuz00215 | SUP crash @ Process = SVC_0 RX IOSD-CC-6 |

| Identifier | Description |
|------------|--|
| CSCuz42461 | SUP IOSd crash with multicast leave |
| CSCuy36957 | cBR:Unconfigured RF ports not configureable after Gemini 2 module upg |
| CSCuy59360 | cm can be seen on offline status @md shutdown @supha |
| CSCuv04305 | Enq:Low-Pri:one interrupt signal for both pipes, when IPH header says BG |
| CSCuw89169 | Interface keep in down status after shut & no shut controller then supha |
| CSCuz58751 | Mixed Annex LCSO port resulting in loss of Annex C video carriers |
| CSCuy61540 | Modem IP ping fail due to zero US hw-flow after LCRP and CDMAN PR |
| CSCuy10043 | NET-Claro CM connectivity issues, CPP queue stuck/Raider2.x.10 |
| CSCva17171 | Statistics on US port incorrect when using Leoben 3 |
| CSCuz51129 | CBR SUP crash on ubr_dp_cm_qos_match_test |
| CSCuz17361 | cBR8: ping from console to subscriber-side device must bypass SBRL |
| CSCuy77823 | DS queue count failed to decrement after DSC |
| CSCuz56738 | IPv6 3.0 modems and STB not pingable after sup switchover |
| CSCuy48185 | memory leak @CMTS Multicast MQC: POLICYMAP_MODULE |
| CSCuy38028 | RBG fail to be deleted due to incorrect AC check |
| CSCuy81512 | 3.0 modems are in p-online(pt) after LCSO on CBR8 |
| CSCuy95431 | cBR - rf-chans wrongly marked as unsuable prevent CM to go W-Online |
| CSCuy39767 | cBR8 cable modem counters remain at zero SUPHA |
| CSCuv61269 | cbr8 set CM to 1 ch USCB when power exceeds threshold for 2 ch |
| CSCuz45964 | CBR8: doesIf3DsChSetChList incomplete for first MAC domain (Cable 0/0/0) |
| CSCuz11642 | cBR8: US Equalizer is Not Set to 8 taps Using TDMA-ATDMA Mixed Mode |
| CSCuy42258 | cdxCmtsMtcCmTable: mib get value is defferent with ubr10k |
| CSCuy73578 | cm offline after LCHA when there are two WB interface with same rf-chan |
| CSCuy70127 | MDD stops sending when DS removed from MD |
| CSCuu16786 | Non-zero Queue-indicator bit statistics reported for non-UGS flows |
| CSCuy90274 | Supervisor Reload After Executing 'show cable l2-vpn dot1q-vc-map vpn #' |
| CSCuz38651 | CBR8 : IPv6 CPE become unpingable after ND resolution fails |
| CSCuz46011 | CMTS submgmt process crash |

| Identifier | Description |
|----------------------------|---|
| CSCuz34011 | CPE overlap IP issue when in VRF using TLV 43 option |
| CSCuy57024 | DHCP packets not being relayed on dot1q encap subinterfaces |
| CSCuy54004 | Dual stack provisioning mode orphans IP address |
| CSCuy78428 | ipv6 l3 ds inject not trigger v6 lq |
| CSCuy88230 | Caprica FPGA isr stop working after LCHA |
| CSCuz87007 | CBR-8-CCAP-CHASS/cBR-CCAP-LC-40G/"facility alarm "clear fail |
| CSCuz12272 | Change fan replace error message |
| CSCuy73678 | CMRP-3-WANPLL_SETUP errmsg prints when cbr boot up |
| CSCuy54609 | CST: The PEM/FM idprom could be read, but is corrupt in slot P10 |
| CSCuz51334 | Manufacture test, bcm3142 init failed with R2 release image |
| CSCuy64215 | PSIT: adding vei in one LED makes session active in another LED |
| CSCuz13015 | Remove Video interfaces from Global Routing Table |
| CSCuz34817 | Identical Session names on the same QAM is not disallowed |
| CSCuz78277 | Sessions not getting created with vcg name of 32 characters |
| CSCuz92510 | Video sessions goes down after SSO |
| CSCuz57812 | Bad checksum of UDP stream w/ vei-bundle configured |
| CSCuy41562 | Some sessions go OFF state after removing vei-bundle for 8064 sessions. |
| CSCuy30325 | US DOCSIS packet outage after restart vidman process |
| CSCuy61879 | Some STB can't receive dsq traffic after upgrade 3gsap to 6gsap |
| CSCuy97717 | LC may crash when CM flaps during 'show interface cable X/X/X modem' |

Open Caveats—Cisco IOS-XE Release 3.18.0Sa

There are no open caveats in Cisco IOS-XE Release 3.18.0Sa.

Resolved Caveats—Cisco IOS-XE Release 3.18.0Sa

| Bug ID | Description |
|----------------------------|---|
| CSCuz13015 | Remove Video interfaces from Global Routing Table |

Open Caveats—Cisco IOS-XE Release 3.18.0S

| Identifier | Description |
|----------------------------|--|
| CSCuy41562 | Some sessions go OFF state after removing vei-bundle for 8064 sessions. |
| CSCux88101 | admission control max-reserve in bonding group issue |
| CSCuy48322 | Could not set value for mib ccqmEnfRuleViolateNotifEnable with OpsConfig |
| CSCuy40674 | sup 0 kept on restart after supha and can't recover |
| CSCux72453 | Shutdown threshold action by Physical OIR Cylon test failed |
| CSCux96966 | Lots of CAUSE_OCE_COUNTER_EXCEED_STACK tracebacks in NG-MVPN testing |
| CSCuy36957 | cBR:Unconfigured RF ports not configureable after Gemini 2 module upg |
| CSCuy59360 | cm can be seen on offline status @md shutdown @supha |
| CSCux88101 | admission control max-reserve in bonding group issue |
| CSCuy44159 | Can't debug platform software mpls in xe318 |
| CSCuy42258 | cdxCmtsMtcCmTable: mib get value is defferent with ubr10k |
| CSCuy73578 | cm offline after LCHA when there are two WB interface with same rf-chan |
| CSCux81933 | TDL memory leak, tdl_epoch_data, detected after LCPR hitless upgrade |
| CSCux66218 | AC failure on other LC seen after reset target LC with PCMM mcast |
| CSCux98336 | apps_pktcbl_delete_gate_ie() disables interrupts for too long |
| CSCuy46851 | EM:CLI cannot clear energy mode events correctly. |
| CSCuy48185 | memory leak @CMTS Multicast MQC: POLICYMAP_MODULE |
| CSCuy06837 | NG-MVPN multicast traffic stop forwarded after SUP-HA |
| CSCuy22380 | "Failed to find free freq block!" message on standby RP |
| CSCuy52378 | LC crashed at dsphy_callout |
| CSCuy40470 | Leoben3 "Failed to read ACT2, USPHY OFDMA cap on slot 3" on standby SUP |
| CSCux76908 | no syslog when upgr hw-prog cmd for dsphy is run on active protect CLC |
| CSCuy14893 | The output of cable monitor CLI is confusing after LCSO |
| CSCuy00822 | Errmsg @ubr_map_get_supported_intvl prints on LC when remove US from MD |
| CSCuy10043 | NET-Claro CM connectivity issues, CPP queue stuck |
| CSCuy38028 | RBG fail to be deleted due to incorrect AC check |

| Identifier | Description |
|-----------------------------|--|
| CSCCuy53119 | cdxCmtsMtcCmEntry/docsIfCmtsStatusEntry/docsIfCmtsMacEntry getone issue |
| CSCCuy02224 | DQoS SF Setup Failures when LC CPU is high. |
| CSCCuy73678 | CMRP-3-WANPLL_SETUP errmsg prints when cbr boot up |
| CSCCuy54609 | CST: The PEM/FM idprom could be read, but is corrupt in slot P10 |
| CSCCuy45596 | ISSU: LC hung during Waiting LCHA group back to final state |
| CSCCuy42577 | snmp cache: polling docsIf3CmtsCmRegStatusEntry.16 error |
| CSCCuy43167 | Changing Default ONID , moves some of the active sessions to Pending |
| CSCCuy51195 | No error message on configuring sessions with same udp using vei/bundle |
| CSCCuy23944 | PME: few sessions goes PENDING state after associating vei-bundle in LED |
| CSCCuy64215 | PSIT: adding vei in one LED makes session active in another LED |
| CSCCuy38312 | PSIT:D6 takes longer time to establish conn after shut/unshut core int |
| CSCCuy55789 | Some sessions going OFF on adding bundle in 8960/8064 session |
| CSCCuy52701 | traceback & static route missed after SSO with QRG modification |
| CSCCuy78532 | cc errors are noted in video show stat after doing LCPR |
| CSCCux88801 | Input Session Discontinuity Error goes up with HA test cases |
| CSCCuy41562 | Some sessions go OFF state after removing vei-bundle for 8064 sessions. |
| CSCCuy30325 | US DOCSIS packet outage after restart vidman process |

Resolved Caveats—Cisco IOS-XE Release 3.18.0S

| Identifier | Description |
|-----------------------------|--|
| CSCCux16537 | "admin-control Cir total" of "cpp cir" un-consistent after ds-resiliency |
| CSCCuw95308 | "sh cable multicast probe" display a very large value |
| CSCCux74172 | aDefault mcast SF w/ CIR created/deleted on RBG, triggering ACFE |
| CSCCux23422 | AdmittedQosParamSet of US not change when CM enter EM mode with CIR |
| CSCCux15646 | After cdmanpr, in CDMAN, modem's US service flow are rebuilt twice |
| CSCCuv62752 | CBR-4-MCAST_ADMISSION_CONTROL_FAILURE seen when do resiliency & LCPR |
| CSCCux48343 | cBR-8 cops listener access-list lost on reload |

| Identifier | Description |
|----------------------------|---|
| CSCux23893 | cBR8 - DHCP circuit-id field is empty Option 82 Suboption 1 |
| CSCuw37519 | cBR8 : Load Balancing - channel In0/0/6:1 in incorrectly initial state |
| CSCux98929 | LB DCC failure for high US frequency, always being counted on "Retries" |
| CSCux41796 | cdman crash in memset when sending ucd |
| CSCuy11987 | CLAB-TOPO-MIB with 32 DS channels configured only reports 24 |
| CSCux24459 | DS-JIB 2 Enq:High-Pri:detect if BG has channel greater than 383 |
| CSCux95623 | "!" not displayed next to RXPWR in CBR8 when CM transmit with max power |
| CSCux78524 | For MGPI of 2, the UGS throughput is low when using Arris CM820 CM's |
| CSCux86092 | Ubr keep printing message Dyn-Chan_Chg is ongoing, forcing to re-range |
| CSCuy33886 | CBR8: SNMP query returns wrong value for BPI encryption |
| CSCux93762 | FAN modules fail and no SNMP trap |

Open Caveats—Cisco IOS-XE Release 3.17.1S

| Identifier | Description |
|----------------------------|--|
| CSCuy37736 | Modems did not come online after sh/no shut of DS controller in all LC's |
| CSCuy79419 | Modems got stuck in different states after shut the DS controller |
| CSCux98929 | LB DCC failure for high US frequency, always being counted on "Retries" |
| CSCux83175 | PRE_REG_DSID null cause CM reject(na) |
| CSCux41796 | cdman crash in memset when sending ucd |
| CSCuy11987 | CLAB-TOPO-MIB with 32 DS channels configured only reports 24 |
| CSCux28031 | CNR decreased a lot after sent traffic |
| CSCux24459 | DS-JIB 2 Enq:High-Pri:detect if BG has channel greater than 383 |
| CSCux47349 | map advance buffer leak |
| CSCuy31792 | cBR8 Subscribers are not able to get the IP address through DHCP relay |
| CSCux85682 | CPP: traceback in cpp_fm_op_ctx_create |
| CSCuy37158 | Stuck CPP client on cbr8 |
| CSCux52080 | traceback cpp_docsis_ea_dyn_precfy_bind |

| Identifier | Description |
|----------------------------|---|
| CSCux95623 | "!" not displayed next to RXPWR in CBR8 when CM transmit with max power |
| CSCuy39767 | cBR8 cable modem counters remain at zero |
| CSCuy33796 | CBR8: "cable rcv-control verbose" no longer active after LCHA or SUP SO |
| CSCux78524 | For MGPI of 2, the UGS throughput is low when using Arris CM820 CM's |
| CSCux28111 | RTPS flow traffic issue after LCHA with RequestOrTxPolicy 0x1CF |
| CSCux86092 | Ubr keep printing message Dyn-Chan_Chg is ongoing, forcing to re-range |
| CSCuy33886 | CBR8: SNMP query returns wrong value for BPI encryption |
| CSCuy06815 | cm can't be online with ipv4 in vrf when leak cnr grt to vrf |
| CSCuv53754 | cBR ROMON - Read access failing on 2GB USB drives |
| CSCux93762 | FAN modules don't provide alarm or SNMP trap when internal fans fail |
| CSCuy40970 | Inconsistent behavior of docsIfCmtsCmStatusDownChannelIfIndex on cBR8 |
| CSCux79465 | MCP:LC can't bootup when system boot from USB subpkg |
| CSCuy12281 | CBR8 Changing ip on Primary Bundle Address not pingable. |
| CSCux51300 | Smart license turns to EVAL EXPIRED after reload from SUP1 |

Resolved Caveats—Cisco IOS-XE Release 3.17.1S

| Identifier | Description |
|----------------------------|--|
| CSCuy41989 | CLC crashed @ INFRA FN SG IPC CLC dispatch task process |
| CSCux93762 | FAN modules fail and no SNMP trap |
| CSCux15646 | After cdmanpr, in CDMAN, modem's US service flow are rebuilt twice |
| CSCux23893 | cBR8 - DHCP circuit-id field is empty Option 82 Suboption 1 |
| CSCuw37519 | cBR8 : Load Balancing - channel In0/0/6:1 in incorrectly initial state |
| CSCux36763 | CPU 100% when exporting SAMIS full record |
| CSCux75638 | Default mcast SF cannot be established since cBR boot up |
| CSCux67665 | Modem exit EM mode,do cdman restart,modem is offline. |
| CSCuw59863 | Number of license on US_License not counting slot 9 consistently |
| CSCux94601 | static mcast sf lost after supha |

| Identifier | Description |
|----------------------------|---|
| CSCuv27870 | support config igmp static-group first, then ip address on bundle |
| CSCuw93063 | The ref-count of qos templates mismatch |
| CSCux50879 | ccsSNRRRequestSNR is not right after cm re-online |
| CSCux17937 | us 2db hotter fix for XE317/318 based images |
| CSCux13023 | After SUPHA, can see ACFE error msg: trying to deduct xxxx out of 0 |
| CSCuw18724 | Standby Linecard may crash during ISSU or after SUPHA and LCHA |
| CSCux68016 | CBR-CCAP-LC-40G linecard stuck with ubr_buffer_print not in MT! message |
| CSCux60028 | cBR8 T4 Multiplier Configuration Not Re-synced to LC After LC Restart |
| CSCuv68479 | Ranging Status stuck at cnt when do dbc followed by LCPR |
| CSCux55975 | Battlestar: IPv6 modem address out-of-sync between SUP and CLC |
| CSCux49572 | cmcc TIMEHOG seen after Cylons and RF-PIC OIR |
| CSCux67670 | Commit raptor ESI v1.58 and enable partial reset to fix lockup issue |
| CSCux20034 | ISSU fail due to lack of required file on Sup |
| CSCux11278 | RAPTOR_ESI_PCIE_LO_INTERRUPT: LOCAL RAPTOR, LOCAL PCIE IF, tx_terr_drp |

Open Caveats—Cisco IOS-XE Release 3.16.7S

| Caveat ID Number | Description |
|----------------------------|--|
| CSCux67012 | cBR-8-PSIT-Perf: SFP not present or SFP IDPROM read error after SUP SO |
| CSCuy84933 | sh hw-module subslot x/y transceiver 0 status has no output |

Resolved Caveats—Cisco IOS-XE Release 3.16.7S

| Caveat ID Number | Description |
|----------------------------|--|
| CSCve77132 | Cisco IOS XE Software for cBR-8 Routers Line Card Console Access Vulnerability |

Open Caveats—Cisco IOS-XE Release 3.16.2S

| Identifier | Description |
|----------------------------|--|
| CSCux67737 | CM offline after US DBC if move to a US which not have CM SF on it |
| CSCux36763 | CPU 100% when exporting SAMIS full record |
| CSCux83175 | PRE_REG_DSID null cause CM reject(na) |
| CSCux12682 | resiliency, no rbg mode, create some rbg wb, some wont free ever |
| CSCux62891 | SERVICE-FLOW template not record US SF when CM enter/exit EM mode |
| CSCux66081 | SF FrwdIF wrong after DBC if target WB same as original WB |
| CSCux74021 | SUP crash @__be_cmts_mqos_validate_session_replication |
| CSCuw93063 | The ref-count of qos templates mismatch |
| CSCux41796 | cdman crash in memset when sending ucd |
| CSCux28031 | CNR decreased a lot after sent traffic |
| CSCux24459 | DS-JIB 2 Enq:High-Pri:detect if BG has channel greater than 383 |
| CSCuw89169 | Interface keep in down status after shut & no shut controller then supha |
| CSCuw89175 | LC high CPU utilization when shutdown & no shutdown DS controller |
| CSCux47349 | map advance buffer leak |
| CSCux68482 | no need data range@default cable specs vl error-adaptive profile X X |
| CSCux68486 | snmp getone slow response for docsLoadbal3GrpStatusEntry |
| CSCux55305 | snmp walk docsIfCmtsDownChannelCounterEntry get slow response |
| CSCux70534 | ubr_specmgmt_compute_timer_interval err msg observed after LCHA |
| CSCux53102 | ubr_ucd_proxy_handle_req_timeout observed after shut/unshut MD/us-chnl |
| CSCux16233 | upstream resiliency modems become UB online after LCPR |
| CSCux38068 | Us flow entry not cleared during reconciliation for cdman only modem |
| CSCuw28196 | Instant Jib4DS Error for PKTP when CM with data-traffic moved by LB |
| CSCux18027 | RP high CPU utilization when shutdown & no shutdown DS controller |
| CSCux31628 | the existed service flow should not be deleted after no acfe |
| CSCux52080 | traceback cpp_docsis_ea_dyn_precfy_bind |
| CSCuv60730 | "mta-battery enable" config inconsistent between LC&SUP after LCHA/LCPR |

| Identifier | Description |
|------------|--|
| CSCuv88937 | "show cable modem tcs summary" output behaviour need align with ubr10k |
| CSCux63568 | %CABLE_IPCCL_LIB-4-SVC_EAGAIN error msg after ccm all delete |
| CSCuu93599 | CBR-8: suddenly changed Upstream Channel for offlined modem |
| CSCux60028 | cBR8 T4 Multiplier Configuration Not Re-synced to LC After LC Restart |
| CSCuv41477 | LC crash with debug cable battery/dbc/mac-add ver, Process = Battery CLC |
| CSCuw59379 | modems in upstream resiliency status drop offline after LCHA or cdman pr |
| CSCuv02125 | no md_ds_sg output after config the fiber-node |
| CSCux55243 | Refix: No lcha config, SF different before and after testcrash lc. |
| CSCux28111 | RTPS flow traffic issue after LCHA with RequestOrTxPolicy 0x1CF |
| CSCux14062 | set value failed for mib cdxCmtsCmChOverTable |
| CSCux19486 | SKB upgrade to R1.1: CPE IP Ping failure |
| CSCux68465 | snmp getone slow response for cdxQosCtrlUpEntry |
| CSCux68467 | snmp getone slow response for cdxQosIfRateLimitEntry |
| CSCux55098 | snmp walk cdxCmtsMtcCmEntry / cdxCmtsUscbSflowEntry get slow response |
| CSCuv88846 | USSF-SUMM-RSP Err msg printed out when show cable up service-flow sum |
| CSCux48979 | "DOCSIS 3.1 Root certificate already learnt" continuously print on LC |
| CSCux55975 | Battlestar: IPv6 modem address out-of-sync between SUP and CLC |
| CSCux50900 | docsBpi2CmtsAuthEntry performance is low on cbr8 |
| CSCux32896 | sup crash@__intel_security_check_cookie observed |
| CSCux62901 | %IOSXE_RP_SPA-4-INCR_CFG_SYNC_FAIL:ASR1000 running-config sync failed |
| CSCux19576 | bypass Viper upgrade if the existing version is the same |
| CSCuv87705 | CBR-8 : 'show software authenticity' should indicate Secure Boot |
| CSCux25053 | CLC iosdb process crashed with DS resiliency |
| CSCux49572 | cmcc TIMEHOG seen after Cylons and RF-PIC OIR |
| CSCux11278 | RAPTOR_ESI_PCIE_LO_INTERRUPT: LOCAL RAPTOR, LOCAL PCIE IF, tx_terr_drp |
| CSCux46066 | stby SUP got reset and cmand core file generated after SUP SO |

Resolved Caveats—Cisco IOS-XE Release 3.16.2S

| Identifier | Description |
|----------------------------|---|
| CSCUw95308 | "sh cable multicast probe" display a very large value |
| CSCUx23422 | AdmittedQosParamSet of US not change when CM enter EM mode with CIR |
| CSCUv62752 | CBR-4-MCAST_ADMISSION_CONTROL_FAILURE seen when do resiliency & LCPR |
| CSCUx20193 | cBR8 - packetcable - unexpected GATE-CLOSE event for PSTN-Modem calls |
| CSCUx42560 | cBR8 IPDR issue with CMQoSVersion on SAMIS-type-1 |
| CSCUx11547 | CPP QoS queue resources leak for MQoS |
| CSCUv83140 | D30 LB modem-list still shows "M" even after mcast session stopped |
| CSCUw61460 | DSG modem could not get online after shut/no shut MD and reload LC |
| CSCUv79196 | DSG service flow throughput decrease after perform LCPR and LCHA |
| CSCUx21841 | Failure counter is failed to record for cm instance when dcc failed. |
| CSCUw82921 | LC crashed on CBR during LB/DCC |
| CSCUx10154 | Mcast traffic block after multiple supha |
| CSCUv62168 | multicast qos share is not same weight as unicast qos share |
| CSCUx36653 | PCMM mcast session-range cfg. reject on CLC |
| CSCUx03600 | REG-RSP-MP has 0 DSID for multicast TLV |
| CSCUx10099 | service flow between lc and sup mismatch after lcha |
| CSCUv43362 | standby sup crash@__be_ubr_mc_dsg_static_group_change |
| CSCUv52587 | sup crash @__be_ubr_dsg_mfib_pltf_upd_entry |
| CSCUw99298 | SUPHA leads pcmm mcast ssm traffic mapping wrong sf with same des group |
| CSCUv68556 | Traceback@ubr_ucm_get_registered_card + 136 (self) after LCHA |
| CSCUv82889 | traffic flow is blocked after change bundle |
| CSCUu62223 | Unfinished show etdb cause crash of sup. |
| CSCUv39795 | add cpu suspend when process queue in cmts_topology_ipdr_process |
| CSCUu88096 | cannot get freq from time schedule specmgmt group after issu N+1 |
| CSCUw79424 | cbr8 - ifStackStatus entry returns "0" for mac domain interface cable |
| CSCUw88436 | CBR8 map advance time is incorrectly capped by max_plant_delay config |

| Identifier | Description |
|------------|---|
| CSCUw27666 | cdman crash @do_lookup_x |
| CSCUv37141 | CLC crash@dcm_qam_mgr.c:4963: "res_grp->routing_port[0][port % 4] |
| CSCUw07551 | Configured upstream channel frequency been changed with noise injection |
| CSCUx16564 | Data SNR abnormal when non-BE US SF on this channel |
| CSCUx17430 | DS Controller missing config after chassis reload |
| CSCUw02861 | entAliasMappingEntry doesn't reflect physical to logical intf mapping |
| CSCUw20717 | frequency assign failed when do no us x spec y & config us x spec y |
| CSCUv07129 | ISSU: Interface status up after ISSU. |
| CSCUv47253 | JIB channel groups are invalid after LCHA/CDMAN restart |
| CSCUu59028 | LC cdman crash during LCHA |
| CSCUw96643 | Modulation changes are not shown in show log |
| CSCUv34379 | Output wrong in "show cable fiber-node" on Cylon |
| CSCUx53222 | should calculate allocated_bw for dcm_rf_chan_config_lcha or lcpr |
| CSCUw23415 | SNMP performance low for cdxDownstreamObjects |
| CSCUw47483 | SNMP random get performance low for docsIfCmtsUpChannelCounterEntry |
| CSCUv04852 | Some channels configuraion were lost and not synced |
| CSCUv12997 | Some us failed to assign frequency by spectrum mgmt at startup |
| CSCUv45490 | Specmgmt freq cannot be assigned with snmpset docsIfUpChannelFrequency |
| CSCUv72788 | SPECMGMT: ubr_specmgmt_clc_request_cand_freq_band() error during bootup |
| CSCUw23097 | Specsvl error adaptive syslog need to be polished |
| CSCUw69676 | specsvl error-adaptive profile cfec&ufec incorrect default value |
| CSCUw85335 | Spectrum group time schedule info is incorrect in Stby LC |
| CSCUw25665 | standby sup crash@be_cfg_cable_fn_cmd |
| CSCUw33549 | sup crash@_be_ubr_specmgmt_cfg_ctrlr_specgrp_num_command observed |
| CSCUw86844 | SUP crashes when polling ifMib by snmp getNext continuously |
| CSCUx11438 | The rf-channel config were not synced between active and standby SUP |
| CSCUx10697 | Traceback: CPU hog with SNMP ENGINE after power cycle |
| CSCUx46445 | us 2db hotter for R1 (XE316 based) image |

| Identifier | Description |
|----------------------------|---|
| CSCUw59436 | US DATA MER is being limited to 36.12 dB on BRCM chip 3142 |
| CSCux83317 | CBR cored on processing punted packet header |
| CSCux27435 | cBR router ucode cored |
| CSCuv62124 | CPU 100% for 2.5 minutes during SUPHA on fully loaded TB |
| CSCUw26754 | Make MTU behavior for BSoD traffic on cBR-8 the same as on the uBR10K |
| CSCuu79998 | MQOS consumed all CPP QoS queue resources |
| CSCuv50596 | MQOS consumed all CPP QoS queue resources |
| CSCUw77985 | multicast shadow and traffic lost after some config and supha |
| CSCux40637 | SUP crash after running data and pcomm traffic |
| CSCux45484 | "no cable diaglog active" can't sync to LCO |
| CSCuv92449 | %UBR_INFRA_LCHA-4-RECONCIL_UMP_MISMATCH, Reason: US SF mis-match |
| CSCux39498 | 'show interface cab x/y/z sid' type should be stat or dync |
| CSCuv87036 | AC:reservable BW not clear to 0 after shutdown all rf chans in controller |
| CSCux32920 | Cable modem can be online on the wideband which line protocol is down. |
| CSCUw22948 | cBR8 CLC Crash IOSXE-WATCHDOG: Process = CMTS CLC PKTCBL |
| CSCux57918 | CDMAN buffer free in us-sched error handling code |
| CSCux56306 | CDMAN buffer leak fix in Ranging and MMM packet allocation/Deallocation |
| CSCux67389 | CDMAN buffer pool 1 leak caused by feature 23 "CDM_BUF_CSMPI_POW_DR" |
| CSCuv62241 | CLC crash @ local_get_docsQos3ServiceFlowSidClusterEntry |
| CSCuv55913 | CLC crash @ubr_ucm_get_us_chan_inst after iosd restart |
| CSCUw85765 | CLC crash at cmts_activate_cfr_deferred in dynamic service flow handling |
| CSCuv53607 | CM attribute-mask not match after LC switchover and reset CM |
| CSCUw24657 | CM dropping offline due to timing offset difference during LCHA |
| CSCux22625 | docsis_sup_sid_mgmt_proc_new_cm_state: ubr_sup_ha_dyn_sync_new_cm ERROR |
| CSCuv88932 | IPDR SERVICE_FLOW Template not consistent with SAMIS after SUPHA |
| CSCuv80915 | LCHA: Ranging MD US table save in interdb and recover for LCHA |
| CSCuv88874 | modems in upstream resiliency status drop offline after LCHA |
| CSCuu16786 | Non-zero Queue-indicator bit statistics reported for non-UGS flows |

| Identifier | Description |
|------------|--|
| CSCUw47726 | SNMP performance low for docsQosCmtsMacToSrvFlowEntry |
| CSCUw41264 | Some objects for docsIfCmtsCmStatusEntry takes long time to response |
| CSCUv18991 | static SF in prov mode after US channel impaired & US resil triggered |
| CSCUx01304 | The cm status from "UB w-online(pt)" to "U4 online(pt)" after clean cm |
| CSCUw47453 | The value of docsIfCmtsCmStatusTimingOffset is incorrect |
| CSCUu54112 | The wrong VPN RD when cm online with sf mapping to one vrf |
| CSCUw18313 | US Frequency Range Capability not reporting 5-65Mhz as Standard for EU |
| CSCUw50274 | [cbr8] Cable qos pre-reg us priority feature not working after reload |
| CSCUx05397 | CBR8 Cable Arp Filter punts not being handled in IOSD |
| CSCUu79528 | CST: %SYS-3-CPUHOG: process = privacy_process |
| CSCUx36214 | PseudoWire status show wrong status information |
| CSCUv76854 | Add a "test lcha toggle show" cli cmd |
| CSCUu85386 | always prints interrupt logs |
| CSCUu85608 | Always see SupCpReset during bootup after supha |
| CSCUw29570 | BPI tek/kek lifetime for iosd-restart support |
| CSCUx32996 | CBR-8 : FRU removal trap does not contain "name" "description" field |
| CSCUw91640 | CBR-8: TenG port with SFP-10G-ZR can not up |
| CSCUx47562 | cBR-8:Line card reloaded due to caprica watchdog timeout |
| CSCUu59350 | CDMAN buffer low with traffic |
| CSCUw95354 | CDMAN buffer pool exhausted after shut/unshut MD with large traffic |
| CSCUp21820 | Change the Octeon inline assemble from "pref" to "pref 28" |
| CSCUw89185 | CLC kept crashing@UBRCCE_CLI_XFER_PARSER |
| CSCUu80289 | CLC2 lost connection at cBR startup |
| CSCUw44672 | cmcc process crashed during SSO |
| CSCUx40053 | dcm qam res record count should be not 0 on stby sup |
| CSCUv43640 | Disable RPR mode CLI for CBR |
| CSCUx74171 | Dump feature stats when fpa buffer low is detected |
| CSCUw09272 | EDVT: Fault log seen on r1 sup |

| Identifier | Description |
|----------------------------|---|
| CSCuw91071 | FAN PSOC failed using latest CLI after executing old CLI |
| CSCuv09082 | Found CMCC traceback and timehog when upgrading Fan or RFSW-PIC FPD. |
| CSCuv89524 | High counts of input errors on TenGig interface of CBR8 |
| CSCux46368 | Modems offline on CLC after CDMINFRA CDM_PT_FPA_TEST SANITY TEST FAILED |
| CSCuv75857 | Physical entity doesn't have Port PhysicalClass err with SUP HA |
| CSCuv04502 | plim default config has to implicitly config to take effect |
| CSCux27497 | Power Budget listed incorrectly |
| CSCuv61095 | Protect LC got reset due to lcha client UBRCCCE_INFRA_CLIENT failed |
| CSCuv66421 | set & get docsIf3CmtsSpectrumAnalysisMeasTable fail after test crash |
| CSCux34556 | show redundancy linecard history is null in tech-support |
| CSCuw74058 | SSO: Significant outage on DOCSIS and VIDEO during SSO event |
| CSCuw97886 | Standby Sup crash, Process = Standby service handler process |
| CSCuu64802 | Traceback@timer_in_stdby_transient |
| CSCux28967 | update "show patch info" version for R1.2 throttle |

Open Caveats—Cisco IOS-XE Release 3.17.0S

| Identifier | Description |
|----------------------------|--|
| CSCuw37519 | cBR8 : Load Balancing - channel In0/0/6:1 in incorrectly initial state |
| CSCuw15163 | D30 Static LB not balanced with no CM with NB service flow can move |
| CSCuw59863 | Number of license on US_License not counting slot 9 consistently |
| CSCuw18780 | console log displays error message like "FMFP-3-OBJ_DWNLD_TO_CPP_FAILED" |
| CSCuw26754 | Make MTU behavior for BSoD traffic on cBR-8 the same as on the uBR10K |
| CSCuw91640 | CBR-8: TenG port with SFP-10G-ZR can not up |
| CSCux07657 | cBR8 never advances past first boot statement on failure |
| CSCuw91071 | FAN PSOC failed using latest CLI after executing old CLI |
| CSCuw18724 | Standby Linecard may crash during ISSU or after SUPHA and LCHA |
| CSCuw29595 | Op Simp: Lots of CMs (~80 out of 300) come NB online ! |

| Identifier | Description |
|----------------------------|--|
| CSCux13023 | After SUPHA, can see ACFE error msg: trying to deduct xxxx out of 0 |
| CSCux17430 | Qam profile order inconsistent with spacing change from default |
| CSCuv15062 | US traffic takes 5 seconds to recover after cdman restart |
| CSCuw42202 | IOSD-CLC process restart info status show No with "disable auto-restart" |
| CSCuw64478 | D3.0 Dynamic cross-MD LB failed if config same US controller in 2 MDs |
| CSCux08225 | entAliasMappingEntry doesn't reflect physical to logical intf mapping |
| CSCuw31319 | dynamic-flow vrf not be removed if no vrf definition |
| CSCux10697 | Traceback: CPU hog with SNMP ENGINE after power cycle |
| CSCuv53607 | CM attribute-mask not match after LC switchover and reset CM |
| CSCux20034 | ISSU fail due to lack of required file on Sup |

Resolved Caveats—Cisco IOS-XE Release 3.17.0S

| Identifier | Description |
|----------------------------|--|
| CSCus61818 | rommon reload when booting system with 2GB Cisco USB stick in USB0 slot |
| CSCuu44979 | SUP hang when 'reset' in ROMMON or 'reload' in IOS is issued |
| CSCuu15634 | SUP rommon needs to print a correct amount of DIMM memory installed |
| CSCuw56857 | DSG traffic not passing any data on cards greater than LC Zero. |
| CSCuw77985 | multicast shadow and traffic lost after some config and supha |
| CSCuw77979 | modems stuck in init(io) due to DSNB flow lost after SUPHA |
| CSCuv26850 | cBR8: allow enable/disable cable forwarding interfaces in CPP |
| CSCuw80390 | Multicast related hw-flows are deleted by reconciliation after SUPHA |
| CSCuv41285 | CST: All linecards crashed after configuring application-type w 16 char |
| CSCuv15036 | CST: Linecard crashing w XE316 image after adding service-type-id config |
| CSCuv83140 | D30 LB modem-list still shows "M" even after mcast session stopped |
| CSCuu07635 | dis/enable multicast-routing will cause some dsg group traffic blocked |
| CSCuv80275 | docsis30-voice calls not mapped to Primary Ch with authorize-vanilla-mta |
| CSCuw61460 | DSG modem could not get online after shut/no shut MD and reload LC |

| Identifier | Description |
|----------------------------|---|
| CSCus72227 | DSG-3-DSG_DA_TO_DSID_DUPLICATED |
| CSCuu90562 | dsid allocated number mismatch with wb modem number |
| CSCuv43086 | Feature Request: Add cm failure for D30 static load balance on cBR8 |
| CSCuv37247 | Group QOS and dsg session mismatch at the border |
| CSCuu30509 | LB doesn't check CM attribute-mask for WBCM |
| CSCuw82921 | LC crashed on CBR during LB/DCC |
| CSCuw80390 | Multicast related hw-flows are deleted by reconciliation after SUPHA |
| CSCuv29453 | Polling docsLoadBalChannelEntry return circular output |
| CSCuv60591 | ServiceTimeCreated value changes slightly with each IPDR export |
| CSCuv13003 | SF created Time in SAMIS & docsQosServiceFlowTimeCreated mismatch |
| CSCuu66373 | show cable LB docsis-group output can't be terminated by any key combo |
| CSCuw41098 | some default multicast sf deleted after sup switchover |
| CSCuw71840 | SR 636678539 : Active SUP crash when replicating GATE-ALLOC |
| CSCuv43841 | SUP crash when add/remove vrf of Bundle with static multicast group |
| CSCuv82889 | traffic flow is blocked after change bundle |
| CSCuu07661 | wrong CmtsMdIfIndex and ServiceTimeCreated in sflog |
| CSCuw79424 | cbr8 - ifStackStatus entry returns "0" for mac domain interface cable |
| CSCuv92857 | CDMAN crashed w/ Assertion failed after system boot up with D31 image |
| CSCuw07551 | Configured upstream channel frequency been changed with noise injection |
| CSCuw03535 | docsIfSignalQualityEntry slow SNMP response CBR8 |
| CSCuw02861 | entAliasMappingEntry doesn't reflect physical to logical intf mapping |
| CSCuv69637 | Erroneous bkt_gap caused by curr_time update |
| CSCuu41357 | fail to ping to some modems after "clear cable modem <md>" command |
| CSCuw05792 | freque still can be shown @us-channel shutdown after SUPHA |
| CSCuu28934 | Gemini 2: FW for PSOC, Apollo and Micro on G2 |
| CSCuu40043 | Gemini FW: release micro 1.8 that fixes QAM output power level issue |
| CSCuu06192 | Gemini FW: release PSOC FW 3.7 that fixes gemini slow booting issue |
| CSCuu71095 | Gemini: Apollo FW that fixes control plane slowness |

| Identifier | Description |
|------------|--|
| CSCUu16301 | Gemini: PSOC FW 3.9 that fixes gemini power lost and slow booting issue |
| CSCUv35546 | Handling of small packets fragments can cause Jib4US lockups |
| CSCUv47253 | JIB channel groups are invalid after LCHA/CDMAN restart |
| CSCUv77341 | Modem offline after remove another FN's service-group profile |
| CSCUs30096 | New active CLC crash after LCSO, @ubr_dsbg_ipc_linestate_save_db |
| CSCUt08459 | no cable upstream 0 equalization-error-recovery applied |
| CSCUv88545 | pkt_drp due to channel pkt Q full on new active LC after LCSO |
| CSCUw30927 | snmp mib doesIfUpstreamChannelEntry performance enhancement |
| CSCUv78726 | Some CMs cannot receive traffic for about 2-5 minutes after LCHA |
| CSCUv72788 | SPECMGMT: ubr_specmgmt_clc_request_cand_freq_band() error during bootup |
| CSCUw23097 | Specsvl error adaptive syslog need to be polished |
| CSCUw33549 | sup crash@_be_ubr_specmgmt_cfg_ctrlr_specgrp_num_command observed |
| CSCUv30479 | Traffic drop count increment after SUP HA |
| CSCUu93276 | ubr_ucm_get_registered_card() Err seen when boots up cBR-8 |
| CSCUv07062 | US channel stats not working for us bonding |
| CSCUu79511 | US MER is being limited to 36.12 dB on BRCM chip 3142 |
| CSCUv26850 | cBR8: allow enable/disable cable forwarding interfaces in CPP |
| CSCUw30681 | CPP Tracebacks @ cpp_qm_obj_reparent in R2 image after ccm all reset |
| CSCUt40424 | CPPOSLIB-3-ERROR_NOTIFY traceback and cpp download fail |
| CSCUv62124 | CPU 100% for 2.5 minutes during SUPHA on fully loaded TB |
| CSCUv64536 | CPUHOG @UBR DSBG CFG Process, ubr_dsbg_intf_bw_update_dp |
| CSCUv90214 | DS L2vpn packets match the normal L3 classifiers |
| CSCUu35431 | ifIndex entries in the system log. |
| CSCUu82050 | IGMP report with combined leave/join can't be correctly handled |
| CSCUv59604 | Modem mac assigned to bundle is not moving from hotlist |
| CSCUw77985 | multicast shadow and traffic lost after some config and supha |
| CSCUx08040 | queue stuck after DS resiliency/recover, cause CM in init(o)/init(t) |
| CSCUu94819 | SUP crash @ cmts_arp_filter_show_interface_detail during arp-filter show |

| Identifier | Description |
|-----------------------------|---|
| CSCCuv88988 | SUP crash @mcprp_ubr_punt_process_platform_header |
| CSCCuu87253 | Two l2vpn DS classifiers weren't supported to use the same service flow |
| CSCCuv45795 | UBRCCE-3-UBR_DP_LOCK_ERR: Failed to lock semaphore when cbr boot |
| CSCCuv53746 | WB qos min-rate can't be guaranteed . |
| CSCCuv79699 | WB rf-channel remove check add |
| CSCCut35411 | %UBR_INFRA-3-NORES: Extra free of element into DMP pool_id: 393625 5 |
| CSCCuv92449 | %UBR_INFRA_LCHA-4-RECONCIL_UMP_MISMATCH, Reason: US SF mis-match |
| CSCCuu52044 | 'scm mac summary total' displays one upstream channel for UB online CM |
| CSCCuv87036 | AC:reservable BW not clear to 0 after shutdown all rf chans in controller |
| CSCCuw18344 | Cable qos pre-reg us priority feature not working after LC revert back |
| CSCCuv50796 | cbr8 - power-adjust continue does not work for USCB modems |
| CSCCuw22948 | cBR8 CLC Crash IOSXE-WATCHDOG: Process = CMTS CLC PKTCBL |
| CSCCuw33127 | cdxCmtsUscbDescr returns wrong value |
| CSCCuu05200 | CM flap w/ EQ coefficient enabled & relatively tough RF condition |
| CSCCuu19039 | DBG failed to be freed and flap between "Free" and "In Delete" |
| CSCCuu91697 | dsx service flow deleted after sup ha |
| CSCCuu67034 | Duplicated records in scm partial-service |
| CSCCuv97944 | Expand fwd_lookup_table size and correct D3.0 fragment size |
| CSCCuu63314 | Incorrect wideband interface status when bonding entries are altered |
| CSCCuu13802 | IOSd memory leak in iosd_2_iosd |
| CSCCuv04776 | ipdr generates unexpected records with 2 CM status session & ad-hoc type |
| CSCCuv88932 | IPDR SERVICE_FLOW Template not consistent with SAMIS after SUPHA |
| CSCCuu90781 | LC crash @ decode_partial_service when AC fails during DBC transaction |
| CSCCuv80915 | LCHA: Ranging MD US table save in interdb and recover for LCHA |
| CSCCuv38946 | Linecard crash after issuing scm <mac> verbose with D3.1 modem present |
| CSCCuv68516 | modem become unpingable due to DSID inconsistent between CMTS and CM |
| CSCCuv88874 | modems in upstream resiliency status drop offline after LCHA |
| CSCCuv84808 | mrc-only CM count doesn't show in "show cable mac-domain rcc" after DCC |

| Identifier | Description |
|----------------------------|--|
| CSCUw19075 | PCMM voice call does not work if "cable docsis30-voice ..." configured |
| CSCUv71055 | ping docsis partially fail after cdman restart |
| CSCUu07757 | Port uBR10k Battery mode large scale code to cBR8 |
| CSCUv50612 | SNMP access of equalization coefficients returns incorrect values |
| CSCUv77809 | snmp performance enhancement |
| CSCUw39347 | Some mibs response time too long if no CM on chassis |
| CSCUv18991 | static SF in prov mode after US channel impaired & US resil triggered |
| CSCUv41419 | Sup crash after reload |
| CSCUu84966 | SUP crash following SO due to packetcable timer |
| CSCUu83105 | sup crash when show cable modem service ds during cm online/offline |
| CSCUv94404 | Supervisor crash due to Segmentation fault in Virtual Exec process |
| CSCUv98908 | US channel shouldn't recover on-fail-disable-chnl after LCHA |
| CSCUv51334 | US flows with fragmentation disabled incorrectly drops packets |
| CSCUw18313 | US Frequency Range Capability not reporting 5-65Mhz as Standard for EU |
| CSCUv46043 | US packet drop issue during longevity / aging testing |
| CSCUv43385 | WB attribute mask doesn't work after lcha |
| CSCUw50274 | [cbr8] Cable qos pre-reg us priority feature not working after reload |
| CSCUw02254 | BPI Tek/Kek lifetime changed while clock set |
| CSCUw23100 | cBR8 cable IPv6 nd timeout triggered by wrong ND state change |
| CSCUv49471 | CBR8 High CPU due to ARP Input. |
| CSCUv97497 | CMTS L2VPN ADJ search method change |
| CSCUv65477 | Complete cbr8 CMTS code to pass CALEA testing using test CLI |
| CSCUu79528 | CST: %SYS-3-CPUHOG: process = privacy_process |
| CSCUv35791 | Dot1q L2VPN traffic go to default DS SF due to wrong priority set in cpp |
| CSCUv22783 | IPv6 DMIC implementation of cBR-8 differs from UBR10K |
| CSCUv86667 | L2vpn DS/US drop after SUPHA for sometimes on port-channel sub-interface |
| CSCUu75854 | L2vpn modem failed to get online with expected packet tag |
| CSCUw47406 | the second modem with PW redundancy failed to get online |

| Identifier | Description |
|----------------------------|---|
| CSCUu59111 | "wrong table id 8 or nominator 52, get failed" when poll 50+ nominators |
| CSCUv18216 | %SYS-NOBLOCK:may_suspend w/block disabled;Process lcha fast ipc process |
| CSCUu39764 | Active SUP crash with standby ASTRO Interlaken error |
| CSCUu46760 | Active SUP kernel crash at free_msi_irqs() when standby SUP OIR |
| CSCUu46622 | Active SUP kernel crash when OIR remove and insert standby SUP |
| CSCUv05660 | add show platform software patch info in show tech |
| CSCUu64222 | Battlestar: Daggits firmware commit V33 to X315 and later branch |
| CSCUw41912 | cBR RP - Checkin new Viper image with Y0_VID change |
| CSCUw21214 | CBR-8: TenG port with SFP-10G-ER can not up |
| CSCUv93779 | cBR8 ROMMON: Vulnerability in package codesign validation |
| CSCUw27500 | CBR8 SUP crash due to double free |
| CSCUu03010 | cBR8: TSS PLL not lock count 1 causes CDMAN crash |
| CSCUv16776 | config snmp entity-diag & entity-red, show wrong. |
| CSCUv45445 | create all in one pkg for r1 rebuild |
| CSCUv82421 | dblib replication: tx and rx counters don't match |
| CSCUv71464 | do sh run i snmp not consistent with config ,5 items |
| CSCUu66240 | Failure to read RSA Key pair from the digital mid plane ACT2 |
| CSCUu54374 | FPD:cylon cannot bootup after finish upgrading daggit with new UBOOT |
| CSCUw22791 | hman Err in btrace log |
| CSCUu11915 | iosdb process stuck after run resiliency longevity |
| CSCUu47817 | Kernel: INFO: task sync:13074 blocked when expanding subpkg to usb |
| CSCUu29363 | LCPR IOSD: increase timeout period for lcpr sm timer |
| CSCUu68417 | Need to add CBR-8 USB Disk in "sh inven" |
| CSCUu44982 | No Core File is Generated for Astro Serdes FATAL Interrupts |
| CSCUv02216 | No IOS cmd for CBR8 SFP+ module diagnostic data |
| CSCUv40038 | OID returns wrong from SNMP & CLI for CBR-8 daughter cards |
| CSCUu08432 | plim default config has to implicitly config to take effect |
| CSCUv04502 | plim default config has to implicitly config to take effect |

| Identifier | Description |
|----------------------------|--|
| CSCUv61095 | Protect LC got reset due to lcha client UBRCCCE_INFRA_CLIENT failed |
| CSCUv44566 | remove bootup log in lcpr_sup_infra_init() |
| CSCUv36564 | remove disable-full-core option under process-restart config commands |
| CSCUv60251 | Remove fno-omit-frame-pointer for mips64 on mcp_dev |
| CSCUv12964 | Remove the LTC3882 accesses to fix the HW issue on cylons board |
| CSCUu51731 | RFSW PIC: there is no RFSW PIC inserted in slot 1 after SUPHA |
| CSCUw30958 | Seen many qstat_rx_error/channel_not_found_err when perform LCHA and SWO |
| CSCUu91382 | show platform software ios <slot> restart info not in show tech |
| CSCUv30481 | Stby-SUP crash at "Process = REDUNDANCY FSM" when reload whole chassis |
| CSCUv69062 | Sup 5 crash after OIR of Sup 4 in R1 |
| CSCUu45356 | TDL mem leak @cm_env_monitor after overnight lc power-cycle |
| CSCUw20643 | To monitor and recover from lost of connection to /harddisk on line card |
| CSCUv98756 | Rogue IP using port 4737 and IPDR stop working |
| CSCUv45520 | SC11: stby pre can't boot up caused by Bulk-sync failure after PRE SO |
| CSCUv32475 | MTA lost after ARP timeout |

Open Caveats—Cisco IOS-XE Release 3.16.1S

| Bug ID | Description |
|----------------------------|--|
| CSCUu89785 | CBR-8 show interface cable modem command - Priv bit value is not correct |
| CSCUw37519 | cBR8 : Load Balancing - channel In0/0/6:1 in incorrectly initial state |
| CSCUw15163 | D30 Static LB not balanced |
| CSCUu07635 | dis/enable multicast-routing will cause some dsg group traffic blocked |
| CSCUw61460 | DSG modem could not get online after shut/no shut MD and reload LC |
| CSCUv43086 | Feature Request: Add cm failure for D30 static load balance on cBR8 |
| CSCUw33092 | IPC take too long time during SUPHA under 7+1 LCHA |
| CSCUu30509 | LB doesn't check CM attribute-mask for WBCM |
| CSCUw55080 | LC crash on test cable load-balance set-stats upstream |

| Bug ID | Description |
|----------------------------|--|
| CSCUw82921 | LC crashed on CBR during LB/DCC |
| CSCUw59863 | Number of license on US_License feature is not correct |
| CSCUv29453 | Polling docsLoadBalChannelEntry return circular output |
| CSCUv13003 | SF created Time in SAMIS & docsQoSServiceFlowTimeCreated mismatch |
| CSCUu66373 | show cable LB docsis-group output can't be terminated by any key combo |
| CSCUv85628 | Show interface Integrated-Cable Downstream Large Reported Service Flows |
| CSCUw23348 | SNMP performance low for docsMcastCmtsReplSessEntry |
| CSCUw88436 | CBR8 map advance time is incorrectly capped by max_plant_delay config |
| CSCUw02861 | entAliasMappingEntry doesn't reflect physical to logical intf mapping |
| CSCUw20717 | frequency assign failed when do no us x spec y & config us x spec y |
| CSCUw89175 | high CPU utilization when shutdown & no shutdown DS controller |
| CSCUw89169 | Interface keep in down status after shut & no shut controller then supha |
| CSCUv94596 | Modem unpingable after docsis-mode change |
| CSCUw47483 | SNMP random get performance low for docsIfCmtsUpChannelCounterEntry |
| CSCUu79511 | US MER is being limited to 36.12 dB on BRCM chip 3142 |
| CSCUv90214 | DS L2vpn packets match the normal L3 classifiers |
| CSCUw40874 | DS L2vpn packets matched to higher priority mac_precfy classifiers |
| CSCUu95682 | High CPU utilization will last 3 minutes after starting ARP-attack |
| CSCUw28196 | Instant Jib4DS Error for PKTP when CM with data-traffic moved by LB |
| CSCUw26754 | Make MTU behavior for BSoD traffic on cBR-8 the same as on the uBR10K |
| CSCUu87253 | Two l2vpn DS classifiers weren't supported to use the same service flow |
| CSCUv60730 | "mta-battery enable" config inconsistent between LC&SUP after LCHA/LCPR |
| CSCUw37428 | "no cable upstream fragment-force" turn fragment-threshold to default |
| CSCUu35411 | %UBR_INFRA-3-NORES: Extra free of element into DMP pool_id: 393625 5 |
| CSCUu52044 | 'scm mac summary total' displays one upstream channel for UB online CM |
| CSCUv87036 | AC:reservable BW not clear to 0 after shutown all rf chans in controller |
| CSCUw59240 | cBR-8 "show cable throttle-modem" output is incorrect |
| CSCUu93599 | CBR-8: suddenly changed Upstream Channel for offlined modem |

| Bug ID | Description |
|------------|--|
| CSCUw91656 | cBR8 : Delayed maps causing voice quality issues |
| CSCUw22948 | cBR8 CLC Crash IOSXE-WATCHDOG: Process = CMTS CLC PKTCBL |
| CSCUw33127 | cdxCmtsUscbDescr returns wrong value |
| CSCUw85765 | CLC crash at cmts_activate_cfr_deferred in dynamic service flow handling |
| CSCUv53607 | CM attribute-mask not match after LC switchover and reset CM |
| CSCUw24657 | CM dropping offline on NSI slot during LCHA |
| CSCUv30942 | CM offline after A/C power up, if use cross-controller DBG enter 1x1 |
| CSCUu67034 | Duplicated records in scm partial-service |
| CSCUw85321 | getone fail in docsQos3ParamSetEntry when modem offline |
| CSCUu63314 | Incorrect wideband interface status when bonding entries are altered |
| CSCUv88932 | IPDR SERVICE_FLOW Template not consistent with SAMIS after SUPHA |
| CSCUv41477 | LC crash with debug cable battery/dbc/mac-add ver, Process = Battery CLC |
| CSCUv02125 | no md_ds_sg output after config the fiber-node |
| CSCUv50612 | SNMP access of equalization coefficients returns incorrect values |
| CSCUw41253 | SNMP performance low for ccsCmFlapEntry |
| CSCUw47726 | SNMP performance low for docsQosCmtsMacToSrvFlowEntry |
| CSCUw41264 | Some objects for docsIfCmtsCmStatusEntry takes long time to response |
| CSCUw18313 | US Frequency Range Capability not reporting 5-65Mhz as Standard for EU |
| CSCUw50274 | [cbr8] Cable qos pre-reg us priority feature not working after reload |
| CSCUw09703 | 802.1Q L2VPN not passing L2CP oam packets downstream |
| CSCUw02254 | BPI Tek/Kek lifetime changed while clock set |
| CSCUw23100 | cBR8 cable IPv6 nd timeout triggered by wrong ND state change |
| CSCUw83942 | CBR8 High CPU seen after SUP SO |
| CSCUu79528 | CST: %SYS-3-CPUHOG: process = privacy_process |
| CSCUv86667 | L2vpn DS/US drop after SUPHA for sometimes on port-channel sub-interface |
| CSCUu75854 | L2vpn modem failed to get online with expected packet tag |
| CSCUu44419 | L2VPN MPLS PWs down after SUP HA |
| CSCUw64156 | "show logging onboard uptime" didn't display full entries |

| Bug ID | Description |
|----------------------------|--|
| CSCuv18216 | %SYS-NOBLOCK:may_suspend w/block disabled;Process lcha fast ipc process |
| CSCuw29570 | BPI tek/kek lifetime for iosd-restart support |
| CSCuv87705 | CBR-8 : 'show software authenticity' should indicate Secure Boot |
| CSCuw91640 | CBR-8: TenG port with SFP-10G-ZR can not up |
| CSCuv51208 | EDVT: sup-60 - Raptor errors seen during sup-60 testing |
| CSCuv58775 | EDVT: SUP-HA: %CBR_SPA-3-ESI_PLL_CTRL_REG_WRITE_ERROR |
| CSCuu66240 | Failure to read RSA Key pair from the digital mid plane ACT2 |
| CSCuv91051 | FPD:log of upgrading stby SUP psoc cannot be output |
| CSCuv89524 | High counts of input errors on TenGig interface of CBR8 |
| CSCuw22791 | hman Err in btrace log |
| CSCuw62203 | IPDR - Stop record with ServiceFlowChSet empty for Broadcast SF |
| CSCuu13826 | itimer in cdman is inaccurate |
| CSCuw13629 | OBFL log display is using "current" time rather than "Historical" time |
| CSCuu51731 | RFSW PIC: there is no RFSW PIC inserted in slot 1 after SUPHA |
| CSCut37529 | Several traceback @ intr_stat_snapshot_and_process about ACFE |
| CSCuv30481 | Stby-SUP crash at "Process = REDUNDANCY FSM" when reload whole chassis |
| CSCuw20643 | To monitor and recover from lost of connection to /harddisk on line card |
| CSCut98756 | Rogue IP using port 4737 and IPDR stop working |

Resolved Caveats—Cisco IOS-XE Release 3.16.1S

| Bug ID | Description |
|----------------------------|--|
| CSCuw47406 | the second modem with PW redundancy failed to get online |
| CSCuw78395 | Clear modem cannot take affect after perform SUPHA |
| CSCuv41285 | CST: All linecards crashed after configuring application-type w 16 char |
| CSCuv15036 | CST: Linecard crashing w XE316 image after adding service-type-id config |
| CSCuv80275 | docsis30-voice calls not mapped to Primary Ch with authorize-vanilla-mta |
| CSCuv60591 | ServiceTimeCreated value changes slightly with each IPDR export |

| Bug ID | Description |
|----------------------------|--|
| CSCUw41098 | some default multicast sf deleted after sup switchover |
| CSCUw71840 | SR 636678539 : Active SUP crash when replicating GATE-ALLOC |
| CSCUv92857 | CDMAN crashed w/ Assertion failed after system boot up with D31 image |
| CSCUw03535 | docsIfSignalQualityEntry slow SNMP response CBR8 |
| CSCUv69637 | Erroneous bkt_gap caused by curr_time update |
| CSCUv35546 | Handling of small packets fragments can cause Jib4US lockups |
| CSCUs30096 | New active CLC crash after LCSO, @ubr_dsbg_ipc_linestate_save_db |
| CSCUv88545 | pkt_drp due to channel pkt Q full on new active LC after LCSO |
| CSCUv78726 | Some CMs cannot receive traffic for about 2-5 minutes after LCHA |
| CSCUv30479 | Traffic drop count increment after SUP HA |
| CSCUu93276 | ubr_ucm_get_registered_card() Err seen when boots up cBR-8 |
| CSCUv07062 | US channel stats not working for us bonding |
| CSCUv26850 | cBR8: allow enable/disable cable forwarding interfaces in CPP |
| CSCUw30681 | CPP Tracebacks @ cpp_qm_obj_reparent in R2 image after ccm all reset |
| CSCUu35431 | ifIndex entries in the system log. |
| CSCUv59604 | Modem mac assigned to bundle is not moving from hotlist |
| CSCUv45795 | UBRCCE-3-UBR_DP_LOCK_ERR: Failed to lock semaphore when cbr boot |
| CSCUv53746 | WB qos min-rate can't be guaranteed . |
| CSCUw18344 | Cable qos pre-reg us priority feature not working after LC revert back |
| CSCUv50796 | cbr8 - power-adjust continue does not work for USCB modems |
| CSCUv97944 | Expand fwd_lookup_table size and correct D3.0 fragment size |
| CSCUu90781 | LC crash @ decode_partial_service when AC fails during DBC transaction |
| CSCUv38946 | Linecard crash after issuing scm <mac> verbose with D3.1 modem present |
| CSCUw19075 | PCMM voice call does not work if "cable docsis30-voice ..." configured |
| CSCUv71055 | ping docsis partially fail after cdman restart |
| CSCUv77809 | snmp performance enhancement |
| CSCUw39347 | Some mibs response time too long if no CM on chassis |
| CSCUu84966 | SUP crash following SO due to packetcable timer |

| Bug ID | Description |
|----------------------------|--|
| CSCuv51334 | US flows with fragmentation disabled incorrectly drops packets |
| CSCuv46043 | US packet drop issue during longevity / aging testing |
| CSCuv43385 | WB attribute mask doesn't work after lcha |
| CSCuv49471 | CBR8 High CPU due to ARP Input. |
| CSCuv35791 | Dot1q L2VPN traffic go to default DS SF due to wrong priority set in cpp |
| CSCuv22783 | IPv6 DMIC implementation of cBR-8 differs from UBR10K |
| CSCuv05660 | add show platform software patch info in show tech |
| CSCuw41912 | cBR RP - Checkin new Viper image with Y0_VID change |
| CSCuw21214 | CBR-8: TenG port with SFP-10G-ER can not up |
| CSCuw27500 | CBR8 SUP crash due to double free |
| CSCuv45445 | create all in one pkg for r1 rebuild |
| CSCuv82421 | dblib replication: tx and rx counters don't match |
| CSCuw85340 | Fan's ramping up speed after a SUP reload |
| CSCuu54374 | FPD:cylon cannot bootup after finish upgrading daggit with new UBOOT |
| CSCuw17057 | Initialization becauseRP Serial Bridge ASIC has failed i No such file or |
| CSCuu11915 | iosdb process stuck after run resiliency longevity |
| CSCuu29363 | LCPR IOSD: increase timeout period for lcpr sm timer |
| CSCuv02216 | No IOS cmd for CBR8 SFP+ module diagnostic data |
| CSCuv40038 | OID returns wrong from SNMP & CLI for CBR-8 daughter cards |
| CSCuw50233 | Re-launch automount on line card |
| CSCuv44566 | remove bootup log in lcpr_sup_infra_init() |
| CSCuv73204 | remove debug option for src-ubr in makefile |
| CSCuv60251 | Remove fno-omit-frame-pointer for mips64 on mcp_dev |
| CSCuv12964 | Remove the LTC3882 accesses to fix the HW issue on cylons board |
| CSCuu91382 | show platform software ios <slot> restart info not in show tech |
| CSCuv69062 | Sup 5 crash after OIR of Sup 4 in R1 |
| CSCuu35089 | UBR10k/cBR-8 crash with ExporterProtocol_DisconnectCallback |
| CSCur45520 | SCI1: stby pre can't boot up caused by Bulk-sync failure after PRE SO |

| Bug ID | Description |
|----------------------------|----------------------------|
| CSCuv32475 | MTA lost after ARP timeout |

Open Caveats—Cisco IOS-XE Release 3.16.0S

| Bug ID | Description |
|----------------------------|--|
| CSCuv15036 | CST: Linecard crashing w XE316 image after adding service-type-id config |
| CSCuv23640 | IPv6 Traffic Loss after SUP HA w/ CSV and default cable nd timeout |
| CSCuu90781 | LC crash @ decode_partial_service when AC fails during DBC transaction |
| CSCuu84966 | SUP crash following SO due to packetcable timer |
| CSCuv22783 | IPv6 DMIC implementation of cBR-8 differs from UBR10K |

Resolved Caveats—Cisco IOS-XE Release 3.16.0S

| Bug ID | Description |
|----------------------------|---|
| CSCuu44979 | SUP hang when 'reset' in ROMMON or 'reload' in IOS is issued |
| CSCus90250 | ad-hoc ipdr topology record can't be generated after supha |
| CSCus72227 | DSG-3-DSG_DA_TO_DSID_DUPLICATED |
| CSCuu90562 | dsid allocated number mismatch with wb modem number |
| CSCut05231 | FR: STBY SUP keep reloading due to Bulk-sync failure @D30 GLBG |
| CSCus91620 | Mem Leak on SUP switchovers followed by bulk PCMM calls test. |
| CSCut15090 | samistype1 export wrong gateId and appId after supha |
| CSCuu07661 | wrong CmtsMdlfIndex and ServiceTimeCreated in sflog |
| CSCut68395 | CBR8:RF output erratic if RF port not admin down before applying config |
| CSCut39282 | DS-JIB reports packet drops for unused channels |
| CSCuu41357 | fail to ping to some modems after "clear cable modem <md>" command |
| CSCuu28934 | Gemini 2: FW for PSOC, Apollo and Micro on G2 |
| CSCuu40043 | Gemini FW: release micro 1.8 that fixes QAM output power level issue |
| CSCuu71095 | Gemini: Apollo FW that fixes control plane slowness |
| CSCuu16301 | Gemini: PSOC FW 3.9 that fixes gemini power lost and slow booting issue |

| Bug ID | Description |
|----------------------------|--|
| CSCut08459 | no cable upstream 0 equalization-error-recovery applied |
| CSCus61568 | DOCSIS counters is not 0 when all the MDs are shut |
| CSCuu94819 | SUP crash @ cmts_arp_filter_show_interface_detail during arp-filter show |
| CSCut83396 | cBR8: Certain CMs fail to range on US with extended freq range |
| CSCuu05200 | CM flap w/ EQ coefficient enabled & relatively tough RF condition |
| CSCuu19039 | DBG failed to be freed and flap between "Free" and "In Delete" |
| CSCut10577 | R0:Modem got reset when controller upstream is shut/no shut |
| CSCut12791 | Saved qos profile CLI cfg can't be applied after cbr8 reload |
| CSCuv41419 | Sup crash after reload on Charter |
| CSCuu83105 | sup crash when show cable modem service ds during cm online/offline |
| CSCut94404 | Supervisor crash due to Segmentation fault in Virtual Exec process |
| CSCut22893 | AtoM L2VPN DS traffic go to default SF after SUP-HA if EAE enabled |
| CSCut97497 | CMTS L2VPN ADJ search method change |
| CSCut11068 | CST: No output from "show cable tech-support" cmd |
| CSCut08826 | CST: show cable modem <ipv6_address> primary-channel cmd missing |
| CSCus05400 | Unable to "no cable l2-vpn-service xconnect nsi mpls" |
| CSCuu39764 | Active SUP crash with standby ASTRO Interlaken error |
| CSCuu46760 | Active SUP kernel crash at free_msi_irqs() when standby SUP OIR |
| CSCuu46622 | Active SUP kernel crash when OIR remove and insert standby SUP |
| CSCuu64222 | Battlestar: Daggits firmware commit V33 to X315 and later branch |
| CSCuu03010 | cBR8: TSS PLL not lock count 1 causes CDMAN crash |
| CSCut70803 | DSG CPUHOG cause iosd hung |
| CSCus98014 | FR: CM fail to online after LC reload and SUPSO |
| CSCut04490 | Incorrect description for new CBR DC power supply |
| CSCut68419 | Lots of memory leak @ __be_mcp_alloc_ipc_tx_msg_once during lcpr |
| CSCut68417 | Need to add CBR-8 USB Disk in "sh inven" |
| CSCut47383 | PID and Serial number to be fixed of CBR-8 Hard Disk in CLI/SNMP data |
| CSCus61818 | rommon reload when booting system with 2GB Cisco USB stick in USB0 slot |

| Bug ID | Description |
|----------------------------|---|
| CSCut61935 | SUP crashed @ IOSXE-WATCHDOG due to memory leak with acfe |

Open Caveats—Cisco IOS-XE Release 3.15.1S

| Bug ID | Description |
|----------------------------|--|
| CSCut13516 | CPU HOG when del/add ip multicast-routing distribute |
| CSCuu90562 | dsid allocated number mismatch with wb modem number |
| CSCuu79511 | US MER is being limited to 36.12 dB on BRCM chip 3142 |
| CSCuu72228 | CM stuck in init(i) state |
| CSCuu94819 | SUP crash @ cmts_arp_filter_show_interface_detail during arp-filter show |
| CSCuu93599 | CBR-8: suddenly changed Upstream Channel for offlined modem |
| CSCuu16786 | Non-zero Queue-indicator bit statistics reported for non-UGS flows |
| CSCuu84966 | SUP crash following SO due to packetcable timer |
| CSCuu04002 | cBR8: : cdman: USPHY: USPHY: Received PWM SRC CHG ISR |
| CSCuu98573 | cBR8: [FTS][SKB]Unexpected CLC reset |

Resolved Caveats—Cisco IOS-XE Release 3.15.1S

| Bug ID | Description |
|----------------------------|---|
| CSCut05231 | FR: STBY SUP keep reloading due to Bulk-sync failure @D30 GLBG |
| CSCut68395 | CBR8:RF output erratic if RF port not admin down before applying config |
| CSCut83396 | cBR8: Certain CMs fail to range on US with extended freq range |
| CSCuu05200 | CM flap w/ EQ coefficient enabled & relatively tough RF condition |
| CSCut10577 | R0:Modem got reset when controller upstream is shut/no shut |
| CSCut94404 | Supervisor crash due to Segmentation fault in Virtual Exec process |
| CSCut97497 | CMTS L2VPN ADJ search method change |
| CSCuu39764 | Active SUP crash with standby ASTRO Interlaken error |
| CSCut61935 | SUP crashed @ IOSXE-WATCHDOG due to memory leak with acfe |

Open Caveats—Cisco IOS-XE Release 3.15.0S

| Bug ID | Description |
|------------|--|
| CSCuq27352 | PFG tos-value is inconsistency from D3.0 spec. as ACL takes 6 bit MSB |
| CSCur22631 | %UBR_INFRA-3-NORES: Extra free of element into DMP pool_id: 399345 4 |
| CSCur76100 | CDMAN error msg DS-JIB:Enq:Low-Pri:channel cfg table after ccm delete |
| CSCus05400 | Unable to \"no cable l2-vpn-service xconnect nsi mpls\" |
| CSCus49401 | EVENTLIB-3-CPUHOG no traceback |
| CSCus56715 | FST: Fan Tray/Module Failure shown as CRITICAL ALERT when cbr boot |
| CSCus61568 | DOCSIS counters is not 0 when all the MDs are shut |
| CSCus61818 | rommon reload when booting system with 2GB Cisco USB stick in USB0 slot |
| CSCus67483 | CDMAN CPUHOG doesn't generate correct traceback |
| CSCus68456 | FST:some PC gates and sf's not deleted long after SUPHA due to IPC drops |
| CSCus72227 | DSG-3-DSG_DA_TO_DSID_DUPLICATED |
| CSCus73398 | Display for 'sh packet cable Gate Sum' on RPs keeps repeating, ok on CLC |
| CSCus75955 | docsis_sup_sid_mgmt_proc_new_cm_state:ubr_sup_ha_dyn_sync_new_cm ERROR |
| CSCus78428 | PMAN-3: pvp.sh: Empty executable used for process iosdb_disable |
| CSCus88577 | remove alignment code from iosd-clc |
| CSCus90250 | ad-hoc ipdr topology record can't be generated after supha |
| CSCus91620 | Mem Leak on SUP switchovers followed by bulk PCMM calls test. |
| CSCus91643 | In some scenario, after SUPHA, hanging PCMM gates without associated SFs |
| CSCus91967 | PCMM pktcbl 2.0 - ACK drops observed on spirent during WB-CMs calls |
| CSCus92283 | FST: WB AUTORESET impact MD that configured no cable mrc-mode |
| CSCus96436 | FR: UBRCCCE-6-CM_INCONSISTENCY shown w/ WB-AUTORESET feature take effect |
| CSCus97896 | usr/binos/conf/hwutil.sh: line 422: lcoal: command not found\" Error msg |
| CSCus98014 | FR: CM fail to online after LC reload and SUPSO |
| CSCus99770 | Tracebacks @ %CMCC-3-IDPROM_ACCESS after RF-PIC OIR |
| CSCut02449 | Modems can't get back to online after MD new mac address configured |
| CSCut04140 | some sfid not apply in DSG tunnel after config srv-class for this tunnel |

| Bug ID | Description |
|------------|--|
| CSCut04490 | Incorrect description for new CBR DC power supply |
| CSCut05231 | FR: STBY SUP keep reloading due to Bulk-sync failure @D30 GLBG |
| CSCut08819 | J4US Interrupt Received: [CCFP][LoPri]:ses_disabled_err_int count |
| CSCut08826 | CST: show cable modem < ipv6_address > primary-channel cmd missing |
| CSCut10577 | R0:Modem got reset when controller upstream is shut/no shut |
| CSCut11068 | CST: No output from \"show cable tech-support\" cmd |
| CSCut12791 | Saved qos profile CLI cfg can't be applied after cbr8 reload |
| CSCut13516 | CPU HOG when del/add ip multicast-routing distribute |
| CSCut14034 | RecType in IPDR xml file is not as expected after changing the IPDR type |
| CSCut14573 | CLC hungs after oir at stress longevity test |
| CSCut14756 | show platform diag shows wrong version for LC's CPLD |
| CSCut15020 | The mfgName of US and DS are different |
| CSCut15090 | samistype1 export wrong gateId and appId after supha |
| CSCut15134 | snmp get qos fragment counter not equal to the one from cli cmd show |
| CSCut15670 | FR: CBR reload fail after SUPHA |
| CSCut15703 | unexpected linux crash(or reset) when sup boot up cause pciehp issue |
| CSCut17779 | Change dsg tunnel service class,Multicast Group QOS info is not deleted |
| CSCut19780 | cbr8: pfg not working when epe device class from host to ePS |
| CSCut20410 | Tengig interface peer down after SUPHA |
| CSCut21612 | No alarm for AC cord removal from PEM |
| CSCut22197 | docsLoadBalChannelStatus can't return US channel |
| CSCut22893 | AtoM L2VPN DS traffic go to default SF after SUP-HA if EAE enabled |
| CSCut23138 | cBR:Reload automatically cmcc core file generated |
| CSCut27399 | Show env lists wrong Yoda die temperature |
| CSCut27817 | PW L2VPN does not honor classifier rule priority |
| CSCut28839 | One CM disappear on SUP but exist on LC after Resiliency & SUP-HA |
| CSCut37743 | Registration reject confirmation 211 is not getting minimum buffer size |
| CSCut39781 | UBR_SUP_Flow-ERROR seen while running md_scale script |

| Bug ID | Description |
|------------|--|
| CSCut46752 | %XCONNECT-3-ILLEGAL Invalid handle error message after resetting all CMs |
| CSCut48821 | Call-home ip http-client has problems with source-interface |
| CSCut48846 | LC crash at boot with llq configured, modem stuck in init(io) afterwards |
| CSCut52421 | R0: CDM_RT crashed at rfid_bmarr_get_bitmap after SUP reload |
| CSCut54215 | CBR8: RSA Key missing after reboot |

Resolved Caveats—Cisco IOS-XE Release 3.15.0S

There is no resolved caveat in Cisco IOS-XE Release 3.15.0S.

