

Cisco WAN Automation Engine Release Notes, Release 6.4.1

First Published: 2016-0902

This document describes the features, limitations, and bugs for Cisco WAN Automation Engine (Cisco WAE) Release 6.4.1.

Contents

This document includes the following sections:

- Introduction, page 1
- New Feature in WAE Live, page 2
- Open Source, page 2
- Bugs, page 2
- Known Limitations, page 4
- Accessibility Features, page 8
- Related Documentation, page 8

Introduction

Cisco WAE is a model-driven path visibility and path computation engine that simulates, automates, and optimizes multi-vendor, multi-layer networks by leveraging time-series traffic and flow data. For more information on Cisco WAE, visit http://www.cisco.com/go/wae.



New Feature in WAE Live

The Time Range tab in the Configure Report dialog box now includes a radio button option to configure reports with a floating window (Previous Time Window). This option reports data based on the time frame when the report was run (the last full window), for example, 7:00 a.m.–7:00 p.m., instead of the time when the report was defined, for example, 6:00 p.m. The time range for the floating window uses the 24-hour clock and can be defined between 00:00:00 and 23:59:59. The allows for a window to transition through two days.

This feature is available for all report types: ad hoc, health, traffic, and deviation. For more information, see the "Configuring and Running Reports" chapter in the *WAE Live 6.4.1 User Guide*.

Open Source

A list of open source software used in WAE can be found in Open Source Software Used in Cisco WAN Automation Engine.

Bugs

The following are descriptions of the open and resolved bugs in Cisco WAE Release 6.4.1. The bug ID links you to the Cisco Bug Search tool.

Open Bugs

Table 1 Open Bugs

Bug ID	Description
CSCux37290	Traffic in interface queues shows zero for dot1q/QinQ encapsulation LAGs.
CSCuz68723	When running WAE Live reports, you cannot filter a user defined property (Real Nodes) for interfaces and nodes.
CSCuz85830	WAE API calls succeed on the initial call, but fail on subsequent calls.
	Workaround: Rerun reports to initiate new job IDs.
CSCva25755	The WAE LIVE map stops responding after a few days.
	Workaround: Clear the map archive and restart the web server.
CSCva41756	Some P2MP LSPs are showing up twice under the P2MP LSPs table and a warning message appears.
	Workaround: This does not affect WAE functionality. Ignore the warning message.
CSCva50465	Affinities do not seem to be collected correctly when running parse_configs and snmp_find_rsvp.
CSCva59980	When running dmd_deduct, demands from the original plan file do not show the demands from the external table file.
CSCva60440	The WAE Live Inventory does not collect information from some Cisco switches; for example, Cisco Catalyst 6500 and Cisco 4000 series.

Table 1 Open Bugs (continued)

Bug ID	Description
CSCva70416	In WAE Live, scheduling registration fails if the "Weekly each" scheduling option is selected.
CSCva94963	After upgrading to 6.5.0, Java exceptions appear in the syslog.
CSCvb02149	WAE - LDAP integration fails with advanced configuration.

Resolved Bugs

Table 2 Resolved Bugs

Bug ID	Description
CSCux18913	RSVP LSPs collected from Huawei routers are set to "Unrouted" and the collected hop IP addresses are not populated in the plan file.
CSCuz75882	LAG ports are incorrectly marked as inactive. After running snmp_find_interfaces, some ports are marked as "Active = F", even when there is measured traffic on the interface.
CSCva56765	In WAE Live, the daily scheduled reports do not work.
CSCva70418	In WAE Live, the TraffIn Raw is not restored with the previous view after changing "Graph Mode."
CSCva74552	When there are multiple networks, WAE Live inventory appears only in the default network, putting the information from both networks in the default network.
CSCva74607	The WAE Live Map takes a long time to load because of a Java process under Linux that uses 100% of one CPU for a long time.
CSCva90491	The Interface attribute of Ports is copied over from the template and overwrites the Interface attribute in the input plan file.
CSCvb00661	Selecting File > Get Plan From > Configs from WAE Design produces a correct plan file only the first time. If the same operation is repeated, it produces an incorrect plan file containing the wrong network topology.

Using the Bug Search Tool

Use the Bug Search tool to search for a specific bug or to search for all bugs in a release.

- **Step 1** Go to http://tools.cisco.com/bugsearch.
- **Step 2** At the Log In screen, enter your registered Cisco.com user name and password; then, click **Log In**. The Bug Search page opens.



Note

If you do not have a Cisco.com user name and password, you can register for them at http://tools.cisco.com/RPF/register/register.do.

Step 3 To search for a specific bug, enter the bug ID in the Search For field and press **Return**.

Step 4 To search for bugs in the current release:

- **a.** In the Search For field, enter a problem, feature, or a product name (for example, **Cisco WAN Automation Engine**) and press **Return**. (Leave the other fields empty.)
- **b.** When the search results are displayed, use the filter tools to find the types of bugs you are looking for. You can search for bugs by modified date, status, severity, and so forth.

To export the results to a spreadsheet, click the **Export Results to Excel** link.

Known Limitations

This section describes the limitations and restrictions for Cisco WAE.

WAE Design

In some Linux installations with Xfce desktop installed, the documentation does not open from the WAE Design GUI Help menu. The workaround is to do one of the following:

- Open the help files from a terminal in the \$CARIDEN_HOME/docs directory.
- Install a default browser.
- Install the following packages:

```
yum install evince
yum groupinstall "X Window System"
yum groupinstall "Desktop"
yum groupinstall "General Purpose Desktop"
```

WAE Collector and WAE Network Interface (NI)

- Due to vendor MIB limitations, Collector cannot represent QoS traffic on interfaces that have more than one VLAN configured. If a network contains such interfaces, their queue traffic statistics are omitted from the collection. The total traffic on these interfaces is still measured. As a result, per class-of-service demands estimated through Demand Deduction are less accurate. Estimates of traffic totals over all classes of services, however, are not affected.
- Due to lack of MIB support, SR tunnel type is not collected for Cisco IOS XR routers through SNMP.
- Collection of interface egress shaping rate for Alcatel-Lucent devices does not support LAG interfaces.

WAE NI

- The interval for continuous LSP discovery in WAE NI cannot be less than 60 seconds.
- LSP's ActualPathHop cannot be resolved when using continuous collection. As a workaround, use interval-based collection.

Collector

- Juniper MIBs do not support P2MP LSPs.
- If upgrading the Collector server from 5.6x to 6.1x or 6.2, the \$CARIDEN_ROOT/etc/collector/server/db-persistence/DiscoveryEngineImplementation.db file must be removed prior to starting the web server. Since installation automatically starts the web server, the recommendation is to remove this prior to installation.
- OSPFv3 and IPv6 IS-IS databases cannot be collected. The workaround is to use a manual snapshot.
- SNMPv3 is not an available option when configuring default credentials.
- snmp find interfaces
 - Does not support association of a GRE tunnel with the physical interface it uses to reach the tunnel destination since the IP-Tunnel MIB lacks this information.
 - Does not update LAG port status if LAGs are discovered running both parse_configs and snmp find interfaces. The workaround is to run only snmp find interfaces.
- Juniper routers: Signaled standby LSP path option is not available from the standard MPLS-TE MIB for Juniper routers. Only the active path option name is collected.
- Cisco IOS XR routers
 - IGP topology collected through parse_igp and login_find_igp_db
 - IS-IS link-state database with TE extensions contains incorrect interface "admin-weights" (TE metric) on Intel-based routers.
 - IPv6 IS-IS link-state database does not contain IPv6 interface addresses or parallel interfaces. This information is only available when Cisco IOS XR supports IS-IS IPv6 TE extensions. The snmp_find_interfaces tool collects this information.
 - MAC Accounting is not supported.
 - snmp_find_rsvp does not set the Standby value in the <LSPPaths> table for signaled backup
 paths or collect named affinities configured with affinity-maps.
- BGP peers
 - find_bgp does not build BGP pseudo-nodes among internal ASNs.
 - find bgp does not collect BGP peers under PE-CE VRFs.
- parse_configs
 - Does not accurately detect the bandwidth of some Juniper 'ge' interfaces that have a capacity of 10 Gbps.
 - Collects POS bundles, but has limitations due to unavailability of the port OperStatus property.
- TE Extended Admin Groups (EAGs), also known as extended affinities, are only supported from Juniper and parse_configs.
- There is no support for building port circuits for LAG members that are not within the same IGP (inter-AS circuits)
- It is not possible to distinguish between physically connected and unconnected LAG ports that are down for LAG port matching.
- snmp_find_ospf_db cannot be used when routers have a large number of links that cannot fit into a single PDU.
- find_bgpls does not support multi-area OSPF or multi-level IS-IS, non-TE-enabled interfaces, and pseudo-nodes. The workaround is to use SNMP- or login-based discovery.

- get inventory does not collect Juniper multi-chassis router hardware inventory.
- Segment routing
 - SR protected adjacency SIDs are not supported.
 - Concurrent RSVP-TE and SR-TE paths are not supported on the same LSP.

Deployer

Cisco Open SDN Controller (OSC)

During detailed PCEP tunnel creation or when modifying PCEP tunnels, affinity values are misinterpreted if multiple affinities are specified. This limits you to specifying one affinity for IncludeAffinity, IncludeAnyAffinity, and ExcludeAffinity, and each of these values must be a number within [0,31].

NSO Controller

- LSP affinities are deployed, while interfaces affinities require separate provisioning.
- LSPs that exist in the network by another controller cannot be updated.
- Deployment of each RSVP-TE named-path or SR-TE segment-list is limited to a single LSP.
- Cisco IOS XR: WAE client specifies the XR LSP signaled-name, while NSO service and device use tunnel-id. The workaround is to deploy all Cisco IOS XR LSPs using the tunnel-id and to make sure that existing LSPs are not redeployed.
- NEDs (NSO console)
 - For Cisco IOS XR, there is no option to give the IP address of the LSP directly; you can only
 specify a loopback address. There is no option to give tunnel affinity values directly; you can
 only specify an affinity-map name.
 - For Junos, there is no inter-domain keyword, which is used only when an inter-area LSP is created.

WAE System

Installation and Startup

- The WAE NI server and the WAE Core server cannot reside on the same device or on the same VM. Note that the *Cisco WAE Server Installation Guide* assumes that they are on the same device. If needed, contact your support representative for further installation details.
- If the OS is using an old CA certificate to verify the integrity of the EPEL repository, you might see this error from the OS vendor:

Error: Cannot retrieve metalink for repository: epel. Please verify its path and try again.

- One workaround is to perform an offline installation. For instructions, refer to the "Offline Installation" chapter in the *Cisco WAE Server Installation Guide*.
- Another workaround is to change https to http.



This is not a secure solution. For information on how to resolve OS security issues, contact your OS vendor.

1. In the /etc/yum.repos.d/epel.repo file, change the first instance of https to http.

```
sudo vim /etc/yum.repos.d/epel.repo
```

Change https to http in the following line:

mirrorlist=[https://mirrors.fedoraproject.org/metalink-repo=epel-6&arch=\$basearch]

2. Execute yum to clean up makecache.

```
sudo yum clean all && yum makecache
```

3. Rerun the installer. For detailed installation instructions, see the *Cisco WAE Server Installation Guide*.

```
sudo bash wae-k9-<version>.bin
```

• The \$CARIDEN_HOME directory is not automatically added to \$PATH (only \$CARIDEN_HOME/bin is). If not in \$CARIDEN_HOME/bin, to start the WAE Design GUI from the command line, you must specify its full path.

/opt/cariden/software/mate/current/mate

Web Server

The embedded_web_server tool is deprecated. The recommendation is to use the wae-web-server service, which is constantly monitored to be brought up automatically.

By default, this web service starts upon installation completion. Therefore, if you stop the web server using the <code>embedded_web_server</code> tool (<code>embedded_web_server</code> -action stop), the web server does not stop. The workaround is the following:

```
service wae-svcs-mon stop
embedded_web_server -action stop
```

WAE Statistics UI

The WAE Statistics page does not open in all browsers. The workaround is the following:

1. Click the WAE Statistics link. The URL format is https://<server_IP>:8443. Example:

```
https://192.0.2.14:8443
```

- 2. Copy the URL of this page to another browser window.
- **3.** In the new browser, change the URL port from 8443 to 8843. Example:

```
https://192.0.2.14::8843 Ex
```

4. Follow the browser messages to accept the connection and add it as an exception.

Web User Management

Both the System UI and the WAE Design Archive UI have local user management capabilities. If both are used to configure users, WAE uses the most recently updated information. The recommendation is to use only the System UI to manage local users.

License Check Failures on Newer Linux Distributions

Some newer Linux distributions have started using a new way (via biosdevname) of naming hardware devices, including the network interfaces. This causes some software that depends on the traditional naming (for example, eth0, eth1) to fail on license checks, including MATE.

The workaround is to append biosdevname=0 to the kernel line of the grub configuration file and reboot. (Syntax varies among distributions.)

After reboot, you should be able to use if config to verify that the NICs are named etho (or eth1, ...) instead of the biosdevname names (such as p34p1).

Java Memory

Certain tools (such as parse_configs) may require more memory to start than what is available. The symptom is an error message similar to the following:

```
Error occurred during initialization of VM.

Could not reserve enough space for object heap.

Error: Could not create the Java Virtual Machine.

Error: A fatal exception has occurred. Program will exit.
```

The workaround is to set the maximum memory to a low enough value in the CARIDEN_JAVA_OPTIONS variable before calling the tool. An example setting is as follows:

```
set CARIDEN_JAVA_OPTIONS=-Xmx1000m \,
```

Accessibility Features

For a list of accessibility features in Cisco WAE, visit Cisco's Voluntary Product Accessibility Template (VPAT) website, or contact accessibility@cisco.com.

All product documents are accessible except for images, graphics and some charts. If you would like to receive the product documentation in audio format, braille, or large print, contact accessibility@cisco.com.

Related Documentation

For related documentation, see the Cisco WAE 6.4 Documentation Roadmap.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2016 Cisco Systems, Inc. All rights reserved.