



Cisco WAN Automation Engine Release Notes, Release 6.4.13

First Published: May 21, 2018

This document describes any features, limitations, and bugs for Cisco WAN Automation Engine (Cisco WAE) Release 6.4.13.

Contents

This document includes the following sections:

- [Introduction, page 1](#)
- [Upgrading to WAE 6.4.13, page 2](#)
- [Resolved Bugs, page 3](#)
- [Using the Cisco Bug Search Tool, page 3](#)
- [Known Limitations, page 4](#)
- [Accessibility Features, page 9](#)
- [Related Documentation, page 9](#)

Introduction

Cisco WAE is a model-driven, path visibility and path computation engine that simulates, automates, and optimizes multi-vendor, multi-layer networks by leveraging time-series traffic and flow data. For more information on Cisco WAE, visit www.cisco.com/go/wae.



Upgrading to WAE 6.4.13

The following is a high-level summary of tasks that should be performed when upgrading from a WAE 6.4.x release.



Note

The following tasks assume you are familiar with WAE and WAE Live installations.

Task	For more information, see the following sections in the <i>WAE Server Installation Guide</i>
1. Disable snapshot processes configured in the WAE user cron job.	—
2. As a root user, stop all WAE services. # /etc/init.d/wae-svcs-boot stop # wae-svcs-boot stop	—
3. Stop the snapshot process and confirm that plan files have been inserted into the WAE Live data store using the <code>ml_insert_ctl -status</code> command. The output should look like this: Last Collection Status: success Last Collected Filename: The last plan file collected by the snapshot process Job Queue Status: Healthy	—
4. Back up the WAE Live data store. Note If WAE is running on a VM, you have the option to take a VM snapshot.	Backing Up the Data Store
5. As a root user, install WAE 6.4.13. At the prompt “Migrate WAE Collector files from previous installation?”, enter yes . # sudo bash <package>.bin	Planning Software Installation
6. As a WAE user, stop WAE services, upgrade the WAE Live data store, and restart WAE services. # service wae-web-server stop # mld -action upgrade # service wae-web-server start To verify that the processes are running: # service wae-web-server status # mld -action status	Upgrading the Data Store
7. Enable the snapshot processes in the cron job that you previously disabled.	—

Resolved Bugs

The following table lists the resolved bugs in Cisco WAE 6.4.13.

Bug ID	Description
CSCvc41269	The existing WAE NI collection.cfg file is replaced with a default configuration file after an upgrade.
CSCvc83104	Access to the application server must be logged.
CSCvh69731	There are unpredictable SNMP timeouts with WAE NI.
CSCvi02271	After deleting an archive (<code>archive_delete</code>), the Time Navigation in the WAE Live Map is not updated.
CSCvi04438	The WAE Live map displays the wrong date in the calendar.
CSCvi21046	The wae-web-server process information is not displayed in the GUI.
CSCvi22184	The WAE Design metric optimization tool continues to run with a failure scenario even if it is turned off in the GUI.
CSCvi22611	WAE Live Map content does not show in Internet Explorer.
CSCvi24113	In WAE Design, when a site is opened, that site panel stays on top of other windows.
CSCvi31376	In the WAE Live Map, the traffic graph takes a long time to appear.
CSCvi34492	Weak ciphers are not removed from the WAE server.
CSCvi55448	WAE Live Map does not update to the previous plan file in Internet Explorer.
CSCvi68135	WAE-Design should manage self-signed certificates better.
CSCvi89639	The WAE software includes an expired certificate (test.crt).
CSCvj00790	When an L1 circuit is attached to a L3 circuit through L3 ports, the filter in the GUI fails to pick up the association.
CSCvj03264	Change the column description in the L1 Link table.
CSCvj06588	PSN remains in its own PSN site on Design Archive even if ASN and PSN are named Site on Template.
CSCvi93548	In WAE Design, Source/Destination Site Property of Demands is not populated.

Using the Cisco Bug Search Tool

You can use the Cisco Bug Search Tool to search for a specific bug or to search for all bugs in a release.

Step 1 Go to the [Cisco Bug Search Tool](#).

Step 2 Enter your registered Cisco.com username and password, and click **Log In**.

The Bug Search page opens.



Note If you do not have a Cisco.com username and password, you can [register here](#).

Step 3 Use any of these options to search for bugs, and then press Enter (Return) to initiate the search:

- To search for a specific bug, enter the bug ID in the Search For field.
- To search for bugs based on specific criteria, enter search criteria in the Search For field, such as a problem description or feature.

- To search for bugs based on products, enter or select a product from the Product list. For example, if you enter “WAE,” you get several options from which to choose.
- To search for bugs based on releases, in the Releases list select whether to search for bugs affecting a specific release, bugs that were fixed in a specific release, or both. Then enter one or more release numbers.

Step 4 To search for bugs based on releases, in the Releases list select whether to search for bugs affecting a specific release, bugs that were fixed in a specific release, or both. Then enter one or more release numbers in the Releases field.

To export the results to a spreadsheet, click **Export Results to Excel**.

Known Limitations

This section describes the limitations and restrictions for this release.

WAE System

Installation

The WAE installer indicates a conflict with `rsync31u` and `ansible1.9`. The WAE Planning `platsvcs` component has a problem with the `ansible1.9` dependency. (This problem is tracked as [CSCuy79752](#).)

This problem occurs because the WAE installer requires an older version of Ansible, which is no longer available on EPEL. If you do `'yum install ansible'`, version 2 is installed and the WAE installation fails. Note also:

- One aspect of the problem is that `ansible1.9` and `rsync31u` are no longer available in EPEL.
- WAE requires `ansible1.9` because an API that WAE uses changed in `ansible2.0`.

As a workaround, do the following:

1. Ensure that Ansible is not installed. (If necessary, uninstall it with **`yum uninstall ansible`**.)
2. Install the EPEL repository, if it is not already present.
3. Download and install `ansible1.9-1.9.6-2.el6.noarch.rpm` and its dependencies.
4. If necessary, install `rsync31u-3.1.2-2.ius.centos6.x86_64.rpm`.
5. Run the WAE installation.

Removal of `wae-dlc`

A `wae-dlc` folder is created under `$CARIDEN_HOME/wae-platsvcs-server` when `wae-dlc` is installed. If the `yum remove wae-dlc` command is used, the `wae-dlc` folder is not deleted. You must manually remove `$CARIDEN_HOME/wae-platsvcs-server/wae-dlc`.

Startup

- The WAE NI server and the WAE Core server cannot reside on the same device or on the same VM. Note that the *Cisco WAE Server Installation Guide* assumes that they are on the same device. If needed, contact your support representative for further installation details.
- If the OS is using an old CA certificate to verify the integrity of the EPEL repository, you might see this error from the OS vendor:

```
Error: Cannot retrieve metalink for repository: epel. Please verify its path and try again.
```

- One workaround is to perform an offline installation. For instructions, see the “Offline Installation” chapter in the *Cisco WAE Server Installation Guide*.
- Another workaround is to change *https* to *http*.



Note This is not a secure solution. For information on how to resolve OS security issues, contact your OS vendor.

1. In the `/etc/yum.repos.d/epel.repo` file, change the first instance of *https* to *http*.

```
sudo vim /etc/yum.repos.d/epel.repo
```

Change *https* to *http* in the following line:

```
mirrorlist=[https://mirrors.fedoraproject.org/metalink-repo=epel-6&arch=$basearch]
```

2. Execute yum to clean up makecache.

```
sudo yum clean all && yum makecache
```

3. Rerun the installer. For instructions, see the *Cisco WAE Server Installation Guide*.

```
sudo bash wae-k9-<version>.bin
```

- The `$CARIDEN_HOME` directory is not automatically added to `$PATH` (only `$CARIDEN_HOME/bin` is). If not in `$CARIDEN_HOME/bin`, to start the WAE Design GUI from the command line, you must specify its full path.

```
/opt/cariden/software/mate/current/mate
```

Web Server

The `embedded_web_server` tool is deprecated. The recommendation is to use the `wae-web-server` service, which is constantly monitored to be brought up automatically.

By default, this web service starts upon installation completion. Therefore, if you stop the web server using the `embedded_web_server` tool (`embedded_web_server -action stop`), the web server does not stop. The workaround is the following:

```
service wae-svcs-mon stop
embedded_web_server -action stop
```

WAE Statistics UI

The WAE Statistics page does not appear in some web browsers if you do not have the correct SSL certificates. To work around this, install the correct SSL certificates (see the “Installing an SSL Web Certificate” section in the *Cisco WAE System Administration Guide*) or do the following:

1. Click the WAE Statistics link. The URL format is `https://<server_IP>:8443`; for example, `https://192.0.2.14:8443`.
2. Copy the URL of the page to another browser window.
3. In the new browser, change the URL port from 8443 to 8843; for example, `https://192.0.2.14:8843`.
4. Follow the browser messages to accept the connection and add it as an exception.

Web User Management

Both the System UI and the WAE Design Archive UI have local user management capabilities. If both are used to configure users, WAE uses the most recently updated information. The recommendation is to use only the System UI to manage local users.

License Check Failures on Newer Linux Distributions

Some newer Linux distributions have started using a new way (via `biosdevname`) of naming hardware devices, including the network interfaces. This causes some software that depends on the traditional naming (for example, `eth0`, `eth1`) to fail on license checks, including MATE.

The workaround is to append `biosdevname=0` to the kernel line of the grub configuration file and reboot. (Syntax varies among distributions.)

After reboot, you should be able to use `ifconfig` to verify that the NICs are named `eth0` (or `eth1`, ...) instead of the `biosdevname` names (such as `p34p1`).

Java Memory

Certain tools (such as `parse_configs`) might require more memory to start than what is available. The symptom is an error message similar to the following:

```
Error occurred during initialization of VM.  
Could not reserve enough space for object heap.  
Error: Could not create the Java Virtual Machine.  
Error: A fatal exception has occurred. Program will exit.
```

The workaround is to set the maximum memory to a low enough value in the `CARIDEN_JAVA_OPTIONS` variable before calling the tool. An example setting is as follows:

```
set CARIDEN_JAVA_OPTIONS=-Xmx1000m
```

NetFlow Collection

NetFlow collection is not supported on Alcatel-Lucent devices.

Coordinated Maintenance

Coordinated Maintenance 1.2.1 is not supported in this release.

WAE Live

After deleting an archive (`archive_delete`), you must do one of the following to remove the deleted plan file from the Time Navigation in the Live Map:

- Restart the web server
- Navigate to a different tab, then return to the Live Map.

WAE Design

macOS Sierra 10.12 and later implements an additional security measure for applications that are not distributed through the App Store; this includes WAE Design.

By default, WAE Design is in a quarantine state as shown by the following command on a terminal:

```
xattr Mate.app
```

The command returns the following output for a quarantined application:

```
com.apple.quarantine
```

As a workaround, remove WAE Design from quarantine by entering the following command in the directory where WAE Design is installed:

```
xattr -r -d com.apple.quarantine Mate.app
```

You can now run WAE Design on macOS Sierra 10.12 and later.

FlexLM License Server

You cannot run the floating license server on a setup (Linux VM or actual host) that uses bonded virtual interfaces (that is, a setup with multiple interfaces that have the same MAC address but different IP addresses within a VM). If the WAE Design client tries to check out a license from a setup that uses bonded virtual interfaces, the license checkout fails with the error “No license found.”

As a workaround, run the floating license server in a standard Linux VM or host.

WAE Collector and WAE Network Interface (NI)

- Due to vendor MIB limitations, Collector cannot represent QoS traffic on interfaces that have more than one VLAN configured. If a network contains such interfaces, their queue traffic statistics are omitted from the collection. The total traffic on these interfaces is still measured. As a result, per class-of-service demands estimated through Demand Deduction are less accurate. Estimates of traffic totals over all classes of services, however, are not affected.
- Due to lack of MIB support, SR tunnel type is not collected for Cisco IOS XR routers through SNMP.

- Collection of interface egress shaping rate for Alcatel-Lucent devices does not support LAG interfaces.

WAE NI

- The interval for continuous LSP discovery in WAE NI cannot be less than 60 seconds.
- LSP's ActualPathHop cannot be resolved when using continuous collection. As a workaround, use interval-based collection.

Collector

- Juniper MIBs do not support P2MP LSPs.
- OSPFv3 and IPv6 IS-IS databases cannot be collected. The workaround is to use a manual snapshot.
- SNMPv3 is not an available option when configuring default credentials.
- snmp_find_interfaces
 - Does not support association of a GRE tunnel with the physical interface it uses to reach the tunnel destination since the IP-Tunnel MIB lacks this information.
 - Does not update LAG port status if LAGs are discovered running both parse_configs and snmp_find_interfaces. The workaround is to run only snmp_find_interfaces.
- Juniper routers: Signaled standby LSP path option is not available from the standard MPLS-TE MIB for Juniper routers. Only the active path option name is collected.
- Cisco IOS XR routers
 - IGP topology collected through parse_igp and login_find_igp_db
 - IS-IS link-state database with TE extensions contains incorrect interface “admin-weights” (TE metric) on Intel-based routers.
 - IPv6 IS-IS link-state database does not contain IPv6 interface addresses or parallel interfaces. This information is only available when Cisco IOS XR supports IS-IS IPv6 TE extensions. The snmp_find_interfaces tool collects this information.
 - snmp_find_rsvp does not set the Standby value in the <LSPPaths> table for signaled backup paths or collect named affinities configured with affinity-maps.
- BGP peers
 - find_bgp does not build BGP pseudo-nodes among internal ASNs.
 - find_bgp does not collect BGP peers under PE-CE VRFs.
- parse_configs
 - Does not accurately detect the bandwidth of some Juniper ‘ge’ interfaces that have a capacity of 10 Gbps.
 - Collects POS bundles, but has limitations due to unavailability of the port OperStatus property.
- TE Extended Admin Groups (EAGs), also known as extended affinities, are only supported from Juniper and parse_configs.
- There is no support for building port circuits for LAG members that are not within the same IGP (inter-AS circuits)
- It is not possible to distinguish between physically connected and unconnected LAG ports that are down for LAG port matching.

- snmp_find_ospf_db cannot be used when routers have a large number of links that cannot fit into a single PDU.
- find_bgpls does not support multi-area OSPF or multi-level IS-IS, non-TE-enabled interfaces, and pseudo-nodes. The workaround is to use SNMP- or login-based discovery.
- get_inventory does not collect Juniper multi-chassis router hardware inventory.
- Segment routing
 - SR protected adjacency SIDs are not supported.
 - Concurrent RSVP-TE and SR-TE paths are not supported on the same LSP.

Cisco Open SDN Controller (OSC)

During detailed PCEP tunnel creation or when modifying PCEP tunnels, affinity values are misinterpreted if multiple affinities are specified. This limits you to specifying one affinity for IncludeAffinity, IncludeAnyAffinity, and ExcludeAffinity, and each of these values must be a number within [0,31].

NSO Controller

- LSP affinities are deployed, while interfaces affinities require separate provisioning.
- LSPs that exist in the network by another controller cannot be updated.
- Deployment of each RSVP-TE named-path or SR-TE segment-list is limited to a single LSP.
- Cisco IOS XR: WAE client specifies the XR LSP signaled-name, while NSO service and device use tunnel-id. The workaround is to deploy all Cisco IOS XR LSPs using the tunnel-id and to make sure that existing LSPs are not redeployed.
- NEDs (NSO console)
 - For Cisco IOS XR, there is no option to give the IP address of the LSP directly; you can only specify a loopback address. There is no option to give tunnel affinity values directly; you can only specify an affinity-map name.
 - For Junos, there is no inter-domain keyword, which is used only when an inter-area LSP is created.

Accessibility Features

For a list of accessibility features in Cisco WAE, visit Cisco's [Voluntary Product Accessibility Template \(VPAT\)](#) website, or contact accessibility@cisco.com.

All product documents are accessible except for images, graphics and some charts. If you would like to receive the product documentation in audio format, braille, or large print, contact accessibility@cisco.com.

Related Documentation

For related documentation, see the [Cisco WAE 6.4 Documentation Roadmap](#).

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2017 Cisco Systems, Inc. All rights reserved.