



Cisco IOS Release 15.8(3)M3 – Release Notes for Cisco IR800 Industrial Integrated Services Routers

Updated: July 30, 2021

The following release notes support the Cisco IOS 15.8(3)M3 release. These release notes are updated to describe new features, limitations, troubleshooting, recommended configurations, caveats, and provide information on how to obtain support and documentation.

Contents

This publication consists of the following sections:

- [Image Information and Supported Platforms, page 1](#)
- [Software Downloads, page 2](#)
- [Known Limitations, page 3](#)
- [Major Enhancements, page 4](#)
- [Related Documentation, page 4](#)
- [Caveats, page 4](#)

Image Information and Supported Platforms

Note: You must have a Cisco.com account to download the software.

Cisco IOS Release 15.8(3)M3 includes the following Cisco IOS images:

IR8x9

- System Bundled Image: `ir800-universalk9-bundle.SPA.158-3.M3`

This bundle contains the following components:

- IOS: `ir800-universalk9-mz.SPA.158-3.M3`
- Guest Operating System: `ir800-ref-gos.img.1.8.4.1.gz`
- Hypervisor: `ir800-hv.srp.SPA.3.0.77`
- FPGA: 2.A.0
- BIOS: 25

Software Downloads

- MCU Application: 33

IR807

- IOS Image: ir800l-universalk9-mz.SPA.158-3.M3

Software Downloads

IR800 Series

The latest image files for the IR800 product family can be found here:

<https://software.cisco.com/download/navigator.html?mdfid=286287045&flowid=75322>

Click on the 807, 809 or 829 link to take you to the specific software you are looking for.

Caution: MANUAL [non-bundle] DOWNGRADE IS STRICTLY PROHIBITED. For newer releases with the PSIRT fix - while bundle downgrade to 158-3.M2/157-3.M4b/156-3.M6b is supported, manual downgrade is unsupported.

IR807

The IR807 link shows the following entries:

- ir800l-universalk9-mz.SPA.<version>.bin
- ir800l-universalk9_npe-mz.SPA.<version>.bin

IR809

The IR809 link shows the following entries:

- IOS Software
 - ir800-universalk9-bundle.<version>.bin
 - ir800-universalk9_npe-bundle.<version>.bin
- IOx Cartridges
 - Yocto 1.7.2 Base Rootfs (ir800_yocto-1.7.2.tar)
 - Python 2.7.3 Language Runtime (ir800_yocto-1.7.2_python-2.7.3.tar)
 - Azul Java 1.7 EJRE (ir800_yocto-1.7.2_zre1.7.0_65.7.6.0.7.tar)
 - Azul Java 1.8 Compact Profile 3 (ir800_yocto-1.7.2_zre1.8.0_65.8.10.0.1.tar)

IR829

The IR829 link shows the following entries:

Software on Chassis

- IOS Software
 - ir800-universalk9-bundle.<version>.bin
 - ir800-universalk9_npe-bundle.<version>.bin

Known Limitations

- IOx Cartridges
 - Yocto 1.7.2 Base Rootfs (ir800_yocto-1.7.2.tar)
 - Python 2.7.3 Language Runtime (ir800_yocto-1.7.2_python-2.7.3.tar)
 - Azul Java 1.7 EJRE (ir800_yocto-1.7.2_zre1.7.0_65.7.6.0.7.tar)
 - Azul Java 1.8 Compact Profile 3 (ir800_yocto-1.7.2_zre1.8.0_65.8.10.0.1.tar)

AP803 Access Point Module

- Autonomous AP IOS Software
 - WIRELESS LAN (ap1g3-k9w7-tar.153-3.JH1.tar)
- Lightweight AP IOS Software
 - WIRELESS LAN (ap1g3-k9w8-tar.153-3.JH1.tar)
 - WIRELESS LAN LWAPP RECOVERY (ap1g3-rcvk9w8-tar.153-3.JH1.tar)

Note: On the IR8x9 devices, the ir800-universalk9-bundle.SPA.158-3.M bundle can be copied via Trivial File Transfer Protocol (TFTP) or SCP to the IR800, and then installed using the `bundle install flash:<image name>` command. The ir800-universalk9-bundle.SPA.158-3.M.bin file can NOT be directly booted using the `boot system flash:/image_name.` Detailed instructions are found in the [Cisco IR800 Integrated Services Router Software Configuration Guide](#).

Note: On the IR8x9 devices, the cipher **dhe-aes-256-cbc-sha** (which is used with the commands **ip http client secure-ciphersuite** and **ip http secure-ciphersuite**) is no longer available in IOS 15.6(3)M and later as part of the weak cipher removal process. This cipher was flagged as a security vulnerability.

Warning about Installing the Image

Note: The bundle can be copied via Trivial File Transfer Protocol (TFTP) or SCP to the device, and then installed using the `bundle install flash:<image name>` command. The bin file can NOT be directly booted using the `boot system flash:/image_name.`

Known Limitations

This release has the following limitations or deviations from expected behavior:

- **For IOx, please do not use the image installed with the bundle!** With this image, the local manager will not work. This has been fixed in the following IOx image download site for [IR809](#) and [IR829](#).

To download image standalone, please execute the following in exec mode:

```
guest-os 1 image install flash:ir800-ioxvm.img.1.8.5.2.gz
wr mem
reload
```

- Please ensure there is a minimum 30MB additional space in the flash: file system before attempting an upgrade or downgrade between releases. Otherwise, the FPGA/BIOS will not have enough space to store files and perform the upgrade. In these current releases, the bundle installation will not display a warning, but future releases from September 2019 going forward will have a warning.
- SSH access to GuestOS:

From 15.8(3)M2, SSH to the Guest-OS (IOx) shell is disabled by default.

Major Enhancements

The ssh access can be enabled using a hidden script for PRIV15 users by following command:

```
Router#iox host exec enablesshaccess IR800-GOS-1
```

To again disable ssh access to highest privilege user again, run following command:

```
Router#iox host exec disablesshaccess IR800-GOS-1
```

Major Enhancements

This section provides details on new features and functionality available in this release. Each new feature is preceded by the platform which it applies to.

Related Documentation

The following documentation is available:

- Cisco IOS 15.8M cross-platform release notes:
<https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/15-8m/release/notes/15-8-3-m-rel-notes.html>
- All of the Cisco IR800 Industrial Integrated Services Router documentation can be found here:
<http://www.cisco.com/c/en/us/support/routers/800-series-industrial-routers/tsd-products-support-series-home.html>
- IoT Field Network Director
<https://www.cisco.com/c/en/us/support/cloud-systems-management/iot-field-network-director/products-installation-and-configuration-guides-list.html>
- Cisco IOx Documentation is found here:
<https://www.cisco.com/c/en/us/support/cloud-systems-management/iox/tsd-products-support-series-home.html>
- Cisco IOx Developer information is found here:
<https://developer.cisco.com/docs/iox/>

Caveats

Caveats describe unexpected behavior in Cisco IOS releases. Caveats listed as open in a prior release are carried forward to the next release as either open or resolved.

Note: You must have a Cisco.com account to log in and access the Cisco Bug Search Tool. If you do not have one, you can [register for an account](#).

For more information about the Cisco Bug Search Tool, see the [Bug Search Tool Help & FAQ](#).

Cisco IOS Release 15.8(3)M3

The following sections list caveats for Cisco IOS Release 15.8(3)M3:

Caveats

Open Caveats

■ CSCvp22063 - IR829

Inserting SIM in Slot 1 disables IP connectivity on a working interface Cell 0/0.

Symptoms: When a SIM is inserted in Slot 1 (Cell 1/0), the first working modem in Slot 0 (Cell 0/0) loses IP connectivity. The cellular 0/0 (related to Slot 0) modem was working before the SIM in Slot 1 was inserted.

Workaround: Remove and re-insert the SIM in Slot 0 and possibly power cycle the Cell 0/0.

Resolved Caveats

The following caveats are fixed with this release:

■ CSCvp47679 - CGR1k Platform

Handling the SD-card password which is stored in CMOS volatile registers.

Note: From Release 15.8(3)M3 onwards, the SD-Card Password will be stored in a FPGA non-volatile registers instead of CMOS volatile registers. In this way, the SD-Card will always be in the protected state if the SD-Card Password is enabled.

■ CSCvq38103 - CGR1k Platform

CGR1k new SPI flash support

Note: From Release 15.8(3)M3 onwards, Winbond SPI flash is added for the CGR1k routers. Serial Flash memory provides a storage solution for systems with limited space, pins and power

■ CSCvp69117 - CGR1k Platform

Secure Boot Bypass PSIRT Fix

Note: From Release 15.8(3)M3 onwards, the bootloader will update the FPGA and BIOS and the bootloader will lock further updates until the system gets power cycled. Secure boot attack can be avoided with this fix.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2019–2020 Cisco Systems, Inc. All rights reserved.