



## **Release Notes for Cisco NCS 4201 and Cisco NCS 4202 Series, Cisco IOS XE Gibraltar 16.12.x**

**First Published:** 2019-07-31

**Last Modified:** 2022-09-02

### **Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
<http://www.cisco.com>  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 527-0883

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

The documentation set for this product strives to use bias-free language. For purposes of this documentation set, bias-free is defined as language that does not imply discrimination based on age, disability, gender, racial identity, ethnic identity, sexual orientation, socioeconomic status, and intersectionality. Exceptions may be present in the documentation due to language that is hardcoded in the user interfaces of the product software, language used based on standards documentation, or language that is used by a referenced third-party product.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2019–2022 Cisco Systems, Inc. All rights reserved.



## CONTENTS

---

### CHAPTER 1

#### **Introduction 1**

- Documentation Updates 1
- Cisco NCS 4201 and Cisco NCS 4202 Overview 2
- Feature Navigator 2
- Hardware Supported 2
- Determining the Software Version 3
- Bundled FPGA Versions 3
- Limitations and Restrictions on the Cisco NCS 4201 and Cisco NCS 4202 Series 4
- Field Notices and Bulletins 4
- MIB Support 5
- Accessibility Features in the Cisco NCS 4201 and Cisco NCS 4202 Series 5

---

### CHAPTER 2

#### **New Features 7**

- New Software Features in Cisco IOS XE Gibraltar 16.12.8 7
- New Hardware Features in Cisco IOS XE Gibraltar 16.12.8 7
- New Software Features in Cisco IOS XE Gibraltar 16.12.7 7
- New Hardware Features in Cisco IOS XE Gibraltar 16.12.7 8
- New Software Features in Cisco IOS XE Gibraltar 16.12.6 8
- New Hardware Features in Cisco IOS XE Gibraltar 16.12.6 8
- New Software Features in Cisco IOS XE Gibraltar 16.12.5 8
- New Hardware Features in Cisco IOS XE Gibraltar 16.12.5 8
- New Software Features in Cisco IOS XE Gibraltar 16.12.4 8
- New Hardware Features in Cisco IOS XE Gibraltar 16.12.4 9
- New Software Features in Cisco IOS XE Gibraltar 16.12.3 9
- New Hardware Features in Cisco IOS XE Gibraltar 16.12.3 9
- New Software Features in Cisco IOS XE Gibraltar 16.12.2a 9

New Hardware Features in Cisco IOS XE Gibraltar 16.12.2a	9
New Software Features in Cisco IOS XE Gibraltar 16.12.1	9
New Hardware Features in Cisco IOS XE Gibraltar 16.12.1	10

---

**CHAPTER 3**
**Caveats 11**

Cisco Bug Search Tool	12
Open Caveats – Cisco IOS XE Gibraltar 16.12.8	12
Resolved Caveats – Cisco IOS XE Gibraltar 16.12.8	12
Open Caveats – Cisco IOS XE Gibraltar 16.12.7	12
Resolved Caveats – Cisco IOS XE Gibraltar 16.12.7	12
Open Caveats – Cisco IOS XE Gibraltar 16.12.6	12
Resolved Caveats – Cisco IOS XE Gibraltar 16.12.6	13
Open Caveats – Platform Independent Cisco IOS XE Gibraltar 16.12.6	14
Closed Caveats – Platform Independent Cisco IOS XE Gibraltar 16.12.6	14
Open Caveats – Cisco IOS XE Gibraltar 16.12.5	14
Open Caveats – Platform Independent Cisco IOS XE Gibraltar 16.12.5	15
Resolved Caveats – Cisco IOS XE Gibraltar 16.12.5	15
Resolved Caveats – Platform Independent Cisco IOS XE Gibraltar 16.12.5	15
Open Caveats – Cisco IOS XE Gibraltar 16.12.4	16
Open Caveats – Platform Independent	16
Resolved Caveats – Cisco IOS XE Gibraltar 16.12.4	19
Resolved Caveats – Platform Independent	19
Open Caveats – Cisco IOS XE Gibraltar 16.12.3	19
Open Caveats – Platform Independent	19
Resolved Caveats – Cisco IOS XE Gibraltar 16.12.3	20
Resolved Caveats – Platform Independent	20
Open Caveats – Cisco IOS XE Gibraltar 16.12.2a	20
Open Caveats – Platform Independent	20
Resolved Caveats – Cisco IOS XE Gibraltar 16.12.2a	22
Resolved Caveats – Platform Independent	22
Open Caveats – Cisco IOS XE Gibraltar 16.12.1	24
Resolved Caveats – Cisco IOS XE Gibraltar 16.12.1	24



# CHAPTER 1

## Introduction

---



- Note** Explore the [Content Hub](#), the all new portal that offers an enhanced product documentation experience.
- Use faceted search to locate content that is most relevant to you.
  - Create customized PDFs for ready reference.
  - Benefit from context-based recommendations.

Get started with the Content Hub at [content.cisco.com](https://content.cisco.com) to craft a personalized documentation experience. Do provide feedback about your experience with the Content Hub.

---

This document provides information about the IOS XE software release for the Cisco NCS 4201 and Cisco NCS 4202 beginning with Cisco IOS XE Release 3.18SP.

- [Documentation Updates, on page 1](#)
- [Cisco NCS 4201 and Cisco NCS 4202 Overview, on page 2](#)
- [Feature Navigator, on page 2](#)
- [Hardware Supported, on page 2](#)
- [Determining the Software Version, on page 3](#)
- [Bundled FPGA Versions, on page 3](#)
- [Limitations and Restrictions on the Cisco NCS 4201 and Cisco NCS 4202 Series, on page 4](#)
- [Field Notices and Bulletins, on page 4](#)
- [MIB Support, on page 5](#)
- [Accessibility Features in the Cisco NCS 4201 and Cisco NCS 4202 Series, on page 5](#)

## Documentation Updates

### Cumulative Configuration Guides for Cisco IOS XE 16 Release Series

From Cisco IOS XE Everest 16.5.1 to Cisco IOS XE Gibraltar 16.12.1, technology configuration guides were published for each release and contained information specific to only that release.

For example, the *MPLS Configuration Guide Cisco IOS XE Everest 16.5.x* contained information specific to only the Cisco IOS XE Everest 16.5.x release.

However, all technology configuration guides will now contain information about all features supported by all releases of the Cisco IOS XE 16 Series.

For example, the *MPLS Configuration Guide Cisco IOS XE 16 Series* is republished and contains information about all MPLS features supported by releases from *Cisco IOS XE Everest 16.5.x to Cisco IOS XE Gibraltar 16.12.x*.

The following documents will help identify release features supported in every release:

- Feature History – A new chapter in all configuration guides. This chapter lists the features and the release in which the features are introduced or updated.
- Release Notes – This document continues to be specific for each release and carries information about the feature supported in that release.
- Feature Compatibility Matrix – A cumulative feature-release matrix, which is available on Cisco.com.
  - [Feature Compatibility Matrix for NCS 4201 and NCS 4202](#)
  - [Feature Compatibility Matrix for NCS 4206 and NCS 4216](#)

## Cisco NCS 4201 and Cisco NCS 4202 Overview

The Cisco NCS 4201 and NCS 4202 Network Convergence Systems are full-featured, compact one-RU high converged access platforms designed for the cost-effective delivery of TDM to IP or MPLS migration services. These temperature-hardened, high-throughput, small-form-factor, low-power-consumption systems are optimized for circuit emulation (CEM) and business applications. NCS 4201 and NCS 4202 chassis allow service providers to deliver dense scale in a compact form factor and unmatched CEM and Carrier Ethernet (CE) capabilities. They also provide a comprehensive and scalable feature set, supporting both Layer 2 VPN (L2VPN) and Layer 3 VPN (L3VPN) services in a compact package .

For more information on the Cisco NCS 4201 Chassis, see the [Cisco NCS 4201 Hardware Installation Guide](#).

For more information on the Cisco NCS 4202 Chassis, see the [Cisco NCS 4202 Hardware Installation Guide](#).

## Feature Navigator

You can use Cisco Feature Navigator to find information about feature, platform, and software image support. To access Cisco Feature Navigator, go to <http://www.cisco.com/go/cfn>. An account on cisco.com is not required.

## Hardware Supported

NCS4201 is a fixed router and does not have any field replaceable units.

The following table lists the hardware supported for Cisco NCS 4202 chassis.

Chassis	Supported Interface Modules	Part Numbers
NCS 4202	8 port T1/E1 CEM Interface Module	NCS4200-8E1T1-CE
	1 port OC-48/STM-16 or 4 port OC-12/OC-3 / STM-1/STM-4 + 12 ports T1/E1 + 4 ports T3/E3	NCS4200-3GMS
	8-Port 1GE RJ45 and 1-Port 10GE SFP+ module	NCS4200-1T8LR-PS

## Determining the Software Version

You can use the following commands to verify your software version:

- Consolidated Package— **show version**
- Individual sub-packages—**show version installed** (lists all installed packages)

**Table 1: ROMMON Version**

Release Version	ROMMON Version
16.12.8	<ul style="list-style-type: none"> <li>• NCS4201—15.6(48r)S</li> <li>• NCS4202—15.6(46r)S</li> </ul>
16.12.7	<ul style="list-style-type: none"> <li>• NCS4201—15.6(48r)S</li> <li>• NCS4202—15.6(46r)S</li> </ul>
16.12.6	<ul style="list-style-type: none"> <li>• NCS4201—15.6(48r)S</li> <li>• NCS4202—15.6(46r)S</li> </ul>
16.12.5	<ul style="list-style-type: none"> <li>• NCS4201—15.6(32r)S</li> <li>• NCS4202—15.6(24r)S</li> </ul>

## Bundled FPGA Versions

The following are HoFPGA versions bundled in the IOS:

- NCS4201—0X00030015
- NCS4202
  - BFD—0X0003001c

- Netflow—0X00020008

The following is the CEM FPGA version:

- NCS4202—0x10050071

The following are HoFPGA versions bundled in IOS for 16.12.8, 16.12.7 and 16.12.6 releases:

- NCS 4201— 0X00040019
- NCS 4202
  - BFD—0X0003001b
  - Netflow—0X00020008

The following is the CEM FPGA version:

- NCS4202—NA

## Limitations and Restrictions on the Cisco NCS 4201 and Cisco NCS 4202 Series

- The **default** *command-name* command is used to default the parameters under that interface. However, when speed is configured on the interface, the following error is displayed:  

```
Speed is configured. Remove speed configuration before enabling auto-negotiation
```
- VCoP/TSoP smart SFPs are not supported.
- Virtual services should be deactivated and uninstalled before performing replace operations.
- IPSec is not supported on the Cisco NCS 4201 and Cisco NCS 4202 routers.
- On Cisco NCS 4202 Series, the following restrictions apply for IPSec:
  - Interface naming is from right to left. For more information, see the [Cisco NCS 4200 Series Software Configuration Guide](#)
  - Packet size greater than 1460 is not supported over IPsec Tunnel.
  - Minimal traffic drop might be seen for a moment when higher rate traffic is sent through the IPsec tunnels for the first time.
  - IPsec is only supported for TCP and UDP and is not supported for SCTP.

## Field Notices and Bulletins

- Field Notices—We recommend that you view the field notices for this release to determine whether your software or hardware platforms are affected. You can find field notices at [http://www.cisco.com/en/US/support/tsd\\_products\\_field\\_notice\\_summary.html](http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html).



- Bulletins—You can find bulletins at [http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod\\_literature.html](http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod_literature.html).

## MIB Support

To view supported MIB, go to <http://tools.cisco.com/ITDIT/MIBS/MainServlet>.

## Accessibility Features in the Cisco NCS 4201 and Cisco NCS 4202 Series

For a list of accessibility features in Cisco NCS 4201 and Cisco NCS 4202 Series, see the [Voluntary Product Accessibility Template \(VPAT\)](#) on the Cisco website, or contact [accessibility@cisco.com](mailto:accessibility@cisco.com).

All product documents are accessible except for images, graphics, and some charts. If you would like to receive the product documentation in audio format, braille, or large print, contact [accessibility@cisco.com](mailto:accessibility@cisco.com).





## CHAPTER 2

# New Features

---

This chapter describes the new hardware and software features that are supported on the Cisco NCS 4201 and Cisco NCS 4202 Series routers.

- [New Software Features in Cisco IOS XE Gibraltar 16.12.8, on page 7](#)
- [New Hardware Features in Cisco IOS XE Gibraltar 16.12.8, on page 7](#)
- [New Software Features in Cisco IOS XE Gibraltar 16.12.7, on page 7](#)
- [New Hardware Features in Cisco IOS XE Gibraltar 16.12.7, on page 8](#)
- [New Software Features in Cisco IOS XE Gibraltar 16.12.6, on page 8](#)
- [New Hardware Features in Cisco IOS XE Gibraltar 16.12.6, on page 8](#)
- [New Software Features in Cisco IOS XE Gibraltar 16.12.5, on page 8](#)
- [New Hardware Features in Cisco IOS XE Gibraltar 16.12.5, on page 8](#)
- [New Software Features in Cisco IOS XE Gibraltar 16.12.4, on page 8](#)
- [New Hardware Features in Cisco IOS XE Gibraltar 16.12.4, on page 9](#)
- [New Software Features in Cisco IOS XE Gibraltar 16.12.3, on page 9](#)
- [New Hardware Features in Cisco IOS XE Gibraltar 16.12.3, on page 9](#)
- [New Software Features in Cisco IOS XE Gibraltar 16.12.2a, on page 9](#)
- [New Hardware Features in Cisco IOS XE Gibraltar 16.12.2a, on page 9](#)
- [New Software Features in Cisco IOS XE Gibraltar 16.12.1, on page 9](#)
- [New Hardware Features in Cisco IOS XE Gibraltar 16.12.1, on page 10](#)

## New Software Features in Cisco IOS XE Gibraltar 16.12.8

There are no new software features for this release.

## New Hardware Features in Cisco IOS XE Gibraltar 16.12.8

There are no new hardware features for this release.

## New Software Features in Cisco IOS XE Gibraltar 16.12.7

There are no new software features for this release.

## New Hardware Features in Cisco IOS XE Gibraltar 16.12.7

There are no new hardware features for this release.

## New Software Features in Cisco IOS XE Gibraltar 16.12.6

There are no new software features for this release.

## New Hardware Features in Cisco IOS XE Gibraltar 16.12.6

There are no new hardware features for this release.

## New Software Features in Cisco IOS XE Gibraltar 16.12.5

There are no new features for this release.

## New Hardware Features in Cisco IOS XE Gibraltar 16.12.5

There are no new features for this release.

## New Software Features in Cisco IOS XE Gibraltar 16.12.4

### • Configurable Y.1564 Service Activation Frame Sizes and EMIX Support

Enterprise traffic (EMIX) packet size (default abceg pattern) is supported. For EMIX traffic, ITU-T Rec. Y.1564 packet sizes of 64, 128, 256, 1024, and 1518 bytes are supported.

For more information, see the [IP SLAs Configuration Guide, Cisco IOS XE Gibraltar 16 \(Cisco NCS 4200 Series\)](#).

### • SADT Overhead Accounting

FPGA measures the following parameters for SADT:

- Throughput
- Frame Loss
- Jitter
- Delay

FPGA has the capability to generate and measure only 1Gbps traffic rate and hence maximum throughput cannot be achieved. To overcome this limitation, use the **platform y1564 shadow-session-enable** command to replicate the packets 10 times in FPGA.

For more information, see [IP SLAs Configuration Guide, Cisco IOS XE Gibraltar 16 \(Cisco NCS 4200 Series\)](#).

## New Hardware Features in Cisco IOS XE Gibraltar 16.12.4

There are no new features for this release.

## New Software Features in Cisco IOS XE Gibraltar 16.12.3

There are no new features for this release.

## New Hardware Features in Cisco IOS XE Gibraltar 16.12.3

There are no new features for this release.

## New Software Features in Cisco IOS XE Gibraltar 16.12.2a

There are no hardware features for this release.

## New Hardware Features in Cisco IOS XE Gibraltar 16.12.2a

There are no hardware features for this release.

## New Software Features in Cisco IOS XE Gibraltar 16.12.1

- **Segment Routing uLoop Avoidance**

The Segment Routing uLoop Avoidance feature prevents the occurrences of microloops during network convergence after a link-down event or link-up event.

For more information, see the [Segment Routing Configuration Guide, Cisco IOS XE Gibraltar 16.12.x \(Cisco NCS 4200 Series\)](#).

- **Transparent PDH over Packet Smart SFP**

The TPoP smart SFP now transparently encapsulates the T1 stream into a SAToP packet for pseudowire transport over the PSN.

For more information on TPoP smart SFP, see the [Time Division Multiplexing Configuration Guide, Cisco IOS XE Gibraltar 16.12.x \(Cisco NCS 4200 Series\)](#).

- **Y.1564 10G internal mode**

Y.1564 is an Ethernet service activation test methodology and is the standard for turning up, installing, and troubleshooting Ethernet and IP based services. Y.1564 is the only standard test methodology that allows a complete validation of Ethernet service-level agreements (SLAs) in a single test.

For more information on the Y.1564. 10G internal mode, see the [IP SLAs Configuration Guide, Cisco IOS XE Gibraltar 16.12.x \(Cisco NCS 4200 Series\)](#).

## New Hardware Features in Cisco IOS XE Gibraltar 16.12.1

There are no hardware features for this release.



## CHAPTER 3

# Caveats

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The “Open Caveats” sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.
- The “Resolved Caveats” sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.



**Note** The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- [Cisco Bug Search Tool, on page 12](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.8, on page 12](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.8, on page 12](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.7, on page 12](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.7, on page 12](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.6, on page 12](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.6, on page 13](#)
- [Open Caveats – Platform Independent Cisco IOS XE Gibraltar 16.12.6, on page 14](#)
- [Closed Caveats – Platform Independent Cisco IOS XE Gibraltar 16.12.6, on page 14](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.5, on page 14](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.5, on page 15](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.4, on page 16](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.4, on page 19](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.3, on page 19](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.3, on page 20](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.2a, on page 20](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.2a, on page 22](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.1, on page 24](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.1, on page 24](#)

## Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at <http://www.cisco.com/web/applicat/cbsshelp/help.html>

## Open Caveats – Cisco IOS XE Gibraltar 16.12.8

There are no open caveats for this release.

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.8

There are no resolved caveats for this release.

## Open Caveats – Cisco IOS XE Gibraltar 16.12.7

There are no open caveats for this release.

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.7

There are no resolved caveats for this release.

## Open Caveats – Cisco IOS XE Gibraltar 16.12.6

Caveat ID Number	Description
<a href="#">CSCvo36974</a>	Traffic drop is observed over IPSEC with dynamic modification in IPSEC tunnel and route
<a href="#">CSCvq93254</a>	After IPV6 nd cache expired, transit traffic fails when ECMP enabled
<a href="#">CSCvs21550</a>	The <b>snmpwalk</b> command is not retrieving vt description in mode vt-15.
<a href="#">CSCvs35755</a>	CEM ACR: shut/no shut on physical SONET controller is causing path to go down
<a href="#">CSCvs82744</a>	Shutting 1 BDI is affecting traffic on other tunnels
<a href="#">CSCvt57044</a>	AINS to be disabled in VCOP and TPOP
<a href="#">CSCvu31005</a>	Enable L-bit propagation in framed SATOP for LOF alarm
<a href="#">CSCvv58669</a>	ROMMON region 0 and 1 verification CLI



Caveat ID Number	Description
<a href="#">CSCvw85788</a>	BFD flaps due to ARP packet loss when other non priority classes congested
<a href="#">CSCvy81362</a>	Controllers are down due to LP-LOP alarm After CE reboots
<a href="#">CSCvy91436</a>	Egress QoS classification issues with Service instance 2 configuration on CE facing interfaces
<a href="#">CSCvz18784</a>	Ingress QoS Policer not freed upon interface going down causing POLICERD leak

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.6

Caveat ID Number	Description
<a href="#">CSCvv73547</a>	Router crashed fib_loadinfo_max_oce_idx
<a href="#">CSCvv99456</a>	ACL entries with FRAGMENT keywords are not working on the router
<a href="#">CSCvw93411</a>	Interface counters not incrementing after 2 yrs, 22+ weeks on ASR920-24SZ-M variant
<a href="#">CSCvx24923</a>	HS1 2.43 FPGA commit for reload/brom select issue
<a href="#">CSCvx41010</a>	Failed to marshal xcvr_sync message: Bad address
<a href="#">CSCvx47340</a>	When insert 10G XFP in 10 Gig port from 1Gig SFP, multicast traffic stops
<a href="#">CSCvx55831</a>	Ingress policy with set qos-group action is creating extra TCAM entry with match on egress policy
<a href="#">CSCvx58983</a>	Xconnect interface flapping when shut or no shut issued or hardware failure in path of Xconnect
<a href="#">CSCvx63370</a>	With channelized T3 mode after IM OIR alarm clear or assert not happening for first T1.
<a href="#">CSCvx99501</a>	Wrong snmp traps are generated for high voltage threshold violations
<a href="#">CSCvy16480</a>	USB flashcards not mounted on new ASR-920-12CZ-A
<a href="#">CSCvy19318</a>	MH-BFD over IPv6 stopped working after upgrade
<a href="#">CSCvy25392</a>	Cannot delete recovered clock configuration from STS-3c

## Open Caveats – Platform Independent Cisco IOS XE Gibraltar 16.12.6

Caveat ID Number	Description
<a href="#">CSCvy78284</a>	Router crashes when zeroised RSA key is regenerated

## Closed Caveats – Platform Independent Cisco IOS XE Gibraltar 16.12.6

Caveat ID Number	Description
<a href="#">CSCvx19209</a>	ISIS crash is seen in isis_sr_tilfa_compute_protection
<a href="#">CSCvx26650</a>	On configuring route tag under ISIS, TI-IFA does not form repair path
<a href="#">CSCvx37945</a>	Crash happens when uea_mgr tries to write an error log
<a href="#">CSCvy20783</a>	<b>show run all</b> does not list default value for debugging

## Open Caveats – Cisco IOS XE Gibraltar 16.12.5

Caveat ID Number	Description
<a href="#">CSCvp12250</a>	caam_jr and asfctrl error logs are observed with IPsec configuration on certain conditions
<a href="#">CSCvs47204</a>	IPSEC - Kernel Crash observed on Reload with Traffic
<a href="#">CSCvs82744</a>	Shutting 1 BDI is affecting traffic on other tunnels
<a href="#">CSCvt42842</a>	Flood of SKB received from Kernel, and could not find SA kernel logs
<a href="#">CSCvu51238</a>	Kernel log messages are seen on the console while doing config replace & interface flap
<a href="#">CSCvw86859</a>	Router may not load-balance traffic on MPLS links even though having ECMP in RIB/CEF

## Open Caveats – Platform Independent Cisco IOS XE Gibraltar 16.12.5

Caveat ID Number	Description
<a href="#">CSCvp98693</a>	MLPPP IPV4 IW: Range for the mlppp group numbers does not match in the configuring CLI
<a href="#">CSCvr39157</a>	Y1731 1DM receive is inactive after delete/add of SLA configuration
<a href="#">CSCvu77385</a>	Full throughput not working priority shaper percent is greater ~40 over 100g nni
<a href="#">CSCvv74332</a>	MAC not flushed/withdrawn in remote peer on VC swichover from active to standby
<a href="#">CSCvw06702</a>	IP SLA Egress classification is not working.

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.5

Caveat ID Number	Description
<a href="#">CSCvu95940</a>	Egress QoS policy config missing on PoCh member link flap
<a href="#">CSCvu97978</a>	Node crashed with core generation in 16.12 throttle
<a href="#">CSCvv16454</a>	Traffic failure due to MPLS ECMP load-balancing in one of the labelled path
<a href="#">CSCvv24059</a>	Mgr crash is noticed on RSP when EMPLSINTD is exhausted.
<a href="#">CSCvw34109</a>	PTP failure due to LSMPI buffer exhaustion
<a href="#">CSCvr43362</a>	NCS 4202: Fan speed control measures for overheating router

## Resolved Caveats – Platform Independent Cisco IOS XE Gibraltar 16.12.5

Caveat ID Number	Description
<a href="#">CSCvu06475</a>	Segment-routing cli cleanup under ospf failing after deleting segment-routing from global configuration
<a href="#">CSCvu23567</a>	RSP3: BGP crash seen on Stand by router when 100 BGP sessions are established.
<a href="#">CSCvu44467</a>	VRRP packets are generated with CS0 marking instead of CS6
<a href="#">CSCvv07825</a>	SR uloop should only be calculated for best path
<a href="#">CSCvv42663</a>	no snmp trap link-status under serial interface disappear after router reload
<a href="#">CSCvv79677</a>	Router crashed after BGP flap

## Open Caveats – Cisco IOS XE Gibraltar 16.12.4

Caveat ID Number	Description
<a href="#">CSCVq93254</a>	After ipv6 nd cache expired, transit traffic fails when ECMP enabled
<a href="#">CSCvr07668</a>	RSP2: FRR with Multi member POCH, LB not working
<a href="#">CSCvr68265</a>	Write error: Bad address message seen with rommon upgrade command
<a href="#">CSCvs03683</a>	Support for SFP Combo IM—8-port SFP Gigabit Ethernet + 1-port 10 Gigabit Ethernet
<a href="#">CSCvs53291</a>	Backout of DDTS CSCvq93254
<a href="#">CSCvs96535</a>	Dual rate port flaps during bootup - resulting VRRP issue
<a href="#">CSCvu14321</a>	Router crashes at the moment of updating next hop
<a href="#">CSCvu49097</a>	Ports on ASR920-12SZ-D are not coming up when 1G SFPs are used
<a href="#">CSCvu57353</a>	SNMP: CPUHOG triggered by FPGA dying gasp
<a href="#">CSCvw34109</a>	PTP failure due to LSMPI buffer exhaustion

## Open Caveats – Platform Independent

Caveat ID Number	Description
<a href="#">CSCuu39858</a>	Polaris_dev: VRF sub mode configurations under aaa group
<a href="#">CSCuw75352</a>	ASR1k-lisp:Standby RP complains when eid-table removed from Active RP
<a href="#">CSCux68415</a>	ASR1k: lisp instance are not operational with vrf Deletion error
<a href="#">CSCvh04941</a>	Small bgp routing prefixes show as RIB-failure due to Mallocfail - subnet ndb with IWAN scale setup
<a href="#">CSCvo32390</a>	show logging process does not decode files when number of new messages is low
<a href="#">CSCvo90459</a>	Cisco-IOS-XE-native (isis): Redistribute application command have issues.
<a href="#">CSCvp60827</a>	Delay of 30 sec while creating a new config file for phone using tftp.
<a href="#">CSCvq01379</a>	Revert the changes of CSCvo75201 in rel21
<a href="#">CSCvq03975</a>	ISIS multicast-intact issue with SR uloop EP.
<a href="#">CSCvq47186</a>	L2 EVPN: Remote MAC not unfrozen when duplicate cleared with no MAC-only route
<a href="#">CSCvq84990</a>	Remove show ip/ipv6 access-list from syncfd-<ewlc-SIT>17.1-Observed Traceback followed by IOSD crash

Caveat ID Number	Description
<a href="#">CSCvr09310</a>	vManage should be able to work with cEdge banners in the same way as with vEdges
<a href="#">CSCvr09408</a>	"tls" CLI is not working which is present under dspfarm profile
<a href="#">CSCvr24434</a>	yang missing for "ipv6 locator reachability minimum-mask-length 128 proxy-etr-only"
<a href="#">CSCvr28935</a>	IOS crash in DHCPd Receive with Unnumbered interfaces
<a href="#">CSCvr39428</a>	L2 EVPN: no l2vpn evpn does not work correctly
<a href="#">CSCvr51558</a>	Evpn import limit counter is wrong
<a href="#">CSCvr58056</a>	Prefix SID and Manual Aj-SID range not correct
<a href="#">CSCvr80334</a>	Pubd process on the controller goes down, managed by DNA-C 1.3.2
<a href="#">CSCvr83340</a>	Add global "ip tcp mss" command to Cedge CLI and Yang
<a href="#">CSCvr91021</a>	SESM Policy-Interface on ISG ignoring Radius Requests on port 1812
<a href="#">CSCvs02944</a>	OSPFv3 distance command is missing per route-type distances for address-family ipv4
<a href="#">CSCvs13561</a>	Post SSO, if service template is getting downloaded and switch crashes, client is stuck in authc
<a href="#">CSCvs15808</a>	VRRPv3 failing on port-channel sub-interface.
<a href="#">CSCvs53280</a>	TCP stuck in CLOSEWAIT when using X25 PVC RBP sessions on ISR 4k
<a href="#">CSCvs58945</a>	Missing constraints and PRCs lead to broken model
<a href="#">CSCvs76180</a>	IS-IS: SRMS Active Policy updates connected sids inappropriately
<a href="#">CSCvs93302</a>	CDP Information Leakage Vulnerability
<a href="#">CSCvs98438</a>	Inter vrf arp failing due to arp req filtered: it's our address
<a href="#">CSCvs99153</a>	Not able to configure logging host <ipv4-addr> vrf <vrf-name>
<a href="#">CSCvt00228</a>	DDNS triggers a crash when an update is sent to delete an entry
<a href="#">CSCvt03033</a>	ISR4351:%BGP-3-BGP_SRTE_FAILURE: BGP SRTE failed to register with TE -Restarting BGP may be required
<a href="#">CSCvt12436</a>	BGP SR ODN policy doesn't become UP.
<a href="#">CSCvt16988</a>	Existing configuration on a cEdge could not be modified by a new template
<a href="#">CSCvt19590</a>	Catalyst 9200L is not sending radius-server attribute 32
<a href="#">CSCvt51568</a>	SR 688450700 : Switch member reloaded
<a href="#">CSCvt56647</a>	TCP session is not established between catalyst 3850 and ISE servers
<a href="#">CSCvt58187</a>	LISP Tracebacks seen on Border/CP node

Caveat ID Number	Description
CSCvt60188	Authentication Config Removal leads to Supervisor Crash
CSCvt65374	Local routes are getting leaked b/w vrf's along with Connected routes
CSCvt68348	Unexpected reload when using "show radius server-group all" or "show aaa server"
CSCvt73592	missing/corrupt IOS-XE PKSC10 format
CSCvt74331	C9300 console authorization does not fail back to local if radius server is not defined
CSCvt75633	It takes long until FlexVPN IKEv2 tunnel re-establishes when tunnel flaps
CSCvt94052	9800 WLC crashes when changing the password for existing user
CSCvt94212	%COMMON_FIB-SW1_DFC6-3-PATH_EXT_DUPLICATE after upgrade from 15-2(1)SY7 to 15.5(1)SY4
CSCvt99272	High CPU usage caused by "TCP Timer" process
CSCvu01690	CPUHOGS produced while executing the command - client fireall access-list ?
CSCvu06475	Segment-routing cli cleanup under ospf not happening after deleting segment-routing from Global
CSCvu06641	tacacs+ single connection packet flow
CSCvu12106	cedge: can not remove "ip ssh client algorithm encryption aes128-ctr aes192-ctr aes256-ctr"
CSCvu16200	Router May Crash When a SSH session is Closed After a TACACS Configuration Change (Part 2)
CSCvu18265	Building Node Cache can consume high CPU when Segment Routing is not enabled
CSCvu27953	Crash due to a segmentation fault in the "IPsec background proc" process
CSCvu31813	ASR1k - valid Vendor Specific TLV dropped for invalid header length
CSCvu36475	Numbered ACLs fail to program to software TCAM if there's an object-group config
CSCvu36476	memory corruption in IOMEM in polaris 16.11.1
CSCvu40093	Crash when tearing down a PPPoE client session
CSCvu42109	Traceback: Standby RSP3 reloads "HSCF Failed to sync private-config"
CSCvu52322	CBR8: do not drop malformed dhcp option 125 packets
CSCvu55783	SSS Key (username) is not updated after receiving CoA with username
CSCvu58791	RADIUS not sent for 802.1x
CSCvu61753	3850 Not Starting MAB Process

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.4

Caveat ID Number	Description
<a href="#">CSCvs36897</a>	OCE consistency check on cEdge causes crash
<a href="#">CSCvt01082</a>	IM deactivate CLI enabled for 10G IMs in Crete
<a href="#">CSCvt10032</a>	ASR920_XE_BIT: CFM RMEP not getting learnt over VPLSoBkp PW BD
<a href="#">CSCvt21903</a>	RSP2 Traffic drops observed with IPSec traffic
<a href="#">CSCvt32521</a>	Duplex half change to full after reload
<a href="#">CSCvr43362</a>	NCS 4202: Fan speed control measures for overheating router

## Resolved Caveats – Platform Independent

Caveat ID Number	Description
<a href="#">CSCvs30865</a>	rLFA for LDP causes loss of MPLS traffic after RSP switchover
<a href="#">CSCvs95815</a>	C1111 telnet refused for link-local addresses when using ipv6 access class
<a href="#">CSCvt14323</a>	ASR903 IGMP: reports received on mLACP Port-Channel dropped incorrectly
<a href="#">CSCvt25458</a>	MPLS TE is not coming UP when bandwidth configured on Juniper head end

## Open Caveats – Cisco IOS XE Gibraltar 16.12.3

Caveat ID Number	Description
<a href="#">CSCvt01082</a>	IM deactivate CLI enabled for 10G IMs
<a href="#">CSCvw34109</a>	PTP failure due to LSMPI buffer exhaustion

## Open Caveats – Platform Independent

Caveat ID Number	Description
<a href="#">CSCvq76305</a>	AutoRP listener functionality issue
<a href="#">CSCvs30865</a>	rLFA for LDP causes loss of MPLS traffic after RSP switchover
<a href="#">CSCvs58498</a>	High CPU on SNMP engine due to CISCO-CEF-MIB

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.3

Caveat ID Number	Description
<a href="#">CSCvs74558</a>	IPV6 Traffic causing Broadcast Storm on port with hwid 3
<a href="#">CSCvr43362</a>	NCS 4202: Fan speed control measures for overheating router

## Resolved Caveats – Platform Independent

Caveat ID Number	Description
<a href="#">CSCvm79556</a>	MSPW VC down after Switchover (Error Local access circuit is not ready for label advertise)

## Open Caveats – Cisco IOS XE Gibraltar 16.12.2a

Caveat ID Number	Description
<a href="#">CSCvr26253</a>	UDP and TCP traffic are not successful when through IPSec tunnel
<a href="#">CSCvr42356</a>	IPSec: Changing IP addresses on LAN interface results in traffic failing over IPSec tunnel
<a href="#">CSCvr50508</a>	Router_RP_0_fman_rp crash is observed on applying conditional crypto debug
<a href="#">CSCvr61371</a>	BFD remains down when using PBR on BDI interface
<a href="#">CSCvw34109</a>	PTP failure due to LSMPI buffer exhaustion

## Open Caveats – Platform Independent

Caveat ID Number	Description
<a href="#">CSCux43298</a>	<b>show interface pseudowire</b> command displays invalid peer information
<a href="#">CSCvn86673</a>	Dialer watch does not disconnect the backup link even after the watched route exists in routing table
<a href="#">CSCvp60827</a>	Delay of 30 sec is observed while creating a new configuration file for phone using TFTP
<a href="#">CSCvq50202</a>	Class-attributes are duplicated after EAP reauthentication in ISG radius proxy scenario
<a href="#">CSCvq65438</a>	Copying configuration file containing SmartPort macros to run fails
<a href="#">CSCvq69866</a>	HSRPv2 crashes while retrieving group from received packet



Caveat ID Number	Description
<a href="#">CSCvq78692</a>	mGRE L3VPN is broken after reload
<a href="#">CSCvq93089</a>	Active switch crashes after standby is reloaded
<a href="#">CSCvq95479</a>	Parser returns invalid PRC to certain commands
<a href="#">CSCvq96794</a>	VPLS label misprogramming occurs after RSP switchover
<a href="#">CSCvr05504</a>	Dialer interface counter does not correlate to the counter of interfaces bounded to
<a href="#">CSCvr08740</a>	Router crashes after receiving EVPN route-type 2 without any ext-community
<a href="#">CSCvr08961</a>	Switch stop responding to CoA
<a href="#">CSCvr18919</a>	9400 SVL - Upon redundancy failover, route being purged on downstream device
<a href="#">CSCvr21440</a>	3850 loops get-response value of object cafSessionClientMacAddress
<a href="#">CSCvr23104</a>	BGP looped update is observed among 3 peers
<a href="#">CSCvr27393</a>	Crash is observed on BGP Router process
<a href="#">CSCvr34118</a>	Removes login and fix broken command
<a href="#">CSCvr34677</a>	DHCP packets are not encrypted in redundant ip helper setup
<a href="#">CSCvr39868</a>	Unexpected reload is observed when issuing <b>show ip mroute vrf &lt;vrf&gt; verbose</b> command
<a href="#">CSCvr45669</a>	cEdge - Template is not pushed because of bad-command <b>no ip domain-name</b>
<a href="#">CSCvr49439</a>	Multiple encapsulations of packet with L2TP headers crash ASR1K
<a href="#">CSCvr51079</a>	PPPoE session is stuck in LCP state due to the wrong invoke of AAA method list
<a href="#">CSCvr54031</a>	TBs are seen with scaled IP SLA configs with <b>ip sla reset</b> command
<a href="#">CSCvr57022</a>	Routers are not removed from routing table when Dialer interface is shut
<a href="#">CSCvr57138</a>	Wrong pointer to next buffer - Catalyst 9300
<a href="#">CSCvr57340</a>	MAB is removed from template that causes authorization failure
<a href="#">CSCvr61879</a>	<b>static ip addresses not configured for the list</b> message is observed
<a href="#">CSCvr70470</a>	sessmgrd crashes with "clear dot1x mac" command
<a href="#">CSCvr73095</a>	After AES encryption is enabled, entering plain aaa dynamic-author keys corrupts key
<a href="#">CSCvr74333</a>	SMD memory leak is observed while sending radius packets
<a href="#">CSCvr74619</a>	Cat 9000 switch crashes during Authentication Failure of Wired Client
<a href="#">CSCvr75640</a>	LNS crashes with Segmentation fault (11) in L2TP mgmt daemon

Caveat ID Number	Description
<a href="#">CSCvr76555</a>	IOS-XE 16.12.1a version, two redundant RPs, VPDN tunnel do not come up
<a href="#">CSCvr79052</a>	cEdge 16.11.1a or 16.12.1b console 0 does not honor the privilege set in the username.

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.2a

Caveat ID Number	Description
<a href="#">CSCvp86320</a>	ASR920 CSDL : Hotspring1 secure FPGA
<a href="#">CSCvp86327</a>	ASR920 CSDL: Hotspring2 secure FPGA
<a href="#">CSCvp86365</a>	Cisco RSP2 Module CSDL : secure FPGA

## Resolved Caveats – Platform Independent

Caveat ID Number	Description
<a href="#">CSCts28315</a>	DHCP-pd reflects the Advertised prefix in Request message
<a href="#">CSCvi22263</a>	Crash is observed when IOS adapts shaping with Adaptive QoS over DMVPN configured
<a href="#">CSCvj76866</a>	Partial Power Failure in Stack Causes Interfaces to Become "shutdown"
<a href="#">CSCvm40566</a>	IP prefix list replacement gets error from IOS side
<a href="#">CSCvo55194</a>	After RSP switchover, label imposition is not programmed in Software on APS standby router
<a href="#">CSCvo55783</a>	Pending objects are observed with respect to to uRPF on reload or soak script run
<a href="#">CSCvp38407</a>	<b>radius-server attribute 31</b> command broken on LNS when LAC sends Remote-Id string
<a href="#">CSCvp66281</a>	<b>default ip forward-protocol udp xx</b> command changes to <b>no ip forward-protocol udp xx</b> command after rollback
<a href="#">CSCvp74674</a>	QoS fails to apply to tunnel2 when underlying tunnel1 reachability change
<a href="#">CSCvp96887</a>	Fails to attach template to Cisco XE SDWAN Rtr if qos-map name is changed after policy-map is attached
<a href="#">CSCvq00263</a>	Device crashes @ radius_io_stats_timer_handler due to dynamic-author
<a href="#">CSCvq04828</a>	VRF aware reverse DNS lookup does not work
<a href="#">CSCvq04989</a>	Ping between two interfaces does work; dialer interface is interferes in the ARP Process

Caveat ID Number	Description
<a href="#">CSCvq09061</a>	.py file check is unsuccessful while registering the policy and the error is seen
<a href="#">CSCvq18328</a>	SSH: host_key->name is not null after reload which prevents SSH from starting up
<a href="#">CSCvq29953</a>	IP SLA reactst for packet loss and successive packet loss does not set \$_ipsla_react_type in EEM
<a href="#">CSCvq33004</a>	Account logon fails for both direct and indirect lite-session in Cisco 16.9.3 Release
<a href="#">CSCvq34893</a>	Template push to CEdge fails when you change the access VLAN on a switchport from VLAN 1
<a href="#">CSCvq35631</a>	9300 crashes due to HTTP Core
<a href="#">CSCvq49721</a>	Telnet access fails when VRF-aware extended VTY ACL is configured
<a href="#">CSCvq54265</a>	IP bootp server is disabled by default as a device hardening best practice
<a href="#">CSCvq56114</a>	Cat3k crashes in IGMP code due to invalid source count in DNS lookup
<a href="#">CSCvq56208</a>	MDT: xpath union operator only outputs data from the left hand expression
<a href="#">CSCvq58265</a>	BGP PIC Repair path breaks after link flap occurs
<a href="#">CSCvq58722</a>	Python script register failure is observed when using custom directory instead of Flash
<a href="#">CSCvq59908</a>	Stack crashes after upgrade
<a href="#">CSCvq60252</a>	PBR works although an interface is down
<a href="#">CSCvq70148</a>	BGP improperly formats the BGP ASSET attribute if ASSET attribute length is beyond 255
<a href="#">CSCvq72298</a>	Router crashes on running <b>show policy-map interface &lt;&gt; output</b> command
<a href="#">CSCvq73364</a>	mVPN - Multicast packets dropped and %MFIB-SW2-3-MFIB_CTXT_DEPTH_EXCEEDED is printed continuously
<a href="#">CSCvq89252</a>	IP SLA for Path-Jitter returning a value which is not defined by the MIB
<a href="#">CSCvq94679</a>	[SDA] Crash is observed due to Segmentation fault(11), Process = ARP Input
<a href="#">CSCvq95645</a>	CAT9800 WLC crashes due to memory corruption
<a href="#">CSCvq97365</a>	Two interfaces of client in different VRF connected to same vlan of server are not able to procure IP via DHCP
<a href="#">CSCvr00183</a>	AAA accounting issue is observed after router reload occurs when mGRE and L3VPN are configured
<a href="#">CSCvr00344</a>	<b>ip access-list logging hash-generation</b> command removes ACL statements upon reload
<a href="#">CSCvr02957</a>	Re-add app-hosting move support is removed in version 16.12.1

Caveat ID Number	Description
<a href="#">CSCvr05406</a>	LISP Map-cache is not updated correctly after wired Host-mobility
<a href="#">CSCvr09014</a>	IGP metric is not detected in MPLS TE topology
<a href="#">CSCvr13213</a>	Session is unauthorized as Redirect ACL Failure. Failed attribute name is POSTURE_REDIRECT.
<a href="#">CSCvr36887</a>	9800 WLC crashes by WNCD process when modifying AAA configs from WebUI

## Open Caveats – Cisco IOS XE Gibraltar 16.12.1

Caveat ID Number	Description
<a href="#">CSCvp59580</a>	DR_10G_PORT_MAP is not correct during SFP OIR.
<a href="#">CSCvq00342</a>	Duplicated packets on MVPN deployment on Cisco NCS router.
<a href="#">CSCvo36974</a>	Data traffic drop is observed over VRF_AWARE_IPSEC with IPSEC profile removal and addition
<a href="#">CSCvp12219</a>	IKEV1 tunnel goes down even after core port un-shut and comes up again
<a href="#">CSCvp28897</a>	Kernel crash observed with 1500 frame size on core port shut or un-shut on peer
<a href="#">CSCvp61200</a>	VRF AWARE IPSEC - One-way traffic hits tunnel during clear crypto process
<a href="#">CSCvp12250</a>	The error logs such as caam_jr and asfctrl are observed
<a href="#">CSCvw34109</a>	PTP failure due to LSMPI buffer exhaustion

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.1

Caveat ID Number	Description
<a href="#">CSCvm50225</a>	GRE: Unable to ping over GRE tunnel if packet size more than 1472 bytes
<a href="#">CSCvn49741</a>	RSP2A-64 and RSP2A-128 _mgr crash.
<a href="#">CSCvn55871</a>	T1 serial interface went down with encapsulation mode as PPP with remote loopback config as iboc.
<a href="#">CSCvo07619</a>	BDI IPv6 ping failure_FMFP_OBJ_Download_Failure
<a href="#">CSCvo19770</a>	Router crashes at hashtable_get_nth_entry
<a href="#">CSCvo35275</a>	MVPN: Unable to pass high MTU multicast packets-MDT-MTU

Caveat ID Number	Description
<a href="#">CSCvo98627</a>	The system stops responding due to nile_cef_adj_gre_delete when the router ospf shut is performed on peer
<a href="#">CSCvq10257</a>	About incorrect I/F notation when enable qos-overhead-accounting Tengigabit interface
<a href="#">CSCvq01602</a>	After IPv6 nd cache expired, transit traffic fails when ECMP

