



## **Release Notes for Cisco NCS 4206 and Cisco NCS 4216 Series, Cisco IOS XE Gibraltar 16.12.x**

**First Published:** 2019-07-31

**Last Modified:** 2021-09-07

### **Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
<http://www.cisco.com>  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 527-0883

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

The documentation set for this product strives to use bias-free language. For purposes of this documentation set, bias-free is defined as language that does not imply discrimination based on age, disability, gender, racial identity, ethnic identity, sexual orientation, socioeconomic status, and intersectionality. Exceptions may be present in the documentation due to language that is hardcoded in the user interfaces of the product software, language used based on standards documentation, or language that is used by a referenced third-party product.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2019–2021 Cisco Systems, Inc. All rights reserved.



## CONTENTS

---

### CHAPTER 1

#### **Introduction 1**

Overview of Cisco NCS 4206 and NCS 4216	1
Cisco NCS 4206	1
Cisco NCS 4216	2
NCS 4216 14RU	2
Feature Navigator	2
Hardware Supported	3
Cisco NCS 4206 Supported Interface Modules	3
Supported Interface Modules	3
Cisco NCS 4216 Supported Interface Modules	5
Swapping of Interface Modules	5
Cisco NCS 4216 F2B Supported Interface Modules	7
Swapping of Interface Modules	7
Restrictions and Limitations for Cisco NCS 4206 and Cisco NCS 4216	8
Determining the Software Version	10
Upgrading to a New Software Release	10
Supported FPGA Versions for NCS 4206 and NCS 4216	10
Deferrals	14
Field Notices and Bulletins	14
MIB Support	14
MIB Documentation	16
Open Source License Notices	16
Communications, Services, and Additional Information	17

---

### CHAPTER 2

#### **New Features 19**

New Software Features in Cisco IOS XE Gibraltar 16.12.8	19
---	----

New Hardware Features in Cisco IOS XE Gibraltar 16.12.8 19

New Software Features in Cisco IOS XE Gibraltar 16.12.7 19

New Hardware Features in Cisco IOS XE Gibraltar 16.12.7 20

New Software Features in Cisco IOS XE Gibraltar 16.12.6 20

New Hardware Features in Cisco IOS XE Gibraltar 16.12.6 20

New Software Features in Cisco IOS XE Gibraltar 16.12.5 20

New Hardware Features in Cisco IOS XE Gibraltar 16.12.5 20

New Hardware Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.4 20

New Software Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.4 20

New Hardware Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.3 21

New Software Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.3 21

New Hardware Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.2 21

New Software Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.2 21

New Hardware Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.1 21

New Software Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.1 22

**CHAPTER 3**

**Caveats 25**

Cisco Bug Search Tool 26

Open Caveats - Cisco IOS XE Gibraltar 16.12.8 26

Resolved Caveats - Cisco IOS XE Gibraltar 16.12.8 26

Open Caveats – Cisco IOS XE Gibraltar 16.12.7 26

Resolved Caveats – Cisco IOS XE Gibraltar 16.12.7 26

Open Caveats – Cisco IOS XE Gibraltar 16.12.6 27

Open Caveats – Cisco IOS XE Gibraltar 16.12.6 - Platform Independent 28

Resolved Caveats – Cisco IOS XE Gibraltar 16.12.6 28

Resolved Caveats – Cisco IOS XE Gibraltar 16.12.6 – Platform Independent 29

Open Caveats – Cisco IOS XE Gibraltar 16.12.5 29

Open Caveats – Cisco IOS XE Gibraltar 16.12.5 - Platform Independent 30

Resolved Caveats – Cisco IOS XE Gibraltar 16.12.5 30

Resolved Caveats – Cisco IOS XE Gibraltar 16.12.5 - Platform Independent 32

Open Caveats – Cisco IOS XE Gibraltar 16.12.4 32

Open Caveats – Cisco IOS XE Gibraltar 16.12.4 - Platform Independent 33

Resolved Caveats – Cisco IOS XE Gibraltar 16.12.4 33

Resolved Caveats – Cisco IOS XE Gibraltar 16.12.4 - Platform Independent 33

Open Caveats – Cisco IOS XE Gibraltar 16.12.3	33
Open Caveats – Platform Independent	34
Resolved Caveats – Cisco IOS XE Gibraltar 16.12.3	34
Resolved Caveats – Platform Independent	35
Open Caveats – Cisco IOS XE Gibraltar 16.12.2a	35
Open Caveats – Platform Independent	35
Resolved Caveats – Cisco IOS XE Gibraltar 16.12.2a	37
Resolved Caveats – Platform Independent	37
Open Caveats – Cisco IOS XE Gibraltar 16.12.1	39
Resolved Caveats – Cisco IOS XE Gibraltar 16.12.1a	40





# CHAPTER 1

## Introduction

---



- Note** Explore the [Content Hub](#), the all new portal that offers an enhanced product documentation experience.
- Use faceted search to locate content that is most relevant to you.
  - Create customized PDFs for ready reference.
  - Benefit from context-based recommendations.

Get started with the Content Hub at [content.cisco.com](https://content.cisco.com) to craft a personalized documentation experience. Do provide feedback about your experience with the Content Hub.

---

This document provides information about the IOS XE software release for the Cisco NCS 4201 and Cisco NCS 4202 beginning with Cisco IOS XE Release 3.18SP.

- [Overview of Cisco NCS 4206 and NCS 4216, on page 1](#)
- [Feature Navigator, on page 2](#)
- [Hardware Supported, on page 3](#)
- [Restrictions and Limitations for Cisco NCS 4206 and Cisco NCS 4216, on page 8](#)
- [Determining the Software Version, on page 10](#)
- [Upgrading to a New Software Release, on page 10](#)
- [Supported FPGA Versions for NCS 4206 and NCS 4216, on page 10](#)
- [Deferrals, on page 14](#)
- [Field Notices and Bulletins, on page 14](#)
- [MIB Support, on page 14](#)
- [Open Source License Notices, on page 16](#)
- [Communications, Services, and Additional Information, on page 17](#)

## Overview of Cisco NCS 4206 and NCS 4216

### Cisco NCS 4206

The Cisco NCS 4206 is a fully-featured aggregation platform designed for the cost-effective delivery of converged mobile and business services. With shallow depth, low power consumption, and an extended

temperature range, this compact 3-rack-unit (RU) chassis provides high service scale, full redundancy, and flexible hardware configuration.

The Cisco NCS 4206 expands the Cisco service provider product portfolio by providing a rich and scalable feature set of Layer 2 VPN (L2VPN) and Layer 3 VPN (L3VPN) services in a compact package. It also supports a variety of software features, including Carrier Ethernet features, Timing over Packet, and pseudowire.

For more information on the Cisco NCS 4206 Chassis, see the [Cisco NCS 4206 Hardware Installation Guide](#).

## Cisco NCS 4216

The Cisco NCS 4216 is a seven-rack (7RU) unit chassis that belongs to the Cisco NCS 4200 family of chassis. This chassis complements Cisco's offerings for IP RAN solutions for the GSM, UMTS, LTE and CDMA. Given its form-factor, interface types and Gigabit Ethernet density the Cisco NCS 4216 can also be positioned as a Carrier Ethernet aggregation platform.

The Cisco NCS 4216 is a cost optimized, fully redundant, centralized forwarding, extended temperature, and flexible pre-aggregation chassis.

For more information about the Cisco NCS 4216 Chassis, see the [Cisco NCS 4216 Hardware Installation Guide](#).

### Cisco NCS 4216 F2B

The Cisco NCS 4216 F2B is a 14-rack unit router that belongs to the Cisco NCS 4200 family of routers. This router complements Cisco's offerings for IP RAN solutions for the GSM, UMTS, LTE, and CDMA. Given its form-factor, interface types, and Gigabit Ethernet density the Cisco NCS 4216 F2B can also be positioned as a Carrier Ethernet aggregation platform.

The Cisco NCS 4216 F2B is a cost optimized, fully redundant, centralized forwarding, extended temperature, and flexible pre-aggregation router.

For more information about the Cisco NCS 4216 F2B Chassis, see the [Cisco NCS 4216 F2B Hardware Installation Guide](#).

## NCS 4216 14RU

The Cisco NCS 4216 14RU is a 14-rack unit router that belongs to the Cisco NCS 4200 family of routers. This router complements Cisco's offerings for IP RAN solutions for the GSM, UMTS, LTE, and CDMA. Given its form-factor, interface types and Gigabit Ethernet density the Cisco NCS 4216 14RU can also be positioned as a Carrier Ethernet aggregation platform.

The Cisco NCS 4216 14RU is a cost optimized, fully redundant, centralized forwarding, extended temperature, and flexible pre-aggregation router.

For more information about the Cisco NCS 4216 14RU chassis, see the [Cisco NCS 4216 14RU Hardware Installation Guide](#).

## Feature Navigator

You can use Cisco Feature Navigator to find information about feature, platform, and software image support. To access Cisco Feature Navigator, go to <http://www.cisco.com/go/cfn>. An account on cisco.com is not required.



# Hardware Supported

The following sections list the hardware supported for Cisco NCS 4206 and Cisco NCS 4216 chassis.

## Cisco NCS 4206 Supported Interface Modules

### Supported Interface Modules



---

**Note** If the **license feature service-offload enable** command is configured, then the NCS4200-1T8LR-PS IM is not supported in the router for RSP3.

---



---

**Note** There are certain restrictions in using the interface modules on different slots in the chassis. Contact Cisco Sales/Support for the valid combinations.

---



---

**Note** FAN OIR is applicable every time the IM based fan speed profile is switched to NCS4200-1H-PK= and NCS4200-2Q-P interface modules. Even though the IMs remain in the Out-of-Service state, they are still considered as present in the chassis.

---

Table 1: NCS420X-RSP Supported Interface Modules and Part Numbers

RSP Module	Supported Interface Modules	Part Numbers	Slot
NCS420X-RSP	8-port 10 Gigabit Ethernet Interface Module (8X10GE)	NCS4200-8T-PS	All
	1-port 100 Gigabit Ethernet Interface Module (1X100GE)	NCS4200-1H-PK=	4 and 5
	2-port 40 Gigabit Ethernet QSFP Interface Module (2X40GE)	NCS4200-2Q-P	4 and 5
	8/16-port 1 Gigabit Ethernet (SFP/SFP) + 1-port 10 Gigabit Ethernet (SFP+) / 2-port 1 Gigabit Ethernet (CSFP) Interface Module	NCS4200-1T16G-PS	0,3,4, and 5
	1-port OC-192 Interface module or 8-port Low Rate Interface Module	NCS4200-1T8S-10CS	2,3,4, and 5
	NCS 4200 1-Port OC-192 or 8-Port Low Rate CEM 20G Bandwidth Interface Module	NCS4200-1T8S-20CS	2,3,4, and 5 <sup>1</sup>
	48-port T1/E1 CEM Interface Module	NCS4200-48T1E1-CE	All
	48-port T3/E3 CEM Interface Module	NCS4200-48T3E3-CE	All
	2-port 100 Gigabit Ethernet (QSFP) Interface Module (2X100GE) <sup>2</sup>	NCS4200-2H-PQ	4,5
	1-port OC48 <sup>3</sup> / STM-16 or 4-port OC-12/OC-3 / STM-1/STM-4 + 12-port T1/E1 + 4-Port T3/E3 CEM Interface Module	NCS4200-3GMS	2,3,4, and 5

<sup>1</sup> These slots are supported on 10G or 20G mode.

<sup>2</sup> IM supports only one port of 100G with RSP3 as QSFP28 on Port 0 in both slots 4 and 5.

<sup>3</sup> If OC48 is enabled, then the remaining 3 ports are disabled.

Table 2: NCS420X-RSP-128 Supported Interface Modules and Part Numbers

RSP Module	Supported Interface Modules	Part Numbers	Slot
NCS420X-RSP	SFP Combo IM—8-port Gigabit Ethernet (8X1GE) + 1-port 10 Gigabit Ethernet Interface Module (1X10GE)	NCS4200-1T8LR-PS	All
	8-port T1/E1 CEM Interface Module	NCS4200-8E1T1-CE	All
	1-port OC48 <sup>4</sup> / STM-16 or 4-port OC-12/OC-3 / STM-1/STM-4 + 12-port T1/E1 + 4-Port T3/E3 CEM Interface Module	NCS4200-3GMS	2,3,4, and 5

<sup>4</sup> If OC48 is enabled, then the remaining 3 ports are disabled.

# Cisco NCS 4216 Supported Interface Modules

For information on supported interface modules, see [Supported Interface Modules](#).

## Swapping of Interface Modules

The following Ethernet interface modules support swapping on the Cisco NCS4216-RSP module:

Use the **hw-module subslot default** command before performing a swap of the modules to default the interfaces on the interface module.

- SFP Combo IM—8-port Gigabit Ethernet (8X1GE) + 1-port 10 Gigabit Ethernet (1X10GE)
- 2-port 40 Gigabit Ethernet Interface Module (2X40GE)
- 8/16-port 1 Gigabit Ethernet (SFP/SFP) + 1-port 10 Gigabit Ethernet (SFP+) / 2-port 1 Gigabit Ethernet (CSFP) Interface Module
- 8-port 10 Gigabit Ethernet Interface Module (8X10GE)
- 1-port 100 Gigabit Ethernet Interface Module (1X100GE)
- 2-port 100 Gigabit Ethernet (QSFP) Interface Module (2X100GE)

Use of **hw-module subslot default** command is not supported on the following interface modules.

- OC-192 Interface Module with 8-port Low Rate CEM Interface Module (10G HO / 10G LO)
- 48 T1/E1 TDM Interface Module (48XT1/E1)
- 48 T3/E3 TDM Interface Module (48XT3/E3)
- 1-port OC48 STM-16 or 4-port OC-12/OC-3 / STM-1/STM-4 + 12-Port T1/E1 + 4-Port T3/E3 CEM Interface Module
- NCS 4200 1-Port OC-192 or 8-Port Low Rate CEM 20G Bandwidth Interface Module



---

**Note** If the **license feature service-offload enable** command is configured, then the NCS4200-1T8LR-PS IM is not supported in the router for RSP3.

---



---

**Note** There are certain restrictions in using the interface modules on different slots in the chassis. Contact Cisco Sales/Support for the valid combinations.

---

Table 3: NCS4216-RSP Supported Interface Modules and Part Numbers

RSP Module	Interface Modules	Part Number	Slot
NCS4216-RSP	SFP Combo IM—8-port Gigabit Ethernet (8X1GE) + 1-port 10 Gigabit Ethernet (1X10GE)	NCS4200-1T8LR-PS	2,5,6,9,10,13,14,15
	1-port 100 Gigabit Ethernet Interface Module (1X100GE)	NCS4200-1H-PK	7,8
	2-port 100 Gigabit Ethernet (QSFP) Interface Module (2X100GE) <sup>5</sup>	NCS4200-2H-PQ	7,8
	2-port 40 Gigabit Ethernet QSFP Interface Module (2X40GE)	NCS4200-2Q-P	3,4,7,8,11,12
	8/16-port 1 Gigabit Ethernet (SFP/SFP) + 1-port 10 Gigabit Ethernet (SFP+) / 2-port 1 Gigabit Ethernet (CSFP) Interface Module	NCS4200-1T16G-PS	All slots
	1-port OC48 <sup>6</sup> / STM-16 or 4-port OC-12/OC-3 / STM-1/STM-4 + 12-port T1/E1 + 4-Port T3/E3 CEM Interface Module	NCS4200-3GMS	All slots
	8-port 10 Gigabit Ethernet Interface Module (8X10GE)	NCS4200-8T-PS	3,4,7,8,11,12
	1-port OC-192 Interface Module with 8-port Low Rate CEM Interface Module (5G/ 10G HO / 10G LO)	NCS4200-1T8S-10CS	3,4,7,8,11,12 (10G mode) 0,1,2,5,6,9,10,13,14,15 (5G mode) <b>Note</b> To enable this IM on slot 0 or slot 1, do the following and reload the router:  Router# configure t Router(config)# license feature service-offload enable
	NCS 4200 1-Port OC-192 or 8-Port Low Rate CEM 20G Bandwidth Interface Module	NCS4200-1T8S-20CS	3,4,7,8,11,12 (20G mode) 0,1,2,5,6,9,10,13,14,15 (10G mode) <b>Note</b> To enable this IM on slot 0 or slot 1, do the following and reload the router:  Router# configure t Router(config)# license feature service-offload enable
	48-port T1/E1 Interface module	NCS4200-48T1E1-CE	2,3,4,5,6,7,8,9,10,13,14,15
48-port T3/E3 Interface module	NCS4200-48T3E3-CE	2,3,4,5,6,7,8,9,10,13,14,15	

<sup>5</sup> IM supports only one port of 100G with RSP3 as QSFP28 on Port 0 in both slots 7 and 8.

<sup>6</sup> If OC48 is enabled, then the remaining 3 ports are disabled.

## Cisco NCS 4216 F2B Supported Interface Modules

For information on supported interface modules, see [Supported Interface Modules](#).

### Swapping of Interface Modules

The following interface modules support swapping on the Cisco NCS4216-RSP module:

- SFP Combo IM—8-port Gigabit Ethernet (8X1GE) + 1-port 10 Gigabit Ethernet (1X10GE)
- 2-port 40 Gigabit Ethernet Interface Module (2X40GE)
- 8-port 10 Gigabit Ethernet Interface Module (8X10GE)
- 1-port 100 Gigabit Ethernet Interface Module (1X100GE)
- 2-port 100 Gigabit Ethernet Interface Module (2X100GE)
- 8/16-port 1 Gigabit Ethernet (SFP/SFP) + 1-port 10 Gigabit Ethernet (SFP+) / 2-port 1 Gigabit Ethernet (CSFP) Interface Module
- 1-port OC-192 Interface Module with 8-port Low Rate CEM Interface Module (10G HO / 10G LO)
- 48-port T1/E1 TDM Interface Module (48XT1/E1)
- 48-port T3/E3 TDM Interface Module (48XT3/E3)
- 1-port OC 482/ STM-16 or 4-port OC-12/OC-3 / STM-1/STM-4 + 12-port T1/E1 + 4-Port T3/E3 CEM Interface Module (NCS4200-3GMS)
- 1-Port 10 Gigabit MR and 8-Port LR 20 Gigabit CEM and iMSG Interface Module (NCS 4200-1T8S-20CS)

Use the **hw-module subslot default** command before performing a swap of the modules to default the interfaces on the interface module.

See the *Cisco NCS 4216 Router Hardware Installation Guide* for information on Supported Interface Modules on the RSP.




---

**Note** If the **license feature service-offload enable** command is configured, then the NCS4200-1T8LR-PS IM is not supported in the router for RSP3.

---




---

**Note** There are certain restrictions in using the interface modules on different slots in the chassis. Contact Cisco Sales/Support for the valid combinations.

---

Table 4: Cisco NCS4216-RSP Supported Interface Modules and Part Numbers

RSP Module	Interface Modules	Part Number	Slot
NCS4216-RSP	SFP Combo IM—8-port Gigabit Ethernet (8X1GE) + 1-port 10 Gigabit Ethernet (1X10GE)	NCS4200-1T8LR-PS	2,5,6,9,10,13,14,15
	1-port 100 Gigabit Ethernet Interface Module (1X100GE)	NCS4200-1H-PK	7,8
	2-port 100 Gigabit Ethernet (QSFP) Interface Module (2X100GE) <sup>7</sup>	NCS4200-2H-PQ	7,8
	2-port 40 Gigabit Ethernet QSFP Interface Module (2X40GE)	NCS4200-2Q-P	3,4,7,8,11,12
	8/16-port 1 Gigabit Ethernet (SFP/SFP) + 1-port 10 Gigabit Ethernet (SFP+) / 2-port 1 Gigabit Ethernet (CSFP) Interface Module	NCS4200-1T16G-PS	All slots
	8-port 10 Gigabit Ethernet Interface Module (8X10GE)	NCS4200-8T-PS	3,4,7,8,11,12
	1-port OC-192 Interface Module with 8-port Low Rate CEM Interface Module (5G/ 10G HO / 10G LO)	NCS4200-1T8S-10CS	3,4,7,8,11,12 (10G mode) 0,1,2,5,6,9,10,13,14,15 (5G mode)
	NCS 4200 1-Port OC-192 or 8-Port Low Rate CEM 20G Bandwidth Interface Module	NCS4200-1T8S-20CS	3,4,7,8,11,12 (20G mode) 0,1,2,5,6,9,10,13,14,15 (10G mode)
	48XT1/E1 Interface module	NCS4200-48T1E1-CE	2,3,4,5,6,7,8,9,10,13,14,15
	48XT3/E3 Interface module	NCS4200-48T3E3-CE	2,3,4,5,6,7,8,9,10,13,14,15
	1-port OC48 <sup>8</sup> / STM-16 or 4-port OC-12/OC-3 / STM-1/STM-4 + 12-port T1/E1 + 4-Port T3/E3 CEM Interface Module	NCS4200-3GMS	All slots

<sup>7</sup> IM supports only one port of 100G with RSP3 as QSFP28 on Port 0 in both slots 7 and 8.

<sup>8</sup> If OC48 is enabled, then the remaining 3 ports are disabled.

## Restrictions and Limitations for Cisco NCS 4206 and Cisco NCS 4216

- In the Cisco IOS XE 16.12.1 release, IPSec is not supported on the Cisco RSP3 module.
- Default and untagged encapsulation types are not supported in an Ethernet service instance where a QoS policy is applied. See [CSCuu19619](#) for more information.
- VT PMON is not supported.
- APS is supported across interface modules. But it is not supported on the same interface module.

- VT loopback is not supported if T1 is configured for the VT mode.
- DS1/DS3 SF/SD is not supported.
- Alternate 0's and 1's BERT pattern is not supported for DS1.
- All zeros BERT pattern on system side does not get in sync on DS3.
- DS3/OCx MDL does not interoperate with legacy Q.921 standards.
- APM is not supported with EPAR on CEP.
- FDL is not supported.
- STS24-c is not supported on 1-port OC-192 or 8-port low rate CEM interface module.
- Port restriction on 1-port OC-192 or 8-port low rate CEM interface module. If you have OC-48 configured on a port, you cannot use the neighboring port.
- Bellcore remote loopbacks are not supported for DS1/DS3. Only T1.403 remote loopbacks are supported.
- CEP MIB is not supported.
- HSPW is not supported on DS3/DS1/OCX card.
- The **ip cef accounting** command is not supported on the chassis.
- A system crash may be observed on the chassis when EoMPLS, CEM, ATM, and IMA Pseudowire Redundancy (PW-redundancy) configurations exist while switchover and fail back of the pseudowires are being triggered, and the **show platform hardware pp active pw eompls** command is executed.
- Configuration sync does not happen on the Standby RSP when the active RSP has Cisco Software Licensing configured, and the standby RSP has Smart Licensing configured on the chassis. If the active RSP has Smart Licensing configured, the state of the standby RSP is undetermined. The state could be pending or authorized as the sync between the RSP modules is not performed.
- Evaluation mode feature licenses may not be available to use after disabling, and enabling the smart licensing on the Cisco NCS 4206. A reload of the chassis is required.
- Ingress counters are not incremented for packets as shown in the format below on the RSP3 module for the 10 Gigabit Ethernet interfaces, 100 Gigabit Ethernet interfaces, and 40 Gigabit Ethernet interfaces:  
Packet format  
MAC header---->Vlan header---->Length/Type  
When these packets are received on the RSP3 module, the packets are not dropped, but the counters are not incremented.
- T1 SAToP, T3 SAToP, and CT3 are supported on an UPSR ring only with local connect mode. Cross connect of T1, T3, and CT3 circuits to UPSR are not supported.
- DCC is supported only on PPP encapsulation. It is not supported on CLNS encapsulation.
- If oversubscription is enabled on 8-port 10 Gigabit Ethernet interface module, PTP is not supported.
- Effective with Cisco IOS XE Everest 16.6.1, the Port-channel (PoCH) scale is reduced to 24 from 48 for Cisco ASR 900 RSP3 module.



---

**Note** The PoCH scale for Cisco NCS 4216 routers is 48.

---

- Remote loopback under STS1E controllers is not supported in Cisco IOS XE Release 16.12.5.

## Determining the Software Version

You can use the following commands to verify your software version:

- Consolidated Package—**show version**
- Individual sub-packages—**show version installed** (lists all installed packages)

## Upgrading to a New Software Release

Only Cisco IOS XE 3S consolidated packages can be downloaded from Cisco.com; users who want to run the chassis using individual subpackages must first download the image from Cisco.com and extract the individual subpackages from the consolidated package.

### ROMMON Version

For software upgrade later than the Cisco IOS XE 16.9.x release, it is mandatory that you upgrade the ROMMON version to 15.6(49r)S.

## Supported FPGA Versions for NCS 4206 and NCS 4216

Use the **show hw-module all fpd** command to display the IM FPGA version on the chassis.

Use the **show platform software agent iomd [slot/subslot] firmware cem-fpga** command to display the CEM FPGA version on the chassis.

The table below lists the FPGA version for the software releases.



---

**Note** During ISSU, TDM interface modules are reset for FPGA upgrade.

---



Table 5: Supported FPGA Versions for NCS 4206-RSP3 and NCS 4216

	Cisco IOS XE Release	48 X T1/E1 CEM Interface Module FPGA	48 X T3/E3 CEM Interface Module FPGA	OC-192 Interface Module + 8-port Low Rate Interface Module FPGA	NCS 4200-1T8S-20CS	NCS4200-3GMS	8x10G FPGA	2x40G FPGA	1x100G FPGA
IM FPGA	3.18SP	1.22	1.22	1.12	—	—	0.17 (0x1100 H)	0.22 (0x1600 H)	0.19 (0x1300 H)
CEM FPGA		4.6	4.6	6.6	—	—	—	—	—
IM FPGA	3.18.1SP	1.22	1.22	1.12	—	—	0.17 (0x1100 H)	0.22 (0x1600 H)	0.19 (0x1300 H)
CEM FPGA		4.6	4.6	7.0	—	—	—	—	—
IM FPGA	16.5.1	1.22	1.22	1.15	—	—	0.21 (0x1500 H)	0.22 (0x1600 H)	0.20 (0x1400 H)
CEM FPGA		0x46310046	0x46310046	5G mode: 0x10070059  10G mode: 0x10050073	—	—	—	—	—
IM FPGA	16.6.1	1.22	1.22	1.15	—	—	0.21 (0x1500 H)	0.22 (0x1600 H)	0.20 (0x1400 H)
CEM FPGA		0x46310046	0x46310046	5G mode: 0x10070059  10G mode: 0x10050073	—	—	—	—	—
IM FPGA	16.7.1	1.22	1.22	1.15	—	2.0	0.21 (0x1500 H)	0.22 (0x1600 H)	0.20 (0x1400 H)
CEM FPGA		0x46410046	0x46410046	5G mode: 0x10780059  10G mode: 0x10120076	—	0x10230039	—	—	—

	Cisco IOS XE Release	48 X T1/E1 CEM Interface Module FPGA	48 X T3/E3 CEM Interface Module FPGA	OC-192 Interface Module + 8-port Low Rate Interface Module FPGA	NCS 4200-1T8S-20CS	NCS4200-3GMS	8x10G FPGA	2x40G FPGA	1x100G FPGA
IM FPGA	16.8.1	1.22	1.22	1.15	—	2.0	0.22	0.22	0.20
CEM FPGA		0x46470046	0x46470046	5G mode: 0x10780059 10G mode: 0x10670075	—	0x10380039	—	—	—
IM FPGA	16.9.1	1.22	1.22	1.15	—	2.0	0.22	0.22	0.20
CEM FPGA		0x50090050	0x50060050	5G mode: 0x10070062 10G mode: 0x10480078	—	0x10520063	—	—	—
IM FPGA	16.10.1	1.22	1.22	1.15	—	2.0	0.22	0.22	0.20
CEM FPGA		0x50090050	0x50060050	5G mode: 0x10070062 10G mode: 0x10480078	—	0x10520063	—	—	—
IM FPGA	16.11.1	1.22	1.22	1.15	—	2.0	0.22	0.22	0.20
CEM FPGA		0x00000051	0x00000051	5G mode: 0x10180062 10G mode: 0x10510078	—	0x10820063	—	—	—
IM FPGA	16.12.1	1.22	1.22	1.15	0.80	2.0	0.22	0.22	0.20
CEM FPGA		0x00000051	0x00000051	5G mode: 0x10180062 10G mode: 0x10510078	10G mode: 0x10260046 20G mode: 0x10710047	0x10050071	—	—	—

	Cisco IOS XE Release	48 X T1/E1 CEM Interface Module FPGA	48 X T3/E3 CEM Interface Module FPGA	OC-192 Interface Module + 8-port Low Rate Interface Module FPGA	NCS 4200-1T8S-20CS	NCS4200-3GMS	8x10G FPGA	2x40G FPGA	1x100G FPGA
IM FPGA	16.12.2	1.22	1.22	1.15	0.80	2.0	0.22	0.22	0.20
CEM FPGA		0x00000051	0x00000051	5G mode: 0x10180062 10G mode: 0x10510078	10G mode: 0x10260046 20G mode: 0x10710047	0x10050071	—	—	—
IM FPGA	16.12.3	0x00000051	0x00000051	1.15	0.80	2.0	0.22	0.22	0.20
CEM FPGA		1.22	1.22	5G mode: 0x10180062 10G mode: 0x10510078	10G mode: 0x10260046 20G mode: 0x10710047	0x10050071	—	—	—
IM FPGA	16.12.4	1.22	1.22	1.15	0.86	2.0	—	—	—
CEM FPGA		0x00000051	0x00000051	0x10510078	0x10260046	0x10050071	—	—	—
IM FPGA	16.12.5	1.22	1.22	1.15	0.86	2.0	—	—	—
CEM FPGA		0x00000051	0x00000051	0x10510078	0x10260046	0x10050071	—	—	—
IM FPGA	16.12.6	1.22	1.22	1.15	0.93	2.0	—	—	—
CEM FPGA		0x00000051	0x00000051	0x10510078	0x10260046	0x10050071	—	—	—
IM FPGA	16.12.7	1.22	1.22	1.15	0.93	2.0	—	—	—
CEM FPGA		0x00000051	0x00000051	0x10510078	0x10260046	0x10050071	—	—	—

	Cisco IOS XE Release	48 X T1/E1 CEM Interface Module FPGA	48 X T3/E3 CEM Interface Module FPGA	OC-192 Interface Module + 8-port Low Rate Interface Module FPGA	NCS 4200-1T8S-20CS	NCS4200-3GMS	8x10G FPGA	2x40G FPGA	1x100G FPGA
IM FPGA	16.12.8	1.22	1.22	1.15	0.93	2.0	—	—	—
CEM FPGA		0x00000051	0x00000051	0x10510078	0x10260046	0x10050071	—	—	—

## Deferrals

Cisco IOS software images are subject to deferral. We recommend that you view the deferral notices at the following location to determine whether your software release is affected:

[http://www.cisco.com/en/US/products/products\\_security\\_advisories\\_listing.html](http://www.cisco.com/en/US/products/products_security_advisories_listing.html).

## Field Notices and Bulletins

- Field Notices—We recommend that you view the field notices for this release to determine whether your software or hardware platforms are affected. You can find field notices at [http://www.cisco.com/en/US/support/tsd\\_products\\_field\\_notice\\_summary.html](http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html).
- Bulletins—You can find bulletins at [http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod\\_literature.html](http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod_literature.html).

## MIB Support

The below table summarizes the supported MIBs on the Cisco NCS 4206 and Cisco NCS 4216.

Supported MIBs		
BGP4-MIB (RFC 1657)	CISCO-IMAGE-LICENSE-MGMT-MIB	MPLS-LDP-STD-MIB (RFC 3815)
CISCO-BGP-POLICY-ACCOUNTING-MIB	CISCO-IMAGE-MIB	MPLS-LSR-STD-MIB (RFC 3813)
CISCO-BGP4-MIB	CISCO-IPMROUTE-MIB	MPLS-TP-MIB
CISCO-BULK-FILE-MIB	CISCO-LICENSE-MGMT-MIB	MSDP-MIB
CISCO-CBP-TARGET-MIB	CISCO-MVPN-MIB	NOTIFICATION-LOG-MIB (RFC 3014)
CISCO-CDP-MIB	CISCO-NETSYNC-MIB	OSPF-MIB (RFC 1850)
CISCO-CEF-MIB	CISCO-OSPF-MIB (draft-ietf-ospf-mib-update-05)	OSPF-TRAP-MIB (RFC 1850)

<b>Supported MIBs</b>		
CISCO-CLASS-BASED-QOS-MIB	CISCO-OSPF-TRAP-MIB (draft-ietf-ospf-mib-update-05)	PIM-MIB (RFC 2934)
CISCO-CONFIG-COPY-MIB	CISCO-PIM-MIB	RFC1213-MIB
CISCO-CONFIG-MAN-MIB	CISCO-PROCESS-MIB	RFC2982-MIB
CISCO-DATA-COLLECTION-MIB	CISCO-PRODUCTS-MIB	RMON-MIB (RFC 1757)
CISCO-EMBEDDED-EVENT-MGR-MIB	CISCO-PTP-MIB	RSVP-MIB
CISCO-ENHANCED-MEMPOOL-MIB	CISCO-RF-MIB	SNMP-COMMUNITY-MIB (RFC 2576)
CISCO-ENTITY-ALARM-MIB	CISCO-RTTMON-MIB	SNMP-FRAMEWORK-MIB (RFC 2571)
CISCO-ENTITY-EXT-MIB	CISCO-SONET-MIB	SNMP-MPD-MIB (RFC 2572)
CISCO-ENTITY-FRU-CONTROL-MIB	CISCO-SYSLOG-MIB	SNMP-NOTIFICATION-MIB (RFC 2573)
CISCO-ENTITY-SENSOR-MIB	DS1-MIB (RFC 2495)	SNMP-PROXY-MIB (RFC 2573)
CISCO-ENTITY-VENDORTYPE-OID-MIB	ENTITY-MIB (RFC 4133)	SNMP-TARGET-MIB (RFC 2573)
CISCO-FLASH-MIB	ENTITY-SENSOR-MIB (RFC 3433)	SNMP-USM-MIB (RFC 2574)
CISCO-FTP-CLIENT-MIB	ENTITY-STATE-MIB	SNMPv2-MIB (RFC 1907)
CISCO-IETF-ISIS-MIB	EVENT-MIB (RFC 2981)	SNMPv2-SMI
CISCO-IETF-PW-ATM-MIB	ETHERLIKE-MIB (RFC 3635)	SNMP-VIEW-BASED-ACM-MIB (RFC 2575)
CISCO-IETF-PW-ENET-MIB	IF-MIB (RFC 2863)	SONET-MIB
CISCO-IETF-PW-MIB	IGMP-STD-MIB (RFC 2933)	TCP-MIB (RFC 4022)
CISCO-IETF-PW-MPLS-MIB	IP-FORWARD-MIB	TUNNEL-MIB (RFC 4087)
CISCO-IETF-PW-TDM-MIB	IP-MIB (RFC 4293)	UDP-MIB (RFC 4113)
CISCO-IF-EXTENSION-MIB	IPROUTE-STD-MIB (RFC 2932)	CISCO-FRAME-RELAY-MIB
CISCO-IGMP-FILTER-MIB	MPLS-LDP-GENERIC-STD-MIB (RFC 3815)	

The below table summarizes the unverified and supported MIBs on the Cisco NCS 4206 and Cisco NCS 4216.

<b>Unverified MIBs</b>		
ATM-MIB	CISCO-IETF-DHCP-SERVER-EXT-MIB	EXPRESSION-MIB
CISCO-ATM-EXT-MIB		HC-ALARM-MIB
CISCO-ATM-IF-MIB	CISCO-IETF-PPVPN-MPLS-VPN-MIB	HC-RMON-MIB
CISCO-ATM-PVC-MIB	CISCO-IP-STAT-MIB	IEEE8021-CFM-MIB
CISCO-ATM-PVCTRAP-EXTN-MIB	CISCO-IPSLA-ETHERNET-MIB	IEEE8021-CFM-V2-MIB

Unverified MIBs		
CISCO-BCP-MIB	CISCO-L2-CONTROL-MIB	IEEE8023-LAG-MIB
CISCO-CALLHOME-MIB	CISCO-LAG-MIB	INT-SERV-GUARANTEED-MIB
CISCO-CIRCUIT-INTERFACE-MIB	CISCO-MAC-NOTIFICATION-MIB	INTEGRATED-SERVICES-MIB
CISCO-CONTEXT-MAPPING-MIB	CISCO-MEMORY-POOL-MIB	MPLS-L3VPN-STD-MIB (RFC 4382)
CISCO-EIGRP-MIB	CISCO-NHRP-EXT-MIB	MPLS-LDP-ATM-STD-MIB (RFC 3815)
CISCO-ERM-MIB	CISCO-NTP-MIB	MPLS-LDP-MIB
CISCO-ETHER-CFM-MIB	CISCO-PING-MIB	MPLS-TE-STD-MIB
CISCO-ETHERLIKE-EXT-MIB	CISCO-RESILIENT-ETHERNET-PROTOCOL-MIB	MPLS-VPN-MIB
CISCO-EVC-MIB	CISCO-RTTMON-ICMP-MIB	NHRP-MIB
CISCO-HSRP-EXT-MIB	CISCO-RTTMON-IP-EXT-MIB	RFC2006-MIB (MIP)
CISCO-HSRP-MIB	CISCO-RTTMON-RTP-MIB	RMON2-MIB (RFC 2021)
CISCO-IETF-ATM2-PVCTRAP-MIB	CISCO-SNMP-TARGET-EXT-MIB	SMON-MIB
CISCO-IETF-ATM2-PVCTRAP-MIB-EXTN	CISCO-TCP-MIB	VRRP-MIB
CISCO-IETF-BFD-MIB	CISCO-VRF-MIB	
CISCO-IETF-DHCP-SERVER-MIB	ETHER-WIS (RFC 3637)	

## MIB Documentation

To locate and download MIBs for selected platforms, Cisco IOS and Cisco IOS XE releases, and feature sets, use Cisco MIB Locator found at the following location: <http://tools.cisco.com/ITDIT/MIBS/servlet/index>

To access Cisco MIB Locator, you must have an account on Cisco.com. If you have forgotten or lost your account information, send a blank e-mail to [cco-locksmith@cisco.com](mailto:cco-locksmith@cisco.com). An automatic check will verify that your e-mail address is registered with Cisco.com. If the check is successful, account details with a new random password will be e-mailed to you. Qualified users can establish an account on Cisco.com by following the directions found at the following location:

<http://tools.cisco.com/RPF/register/register.do>

## Open Source License Notices

For a listing of the license notices for open source software used in Cisco IOS XE 3S Releases, see the documents accessible from the License Information page at the following location:

[http://www.cisco.com/en/US/products/ps11174/products\\_licensing\\_information\\_listing.html](http://www.cisco.com/en/US/products/ps11174/products_licensing_information_listing.html)

# Communications, Services, and Additional Information

- To receive timely, relevant information from Cisco, sign up at [Cisco Profile Manager](#).
- To get the business impact you're looking for with the technologies that matter, visit [Cisco Services](#).
- To submit a service request, visit [Cisco Support](#).
- To discover and browse secure, validated enterprise-class apps, products, solutions and services, visit [Cisco Marketplace](#).
- To obtain general networking, training, and certification titles, visit [Cisco Press](#).
- To find warranty information for a specific product or product family, access [Cisco Warranty Finder](#).

## Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST) is a web-based tool that acts as a gateway to the Cisco bug tracking system that maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. BST provides you with detailed defect information about your products and software.







## CHAPTER 2

# New Features

---

This chapter describes the new hardware and software features supported on the Cisco NCS 4200 Series in this release.

- [New Software Features in Cisco IOS XE Gibraltar 16.12.8, on page 19](#)
- [New Hardware Features in Cisco IOS XE Gibraltar 16.12.8, on page 19](#)
- [New Software Features in Cisco IOS XE Gibraltar 16.12.7, on page 19](#)
- [New Hardware Features in Cisco IOS XE Gibraltar 16.12.7, on page 20](#)
- [New Software Features in Cisco IOS XE Gibraltar 16.12.6, on page 20](#)
- [New Hardware Features in Cisco IOS XE Gibraltar 16.12.6, on page 20](#)
- [New Software Features in Cisco IOS XE Gibraltar 16.12.5, on page 20](#)
- [New Hardware Features in Cisco IOS XE Gibraltar 16.12.5, on page 20](#)
- [New Hardware Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.4, on page 20](#)
- [New Software Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.4, on page 20](#)
- [New Hardware Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.3, on page 21](#)
- [New Software Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.3, on page 21](#)
- [New Hardware Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.2, on page 21](#)
- [New Software Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.2, on page 21](#)
- [New Hardware Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.1, on page 21](#)
- [New Software Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.1, on page 22](#)

## New Software Features in Cisco IOS XE Gibraltar 16.12.8

There are no new software features introduced for Cisco IOS XE Release 16.12.8.

## New Hardware Features in Cisco IOS XE Gibraltar 16.12.8

There are no new hardware features introduced for Cisco IOS XE Release 16.12.8.

## New Software Features in Cisco IOS XE Gibraltar 16.12.7

There are no new software features introduced for Cisco IOS XE Release 16.12.7.

## New Hardware Features in Cisco IOS XE Gibraltar 16.12.7

There are no new hardware features introduced for Cisco IOS XE Release 16.12.7.

## New Software Features in Cisco IOS XE Gibraltar 16.12.6

There are no new software features introduced for Cisco IOS XE Release 16.12.6.

## New Hardware Features in Cisco IOS XE Gibraltar 16.12.6

There are no new hardware features introduced for Cisco IOS XE Release 16.12.6.

## New Software Features in Cisco IOS XE Gibraltar 16.12.5

There are no new software features introduced for Cisco IOS XE Release 16.12.5.

## New Hardware Features in Cisco IOS XE Gibraltar 16.12.5

There are no new hardware features introduced for Cisco IOS XE Release 16.12.5.

## New Hardware Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.4

There are no new features introduced for this release.

## New Software Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.4

- **Configurable Y.1564 Service Activation Frame Sizes and EMIX Support**

Enterprise traffic (EMIX) packet size (default abceg pattern) is supported. For EMIX traffic, ITU-T Rec. Y.1564 packet sizes of 64, 128, 256, 1024, and 1518 bytes are supported.

For more information, see the [IP SLAs Configuration Guide, Cisco IOS XE 17 \(Cisco ASR 4200 Series\)](#).

- **OPTICS: ONS-SI-GE-EX and ONS-SI-GE-LX Support**

The optics, ONS-SI-GE-EX and ONS-SI-GE-LX are supported on the Cisco NCS4200-1T16G-PS interface module.

For more information, see the [Optics Matrix for ASR 900](#).

## New Hardware Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.3

There are no new features introduced for this release.

## New Software Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.3

There are no new features introduced for this release.

## New Hardware Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.2

There are no new features introduced for this release.

## New Software Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.2

There are no new features introduced for this release.

## New Hardware Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.1

- **NCS 4200 1x10 Gigabit MR + 8-Port Low Rate 20 Gigabit CEM, iMSG Interface Module (NCS4200-1T8S-20CS)**

The 1-Port 10 Gigabit MR and 8-Port LR 20 Gigabit CEM and iMSG Interface Module is a cost-effective interface module (IM) that supports CEM features on the OCn interfaces. This interface module is supported on the Cisco NCS 4206 Router, Cisco NCS 4216 Router, and Cisco NCS 4216 F2B Router.

For more information about this IM for any of the supported routers, see the [NCS 4200 Series Aggregation Services Routers Hardware Installation Guides](#).

For more information on Feature Optics Matrix, see the [Cisco NCS 4206-16 Series Aggregation Services Routers Feature Optics Matrix](#).

# New Software Features for NCS 4206 and NCS 4216 in Cisco IOS XE Gibraltar 16.12.1

## • 1-Port 10 Gigabit MR and 8-Port LR 20 Gigabit CEM and iMSG Interface Module Support

The 1-Port 10 Gigabit MR and 8-Port LR 20 Gigabit CEM and iMSG interface module (NCS4200-1T8S-20CS) is supported on the Cisco RSP3 module and has the capability for SONET or SDH termination, SAToP, CESoP, and CEP.

For more information on configuring the NCS4200-1T8S-20CS interface module, see the 1-Port OC-192 or 8-Port Low Rate CEM Interface Module Configuration Guide, Cisco IOS XE Gibraltar 16.12.x (Cisco NCS 4200 Series).



---

**Note** The Multiservice Gateway features are not supported on this IM for Cisco IOS XE Release 16.12.1.

---

## • Five-Tuple Hash Load Balancing Support

The router supports different load balancing hash algorithms with combinations of MAC (Layer 2) or IP (Layer 3) headers on the RSP3 platform to find the hash key. The five-Tuple hash algorithm on RSP3 includes protocol field and Layer 4 port numbers while calculating the hash key.

For more information, see the [Ethernet Channel Configuration Guide Cisco IOS XE Gibraltar 16.12.x \(Cisco NCS 4200 Series\)](#).

## • Generic Routing Encapsulation (GRE) Feature Updates

Generic Routing Encapsulation (GRE) tunneling protocol provides a simple generic approach to transport packets of one protocol over another protocol by means of encapsulation.

GRE supports the following features:

- IPv4 or IPv6 Global over GRE (IPv4 Core)
- VRF Lite over GRE

For more information on GRE, see the [MPLS: Layer 3 VPNs Configuration Guide, Cisco IOS XE Gibraltar 16.12.x \(Cisco NCS 4200 Series\)](#)

## • Maximum Transmission Unit Support on Bridge Domain Interface

On the Cisco RSP3 module, filtering of IP packets and MPLS-IP packets that egress out Bridge Domain Interface (BDI) is performed based on the Maximum Transmission Unit (MTU) value of the physical interface. The constraint where the BDI inherits the physical interface's MTU causes a limitation, for example, fragmentation or dropping of packets, during network deployments. To avoid such limitation, ensure that you configure BDI MTU.

For more information on BDI MTU support, see the [Carrier Ethernet Configuration Guide, Cisco IOS XE Gibraltar 16.12.x \(Cisco NCS 4200 Series\)](#).

## • MPLS Layer 3 VPN Conditional Marking

The MPLS Layer 3 conditional marking feature marks the traffic with appropriate QoS group and sets policer to mark the color (discard class) based on Committed Information Rate (CIR) and Peak Information Rate (PIR) values. You can use the QoS group to create ingress policy map.

For more information to configure MPLS Layer 3 VPN conditional marking, see the [Quality of Service Configuration Guidelines, Cisco IOS XE Gibraltar 16.12.x \(Cisco NCS4200 Series\)](#).

- **Pseudowire Scale Support**

Effective from the Cisco IOS XE 16.12.x release, CEM scale of 21504 pseudowires is supported on the Cisco routers.

For more information on the pseudowire scale support, see the [1-Port OC-192 or 8-Port Low Rate CEM Interface Module Configuration Guide, Cisco IOS XE Gibraltar 16.12.x \(Cisco NCS 4200 Series\)](#).

- **QoS Short-pipe Mode**

QoS short-pipe mode is supported on the RSP3 module. You can enable this feature using the SDM template.

You can identify the egress traffic on an interface or on EVC and classify based on DSCP, mark qos-group, and color using the **platform table-map** command.

For more information on how to enable short-pipe mode, see the [Quality of Service Configuration Guidelines, Cisco IOS XE Gibraltar 16.12.x \(Cisco NCS 4200 Series\)](#).

- **Segment Routing uLoop Avoidance**

The Segment Routing uLoop Avoidance feature prevents the occurrences of microloops during network convergence after a link-down event or link-up event.

For more information, see the [Segment Routing Configuration Guide, Cisco IOS XE Gibraltar 16.12.x \(Cisco NCS 4200 Series\)](#).





## CHAPTER 3

# Caveats

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The “Open Caveats” sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.
- The “Resolved Caveats” sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.



**Note** The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- [Cisco Bug Search Tool, on page 26](#)
- [Open Caveats - Cisco IOS XE Gibraltar 16.12.8, on page 26](#)
- [Resolved Caveats - Cisco IOS XE Gibraltar 16.12.8, on page 26](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.7, on page 26](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.7, on page 26](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.6, on page 27](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.6 - Platform Independent, on page 28](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.6, on page 28](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.6 – Platform Independent, on page 29](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.5, on page 29](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.5 - Platform Independent, on page 30](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.5, on page 30](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.5 - Platform Independent, on page 32](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.4, on page 32](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.4 - Platform Independent, on page 33](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.4, on page 33](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.4 - Platform Independent, on page 33](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.3, on page 33](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.3, on page 34](#)
- [Open Caveats – Cisco IOS XE Gibraltar 16.12.2a, on page 35](#)
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.2a, on page 37](#)

- [Open Caveats – Cisco IOS XE Gibraltar 16.12.1](#), on page 39
- [Resolved Caveats – Cisco IOS XE Gibraltar 16.12.1a](#), on page 40

## Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at <http://www.cisco.com/web/applicat/cbsshelp/help.html>

## Open Caveats - Cisco IOS XE Gibraltar 16.12.8

There are no open caveats for this release.

## Resolved Caveats - Cisco IOS XE Gibraltar 16.12.8

Identifier	Headline
<a href="#">CSCwb26335</a>	RSP3:Error reading data from the table dmi-general: Could not get boolean value for feature.side_effect_sync.
<a href="#">CSCwa79398</a>	rs232 service on port-8 gives SLIP errors when databits is set on other ports.

## Open Caveats – Cisco IOS XE Gibraltar 16.12.7

Identifier	Headline
<a href="#">CSCvx34215</a>	APS 1+1 Uni - Traffic hit due to sonet controllers down after inactive IMOIR then SSO.

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.7

Caveat ID Number	Description
<a href="#">CSCwa35351</a>	Memory leak observed in tcp raw-socket when L1 is down



## Open Caveats – Cisco IOS XE Gibraltar 16.12.6

Caveat ID Number	Description
<a href="#">CSCvo36974</a>	Traffic drop is observed over IPSEC with dynamic modification in IPSEC tunnel and route
<a href="#">CSCvq68615</a>	SRTE: Complete traffic drops for prefixes with 2 Transport + 2 service Labels.
<a href="#">CSCvq93254</a>	After ipv6 nd cache expired, transit traffic fails when ECMP enabled
<a href="#">CSCvr25131</a>	VZ-WRT -V171-dcc1 -After reload the SDC interface is down
<a href="#">CSCvs04458</a>	RS485 - Show running-config output does not display the duplex mode config details
<a href="#">CSCvs21550</a>	The <b>snmpwalk</b> command is not retrieving vt description in mode vt-15.
<a href="#">CSCvs35755</a>	CEM ACR: shut/no shut on physical sonet controller is causing path to go down
<a href="#">CSCvs82744</a>	Shutting one BDI is affecting traffic on other tunnels
<a href="#">CSCvu31005</a>	Enable L-bit propagation in framed SATOP for LOF alarm
<a href="#">CSCvu38228</a>	High convergence time seen over port-channel switchover for CEM-TDM traffic
<a href="#">CSCvv58669</a>	ROMMON region 0 and 1 verification CLI
<a href="#">CSCvv92835</a>	APS full scale OC192 - Traffic outage after IMOIR as IM goes to out of service and CPUHOG
<a href="#">CSCvw85788</a>	BFD flaps due to ARP packet loss when other non priority classes congested
<a href="#">CSCvx32380</a>	RSP3: SFP GLC-FE-100LX-RGD show incorrect description
<a href="#">CSCvx84476</a>	RSP3: FATAL crash happening with Mcast MVPN profile 0 scenario when hardware resources exhausted.
<a href="#">CSCvy75452</a>	SYNLOSS on client port of 100G-CK-C after interface flap
<a href="#">CSCvy82376</a>	IMs on slots 13, 14 and 15 out of service on ASR-907 chassis
<a href="#">CSCvy91436</a>	Egress QoS classification issues with Service instance 2 configuration on CE facing interfaces
<a href="#">CSCvz02262</a>	TCAM corruption happening at bank boundary when one of the bank is full.
<a href="#">CSCvz07477</a>	DWDM SFPs threshold Value set to 0.0 dbm for RX/TX and -0.0 C for temperature. Version 16.12.4
<a href="#">CSCvz18784</a>	Ingress QoS policer not freed upon interface going down causing POLICERD leak
<a href="#">CSCvz19022</a>	RSP3C 16.9.3 and 16.12.3 ping issue with MTU greater than 1508
<a href="#">CSCvy34396</a>	MAC table inconsistency due to parity error

## Open Caveats – Cisco IOS XE Gibraltar 16.12.6 - Platform Independent

Caveat ID Number	Description
<a href="#">CSCvy78284</a>	The router crashes when zeroised RSA key is regenerated

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.6

Caveat ID Number	Description
<a href="#">CSCvv72192</a>	IMA2Z IM, xfp and sfp+ are present then XFP is removed LED still shows as green
<a href="#">CSCvv99456</a>	ACL entries with FRAGMENT keywords are not working on the ASR920 platform
<a href="#">CSCvw46012</a>	Traffic not passing via BDI after physical interface flaps
<a href="#">CSCvx07262</a>	[RSP3-DHCP-Relay]: dhcp relay unicast is dropped in transparent case with HSRP/VRRP/GLBP on EVC-BD
<a href="#">CSCvx08446</a>	show recovered-clock output shows Type as T1/E1 in RSP2
<a href="#">CSCvx55831</a>	Ingress Policy with set qos-group action is creating extra TCAM entry with match on Egress Policy
<a href="#">CSCvx63370</a>	With channelized T3 mode after IM OIR alarm clear/assert not happening for first T1.
<a href="#">CSCvx69665</a>	ASR903-RSP3: Continuous Ipv6 Neighbor addition retries exhausting the platform resources.
<a href="#">CSCvy23345</a>	ASR90X-RSP3: MAC address is getting learned for L2CP control frames over the G.8032 Blocked port
<a href="#">CSCvy25392</a>	Cannot delete recovered clock configuration from STS-3c
<a href="#">CSCvy26121</a>	Object down failures observed on ASR903 devices post upgrade to 16.12.3
<a href="#">CSCvy29290</a>	ASR90x-RSP3 : Pending objects for BDI Tx Channel on creation of Port channel with member link
<a href="#">CSCvy51848</a>	Active RP HW gone bad during an IO FPGA Upgrade and Standby started booting in Loop
<a href="#">CSCvy50955</a>	CEM traffic not resuming after IM shut/unshut with service inst on Gig created when TDM IM is shut
<a href="#">CSCvv40968</a>	The cman_fp process crashed while booting up
<a href="#">CSCvx92879</a>	IMA8T1Z is going for continuous reload with IM authentication error message

Caveat ID Number	Description
<a href="#">CSCvv73547</a>	Router crashed fib_loadinfo_max_oce_idx
<a href="#">CSCvx64624</a>	Default buffer length needs to be adjusted in latest releases

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.6 – Platform Independent

Caveat ID Number	Description
<a href="#">CSCvx19209</a>	ISIS crash in isis_sr_tilfa_compute_protection
<a href="#">CSCvx37945</a>	Crash happened when uea_mgr was trying to write an error log
<a href="#">CSCvy20783</a>	The <b>show run all</b> command does not list default value for debugging

## Open Caveats – Cisco IOS XE Gibraltar 16.12.5

Caveat ID Number	Description
<a href="#">CSCvm84355</a>	LinkDown trap should not be sent when the port is in AINS mode
<a href="#">CSCvp12250</a>	caam_jr and asfctrl error logs are observed with IPsec configuration on certain conditions
<a href="#">CSCvs21550</a>	<b>snmpwalk</b> command does not retrieve VT description in mode vt-15
<a href="#">CSCvs44915</a>	PATH TRACE BUFFER : UNSTABLE attriibute is shown under show controller
<a href="#">CSCvs47204</a>	IPSEC - Kernel crash is observed on reload with traffic
<a href="#">CSCvs52712</a>	REDUNDANCY-3-STANDBY_LOST: Standby processor fault (KEEPALIVE_FAILURE)
<a href="#">CSCvs74016</a>	Kernel Crash XFRM State lookup
<a href="#">CSCvs74471</a>	Crypto Session is down post SSO event
<a href="#">CSCvs82744</a>	Shutting 1 BDI affects traffic on other tunnels
<a href="#">CSCvw86859</a>	Router may not load-balance traffic on MPLS links even having ECMP in RIB/CEF
<a href="#">CSCvt42842</a>	Flood of SKB is received from Kernel and cannot find SA kernel logs
<a href="#">CSCvu51238</a>	Kernel log messages are seen on the console while doing config replace & interface flap

Caveat ID Number	Description
<a href="#">CSCvv72192</a>	When IMA2Z IM, XFP and SFP+ are present and then XFP is removed, LED still shows as green

## Open Caveats – Cisco IOS XE Gibraltar 16.12.5 - Platform Independent

Caveat ID Number	Description
<a href="#">CSCvp98693</a>	MLPPP IPV4 IW: Range for the MLPPP group numbers does not match in the configuring CLIs
<a href="#">CSCvr39157</a>	Cisco RSP3 Module: Y1731 1DM receive is inactive after delete or add of SLA configuration
<a href="#">CSCvu77385</a>	Full throughput is not working priority shaper percent is > ~40" 4206/4216 over 100g NNI
<a href="#">CSCvv74332</a>	VPLSo BKPW: MAC not is flushed or withdrawn in remote peer on VC swichover from active to standby
<a href="#">CSCvw06702</a>	IP SLA Egress classification is not working

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.5

Caveat ID Number	Description
<a href="#">CSCvn47496</a>	RSP3C Request for overriding restriction: 'MVPN-GRE VRF-SM: RP must be at Encap PE'
<a href="#">CSCvp16947</a>	Router shows CRITICAL alarm when one of the power supplies is missing
<a href="#">CSCvs86113</a>	MAC learning issue results in P2P ping fail or protocols are down
<a href="#">CSCvt35963</a>	Uea_mgr and keealive crashes are observed in a sequence after attempting to enable service-offload
<a href="#">CSCvt42183</a>	Traffic outage is observed due to l2-flood-list failure over multi-active PC QoS
<a href="#">CSCvt58155</a>	Kernel crash is observed bcmINTR rcu_check_callback
<a href="#">CSCvt82525</a>	Router crashes while IPV6 updates prefixes
<a href="#">CSCvt98075</a>	Memory leak is seen on SNMP DG when IGP flaps
<a href="#">CSCvu18276</a>	Standby Cisco RSP3 module crashes during IOS upgrade
<a href="#">CSCvu30972</a>	All readings for Power supply unit reflect as zero though the unit is functional

Caveat ID Number	Description
<a href="#">CSCvu36636</a>	ROMMON region 0 and 1 verification CLI
<a href="#">CSCvu57879</a>	OIR of 48-port T3/E3 CEM Interface Module in bay 12 affects RX traffic of 1-port OC-192 Interface module or 8-port Low Rate Interface Module (ASR 900 Combo 8 port SFP GE and 1 port 10GE IM with CEM, 10G) in bay 0
<a href="#">CSCvu73172</a>	Suppress alarm if one of the power feeds to 900W dual feed PSU is missing
<a href="#">CSCvu95940</a>	Egress QoS policy config missing on PoCh member link flap
<a href="#">CSCvu97978</a>	Cisco RSP2 node crashed with core generation in 16.12 throttle
<a href="#">CSCvv13495</a>	Loopback local is not working on T3 card protection physically connected ports
<a href="#">CSCvv16454</a>	Traffic failure is observed due to MPLS ECMP load-balancing in one of the labelled paths
<a href="#">CSCvv24059</a>	Cylon mgr crash is noticed on RSP when EMPLSINTD is exhausted.
<a href="#">CSCvv51145</a>	Crash is seen on <b>show plat hard pp active feature multicast database ipv4 table label &lt;eos &gt;</b>
<a href="#">CSCvv59312</a>	OC-48 SONET controller status shows UP without receiving signal
<a href="#">CSCvv74342</a>	MAC is not flushed or withdrawn in remote peer on VC swichover from active to standby
<a href="#">CSCvv76949</a>	Op state and Ad state show NA for all slot with Bandwidth command
<a href="#">CSCvv83093</a>	OBFL updation with valid time after NTP Sync in RTC failure case
<a href="#">CSCvv91704</a>	Mac flap is observed when shut or no-shut is executed over ME3400
<a href="#">CSCvv95745</a>	Crash of standby supervisor is observed because of QoS Overhead Accounting
<a href="#">CSCvw04366</a>	Display GNSS Chassis SN instead of PCB SN in show CLIs
<a href="#">CSCvw34109</a>	PTP failure due to LSMPI buffer exhaustion
<a href="#">CSCvw56612</a>	<b>show lic</b> CLI does not show port details
<a href="#">CSCvw57114</a>	IGMP queries are dropped entering a Poch
<a href="#">CSCvw64784</a>	Not able to reuse same clock ID on another controller after deleted clock ID
<a href="#">CSCvw71735</a>	Async Line raw-socket packet-length Configure to 0 on Switchover
<a href="#">CSCvw72143</a>	CPUHOG and Dying GASP related traceback seen on router reload
<a href="#">CSCvw81102</a>	Copy recent standby logs and corefiles to Active

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.5 - Platform Independent

Caveat ID Number	Description
<a href="#">CSCvu23567</a>	RSP3: BGP crash seen on Stand by router when 100 BGP sessions are established.
<a href="#">CSCvu44467</a>	VRRP packets are generated with CS0 marking instead of CS6
<a href="#">CSCvu06475</a>	Segment routing CLI cleanup under OSPF not happening after deleting segment routing from Global
<a href="#">CSCvv07825</a>	SR uloop should only be calculated for best path
<a href="#">CSCvv42663</a>	<b>no snmp trap link-status</b> under serial interface disappear after router reload
<a href="#">CSCvv79677</a>	ASR902-RSP2 crashes after BGP flaps

## Open Caveats – Cisco IOS XE Gibraltar 16.12.4

Caveat ID Number	Description
<a href="#">CSCvn47496</a>	RSP3C Request for overriding restriction "MVPN-GRE VRF-SM: RP must be at Encapsulation PE"
<a href="#">CSCvs08297</a>	Hidden CLI service <b>enable-optics-threshold-clear-notification</b> should be made as normal CLI
<a href="#">CSCvs86109</a>	AG1 - BFD is down over single BDI
<a href="#">CSCvt01049</a>	Description cannot add on ACR STS1/AU4 entities in the SONET/SDH-ACR
<a href="#">CSCvt82525</a>	Router crashes while IPV6 updating prefixes
<a href="#">CSCvu30972</a>	All readings for Power supply unit reflect as zero though the unit is functional
<a href="#">CSCvu36636</a>	ASR900 ROMMON region 0 and 1 verification CLI
<a href="#">CSCvu66126</a>	OC192 APS Group is stuck with Signal Fail condition
<a href="#">CSCvw34109</a>	PTP failure due to LSMPI buffer exhaustion

## Open Caveats – Cisco IOS XE Gibraltar 16.12.4 - Platform Independent

Caveat ID Number	Description
<a href="#">CSCvu37848</a>	Traceback: Processes show 0% usage in show processes CPU platform sorted location

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.4

Caveat ID Number	Description
<a href="#">CSCvs34482</a>	ISSU is not working on Cisco RSP2 nodes
<a href="#">CSCvs71834</a>	Router stops forwarding over VC after dot1.q tag is removed and is added back to service instance
<a href="#">CSCvt61512</a>	DS3 Admin Down Alarm persists in card protected setup
<a href="#">CSCvt64706</a>	CPU HOG occurs due to constant soft-parity errors
<a href="#">CSCvu38550</a>	For VCOP configured with type DS3, Applique type should be Subrate T3 instead of Channelized T3/T1

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.4 - Platform Independent

Caveat ID Number	Description
<a href="#">CSCvs30865</a>	rLFA for LDP causes loss of MPLS traffic after RSP switchover
<a href="#">CSCvt14323</a>	IGMP reports received on mLACP Port-Channel drop incorrectly
<a href="#">CSCvt25458</a>	MPLS TE does not come up when bandwidth is configured on Juniper head end
<a href="#">CSCvs95815</a>	C1111 telnet refused for link-local addresses when using ipv6 access class

## Open Caveats – Cisco IOS XE Gibraltar 16.12.3

Caveat ID Number	Description
<a href="#">CSCvm84355</a>	[SVSP-299]-linkDown trap should not be sent when the port is in AINS mode-[SVSPE-570]

Caveat ID Number	Description
<a href="#">CSCvs54101</a>	OC192 APS: OCx T1 scale setup : alarm gets cleared after SSO
<a href="#">CSCvs71834</a>	Stops forwarding over VC after dot1.q tag is removed and added back to service instance
<a href="#">CSCvs63874</a>	Reworked: Invalid ifindex during notification causing lldp localport table mib walk failure
<a href="#">CSCvs21550</a>	snmpwalk command is not retrieving vt description in mode vt-15
<a href="#">CSCvs43077</a>	R0/0: kernel: pci 0001:0e:00.0: BAR 0: error updating (high 0x00000f != 0x000000)
<a href="#">CSCvw34109</a>	PTP failure due to LSMPI buffer exhaustion

## Open Caveats – Platform Independent

Caveat ID Number	Description
<a href="#">CSCvq76305</a>	AutoRP listener functionality issue
<a href="#">CSCvs30865</a>	rLFA for LDP causes loss of MPLS traffic after RSP switchover
<a href="#">CSCvs58498</a>	High CPU on SNMP engine due to CISCO-CEF-MIB

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.3

Caveat ID Number	Description
<a href="#">CSCvm31596</a>	ASR903 RSP3C-400-S going in hang state
<a href="#">CSCvm38889</a>	New fan tray speed algorithm based upon type of IMs present in the chassis
<a href="#">CSCvq61092</a>	IM keeps reloading or router reloads once silently, beyond 400 CEM circuits on Port 8-OC192
<a href="#">CSCvq64605</a>	RLFA resource leak on FRR create/delete with link flaps
<a href="#">CSCvr28956</a>	Show debug memory leak should not be the part of "show tech" as this is intrusive command
<a href="#">CSCvr50508</a>	Router_RP_0_fman_rp crash on applying conditional crypto debug
<a href="#">CSCvs52494</a>	CRASH: Equipment reboot after "No shut" command is applied on T3 interface having VCOP (smart SFP).
<a href="#">CSCvs74558</a>	IPV6 Traffic causing Broadcast Storm on port with hwid 3
<a href="#">CSCvs39740</a>	User defined dummy pattern implementation and handle AIS alarm during xconnect down.



Caveat ID Number	Description
<a href="#">CSCvr40788</a>	BERT is allowed to run without timeslot option in CESOP mode
<a href="#">CSCvs03541</a>	With framed satop configured, T1 goes into loop on receiving inband loopcode
<a href="#">CSCvs58434</a>	DS1 card prot : Change the fix of CSCvq85371 from AIS to LOS

## Resolved Caveats – Platform Independent

Caveat ID Number	Description
<a href="#">CSCvm79556</a>	MSPW VC down after Switchover (Error Local access circuit is not ready for label advertise)

## Open Caveats – Cisco IOS XE Gibraltar 16.12.2a

Caveat ID Number	Description
<a href="#">CSCvm31596</a>	The router is not responding.
<a href="#">CSCvq08730</a>	With license service offload enable rsp3-200 fails to boot with Crash in PE image
<a href="#">CSCvq11964</a>	SDH : Change mode from TUG-3 to VC4 causes PW provisioning failure
<a href="#">CSCvq64605</a>	RLFA resource leak on FRR create/delete with link flaps
<a href="#">CSCvr61371</a>	BFD remains down when using PBR on BDI/interface
<a href="#">CSCvw34109</a>	PTP failure due to LSMPI buffer exhaustion

## Open Caveats – Platform Independent

Caveat ID Number	Description
<a href="#">CSCux43298</a>	The show interface pseudowire displays invalid peer info
<a href="#">CSCvm79556</a>	RSP3: MSPW VC down after Switchover (Error Local access circuit is not ready for label advertise)
<a href="#">CSCvn86673</a>	Dialer watch not disconnecting the backup link even after the watched route exists in routing table.
<a href="#">CSCvp60827</a>	Delay of 30 sec while creating a new config file for phone using tftp.
<a href="#">CSCvq50202</a>	Class-attributes duplicated after EAP reauthen. in ISG radius proxy scenario
<a href="#">CSCvq65438</a>	Copying config file containing SmartPort macros to run fails

Caveat ID Number	Description
<a href="#">CSCVq69866</a>	HSRPv2 crash whilst retrieving group from received packet
<a href="#">CSCVq76305</a>	ASR900 autoRP listener functionality issue
<a href="#">CSCVq78692</a>	mGRE L3VPN broken after reload
<a href="#">CSCVq93089</a>	Active switch crashed after standby reloaded
<a href="#">CSCVq95479</a>	Parser returning invalid PRC to certain commands
<a href="#">CSCVq96794</a>	VPLS label misprogramming after RSP switchover
<a href="#">CSCvr05504</a>	Dialer interface counter does not correlate to the counter of interfaces bounded to
<a href="#">CSCvr08740</a>	Router crash after receiving EVPN route-type 2 without any ext-community
<a href="#">CSCvr08961</a>	Switch stop responding to CoA
<a href="#">CSCvr18919</a>	9400 SVL - Upon redundancy failover, route being purged on downstream device
<a href="#">CSCvr21440</a>	3850 loops get-response value of object cafSessionClientMacAddress
<a href="#">CSCvr23104</a>	BGP looped update among 3 peers
<a href="#">CSCvr27393</a>	Crash on "BGP Router" process
<a href="#">CSCvr34118</a>	remove login and fix broken command
<a href="#">CSCvr34677</a>	DHCP packets are not encrypted in redundant ip helper setup
<a href="#">CSCvr39868</a>	Unexpected reload when issueing show ip mroute vrf <vrf> verbose
<a href="#">CSCvr40112</a>	Removing pseudowire-class for 1 peer makes all the peers fail.
<a href="#">CSCvr45669</a>	cEdge - Template is not push because of bad-command "no ip domain-name"
<a href="#">CSCvr49439</a>	Multiple encapsulations of packet with L2TP headers crash ASR1K
<a href="#">CSCvr51079</a>	PPPoE session stuck in LCP state due to the wrong invoke of AAA method list.
<a href="#">CSCvr54031</a>	TBs seen with scaled IP SLA configs with "ip sla reset"
<a href="#">CSCvr57022</a>	Routes not removed from routing table when Dialer interface is shut
<a href="#">CSCvr57138</a>	Wrong pointer to next buffer - Catalyst 9300
<a href="#">CSCvr57340</a>	MAB is getting removed from template and causing Authorization failure.
<a href="#">CSCvr61879</a>	static ip addresses not configured for the list message
<a href="#">CSCvr70470</a>	sessmgrd crash with "clear dot1x mac" command
<a href="#">CSCvr73095</a>	After aes encryption is enabled, entering plain aaa dynamic-author keys corrupts key
<a href="#">CSCvr74333</a>	smd memory leak sending radius packets

Caveat ID Number	Description
<a href="#">CSCvr74619</a>	Cat 9000 switch crashes during Authentication Failure of Wired Client
<a href="#">CSCvr75640</a>	LNS crash with Segmentation fault(11) in L2TP mgmt daemon
<a href="#">CSCvr76555</a>	In two redundant RPs, VPDN tunnel did not come up
<a href="#">CSCvr79052</a>	In the cEdge console, 0 does not honor the privilege set in the username.

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.2a

Caveat ID Number	Description
<a href="#">CSCvp78600</a>	V1612:IPSEC_THS Traffic is not happening "hash algorithm ESP-MD5-HMAC" tunnels
<a href="#">CSCvp91087</a>	PRBS/BERT line is not working on pdh de1 of 3GMS IM
<a href="#">CSCvq00404</a>	Beast packets are punted to CPU on the disposition node
<a href="#">CSCvq67129</a>	The router forwards directed broadcast out same interface if uRPF is enabled on BDI

## Resolved Caveats – Platform Independent

Caveat ID Number	Description
<a href="#">CSCts28315</a>	DHCP-pd reflect the Advertised prefix in Request message
<a href="#">CSCvi22263</a>	Crash when IOS is adapting shaping with Adaptive QoS over DMVPN configured
<a href="#">CSCvj76866</a>	Partial Power Failure in Stack Causes Interfaces to Become "shutdown"
<a href="#">CSCvm40566</a>	IP prefix list replacement gets error from IOS side
<a href="#">CSCvo55194</a>	After RSP switchover label imposition was not programmed in Software on APS standby router
<a href="#">CSCvo55783</a>	Pending objects wrt to uRPF on reload or soak script run
<a href="#">CSCvp38407</a>	The "Radius-server attribute 31" command broken on LNS when LAC sends Remote-Id string
<a href="#">CSCvp66281</a>	default ip forward-protocol udp xx changed to no ip forward-protocol udp xx after rollback
<a href="#">CSCvp74674</a>	QoS fails to apply to tunnel2 when underlying tunnel1 reachability change
<a href="#">CSCvp96887</a>	Failed to attach template to Cisco XE SDWAN Rtr if qos-map name changed after policy-map is attached

Caveat ID Number	Description
<a href="#">CSCVq00263</a>	Device crashed @ radius_io_stats_timer_handler due to dynamic-author
<a href="#">CSCVq04828</a>	VRF aware reverse DNS lookup not working
<a href="#">CSCVq04989</a>	Ping between 2 Interfaces is not working , dialer interface is interfering in the ARP Process
<a href="#">CSCVq09061</a>	The .py file check is not done while registering the policy and the error is seen
<a href="#">CSCVq18328</a>	SSH: host_key->name is not null after reload which prevents SSH from starting up
<a href="#">CSCVq29953</a>	IP SLA react for packetloss and successivepacketloss do not set \$_ipsla_react_type in EEM
<a href="#">CSCVq33004</a>	Account logon failing for both direct and indirect lite-session in 16.9.3
<a href="#">CSCVq34893</a>	Template push to CEdge fails when we change the access VLAN on a switchport from VLAN 1
<a href="#">CSCVq35631</a>	Crash due to HTTP Core
<a href="#">CSCVq49721</a>	Telnet access fails when VRF-aware extended VTY ACL is configured
<a href="#">CSCVq54265</a>	Ip bootp server should be disabled by default as a device hardening best practice
<a href="#">CSCVq56114</a>	Crash in IGMP code due to invalid source count in DNS lookup
<a href="#">CSCVq56208</a>	MDT: xpath union operator only outputs data from the left hand expression
<a href="#">CSCVq58265</a>	BGP PIC Repair path broke after link flap
<a href="#">CSCVq58722</a>	Python script register failure when using custom directory instead of Flash
<a href="#">CSCVq59908</a>	Stack crashed after upgrade
<a href="#">CSCVq60252</a>	PBR works although an interface is down.
<a href="#">CSCVq70148</a>	BGP is improperly formatting the BGP ASSET attribute if ASSET attribute length is beyond 255
<a href="#">CSCVq72298</a>	Router crashed on running show policy-map interface <> output command
<a href="#">CSCVq73364</a>	mVPN - Multicast packets dropped and "%MFIB-SW2-3-MFIB_CTXT_DEPTH_EXCEEDED" printed continuously
<a href="#">CSCVq89252</a>	IP SLA for Path-Jitter returning a value which isn't defined by the MIB
<a href="#">CSCVq94679</a>	[SDA] Crash due to Segmentation fault(11), Process = ARP Input
<a href="#">CSCVq95645</a>	WLC crashed due to Memory Corruption
<a href="#">CSCVq97365</a>	2 interfaces of client in different vrf connected to same vlan of server not able to get ip via dhcp

Caveat ID Number	Description
<a href="#">CSCvr00183</a>	AAA accounting issue after router reload when mGRE and L3VPN configured
<a href="#">CSCvr00344</a>	"ip access-list logging hash-generation" removes ACL statements upon reload
<a href="#">CSCvr02957</a>	Re-add app-hosting move support - removed in v16.12.1
<a href="#">CSCvr05406</a>	LISP Map-cache not updated correctly after wired Host-mobility
<a href="#">CSCvr09014</a>	IGP metric not detected MPLS TE topology
<a href="#">CSCvr13213</a>	Session unauthorized as Redirect ACL Failure. Failed attribute name POSTURE_REDIRECT.
<a href="#">CSCvr36887</a>	WLC crashes by wncd process when modifying AAA configs from WebUI

## Open Caveats – Cisco IOS XE Gibraltar 16.12.1

Caveat ID Number	Description
<a href="#">CSCvm31596</a>	ASR903 RSP3C-400-S stops responding
<a href="#">CSCvp78600</a>	V1612:IPSEC_THS Traffic is not happening "hash algorithm ESP-MD5-HMAC" tunnels
<a href="#">CSCvp91087</a>	PRBS/BERT line is not working on pdh de1 of 3GMS IM
<a href="#">CSCvn27921</a>	LPPS TE Absolute Avg Time is failing for N560-IMA2C
<a href="#">CSCvo18347</a>	RSP2:Service impact seen while enabling the netconf-yang model
<a href="#">CSCvp35154</a>	RSP3: arp not getting resolved resulting in back to back BDI ping fail post IM OIR trigger
<a href="#">CSCvp59580</a>	Striker-O DR_10G_PORT_MAP is not correct during SFP OIR
<a href="#">CSCvq00342</a>	Duplicated packets on MVPN deployment on ASR920
<a href="#">CSCvq00404</a>	RSP3: Beast packets are punted to CPU on the disposition node
<a href="#">CSCvq01602</a>	After IPv6 and cache expired, transit traffic fails when ECMP
<a href="#">CSCvq08730</a>	RSP3 :With license service offload enable rsp3-200 fails to boot with Crash in PE image
<a href="#">CSCvq11964</a>	SDH : Change mode from TUG-3 to VC4 causes PW provisioning failure
<a href="#">CSCvq40026</a>	SSFPD memory leak with ONS-SI-PDH-VCOP
<a href="#">CSCvp11822</a>	RSP3 Crash during recursive routing for GRE Tunnel
<a href="#">CSCvp52636</a>	RSP3-903: After doing IM-OIR of A900-IMA8S device, the device stops responding.

Caveat ID Number	Description
<a href="#">CSCvo13032</a>	ROMMON: Invalid USB device handle error while doing dir USB0.
<a href="#">CSCvo36974</a>	Data traffic drop is observed over VRF_AWARE_IPSEC with IPSEC profile removal and addition
<a href="#">CSCvp12219</a>	IKEV1 tunnel goes down even after core port un-shut and comes up again
<a href="#">CSCvp28897</a>	Kernel crash observed with 1500 frame size on core port shut or un-shut on peer
<a href="#">CSCvp61200</a>	VRF AWARE IPSEC - One-way traffic hits tunnel during clear crypto process
<a href="#">CSCvp12250</a>	The error logs such as caam_jr and asfctrl are observed
<a href="#">CSCvw34109</a>	PTP failure due to LSMPI buffer exhaustion

## Resolved Caveats – Cisco IOS XE Gibraltar 16.12.1a

Caveat ID Number	Description
<a href="#">CSCvi93315</a>	RSP2: Cylon_Mgr Crash in Multicast on RP SSO Soak
<a href="#">CSCvj75078</a>	RSP3: IOMD crash @ iomd_bsess_open_callback_retry on new active after RP SSO
<a href="#">CSCvj87085</a>	PTPD crashed after removing the ptp configs, default profile <169>
<a href="#">CSCvk13764</a>	The <b>uea_mgr fault on fp_0_0</b> issue leads to 907 crash on boot-up .
<a href="#">CSCvk32423</a>	IMA8Z 6-port mode, hwidx not created leading to complete traffic drop
<a href="#">CSCvk54023</a>	Convergence delay in active RSP removal
<a href="#">CSCvn19901</a>	After upgrade (318SP2-1671) the router stayed down
<a href="#">CSCvn49741</a>	ASR903/920 cylon_mgr crash.
<a href="#">CSCvn55871</a>	T1 serial interface went down with encapsulation mode as PPP with remote loopback config as iboc.
<a href="#">CSCvn64973</a>	A900-IMA4OS module reload with controller mode change
<a href="#">CSCvn82547</a>	ASR903 : OSPF packets over VPLS are punted to CPU queue 15
<a href="#">CSCvn97073</a>	Serdes release does not happen for OCx IM when moved from slot 14 to slot 12
<a href="#">CSCvo07619</a>	ASR920-BDI IPv6 ping failure_FMFP_OBJ_Download_Failure
<a href="#">CSCvo10847</a>	RSP3:POCH TE-FRR with Min Link less than No of Members Triggers FRR Via FLCD
<a href="#">CSCvo19770</a>	Router crashes at hashtable_get_nth_entry

Caveat ID Number	Description
<a href="#">CSCvo35275</a>	ASR-920:MVPN: Unable to pass high MTU multicast packets-MDT-MTU
<a href="#">CSCvo40953</a>	SDH : Serial interface stay in up/down status for SDH Modes
<a href="#">CSCvo44727</a>	OC-3 port will not clear PUNEQ alarm
<a href="#">CSCvo44745</a>	OCn IM shows as insertable-hw-module in slots where it is not supported in 10G_CEM mode
<a href="#">CSCvo65688</a>	16.9.3-QIP-crete-TOD flaps in Crete (master) when setup is left overnight
<a href="#">CSCvp16487</a>	High CPU utilisation observed for iomd process
<a href="#">CSCvp19127</a>	Card-protection : Channelized T1 circuits fails to pass traffic , after RSP switchover
<a href="#">CSCvp25241</a>	APS group OC48 does not send signal fail indication in K1 byte
<a href="#">CSCvp27918</a>	ASR900 Router should throw out warning when wrong FAN TRAY installed (Module overheat and shut down)
<a href="#">CSCvq08464</a>	ELBORON: Restrict max. supported CESoP PWs to 672 only in 16.12.1 release
<a href="#">CSCvq10257</a>	About incorrect I/F notation when enable qos-overhead-accounting Tengig interface
<a href="#">CSCvo25659</a>	ASR903-RSP3C-400:IMA8s Link set to down as serdes peer is not ready





THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

The documentation set for this product strives to use bias-free language. For purposes of this documentation set, bias-free is defined as language that does not imply discrimination based on age, disability, gender, racial identity, ethnic identity, sexual orientation, socioeconomic status, and intersectionality. Exceptions may be present in the documentation due to language that is hardcoded in the user interfaces of the product software, language used based on standards documentation, or language that is used by a referenced third-party product.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2019–2021 Cisco Systems, Inc. All rights reserved.

