

Release Notes for Cisco Wireless Controllers and Lightweight Access Points for Cisco Wireless Release 8.1.131.0

First Published: November 06, 2015

This release notes document describes what is new in Cisco Wireless Release 8.1.131.0, instructions to upgrade to this release, and open and resolved caveats for this release. Unless otherwise noted, in this document, all Cisco Wireless Controllers are referred to as *Cisco WLCs*, and all Cisco lightweight access points are referred to as *access points* or *Cisco APs*.



For information specific to the Cisco Mobility Express solution, see "Cisco Mobility Express Solution Release Notes" section on page 36.



Revision History

| Modification Date | Modification Details |
|-------------------|---|
| October 10, 2017 | Features Not Supported on Cisco Virtual WLCs, page 25 |
| | - Added Wired Guest. |
| September 14, | Features Not Supported on Cisco Flex 7510 WLCs, page 24 |
| 2016 | Removed: TrustSec SXP from features not supported on Cisco Flex 7510 WLCs section. |
| August 19, 2016 | Guidelines and Limitations, page 11 |
| | - Added information about CSCva84464. |
| August 17, 2016 | Guidelines and Limitations, page 11 |
| | Added this statement: If you downgrade from Release 8.3 to Release 8.1, the Cisco Aironet 1850 Series AP, whose mode prior to the downgrade was Sensor is shown to be in unknown mode after the downgrade. This is because the Sensor mode is not supported in Release 8.1. |
| May 18, 2016 | Open Caveats, page 29 |
| | Added bug: CSCuw48922 - IW 3702: Poor roaming behavior with 2 6M video streams |
| May 17, 2016 | Upgrading to Cisco WLC Software Release 8.1.131.0, page 11 |
| | Added this statement: "If you upgrade from Release 8.0.110.0 to a later release, the config redundancy mobilitymac mac-addr command's setting is removed. You must manually reconfigure the mobility MAC address after the upgrade." |
| February 18, 2016 | • Features Not Supported on Cisco Aironet 1830 and 1850 APs, page 26 |
| | - Added Telnet to the list of unsupported features |

Cisco Wireless Controller and Cisco Lightweight Access Point Platforms

The section contains the following subsections:

- Supported Cisco Wireless Controller Platforms, page 2
- Supported Access Point Platforms, page 3
- Unsupported Cisco Wireless Controller Platforms, page 4

Supported Cisco Wireless Controller Platforms

The following Cisco WLC platforms are supported in this release:

- Cisco 2500 Series Wireless Controllers (Cisco 2504 Wireless Controller)
- Cisco 5500 Series Wireless Controllers (5508 and 5520 Wireless Controllers)

- Cisco Flex 7500 Series Wireless Controllers (Cisco Flex 7510 Wireless Controller)
- Cisco 8500 Series Wireless Controllers (8510 and 8540 Wireless Controllers)
- Cisco Virtual Wireless Controllers on the Cisco Services-Ready Engine (Cisco SRE) or the Cisco Wireless LAN Controller Module for Cisco Integrated Services Routers G2 (UCS-E)

Kernel-based virtual machine (KVM) is supported in Cisco Wireless Release 8.1.131.0 and later releases.

Note

- After KVM is deployed, we recommend that you do not downgrade to a Cisco Wireless release that is older than Release 8.1.131.0.
- Cisco Wireless Controllers for High Availability for Cisco 2504 WLC (no AP SSO support), Cisco 5508 WLC, Cisco 5520 WLC, Cisco Wireless Services Module 2 (Cisco WiSM2), Cisco Flex 7510 WLC, Cisco 8510 WLC, and Cisco 8540 WLC.



AP Stateful switchover (SSO) is not supported on Cisco 2504 WLCs.

- Cisco WiSM2 for Catalyst 6500 Series Switches
- Cisco Mobility Express Solution

For information about features that are not supported on the Cisco WLC platforms, see Features Not Supported on Cisco WLC Platforms, page 23.

Supported Access Point Platforms

The following access point platforms are supported in this release:

- Cisco Aironet 1040 Series Access Points
- Cisco Aironet 1140 Series Access Points
- Cisco Aironet 1260 Series Access Points
- Cisco Aironet 1600 Series Access Points
- Cisco Aironet 1700 Series Access Points
- Cisco Aironet 1830 Series Access Points
- Cisco Aironet 1850 Series Access Points
- Cisco Aironet 2600 Series Access Points
- Cisco Aironet 2700 Series Access Points
- Cisco Aironet 3500 Series Access Points
- Cisco Aironet 3600 Series Access Points
- Cisco Aironet 3700 Series Access Points
- Cisco Aironet 600 Series OfficeExtend Access Points
- Cisco Aironet 700 Series Access Points
- Cisco Aironet 700W Series Access Points
- Cisco AP802 Integrated Access Point

- Cisco AP803 Integrated Access Point
- Cisco ASA 5506W-AP702
- Cisco Aironet 1530 Series Access Points
- Cisco Aironet 1550 Series Access Points
- Cisco Aironet 1570 Series Access Points
- Cisco Industrial Wireless 3700 Series Access Points

Note The Cisco 1040 Series, 1140 Series, and 1260 Series access points have feature parity with Cisco Wireless Release 8.0. Features introduced in Cisco Wireless Release 8.1 and later are not supported on these access points.

For information about features that are not supported on some access point platforms, see Features Not Supported on Access Point Platforms, page 26.



Note

Cisco AP802 is an integrated access point on the Cisco 800 Series Integrated Services Routers (ISRs). For more information about the stock-keeping units (SKUs) for the AP802s and the Cisco ISRs, see the following data sheets:

• AP860:

http://www.cisco.com/c/en/us/products/collateral/routers/800-series-routers/data_sheet_c78_4615 43.html

• AP880:

http://www.cisco.com/c/en/us/products/collateral/routers/887-integrated-services-router-isr/data_s heet_c78_459542.html

http://www.cisco.com/c/en/us/products/collateral/routers/800-series-routers/data_sheet_c78-61348 1.html

http://www.cisco.com/c/en/us/products/collateral/routers/880-3g-integrated-services-router-isr/dat a_sheet_c78_498096.html

http://www.cisco.com/c/en/us/products/collateral/routers/880g-integrated-services-router-isr/data_sheet_c78-682548.html

• AP890:

http://www.cisco.com/c/en/us/products/collateral/routers/800-series-routers/data_sheet_c78-51993 0.html

Before you use a Cisco AP802 series lightweight access point with Cisco Wireless Release 8.1.131.0, you must upgrade the software in the Cisco 880 Series ISRs to Cisco IOS 15.1(4)M or later releases.

Unsupported Cisco Wireless Controller Platforms

The following Cisco Wireless Controller platforms are not supported:

- Cisco 4400 Series Wireless LAN Controller
- Cisco 2100 Series Wireless LAN Controller
- Cisco Catalyst 3750G Integrated Wireless LAN Controller

- Cisco Wireless Controller software for Cisco SRE Internal Services Module (ISM) 300, Cisco SRE Service Module (SM) 700, Cisco SRE Service Module (SM) 710, Cisco SRE Service Module (SM) 900, and Cisco SRE Service Module (SM) 910.
- Cisco Catalyst 6500 Series and 7600 Series WiSM
- Cisco Wireless LAN Controller Module (NM/NME)

What's New in This Release

Cisco Hyperlocation

Cisco Hyperlocation is an ultra-precise location solution that attaches to the back of your Cisco Aironet 3700i and 3600i Series wireless access points. It combines Wi-Fi and Bluetooth Low Energy (BLE) technologies to pinpoint beacons, inventory, and personal mobile devices. While some other networks use multiple access points to get location coordinates within 5 to 7 meters of accuracy, Cisco Hyperlocation can track locations to within a single meter.

You can integrate Cisco Hyperlocation with other Cisco wireless solutions for additional uses. Combining it with Cisco Connected Mobile Experiences (CMX), for instance, can result in more precise location analytics that help you deliver more targeted content to users. When you use CMX with Cisco CleanAir® frequency scanning, it's simple to locate failed, lost, and even rogue beacons.

For more information about Cisco Hyperlocation, see the following documents:

- Cisco CMX Release Notes
- The Hyperlocation section in the Cisco Wireless Controller Configuration Guide

Software Release Support for Access Points

Table 2 lists the Cisco WLC software releases that support specific Cisco access points. The First Support column lists the earliest Cisco WLC software release that supports the corresponding access point. For APs that are not supported in ongoing releases, the Last Support column lists the last release that supports the corresponding APs.



Third-party antennas are not supported with Cisco indoor APs.

| Access Points | | First Support | Last Support |
|---------------|-------------------|---------------|--------------|
| 700 Series | AIR-CAP702I-x-K9 | 7.5.102.0 | — |
| | AIR-CAP702I-xK910 | 7.5.102.0 | — |
| 700W Series | AIR-CAP702Wx-K9 | 7.6.120.0 | _ |
| | AIR-CAP702W-xK910 | 7.6.120.0 | — |

| Table 2 | Software Support for Access Points |
|---------|------------------------------------|
|---------|------------------------------------|

| Access Points | | First Support | Last Support |
|---------------|--------------------|---------------|--------------|
| 1000 Series | AIR-AP1010 | 3.0.100.0 | 4.2.209.0 |
| | AIR-AP1020 | 3.0.100.0 | 4.2.209.0 |
| | AIR-AP1030 | 3.0.100.0 | 4.2.209.0 |
| | Airespace AS1200 | | 4.0 |
| | AIR-LAP1041N | 7.0.98.0 | _ |
| | AIR-LAP1042N | 7.0.98.0 | _ |
| 1100 Series | AIR-LAP1121 | 4.0.155.0 | 7.0.x |
| 1130 Series | AIR-LAP1131 | 3.1.59.24 | 8.0.x |
| 1140 Series | AIR-LAP1141N | 5.2.157.0 | _ |
| | AIR-LAP1142N | 5.2.157.0 | _ |
| 1220 Series | AIR-AP1220A | 3.1.59.24 | 7.0.x |
| | AIR-AP1220B | 3.1.59.24 | 7.0.x |
| 1230 Series | AIR-AP1230A | 3.1.59.24 | 7.0.x |
| | AIR-AP1230B | 3.1.59.24 | 7.0.x |
| | AIR-LAP1231G | 3.1.59.24 | 7.0.x |
| | AIR-LAP1232AG | 3.1.59.24 | 7.0.x |
| 1240 Series | AIR-LAP1242G | 3.1.59.24 | 8.0.x |
| | AIR-LAP1242AG | 3.1.59.24 | 8.0.x |
| 1250 Series | AIR-LAP1250 | 4.2.61.0 | 8.0.x |
| | AIR-LAP1252G | 4.2.61.0 | 8.0.x |
| | AIR-LAP1252AG | 4.2.61.0 | 8.0.x |
| 1260 Series | AIR-LAP1261N | 7.0.116.0 | _ |
| | AIR-LAP1262N | 7.0.98.0 | _ |
| 1300 Series | AIR-BR1310G | 4.0.155.0 | 7.0.x |
| 1400 Series | Standalone Only | | _ |
| 1600 Series | AIR-CAP1602I-x-K9 | 7.4.100.0 | _ |
| | AIR-CAP1602I-xK910 | 7.4.100.0 | _ |
| | AIR-SAP1602I-x-K9 | 7.4.100.0 | _ |
| | AIR-SAP1602I-xK9-5 | 7.4.100.0 | _ |
| | AIR-CAP1602E-x-K9 | 7.4.100.0 | _ |
| | AIR-SAP1602E-xK9-5 | 7.4.100.0 | _ |
| 1700 Series | AIR-CAP1702I-x-K9 | 8.0.100.0 | — |
| | AIR-CAP1702I-xK910 | 8.0.100.0 | _ |
| 1830 Series | AIR-AP1832I-UXK9 | 8.1.120.0 | _ |
| | AIR-AP1832I-x-K9 | 8.1.120.0 | |

 Table 2
 Software Support for Access Points (continued)

1

| Access Points | | First Support | Last Support |
|--------------------|--------------------|---------------|--------------|
| 1850 Series | AIR-AP1852I-UXK9 | 8.1.111.0 | _ |
| | AIR-AP1852I-UXK910 | 8.1.111.0 | _ |
| | AIR-AP1852I-UXK9C | 8.1.111.0 | _ |
| | AIRAP1852I-UXK910C | 8.1.111.0 | _ |
| | AIR-AP1852E-UXK9 | 8.1.111.0 | _ |
| | AIR-AP1852E-UXK910 | 8.1.111.0 | _ |
| | AIR-AP1852E-UXK9C | 8.1.111.0 | _ |
| | AIRAP1852E-UXK910C | 8.1.111.0 | _ |
| | AIR-AP1852E-x-K9 | 8.1.111.0 | _ |
| | AIR-AP1852E-x-K9C | 8.1.111.0 | _ |
| | AIR-AP1852I-x-K9 | 8.1.111.0 | _ |
| | AIR-AP1852I-x-K9C | 8.1.111.0 | _ |
| AP801 | | 5.1.151.0 | 8.0.x |
| AP802 | | 7.0.98.0 | _ |
| AP802H | | 7.3.101.0 | _ |
| AP803 | | 8.1.120.0 | _ |
| ASA5506W- AP702 | _ | 8.1.120.0 | _ |
| 2600 Series | AIR-CAP2602I-x-K9 | 7.2.110.0 | |
| | AIR-CAP2602I-xK910 | 7.2.110.0 | _ |
| | AIR-SAP2602I-x-K9 | 7.2.110.0 | _ |
| | AIR-SAP2602I-x-K95 | 7.2.110.0 | _ |
| | AIR-CAP2602E-x-K9 | 7.2.110.0 | _ |
| | AIR-CAP2602E-xK910 | 7.2.110.0 | _ |
| | AIR-SAP2602E-x-K9 | 7.2.110.0 | _ |
| | AIR-SAP2602E-x-K95 | 7.2.110.0 | _ |
| 2700 Series | AIR-CAP2702I-x-K9 | 7.6.120.0 | _ |
| | AIR-CAP2702I-xK910 | 7.6.120.0 | _ |
| | AIR-CAP2702E-x-K9 | 7.6.120.0 | _ |
| | AIR-CAP2702E-xK910 | 7.6.120.0 | _ |
| | AIR-AP2702I-UXK9 | 8.0.110.0 | _ |
| 3500 Series | AIR-CAP3501E | 7.0.98.0 | _ |
| | AIR-CAP3501I | 7.0.98.0 | _ |
| | AIR-CAP3502E | 7.0.98.0 | _ |
| | AIR-CAP3502I | 7.0.98.0 | |
| | AIR-CAP3502P | 7.0.116.0 | |

Table 2 Software Support for Access Points (continued)

Γ

| Access Points | | First Support | Last Support |
|--------------------------|--------------------|---------------|--------------|
| 3600 Series ¹ | AIR-CAP3602I-x-K9 | 7.1.91.0 | _ |
| | AIR-CAP3602I-xK910 | 7.1.91.0 | _ |
| | AIR-CAP3602E-x-K9 | 7.1.91.0 | |
| | AIR-CAP3602E-xK910 | 7.1.91.0 | _ |
| | USC5101-AI-AIR-K9 | 7.6 | |
| 3700 Series | AIR-CAP3702I | 7.6 | _ |
| | AIR-CAP3702E | 7.6 | _ |
| | AIR-CAP3702P | 7.6 | _ |
| 600 Series | AIR-OEAP602I | 7.0.116.0 | _ |
| 1500 Mesh Series | AIR-LAP-150 | 3.1.59.24 | 4.2.207.54M |
| | AIR-LAP-1510 | 3.1.59.24 | 4.2.207.54M |

1

Table 2 Software Support for Access Points (continued)

| Access Points | | First Support | Last Support | |
|---------------------|--------------------|---|--------------|--|
| 1520 Mesh Series | AIR-LAP1522AG | -A and N: 4.1.190.1 or 5.2 or later ² | 8.0.x | |
| | | All other reg. domains: 4.1.191.24M or 5.2 or later ¹ | 8.0.x | |
| | AIR-LAP1522HZ | -A and N: 4.1.190.1 or 5.2 or later ¹ | 8.0.x | |
| | | All other reg. domains: 4.1.191.24M or 5.2 or later ¹ | 8.0.x | |
| | AIR-LAP1522PC | -A and N: 4.1.190.1 or 5.2 or later ¹ | 8.0.x | |
| | | All other reg. domains: 4.1.191.24M or 5.2 or later ¹ | 8.0.x | |
| | AIR-LAP1522CM | 7.0.116.0 or later. | 8.0.x | |
| | AIR-LAP1524SB | -A, C and N: 6.0 or later | 8.0.x | |
| | | All other reg. domains: 7.0.116.0 or later. | 8.0.x | |
| | AIR-LAP1524PS | -A: 4.1.192.22M or 5.2 or later ¹ | 8.0.x | |
| 1530 | AIR-CAP1532I-x-K9 | 7.6 | | |
| | AIR-CAP1532E-x-K9 | 7.6 | | |
| 1550 | AIR-CAP1552C-x-K9 | 7.0.116.0 | — | |
| | AIR-CAP1552E-x-K9 | 7.0.116.0 | <u> </u> | |
| | AIR-CAP1552H-x-K9 | 7.0.116.0 | | |
| | AIR-CAP1552I-x-K9 | 7.0.116.0 | <u> </u> | |
| | AIR-CAP1552EU-x-K9 | 7.3.101.0 | <u> </u> | |
| | AIR-CAP1552CU-x-K9 | 7.3.101.0 | <u> </u> | |
| | AIR-CAP1552WU-x-K9 | 8.0.100.0 | <u> </u> | |

| Table 2 Software Support for Access Points (continued) |
|--|
|--|

L

Γ

| Access Points | | First Support | Last Support |
|---------------|----------------------------------|---------------|--------------|
| 1552S | AIR-CAP1552SA-x-K9 | 7.0.220.0 | _ |
| | AIR-CAP1552SD-x-K9 | 7.0.220.0 | _ |
| 1570 | AIR-AP1572EAC-x-K9 | 8.0.110.0 | _ |
| | AIR-AP1572ICy ³ -x-K9 | 8.0.110.0 | _ |
| | AIR-AP1572ECy-x-K9 | 8.0.110.0 | _ |
| IW3700 | IW3702-2E-UXK9 | 8.0.120.0 | _ |
| | IW3702-4E-UXK9 | 8.0.120.0 | _ |

1

| Table 2 | Software Support for Access Points (continued) |
|---------|--|
| | Soliware Support for Access Fornts (continueu) |

1. The Cisco 3600 AP was introduced in Cisco Wireless Release 7.1.91.0. If your network deployment uses Cisco 3600 APs with Cisco Wireless Release 7.1.91.0, we highly recommend that you upgrade to Cisco Wireless Release 7.2.115.2 or a later release.

2. These access points are supported in a separate 4.1.19x.x mesh software release and in Release 5.2 or later releases. These access points are not supported in the 4.2, 5.0, and 5.1 releases.

3. y-Country DOCSIS Compliance, see ordering guide for details.

Software Release Types and Recommendations

This section contains the following topics:

- Release Types, page 10
- Software Release Recommendations, page 11

Release Types

| Release Type | Description | Benefit |
|---|--|--|
| Maintenance Deploy- ment (MD) releases | Software releases that provide bug-fix support and ongoing software maintenance. These releases are categorized as Mainte- nance Deployment (MD) and may be part of the AssureWave program. ¹ These are releases with long life and | Provides you with a software release that offers stability and long support duration with periodic maintenance releases (MRs). |
| | ongoing software maintenance. | |
| Early Deployment (ED) releases | Software releases that provide new features and new hardware platform support in addition to bug fixes. These releases are categorized as Early Deployment (ED). These are short-lived releases. | Allows you to deploy the latest features and new hardware platforms or modules. |

Table 3Release Types

1. AssureWave is a Cisco program that focuses on satisfying customer quality requirements in key industry segments in the mobility space. This program links and expands on product testing conducted within development engineering, regression testing, and system test groups within Cisco. The AssureWave program has established partnerships with major device and application vendors to help ensure broader interoperability with our new release. The AssureWave certification marks the successful completion of extensive wireless LAN controller and access point testing in real-world use cases with a variety of mobile client devices applicable in a specific industry.

Software Release Recommendations

| Type of Release | Deployed Release | Recommended Release |
|---|---|---|
| Maintenance Deployment (MD) releases | 7.0 MD release train (latest release: 7.0.252.0) | 7.4 MD release train (7.4.140.0 is the MD release) |
| Early Deployment (ED) releases for pre-802.11ac de- ployments | 7.2 ED releases7.3 ED releases | 7.4 MD release train (7.4.140.0 is the MD release) |
| Early Deployment (ED) releases for 802.11ac deploy- ments | 7.5 ED release 7.6 ED release | 8.0 ED release (8.0.120.0 is 8.0MR2 on the 8.0 release train) |

Table 4 Software Release Recommendations

For detailed release recommendations, see the software release bulletin:

http://www.cisco.com/c/en/us/products/collateral/wireless/8500-series-wireless-controllers/bulletin-c2 5-730741.html

For more information about the Cisco Wireless solution compatibility matrix, see http://www.cisco.com/c/en/us/td/docs/wireless/compatibility/matrix/compatibility-matrix.html.

Upgrading to Cisco WLC Software Release 8.1.131.0

Guidelines and Limitations

- When you change the WLAN profile name, then FlexConnect APs (using AP-specific VLAN mapping) will become WLAN-specific. If FlexConnect Groups are properly configured, the VLAN mapping will become Group-specific.
- If you are using Cisco Virtual Wireless Controller and upgrade from Release 8.0.x to Release 8.1.x, the AP counts from the license are not retained. The workaround is to remove the license file and manually add the AP count using the Right to Use Licensing feature.

For more information about using the Right to Use Licensing feature, see the Configuring Right to Use Licensing section in the *Cisco Wireless Controller Configuration Guide*.

 Cisco WLC Release 7.3.112.0, which is configured for new mobility, might revert to old mobility after upgrading to Release 7.6, even though Release 7.6 supports new mobility. This issue occurs when new mobility, which is compatible with the Cisco 5760 Wireless LAN Controller and the Cisco Catalyst 3850 Series Switch, are in use. However, old mobility is not affected.

The workaround is as follows:

a. Enter the following commands:

```
config boot backup
show boot
Primary Boot Image...... 7.6.100.0
Backup Boot Image..... 7.3.112.0 (default) (active)
```

- **b.** After the reboot, press **Esc** on the console, and use the boot menu to select **Release 7.6**.
- **c.** After booting on Release 7.6, set back the primary boot, and save the configuration by entering the following command:

config boot primary



The epings are not available in the Cisco 5500 Series WLC when New Mobility is enabled.



- If you downgrade from a Cisco WLC release that supports new mobility to a Cisco WLC release that does not support new mobility, for example, Cisco Wireless Release 7.6 to Release 7.3.x and you download the 7.6 configuration file with new mobility in enabled state, the release that does not support new mobility will have the new mobility feature in enabled state.
- If you downgrade from Release 8.1.131.0 to a 7.x release, the trap configuration is lost and must be reconfigured.
- If you upgrade from Release 8.0.110.0 to a later release, the **config redundancy mobilitymac** *mac-addr* command's setting is removed. You must manually reconfigure the mobility MAC address after the upgrade.
- If you are upgrading from Release 8.0.140.0 or 8.0.15x.0 to a later release and also have the multiple country code feature configured, the feature configuration is corrupted after the upgrade. For more information, see CSCve41740.
- If you have ACL configurations in a Cisco WLC, and downgrade from a 7.4 or later release to a 7.3 or earlier release, you might experience XML errors on rebooting the Cisco WLC. However, these errors do not have any impact on any of the functionalities or configurations.
- If you are upgrading from a 7.4.x or earlier release to a release later than 7.4, the Called Station ID type information is mapped to the RADIUS Accounting Called Station ID type; which, by default, is set to apradio-mac-ssid. You can configure the RADIUS Authentication Called Station ID type information by using the **config radius auth callStationIdType** command.
- When FlexConnect APs (known as H-REAP APs in the 7.0.x releases) that are associated with a Cisco WLC that has all the 7.0.x software releases prior to Release 7.0.240.0, upgrade to Release 8.1.131.0, the APs lose the enabled VLAN support configuration. The VLAN mappings revert to the default values of the VLAN of the associated interface. The workaround is to upgrade from Release 7.0.240.0 and later 7.0.x releases to Release 8.1.131.0.



- In case of FlexConnect VLAN mapping deployment, we recommend that the deployment be done using FlexConnect groups. This allows you to recover VLAN mapping after an AP rejoins the Cisco WLC without having to manually reassign the VLAN mappings.
- When a client sends an HTTP request, the Cisco WLC intercepts it for redirection to the login page. If the HTTP GET request that is intercepted by the Cisco WLC is longer than 2000 bytes, the Cisco WLC drops the packet. Track CSCuy81133 for a possible enhancement to address this restriction.

• We recommend that you install Release 1.9.0.0 of Cisco Wireless LAN Controller Field Upgrade Software (FUS), which is a special AES package that contains several system-related component upgrades. These include the bootloader, field recovery image, and FPGA/MCU firmware. Installing the FUS image requires special attention because it installs some critical firmware. The FUS image is independent of the runtime image. For more information, see

http://www.cisco.com/c/en/us/td/docs/wireless/controller/release/notes/fus_rn_OL-31390-01.html.



The FUS image installation process reboots the Cisco WLC several times and reboots the runtime image. The entire process takes approximately 30 minutes. We recommend that you install the FUS image in a planned outage window.



If you are using a Cisco 2500 Series controller and you intend to use the Application Visibility and Control (AVC) and NetFlow protocol features, you must install Release 1.9.0.0 of Cisco Wireless LAN Controller FUS. This is not required if you are using other controller hardware models.

- After you upgrade to Release 7.4, networks that were not affected by the existing preauthentication access control lists might not work because the rules are now enforced. That is, networks with clients configured with static DNS servers might not work unless the static server is defined in the preauthentication ACL.
- On the Cisco Flex 7500 Series WLCs, if FIPS is enabled, the reduced boot options are displayed only after a bootloader upgrade.



Bootloader upgrade is not required if FIPS is disabled.

- If you have to downgrade from one release to another, you might lose the configuration from your current release. The workaround is to reload the previous Cisco WLC configuration files saved on the backup server, or to reconfigure the Cisco WLC.
- It is not possible to directly upgrade to Release 8.1.131.0 release from a release that is earlier than Release 7.0.98.0.
- You can upgrade or downgrade the Cisco WLC software only between certain releases. In some instances, you must first install an intermediate release prior to upgrading to Release 8.1.131.0.
 Table 5 shows the upgrade path that you must follow before downloading Release 8.1.131.0.

Caution

If you upgrade directly to 7.6.x or a later release from a release that is earlier than 7.5, the predownload functionality on Cisco Aironet 2600 and 3600 APs fails. The predownload functionality failure is only a one-time failure. After the upgrade to 7.6.x or a later release, the new image is loaded on the said Cisco APs, and the predownload functionality works as expected.

| Current Software Release | Upgrade Path to 8.1.131.0 Software | |
|--------------------------|---|--|
| 7.0.x releases | You can upgrade directly to 8.1.131.0. | |
| | Note If you have VLAN support and VLAN mappings defined on H-REAP access points and are currently using a 7.0.x Cisco WLC software release that is earlier than 7.0.240.0, we recommend that you upgrade to the 7.0.240.0 release and then upgrade to 8.1.131.0 to avoid losing those VLAN settings. | |
| | Note In case of FlexConnect VLAN mapping deployment, we recommend that the deployment be done using FlexConnect groups. This allows you to recover VLAN mapping after an AP rejoins the Cisco WLC without having to manually reassign the VLAN mappings. | |
| 7.1.91.0 | You can upgrade directly to 8.1.131.0. | |
| 7.2.x releases | You can upgrade directly to 8.1.131.0. | |
| | Note If you have an 802.11u HotSpot configuration on the WLANs, we recommend that you first upgrade to the 7.3.101.0 Cisco WLC software release and then to the 8.1.131.0 Cisco WLC software release. | |
| | You must downgrade from the 8.1.131.0 Cisco WLC software release to a 7.2.x Cisco WLC software release if you have an 802.11u HotSpot configuration on the WLANs that are not supported. | |
| 7.3.x releases | You can upgrade directly to 8.1.131.0. | |
| 7.4.x releases | You can upgrade directly to 8.1.131.0. | |
| 7.5.x releases | You can upgrade directly to 8.1.131.0. | |
| 7.6.x | You can upgrade directly to 8.1.131.0. | |
| 8.0.x | You can upgrade directly to 8.1.131.0. | |
| 8.1.x | You can upgrade directly to 8.1.131.0. | |

1

| Table 5 | Upgrade Path to Cisco WLC Software Release 8.1.131.0 |
|---------|--|
| | |

- When you upgrade the Cisco WLC to an intermediate software release, you must wait until all of the access points that are associated with the Cisco WLC are upgraded to the intermediate release before you install the latest Cisco WLC software. In large networks, it can take some time to download the software on each access point.
- You can upgrade to a new release of the Cisco WLC software or downgrade to an earlier release even if Federal Information Processing Standard (FIPS) is enabled.

- When you upgrade to the latest software release, the software on the access points associated with the Cisco WLC is also automatically upgraded. When an access point is loading software, each of its LEDs blinks in succession.
- We recommend that you access the Cisco WLC GUI using Microsoft Internet Explorer 9 or a later version or Mozilla Firefox 17 or a later version.

- **Note** Microsoft Internet Explorer 8 might fail to connect over HTTPS because of compatibility issues. In such cases, you can explicitly enable SSLv3 by entering the **config network secureweb sslv3 enable** command.
- Cisco WLCs support standard SNMP MIB files. MIBs can be downloaded from the Software Center on Cisco.com.
- The Cisco WLC software is factory installed on your Cisco WLC and is automatically downloaded to the access points after a release upgrade and whenever an access point joins a Cisco WLC. We recommend that you install the latest software version available for maximum operational benefit.
- Ensure that you have a TFTP, FTP, or SFTP server available for the software upgrade. Follow these guidelines when setting up a server:
 - Ensure that your TFTP server supports files that are larger than the size of Cisco WLC software Release 8.1.131.0. Some TFTP servers that support files of this size are tftpd32 and the TFTP server within the Prime Infrastructure. If you attempt to download the 8.1.131.0 Cisco WLC software and your TFTP server does not support files of this size, the following error message appears:

TFTP failure while storing in flash.

- If you are upgrading through the distribution system network port, the TFTP or FTP server can be on the same subnet or a different subnet because the distribution system port is routable.
- When you plug a Cisco WLC into an AC power source, the bootup script and power-on self test is run to initialize the system. During this time, press **Esc** to display the bootloader Boot Options menu. The menu options for the Cisco 5500 Series WLC differ from the menu options for the other Cisco WLC platforms.

Bootloader menu for Cisco 5500 Series WLC:

Boot Options Please choose an option from below: 1. Run primary image 2. Run backup image 3. Change active boot image 4. Clear Configuration 5. Format FLASH Drive 6. Manually update images Please enter your choice: Bootloader menu for other Cisco WLC platforms: Boot Options

Please choose an option from below:

- 1. Run primary image
- 2. Run backup image
- 3. Manually update images
- 4. Change active boot image
- 5. Clear Configuration

Please enter your choice:

Enter 1 to run the current software, enter 2 to run the previous software, enter 4 (on Cisco 5500 Series WLC), or enter 5 (on Cisco WLC platforms other than 5500 series) to run the current software and set the Cisco WLC configuration to factory defaults. Do not choose the other options unless directed to do so.



See the Installation Guide or the Quick Start Guide pertaining to your Cisco WLC platform for more details on running the bootup script and power-on self test.

• The Cisco WLC bootloader stores a copy of the active primary image and the backup image. If the primary image becomes corrupted, you can use the bootloader to boot with the backup image.

With the backup image stored before rebooting, choose **Option 2: Run Backup Image** from the boot menu to boot from the backup image. Then, upgrade with a known working image and reboot the Cisco WLC.

• You can control the addresses that are sent in the Control and Provisioning of Wireless Access Points (CAPWAP) discovery responses when NAT is enabled on the Management Interface using the following command:

config network ap-discovery nat-ip-only {enable | disable}

Here:

- **enable**—Enables use of NAT IP only in a discovery response. This is the default. Use this command if all the APs are outside the NAT gateway.
- disable—Enables use of both NAT IP and non-NAT IP in a discovery response. Use this command if APs are on the inside and outside the NAT gateway, for example, Local Mode and OfficeExtend APs are on the same Cisco WLC.



To avoid stranding of APs, you must disable AP link latency (if enabled) before you use the disable option for the **config network ap-discovery nat-ip-only** command. To disable AP link latency, use the **config ap link-latency disable all** command.

- You can configure 802.1p tagging by using the **config qos dot1p-tag {bronze | silver | gold | platinum**} command. For Release 7.2.103.0 and later releases, if you tag 802.1p packets, the tagging has an impact on only wired packets. Wireless packets are impacted only by the maximum priority level set for QoS.
- You can reduce the network downtime using the following options:
 - You can predownload the AP image.
 - For FlexConnect access points, use the FlexConnect AP upgrade feature to reduce traffic between the Cisco WLC and the AP (main site and the branch). For more information about the FlexConnect AP upgrade feature, see the *Cisco Wireless Controller Configuration Guide*.



- Predownloading Release 8.1.131.0 on a Cisco Aironet 1240 access point is not supported when upgrading from a previous Cisco WLC release. If predownloading is attempted on a Cisco Aironet 1240 access point, an AP disconnect will occur momentarily.
- Do not power down the Cisco WLC or any access point during the upgrade process; otherwise, you might corrupt the software image. Upgrading a Cisco WLC with a large number of access points can take as long as 30 minutes, depending on the size of your network. However, with the increased

number of concurrent access point upgrades supported, the upgrade time should be significantly reduced. The access points must remain powered, and the Cisco WLC must not be reset during this time.

- To downgrade from Release 8.1.131.0 to Release 6.0 or an earlier release, perform either of these tasks:
 - Delete all the WLANs that are mapped to interface groups, and create new ones.
 - Ensure that all the WLANs are mapped to interfaces rather than interface groups.
- After you perform the following functions on the Cisco WLC, reboot the Cisco WLC for the changes to take effect:
 - Enable or disable link aggregation (LAG)
 - Enable a feature that is dependent on certificates (such as HTTPS and web authentication)
 - Add a new license or modify an existing license
 - Increase the priority of a license
 - Enable HA
 - Install the SSL certificate
 - Configure the database size
 - Install the vendor-device certificate
 - Download the CA certificate
 - Upload the configuration file
 - Install the Web Authentication certificate
 - Make changes to the management interface or the virtual interface
 - Make changes to TCP MSS settings
- If you downgrade from Release 8.3 to Release 8.1, the Cisco Aironet 1850 Series AP, whose mode prior to the downgrade was Sensor is shown to be in unknown mode after the downgrade. This is because the Sensor mode is not supported in Release 8.1.

Upgrading to Cisco WLC Software Release 8.1.131.0 (GUI)

Step 1 Upload your Cisco WLC configuration files to a server to back up the configuration files.



• We highly recommend that you back up your Cisco WLC configuration files prior to upgrading the Cisco WLC software.

- **Step 2** Follow these steps to obtain Cisco Wireless Release 8.1.131.0 software:
 - **a**. Click this URL to go to the Software Center:

http://www.cisco.com/cisco/software/navigator.html

- b. Choose Wireless from the center selection window.
- c. Click Wireless LAN Controllers.

The following options are displayed. Depending on your Cisco WLC platform, select either of these options:

- Integrated Controllers and Controller Modules
- Standalone Controllers
- d. Select the Cisco WLC model number or name.

The **Download Software** page is displayed.

- **e.** The software releases are labeled as follows to help you determine which release to download. Click a Cisco WLC software release number:
 - Early Deployment (ED)—These software releases provide new features and new hardware platform support as well as bug fixes.
 - Maintenance Deployment (MD)—These software releases provide bug fixes and ongoing software maintenance.
 - **Deferred (DF)**—These software releases have been deferred. We recommend that you migrate to an upgraded release.
- f. Click the filename (*filename*.aes).
- g. Click Download.
- h. Read the Cisco End User Software License Agreement and click Agree.
- i. Save the file to your hard drive.
- j. Repeat steps a. through i. to download the remaining file.
- **Step 3** Copy the Cisco WLC software file (*filename*.aes) to the default directory on your TFTP, FTP, or SFTP server.
- **Step 4** (Optional) Disable the Cisco WLC 802.11a/n and 802.11b/g/n networks.

٩,

Note For busy networks, Cisco WLCs on high utilization, and small Cisco WLC platforms, we recommend that you disable the 802.11a/n and 802.11b/g/n networks as a precautionary measure.

- **Step 5** Choose **Commands > Download File** to open the Download File to Controller page.
- **Step 6** From the **File Type** drop-down list, choose **Code**.
- Step 7 From the Transfer Mode drop-down list, choose TFTP, FTP, or SFTP.
- **Step 8** In the **IP Address** text box, enter the IP address of the TFTP, FTP, or SFTP server.
- **Step 9** If you are using a TFTP server, the default value of 10 retries for the **Maximum Retries** text field, and 6 seconds for the Timeout text field should work correctly without any adjustment. However, you can change these values, if desired. To do so, enter the maximum number of times that the TFTP server attempts to download the software in the Maximum Retries text box and the amount of time (in seconds) for which the TFTP server attempts to download the software, in the **Timeout** text box.
- **Step 10** In the **File Path** text box, enter the directory path of the software.
- **Step 11** In the **File Name** text box, enter the name of the software file (*filename*.aes).
- **Step 12** If you are using an FTP server, perform these steps:
 - a. In the Server Login Username text box, enter the username with which to log on to the FTP server.
 - **b.** In the **Server Login Password** text box, enter the password with which to log on to the FTP server.
 - **c.** In the **Server Port Number** text box, enter the port number on the FTP server through which the download occurs. The default value is 21.
- **Step 13** Click **Download** to download the software to the Cisco WLC.

A message appears indicating the status of the download.

- **Step 14** After the download is complete, click **Reboot**.
- **Step 15** If you are prompted to save your changes, click **Save and Reboot**.
- Step 16 Click OK to confirm your decision to reboot the Cisco WLC.
- **Step 17** For Cisco WiSM2 on the Catalyst switch, check the port channel and re-enable the port channel if necessary.
- Step 18 If you have disabled the 802.11a/n and 802.11b/g/n networks in Step 4, re-enable them.
- **Step 19** To verify that the 8.1.131.0 Cisco WLC software is installed on your Cisco WLC, click **Monitor** on the Cisco WLC GUI and view the Software Version field under Controller Summary.

Special Notes for Licensed Data Payload Encryption on Cisco Wireless LAN Controllers

Datagram Transport Layer Security (DTLS) is required for all Cisco 600 Series OfficeExtend Access Point deployments to encrypt data plane traffic between the APs and the Cisco WLC. You can purchase Cisco Wireless LAN Controllers with either DTLS that is enabled (non-LDPE) or disabled (LDPE). If DTLS is disabled, you must install a DTLS license to enable DTLS encryption. The DTLS license is available for download on Cisco.com.

Important Note for Customers in Russia

If you plan to install a Cisco Wireless LAN Controller in Russia, you must get a Paper PAK, and not download the license from Cisco.com. The DTLS Paper PAK license is for customers who purchase a Cisco WLC with DTLS that is disabled due to import restrictions, but have authorization from local regulators to add DTLS support after the initial purchase. Refer to your local government regulations to ensure that DTLS encryption is permitted.

Note

Paper PAKs and electronic licenses that are available are outlined in the respective Cisco WLC platform data sheets.

Downloading and Installing a DTLS License for an LDPE Cisco WLC

Step 1

To download the Cisco DTLS license:

a. Go to the Cisco Software Center at this URL:

https://tools.cisco.com/SWIFT/LicensingUI/Home

- **b.** From the Product License Registration page from the **Get Other Licenses** drop-down list, click **IPS**, **Crypto**, **Other**
- c. In the Wireless section, click Cisco Wireless Controllers (2500/5500/7500/WiSM2) DTLS License and click Next.
- **d.** Follow the on-screen instructions to generate the license file. The license file information will be sent to you in an e-mail.

- **Step 2** Copy the license file to your TFTP server.
- **Step 3** Install the DTLS license either by using the Cisco WLC web GUI interface or the CLI:
 - To install the license using the WLC web GUI, choose:
 - Management > Software Activation > Commands > Action: Install License
 - To install the license using the CLI, enter this command: license install tftp://ipaddress /path /extracted-file

After the installation of the DTLS license, reboot the system. Ensure that the DTLS license that is installed is active.

Upgrading from an LDPE to a Non-LDPE Cisco WLC

Step 1 Download the non-LDPE software release:

- a. Go to the Cisco Software Center at: http://www.cisco.com/cisco/software/navigator.html?mdfid=282585015&i=rm
- b. Choose the Cisco WLC model.
- c. Click Wireless LAN Controller Software.
- **d.** In the left navigation pane, click the software release number for which you want to install the non-LDPE software.
- e. Choose the non-LDPE software release: AIR-X-K9-X-X.X.aes
- f. Click Download.
- g. Read the Cisco End User Software License Agreement and then click Agree.
- **h.** Save the file to your hard drive.
- **Step 2** Copy the Cisco WLC software file (*filename*.aes) to the default directory on your TFTP server or FTP server.
- **Step 3** Upgrade the Cisco WLC with this version by performing Step 3 through Step 19 detailed in the "Upgrading to Cisco WLC Software Release 8.1.131.0" section on page 11.

Interoperability with Other Clients

This section describes the interoperability of Cisco WLC Software, Release 8.1.131.0 with other client devices.

Table 6 describes the configuration used for testing the client devices.

Table 6 Test Bed Configuration for Interoperability

| Hardware/Software Parameter | Hardware/Software Configuration Type |
|-----------------------------|--------------------------------------|
| Release | 8.1.131.0 |
| Cisco WLC | Cisco 55xx Controller |

| Access points | 1142, 3502, 3602, 1602, 2602, 1702, 2702, 3702, 702, 702W, 1852 |
|----------------|---|
| Radio | 802.11ac, 802.11a, 802.11g, 802.11n2, 802.11n5 |
| Security | Open, WEP, PSK (WPA and WPA2), 802.1X (WPA-TKIP and WPA2-AES) (LEAP, PEAP, EAP-FAST, EAP-TLS) |
| RADIUS | ACS 4.2, ACS 5.2 |
| Types of tests | Connectivity, traffic, and roaming between two access points |

 Table 6
 Test Bed Configuration for Interoperability (continued)

Table 7 lists the client types on which the tests were conducted, including laptops, handheld devices, phones, and printers.

| Client Type and Name | Version |
|---|--------------------------|
| Laptop | |
| Intel 4965 | v13.4 |
| Intel 5100/5300 | v14.3.2.1 |
| Intel 6200 | 15.15.0.1 |
| Intel 6300 | 15.16.0.2 |
| Intel 6205 | 15.16.0.2 |
| Intel 1000/1030 | v14.3.0.6 |
| Intel 7260 | 17.16.0.4 |
| Intel 7265 | 17.16.0.4 |
| Intel 3160 | 17.16.0.4 |
| Broadcom 4360 | 6.30.163.2005 |
| Linksys AE6000 (USB) | 5.1.2.0 |
| Netgear A6200 (USB) | 6.30.145.30 |
| Netgear A6210(USB) | 5.1.18.0 |
| D-Link DWA-182 (USB) | 6.30.145.30 |
| Engenius EUB 1200AC(USB) | 1026.5.1118.2013 |
| Asus AC56(USB) | |
| Dell 1395/1397/Broadcom 4312HMG(L) | 5.30.21.0 |
| Dell 1501 (Broadcom BCM4313) | v5.60.48.35/v5.60.350.11 |
| Dell 1505/1510/Broadcom 4321MCAG/4322HM | 5.60.18.8 |
| Dell 1515(Atheros) | 8.0.0.239 |
| Dell 1520/Broadcom 43224HMS | 5.60.48.18 |
| Dell 1530 (Broadcom BCM4359) | 5.100.235.12 |
| Dell 1540 | 6.30.223.215 |
| Cisco CB21 | 1.3.0.532 |
| Atheros HB92/HB97 | 8.0.0.320 |

Table 7Client Types

Γ

| Client Type and Name | Version | |
|---------------------------------------|------------------------------------|--|
| Atheros HB95 | 7.7.0.358 | |
| MacBook Pro | OSX 10.10.4 | |
| MacBook Air old | OSX 10.10.4 | |
| MacBook Air new | OSX 10.10.4 | |
| Macbook Pro with Retina Display | OSX 10.10.4 | |
| Macbook New 2015 | OSX 10.10.4 | |
| Tablets | | |
| Apple iPad2 | iOS 8.4(12H143) | |
| Apple iPad3 | iOS 8.4(12H143) | |
| Apple iPad mini with Retina display | iOS 8.4(12H143) | |
| Apple iPad Air | iOS 8.4(12H143) | |
| Apple iPad Air 2 | iOS 8.4(12H143) | |
| Samsung Galaxy Tab Pro SM-T320 | Android 4.4.2 | |
| Samsung Galaxy Tab 10.1- 2014 SM-P600 | Android 4.4.2 | |
| Samsung Galaxy Note 3 - SM-N900 | Android 5.0 | |
| Microsoft Surface Pro 3 | Windows 8.1 | |
| Microsoft Surface Pro 2 | Windows 8.1 | |
| Google Nexus 9 | Android 5.0.2 | |
| Google Nexus 7 2nd Gen | Android 5.0 | |
| Intermec CK70 | Windows Mobile 6.5 / 2.01.06.0355 | |
| Intermec CN50 | Windows Mobile 6.1 / 2.01.06.0333 | |
| Symbol MC5590 | Windows Mobile 6.5 / 3.00.0.051R | |
| Symbol MC75 | Windows Mobile 6.5 / 3.00.2.0.006R | |
| Phones and Printers | | |
| Cisco 7921G | 1.4.5.3.LOADS | |
| Cisco 7925G | 1.4.5.3.LOADS | |
| Cisco 8861 | Sip88xx.10-2-1-16 | |
| Ascom i75 | 1.8.0 | |
| Spectralink 8030 | 119.081/131.030/132.030 | |
| Apple iPhone 4S | iOS 8.4(12H143))) | |
| Apple iPhone 5 | iOS 8.4(12H143) | |
| Apple iPhone 5s | iOS 8.4(12H143) | |
| Apple iPhone 5c | iOS 8.4(12H143) | |
| Apple iPhone 6 | iOS 8.4(12H143) | |
| Apple iPhone 6 Plus | iOS 8.4(12H143) | |
| HTC One | Android 5.0 | |

1

Table 7 Client Types (continued)

| Client Type and Name | Version |
|------------------------------|-----------------------|
| OnePlusOne | Android 4.3 |
| Samsung Galaxy S4 T-I9500 | Android 5.0.1 |
| Sony Xperia Z Ultra | Android 4.4.2 |
| Nokia Lumia 1520 | Windows Phone 8.1 |
| Google Nexus 5 | Android 5.1 |
| Nexus 6 | Android 5.1.1 |
| Samsung Galaxy S5-SM-G900A | Android 4.4.2 |
| Huawei Ascend P7 | Android 4.4.2 |
| Samsung Galaxy S III | Android 4.3 |
| SpectraLink 8450 | 3.0.2.6098/5.0.0.8774 |
| Samsung Galaxy Nexus GTI9200 | Android 4.4.2 |
| Samsung Galaxy Mega SM900 | Android 4.4.2 |
| Samsung Galaxy S6 | Android 5.0.2 |

Table 7 Client Types (continued)

Features Not Supported on Cisco WLC Platforms

This section lists the features that are not supported on the different Cisco WLC platforms:

- Features Not Supported on Cisco 2504 WLC, page 23
- Features Not Supported on Cisco WiSM2 and Cisco 5508 WLC, page 24
- Features Not Supported on Cisco Flex 7510 WLCs, page 24
- Features Not Supported on Cisco 5520, 8510, and 8540 WLCs, page 25
- Features Not Supported on Cisco Virtual WLCs, page 25
- Features Not Supported on Mesh Networks, page 26



I

In a converged access environment that has Cisco WLCs running AireOS code, High Availability Client SSO and native IPv6 are not supported.

Features Not Supported on Cisco 2504 WLC

- Autoinstall
- Cisco WLC integration with Lync SDN API
- Bonjour Gateway
- Application Visibility and Control (AVC) for FlexConnect local switched access points



However, AVC for local mode APs is supported.

- Bandwidth Contract
- Service Port
- AppleTalk Bridging
- Right-to-Use Licensing
- PMIPv6
- AP Stateful Switchover (SSO) and client SSO
- Multicast-to-Unicast

Note

The features that are not supported on Cisco WiSM2 and Cisco 5500 Series WLCs are not supported on Cisco 2500 Series WLCs too.



Directly connected APs are supported only in the local mode.

Features Not Supported on Cisco WiSM2 and Cisco 5508 WLC

- Spanning Tree Protocol (STP)
- Port Mirroring
- VPN Termination (such as IPsec and L2TP)
- VPN Passthrough Option



Note You can replicate this functionality on a Cisco 5500 Series WLC by creating an open WLAN using an ACL.

- Configuration of 802.3 bridging, AppleTalk, and Point-to-Point Protocol over Ethernet (PPPoE)
- Fragmented pings on any interface
- Right-to-Use Licensing
- Cisco 5508 WLC cannot function as mobility controller (MC). However, Cisco 5508 WLC can function as guest anchor in a New Mobility environment.

Features Not Supported on Cisco Flex 7510 WLCs


Static AP-manager interface



Note For Cisco Flex 7500 Series WLCs, it is not necessary to configure an AP-manager interface. The management interface acts as an AP-manager interface by default, and the access points can join on this interface.

1

• IPv6 and Dual Stack client visibility



- FlexConnect local-switched multicast traffic is bridged transparently for both wired and wireless on the same VLAN. FlexConnect access points do not limit traffic based on Internet Group Management Protocol (IGMP) or MLD snooping.
- PMIPv6

Features Not Supported on Cisco 5520, 8510, and 8540 WLCs

- Internal DHCP Server
- Local Authentication
- Wired Guest
- Mobility controller functionality in converged access mode



We recommend that you do not use the multicast-unicast mode in these Cisco WLCs.

Features Not Supported on Cisco Virtual WLCs

- Cisco Aironet 1830 and 1850 Series APs
- Internal DHCP server
- TrustSec SXP
- Access points in local mode
- Mobility/Guest Anchor
- Wired Guest
- Multicast

Note

FlexConnect local-switched multicast traffic is bridged transparently for both wired and wireless on the same VLAN. FlexConnect access points do not limit traffic based on IGMP or MLD snooping.

- High Availability
- PMIPv6
- Workgroup Bridges
- Client downstream rate limiting for central switching
- SHA2 certificates

Features Not Supported on Mesh Networks

- Load-based call admission control (CAC). Mesh networks support only bandwidth-based CAC or static CAC
- High availability (fast heartbeat and primary discovery join timer)
- AP acting as supplicant with EAP-FASTv1 and 802.1X authentication
- Access point join priority (mesh access points have a fixed priority)
- Location-based services

Features Not Supported on Access Point Platforms

- Features Not Supported on Cisco Aironet 1830 and 1850 APs, page 26
- Features Not Supported on Cisco Aironet 1550 APs (with 64-MB Memory), page 27

Features Not Supported on Cisco Aironet 1830 and 1850 APs

- Cisco Virtual Wireless Controller
- Mesh mode
- Flex mode
- Monitor mode
- Sniffer mode
- Workgroup Bridge (WGB) mode
- OfficeExtend mode
- Enhanced Local Mode (ELM)
- Integrated BLE
- Basic spectrum analysis
- USB-based Bluetooth Low Energy (BLE) device support
- Cisco CleanAir
- Cisco Wireless ClientLink 3.0

- Rogue Location Discovery Protocol (RLDP)
- Cisco Compatible eXtensions (CCX) Specification
- 802.1x supplicant for AP authentication on the wired port
- Static WEP key for TKIP or CKIP
- Dynamic Transmit Power Control (DTPC)
- Federal Information Processing Standard (FIPS) and Common Criteria
- 40-MHz Rogue detection
- Native IPv6
- Telnet



For Cisco Aironet1850 Series AP technical specifications with details on currently supported features, see the *Cisco Aironet 1850 Series Access Points Data Sheet*.

Features Not Supported on Cisco Aironet 1550 APs (with 64-MB Memory)

- PPPoE
- PMIPv6



To see the amount of memory in a Cisco Aironet 1550 AP, enter the following command:

(Cisco Controller) > show mesh ap summary

Caveats

I

- Cisco Bug Search Tool, page 27
- Open Caveats, page 29
- Resolved Caveats, page 33

Cisco Bug Search Tool

The Bug Search Tool (BST), which is the online successor to the Bug Toolkit, is designed to improve the effectiveness in network risk management and device troubleshooting. The BST allows Cisco partners and customers to search for software bugs based on product, release, keyword, and aggregates key data, such as bug details, product, and version. The tool has a provision to filter bugs based on credentials to provide external and internal bug views for the search input.

To view the details of a caveat listed in this document:

- 1. Access the BST (use your Cisco user ID and password) at https://tools.cisco.com/bugsearch/.
- 2. Enter the bug ID in the Search For: field.



Using the BST, you can also find information about the bugs that are not listed in this section.

1

Open Caveats

I

Γ

Use Cisco Bug Search Tool (BST) to view the details of a caveat listed in this section. For more information about the BST, see the "Cisco Bug Search Tool" section on page 27

| Table 8 | Open Caveats |
|------------|--|
| Bug ID | Headline |
| CSCul07738 | DPAA Tx/Rx stuck; reload due to Ethernet interface receive failure [FSL] |
| CSCun52472 | Show dtls connection shows blank in AP Name column for Capwap_Data |
| CSCuq73590 | WLC adds incorrect class attribute in accounting stop |
| CSCuq76115 | Cisco Work Group Bridge (WGB) clients with DSCP marking to QoS queue mapping does not work on Cisco 819 router |
| CSCuq86263 | False DFS detection on Cisco 1600AP |
| CSCur58057 | Cisco Flex AP loses some WLANs after radio resets |
| CSCus02070 | FlexConnect AP losing vLAN Mapping and falling on Native vLAN |
| CSCus61445 | DNS ACL on WLC is not working - AP not Send DTLS to WLC |
| CSCus64550 | Mobility client IP Address as 0.0.0.0 in foreign controller |
| CSCus77368 | WLC: Unexpectedly reloads on ewaFormSubmit_cell_edit |
| CSCus79056 | Cisco 5508 controller management frames are not marked with CS6 |
| CSCus80685 | AP sends few frames with previous security association's packet number |
| CSCus91214 | Cisco AP802 running 15.3(3)JAB always reloads unexpectedly on entering the dir all-filesystems on Cisco ISR C881W router |
| CSCus92667 | GET on AP groups Table after set - response missing |
| CSCus97021 | Cisco 2500 and Cisco 5508 WLC possible bricking on kernel unexpected reload |
| CSCus97953 | Cisco 8510 WLC reloads unexpectedly on Uhhuh. NMI received for unknown reason 2d |
| CSCut23325 | Cisco 1700AP not encrypting ICMP and ARP sent from the client over the air |
| CSCut42406 | Cisco 5508WLC reloaded unexpectedly while disabling Mobility oracle. |
| CSCut42926 | WLC unexpectedly reloads on SNMPtask after doing configuration audit from PI |
| CSCut45010 | Issue with installing certificates in UTC |
| CSCut52223 | FlexConnect AP loses local EAP certificate when it looses registration with the WLC |
| CSCut63507 | vWLC showing application ID instead of application name |
| CSCut66994 | Anchor / Foreign WLC accounting packets has nas-update=true |
| CSCut68661 | Cisco 702AP unexpectedly reloads on ar9300_set_desc_link |
| CSCut74263 | Mobile Access Gateway on AP does not clear bindings after session/user timeout & de-authentication |
| CSCut80440 | WLC not sending Flex AVC configuration to Mesh AP |
| CSCut82091 | Cisco 3702/3602/1602 AP unexpectedly reloads on CAPWAP CLIENT process |
| CSCut88319 | WLC does NOT support FF08::/16 range of organization-local IPv6 multicast addresses |

| Table 8 | Open Caveats |
|------------|--|
| Bug ID | Headline (continued) |
| CSCut92934 | vWLC - AP with expire Manufacturing Installed Certificates (MIC) not able to join with Ignore MIC settings |
| CSCut95812 | AP radio reset with beacons stuck |
| CSCut95835 | AP radio reset with PAK stuck |
| CSCut98540 | Cisco Mobility Express Port statistics are not correct and are not cleared completely |
| CSCut99150 | Cisco 2702AP requesting as a Type 1 power device instead of Type 2 |
| CSCuu02281 | APs on WLC with wireless networks disabled detecting rogues |
| CSCuu04464 | License command causes WLC to reload unexpectedly (possible buffer size overwrite) |
| CSCuu06047 | Packet drops on Cisco 2702 AP in Cisco FlexConnect local authentication /local switch mode |
| CSCuu07107 | SNMP walk on clsNetworkRouteConfigTable fails |
| CSCuu07274 | FP0.00: failed to find scb prints at Cisco 5500 WLC standby console |
| CSCuu08012 | Cisco 2700AP CleanAir sensor died (src/dspm_main.c:389) - slot 0 |
| CSCuu08592 | Override interf interf-group not been applied on re-authentication for IPv6 clients |
| CSCuu10781 | Multicast configuration mismatch on Web / CLI |
| CSCuu11959 | Cisco 7925 phone using CCKM does not roam gracefully in FlexConnect environment |
| CSCuu12944 | Increase WPA handshake timeout for flex local Authentication |
| CSCuu13860 | 'autoconvert flexconnect' is stored as 'disable' on startup-commands |
| CSCuu14124 | RF-profile losing the channel and coverage values after downloading configuration file |
| CSCuu15866 | Local EAP authentication terminates unexpectedly. |
| CSCuu22083 | AP unexpectedly reloads on MESH ASTools PROCESS during mesh initialization |
| CSCuu24920 | Guest clients roam from MC to MA failing |
| CSCuu31357 | AP unexpectedly reloads on VW-ap1530.cc6c.map2 |
| CSCuu33740 | WLC unexpectedly reloads while editing SNMP community - waFormSubmit_snmp_comm_list |
| CSCuu42378 | Rx-SOP threshold not working correctly |
| CSCuu45186 | 802.11 arp-cache does not work as expected |
| CSCuu54431 | In WLC CLI, copying new tunnel profile with same name unexpectedly reloads the WLC |
| CSCuu59340 | SNR alarms for mesh APs have invalid content and are not working as expected |
| CSCuu60475 | Cisco 3702AP in continuous integration reloads unexpectedly in Process: Net Background |
| CSCuu63964 | Apple clients cannot reconnect Cisco 1850i on forceful de-authentication |
| CSCuu64295 | Domain mismatched on Cisco 1832I,1852I APs |
| CSCuu64447 | CleanAir device commands are disabled after restoring backup configuration file |

1

| Table 8 | Open Caveats |
|------------|---|
| Bug ID | Headline (continued) |
| CSCuu65672 | DTLS Capwap_Ctrl connections not cleared for APs connecting through WAN |
| CSCuu66484 | WLC: GUI 'downloaded AVP' page just keeps reloading |
| CSCuu66675 | During CMCC external authentication, lock unexpectedly reloads on radiusTransportThread |
| CSCuu71017 | Invalid neighbors with bogus IP/RSSI/channel are seen with NDP protected mode |
| CSCuu72585 | When AP is in FlexConnect mode, WLC AAA override cause traffic Black holing |
| CSCuu75181 | Cisco 3702AP under 80MHz is showing "0" as channel or stuck on 40MHz |
| CSCuu77738 | Prime Infrastructure 3.0 Auto Provisioning is not working |
| CSCuu78888 | Web GUI unresponsive after HTTPS-redirect enabled |
| CSCuu80383 | Clients are denied association by neighboring AP during optimized roaming |
| CSCuu83748 | WLC sends bsnRogueAPRemoved Trap when notify configured value is none |
| CSCuu83941 | Cisco 8510WLC: Error enabling global multicast with CAPWAP mode on unicast |
| CSCuu86781 | Cisco 8.1.x release running Cisco 2702AP unexpectedly reloads on LWAPP REAP PROCESS |
| CSCuu89294 | Primary AP in Flex Group not saved in WLC CFG nor in commands backup |
| CSCuu90899 | Cisco 1850AP: Setting telnet to AP specific, enable, changes the AP to WIPS |
| CSCuu91001 | Netflow record sent without client IP address |
| CSCuu93296 | EAP-TLS loosing device certificate in standalone mode after reboot |
| CSCuu97757 | Turning off 2.4GHz & 5 GHz band not reflecting on SPARTAN |
| CSCuu98988 | CAPWAPv6 not doing DNSv6 query for CISCO-CAPWAP-CONTROLLER |
| CSCuu99344 | WLC unexpectedly reloads when DHCP packet content sent is not properly handled while on new mobility |
| CSCuv03380 | During Mesh Roam, security error, Gateway not reachable leading to CAPWAP Restart |
| CSCuv03963 | Multiple Cisco 8510WLC running 8.0.110.18 release unexpectedly reloads Data Plane |
| CSCuv04255 | Cisco 8510 WLC not getting portal page while doing central web authentication |
| CSCuv08570 | Cisco 1532AP loses all configuration at times after power cycle |
| CSCuv10692 | AckFailureCount getting huge value in short period. |
| CSCuv18403 | WLC not lifting mobility tunnel (Data Path Down) running 8.1 release |
| CSCuv20940 | Client fail to ping IPv6 gateway, clients with HA switchover |
| CSCuv22052 | Link local multicast control traffic sent by APs, with IGMP Snooping Enabled |
| CSCuv22951 | Radio reset with reset code of 37 |
| CSCuv27120 | Cannot configure IP address x.x.x.255 or x.x.x.0 as gateway |
| CSCuv27320 | Wired clients in Cisco 702W AP leaking traffic across ports/vLANs |
| CSCuv30948 | Local Net Users not saved in configuration backup file |
| CSCuv33255 | Cisco Mobility Express UI: CDP/LLDP showing blank for IOS AP -should display Cisco Discovery Protocol (CDP) info |

Table 8 **Open Caveats**

Γ

| Table 8 | Open Caveats |
|------------|---|
| Bug ID | Headline (continued) |
| CSCuv36096 | Some clients are not getting classified even though they are online for flex local switching |
| CSCuv36306 | Cisco 2702AP in Monitor Mode sensord_crashFile with no CleanAir measurements |
| CSCuv40033 | Cisco WLC IPv6 IAPP WIPS reports vulnerability |
| CSCuv41888 | Cisco 1570AP receive 153-3-JA3/JA4 image, sends BPDU to the network |
| CSCuv48278 | Unable to connect clients in 802.11ac Mode for -D domain |
| CSCuv57038 | Cisco 1850 AP - One or more clients ARP not reachable in 200 clients test |
| CSCuv59060 | Cisco Mobility Express: RADIUS authentication will not work if you have multiple servers and delete one of them |
| CSCuv59274 | CPU spike in Cisco 1142AP and utilization is at 100% all the time |
| CSCuv60759 | WLAN: Reading from controller for multiple scenarios (listed) is not working |
| CSCuv61271 | Window DHCP BAD_ADDRESS for Access Points |
| CSCuv69967 | OEAP600 wired 802.1x remote LAN forward traffic in 802.1x Required State |
| CSCuv78137 | Internal AP of Mobility Express unexpectedly reloads in CAPWAP during pre-image download |
| CSCuv78490 | Cisco Mobility Express: No provision to delete the ACL name created in UI |
| CSCuv80382 | Cisco Mobility Express: Kernel panic due possible reuse of buffer |
| CSCuv80668 | Multicast traffic not forwarded when WLAN ID is an even number |
| CSCuv82711 | WLC 5508 8.1.111.0. RFC-3576 Disconnect-Request not heard from port 3799 |
| CSCuw02258 | Severity Filter for Monitoring CleanAir Interferes does not work |
| CSCuw12472 | Cisco 5520/8540 controllers show unexpected behavior on Port Link Status/LED activity |
| CSCuw12544 | Rate-limiting is causing 500ms gap of traffic when roaming |
| CSCuw13264 | Cisco 702W AP missing interface information on controller after HA failover |
| CSCuw19713 | Increased Ping latency & Reduced traffic on Cisco 8510WLC with AVC enabled |
| CSCuw21701 | Cisco 1600AP running on 8.2.x release unexpectedly reloads on CFT timer process |
| CSCuw24958 | AP fails to transmit ADDBA response if a data packet is retried previously |
| CSCuw26377 | Cisco WLC reloads unexpectedly because of invalid for field validation on switch_cfg_rw.html |
| CSCuw26629 | MIB message on power supply status on Cisco Flex 7500 WLC is wrong |
| CSCuw27420 | Cisco 3702AP unexpectedly reloads on 8.1MR2 cco image - CFT Timer Process |
| CSCuw28141 | Reaper Reset: Task SNMPTask missed software watchdog |
| CSCuw28246 | Cisco 5520/8540 controllers does not detect power supply cable failure |
| CSCuw31813 | FlexConnect local authentication, client roaming in-out-in during 802.1x |
| CSCuw31820 | WLC CP reloads unexpectedly due to System for apfMsConnTask_6 |
| CSCuw33715 | WLC unexpectedly reloads on 802.11k processing |
| CSCuw48922 | IW 3702: Poor roaming behavior with 2 6M video streams |

1

| Bug ID | Headline (continued) |
|------------|--|
| CSCuw50324 | System unexpectedly reloads on high CPU for bonjour |
| CSCuw51155 | Cisco Mobility Express: Overwrites some WLAN configurations when edited using the UI |
| CSCuw52341 | WLC unexpectedly reloads with RRM task RRM-CLNT-5_0 |
| CSCuw60505 | WLC system reloads unexpectedly at apfFreeMobileStationEntry during 802.11x scale test |
| CSCuw60983 | Cisco 3602 AP unexpectedly reloads due to DHCP Client Process |
| CSCuw61235 | Cisco Mobility Express: Multiple 1850APs may become primary controllers at the same time |
| CSCuw74421 | Cisco Mobility Express: Apple iOS devices not connecting to Fast Transition enabled WLAN on IOS APs |
| CSCuw89581 | WLC System unexpectedly reloads on apfReceive Task |

Table 8Open Caveats

Resolved Caveats

ſ

Use the Cisco BST to view the details of a caveat listed in this section. For more information about the Cisco BST, see the "Cisco Bug Search Tool" section on page 27.

| Bug ID | Headline |
|------------|--|
| CSCtu45614 | Spectrum Management Bit Should be set to 1 all the time |
| CSCuq79283 | Cisco 1142n 1042n 1140 APs traceback dot11_set_frame_templates |
| CSCur71315 | Cisco 1552 MESH AP bridge Transmit voice queue stuck, leading to out of Tx buffers |
| CSCus53495 | DFS detection due to Broadcom spurious emissions in Cisco 2700 and 3700 APs |
| CSCus61679 | Issue in client statistics reports |
| CSCut07170 | Cisco 1532AP: WGB intermittently doesn't see incoming probe responses |
| CSCut33114 | LAG with 1G does not work in Cisco 5520 and Cisco 8540 WLCs |
| CSCut62319 | Broadcast Key Rotation does not occur after MAC Filtering is enabled |
| CSCut83422 | Cisco vWLC serial number changed after management interface ip change |
| CSCut98006 | DFS detections due to high energy profile signature on Cisco 2600AP and 3600AP |
| CSCuu05565 | NDP packets not transmitted on secondary 20 channels |
| CSCuu32049 | WGB attempts to send IAPP change channel event during scanning, roaming |
| CSCuu34220 | Observed traceback in Cisco WLC doing rogue test. |
| CSCuu37437 | Cisco 8510 WLC restarts unexpectedly while NMSP polling in progress |
| CSCuu47016 | Cisco Application Visibility and Control UDP Vulnerability |
| CSCuu54100 | Switching between SSIDs fails with FAST SSID enabled on PMIPv6 WLANs |
| CSCuu59589 | False positive AP sourced AP impersonation on corrupted beacon |

Table 9 Resolved Caveats

| Table 9 | Resolved Caveats |
|------------|---|
| Bug ID | Headline (continued) |
| CSCuu68490 | Duplicate radius-acct update message sent while roaming |
| CSCuu72366 | Cisco 5508 WLC reloads unexpectedly on 8.0.110.x mmListen process |
| CSCuu82416 | Evaluation of WLC for OpenSSL June 2015 |
| CSCuu85603 | FlexConnect + MeshAP shows Incorrect channel info in sh mesh convergence list output |
| CSCuu86265 | FlexConnect AP Local switching WLAN specific losing VLAN Mapping configuration |
| CSCuu86587 | DN1/DN2: Need closed loop on Cisco 5520 and 8540 WLC cavium fan control |
| CSCuu98667 | vWLC: Low Scale VM auto reboots while downloading image -2GB default memory |
| CSCuu99823 | 8.0.x: Cisco 7510 WLC and Cisco 8510 WLC reloads unexpectedly with Taskname: Spamreceivetask |
| CSCuv00107 | PMIPv6 client MAC address shows up on the MAC address table of the switch |
| CSCuv00598 | Optimized Roaming per WLAN feature |
| CSCuv00856 | CleanAir process fails to start for 1572 AP when using 169,173 Channel |
| CSCuv09655 | On 8.0.110.x the anchor reloads unexpectedly on new mobility apf_msDeleteTblEntry |
| CSCuv28555 | Cisco 3702 AP - Voice Queue stuck, with no new clients able to associate |
| CSCuv34946 | EOGRE and PMIPv6 client fails to move to Run state |
| CSCuv37613 | Apple devices failing 802.11r Fast Transition roaming |
| CSCuv43057 | Cisco Mobility Express: System reloads unexpectedly on ConfigSynctoAp |
| CSCuv44568 | Downloading RADIUS AVP via GUI does not load Vendor IDs correctly. |
| CSCuv47241 | Cisco 5500 WLC reloads unexpectedly with SNMP walk on 8.2.1.43 |
| CSCuv47679 | EoGRE client traffic packet with DF bit set is getting fragmented |
| CSCuv48219 | Cisco Universal Small Cell module does not turn operational after AP reboot in centralized mode |
| CSCuv51521 | Active WLC should send GARPs when HA Re-Paring after Active-Active state |
| CSCuv57159 | Cisco Mobility Express: MC2UC conversion not happening |
| CSCuv61883 | Error message to be corrected for error popped up (a generic issue) |
| CSCuv63073 | Cisco Mobility Express: Confusing message when next-preferred-primary is the current primary AP |
| CSCuv72545 | Mobility Express Controller takes a long time to come up in Day 0 mode |
| CSCuv74068 | Cisco 3700AP low throughput with Cisco 3700 WGB 40mhz |
| CSCuv74590 | Please delay reboot if image upgrade is in progress |
| CSCuv79694 | Cisco Aironet 1850 Access Point Privileged Escalation Vulnerability |
| CSCuv80866 | WLAN Security 'WPA2 Personal' has WPA AES policy enabled |
| CSCuv81907 | Cisco Mobility Express: Show time has garbage on NTP authentication status |
| CSCuv83856 | Read/Write user is unable to edit settings from GUI |

1

| Bug ID | Headline (continued) | | |
|------------|--|--|--|
| | | | |
| CSCuv86624 | Cisco Mobility Express: HTTPS Day-1 GUI connection presents WebAuth cert instead of WebAdmin | | |
| CSCuv88543 | Cisco Mobility Express -UI: Uploads with special characters under Admin acc GUI Kicks off | | |
| CSCuv90042 | Cisco FastLocate distant clients have strong RSSI value from AP intermittently | | |
| CSCuv90508 | WLAN Count: Deleting last WLAN does not update WLAN count | | |
| CSCuv90567 | Cisco Mobility Express: Changing controller country code does not update Internal AP | | |
| CSCuv90769 | Unable to schedule pre-image download for 12 - 12.30PM | | |
| CSCuv92645 | SNMP walk on clsDownloadFileType returns invalid enum for Cisco Mobility Express controller | | |
| CSCuv92719 | vWLC unexpectedly reloads on 8.1.111.x serving the RF dashboard web page | | |
| CSCuv93732 | Cisco Hyperlocation not working after adding WLC to CMX | | |
| CSCuv95254 | Failed to associate Cisco 7925 phones | | |
| CSCuv97538 | Mu-beamformee field in VHT Cap IE is enabled in association response | | |
| CSCuw02126 | Cisco Hyperlocation last digit of NTP server is dropped when address has 12 digits | | |
| CSCuw02922 | Show rules is empty for Cisco Mobility Express controller | | |
| CSCuw06153 | Unauthorized configuration change for web management | | |
| CSCuw19551 | Cisco Mobility Express: show time not shown as "AUTH SUCCESS" when NTP Sync happens | | |
| CSCuw29419 | Cisco WLC: Radius Packet of Disconnect Vulnerability | | |
| CSCuw30799 | Kernel panic at IPReassembler on internal AP, while pre-image download | | |
| CSCuw38455 | Cisco 1832AP unable to detect rogue ap | | |
| CSCuw40623 | NBAR timer running for 7 weeks may trigger an unexpected reload | | |
| CSCuw47234 | Cisco Mobility Express: Transfer upload datatype coredump broken | | |
| CSCuw48570 | Cisco Mobility Express UI: Apply button in creating WLAN is not working | | |

Table 9Resolved Caveats

Γ

Cisco Mobility Express Solution Release Notes

Note

The Cisco Mobility Express wireless network solution is available starting from Cisco Wireless Release 8.1.122.0 only.

The Cisco Mobility Express wireless network solution provides a wireless LAN controller functionality bundled into, currently, the Cisco Aironet 1850 and 1830 series access points. This functionality provides a simplified Wi-Fi architecture with limited enterprise-level WLAN capability to small and medium deployments.

In the Cisco Mobility Express wireless network solution, one access point, running the Cisco Mobility Express wireless controller, is designated as the primary AP. Other access points, referred to as Subordinate APs, associate to this primary AP.

The primary AP operates as a wireless LAN controller, to manage and control the subordinate APs, and also operates as an access point to serve clients. The subordinate APs behave as normal lightweight access points to serve clients.

For more information on the solution, including set up and configuration, see the *Cisco Mobility Express* User Guide for Release 8.1, at this URL:

http://www.cisco.com/c/en/us/td/docs/wireless/access_point/mob_exp/1/user_guide/b_ME_User_Guid e.html

| APs supported as Primary (support integrated wireless controller capability) | APs supported as Subordinates | |
|--|--|--|
| Cisco Aironet 1850 Series | In addition to the following, all APs that are supported as primary APs are also supported as subordinate APs. | |
| Cisco Aironet 1830 Series | | |
| | Cisco Aironet 700i Series | |
| | Cisco Aironet 700w Series | |
| | Cisco Aironet 1600 Series | |
| | Cisco Aironet 1700 Series | |
| | Cisco Aironet 2600 Series | |
| | Cisco Aironet 2700 Series | |
| | Cisco Aironet 3500 Series | |
| | Cisco Aironet 3600 Series | |
| | Cisco Aironet 3700 Series | |

Supported Cisco Aironet Access Points

Supported Features

- Scalability:
 - Up to 25 APs
 - Up to 500 clients
 - Up to 16 WLANs
 - Up to 100 rogue APs
 - Up to 1000 rogue clients
- License—Does not require any licenses (Cisco Right-To-Use License or Swift) for access points.
- Operation— The primary AP can concurrently function as controller (to manage APs) and as an AP (to serve clients).
- Initial configuration wizard.
- Priming at distribution site.
- Default Service Set Identifier (SSID), set from factory—Yes, for initial provisioning only.
- Management—Through a web interface monitoring dashboard.
- Cisco Wireless Controller Best Practices.
- Quality of Service (QoS).
- Multicast with default settings.
- Application Visibility and Control (AVC)—Limited HTTP, with only Application Visibility and not Control. Deep packet inspection with 1,500+ signatures.
- WLAN access control lists (ACLs).
- Roaming—Layer 2 roaming without mobility groups.
- IPv6—For client bridging only.
- High Density Experience (HDX)—Supported when managing access points that support HDX.
- Radio Resource Management (RRM)—Supported within AP group only.
- WPA2 Security.
- WLAN-VLAN Mapping.
- Guest WLAN login (Web Authorization).
- Local EAP Authentication (Local Radius Server) .
- Local Profile.
- Network Time Protocol (NTP) Server.
- Cisco Discovery Protocol (CDP) and Link Layer Discovery Protocol (LLDP).
- Clean Air.

ſ

- Simple Network Management Protocol (SNMP).
- Management SSH / Telnet / Admin users.
- Reset to factory defaults.
- Serviceability Core file and core options, Logging and syslog.
- Cisco Prime Infrastructure.

- CMX 10.x Only Location Presence.
- BYOD On boarding only.
- UX Regulatory Domain.
- Allow Authentication, Authorization, Accounting (AAA) Override.
- IEEE 802.11k
- IEEE 802.11r.
 - Supported: Over-the-Air Fast BSS transition method
 - Not Supported: Over-the-DS Fast BSS transition and Fast Transition PSK authentication
- Passive Client
- Voice with Call admission control (CAC), with Traffic Specification (TSpec)
- Fast SSID
- TACACS (Terminal Access Controller Access Control System)
- Management over wireless
- High Availability and Redundancy—Built-in redundancy mechanism to self-select a primary AP and to select a new AP as primary in case of a failure. Supported using VRRP.
- Software upgrade with pre image download
- Migration to controller-based deployment.

Compatibility with Other Cisco Wireless Solutions

See the *Cisco Wireless Solutions Software Compatibility Matrix*, at the following URL: http://www.cisco.com/c/en/us/td/docs/wireless/compatibility/matrix/compatibility-matrix.html

New Features and Functionalities

This release focuses on bug fixes. No new features or functionalities have been introduced in this release in comparison to the previous release.

Software Release Information

| Software type and purpose | For AP 1850 | For AP 1830 |
|---|--------------------------------|--------------------------------|
| Software to be used only for conversion from Unified Wireless Network Lightweight Access Points software to Cisco Mobility Express software. | AIR-AP1850-K9-8.1.131.0.tar | AIR-AP1830-K9-8.1.131.0.tar |
| Access Point software image bundle, to be used for software update and/or supported access points images. | AIR-AP1850-K9-ME-8-1-131-0.zip | AIR-AP1830-K9-ME-8-1-131-0.zip |

Cisco Mobility Express software for Cisco Wireless Release 8.1.131.0, is as follows:

Installing Mobility Express Software

See the Getting Started section in the Mobility Express User Guide at the following URL:

http://www.cisco.com/c/en/us/td/docs/wireless/access_point/mob_exp/1/user_guide/b_ME_User_Guid e.html

Caveats

I

The open caveats applicable to the Cisco Mobility Express solution are listed under the "Caveats" section on page 27. All caveats associated with the Cisco Mobility Express solution have *Cisco Mobility Express* mentioned in the headline.

Related Documentation

• Cisco Mobility Express User Guide

http://www.cisco.com/c/en/us/td/docs/wireless/access_point/mob_exp/1/user_guide/b_ME_User_Guid e.html

• Cisco Aironet Universal AP Priming and Cisco AirProvision User Guide

http://www.cisco.com/c/en/us/td/docs/wireless/access_point/ux-ap/guide/uxap-mobapp-g.html

Installation Notes

This section contains important information to keep in mind when installing Cisco WLCs and access points.

Warnings



This warning means danger. You are in a situation that could cause bodily injury. Before you work on any equipment, be aware of the hazards involved with electrical circuitry and be familiar with standard practices for preventing accidents. Use the statement number provided at the end of each warning to locate its translation in the translated safety warnings that accompanied this device. Statement 1071

Warning

Only trained and qualified personnel should be allowed to install, replace, or service this equipment. Statement 1030



Do not locate the antenna near overhead power lines or other electric light or power circuits, or where it can come into contact with such circuits. When installing the antenna, take extreme care not to come into contact with such circuits, as they may cause serious injury or death. For proper installation and grounding of the antenna, please refer to national and local codes (e.g. U.S.: NFPA 70, National Electrical Code, Article 810, Canada: Canadian Electrical Code, Section 54). Statement 280



This product relies on the building's installation for short-circuit (overcurrent) protection. Ensure that a fuse or circuit breaker no larger than 120 VAC, 15A U.S. (240 VAC, 10A international) is used on the phase conductors (all current-carrying conductors). Statement 13



This equipment must be grounded. Never defeat the ground conductor or operate the equipment in the absence of a suitably installed ground connector. Contact the appropriate electrical inspection authority or an electrician if you are uncertain that suitable grounding is available. Statement 1024



Read the installation instructions before you connect the system to its power source. Statement 10



Do not work on the system or connect or disconnect any cables (Ethernet, cable, or power) during periods of lightning activity. The possibility of serious physical injury exists if lightning should strike and travel through those cables. In addition, the equipment could be damaged by the higher levels of static electricity present in the atmosphere. Statement 276



Do not operate the unit near unshielded blasting caps or in an explosive environment unless the device has been modified to be especially qualified for such use. Statement 364



In order to comply with radio frequency (RF) exposure limits, the antennas for this product should be positioned no less than 6.56 ft. (2 m) from your body or nearby persons. Statement 339



This unit is intended for installation in restricted access areas. A restricted access area can be accessed only through the use of a special tool, lock and key, or other means of security. Statement 1017

Safety Information

Follow the guidelines in this section to ensure proper operation and safe use of the Cisco WLCs and access points.

FCC Safety Compliance Statement

FCC Compliance with its action in ET Docket 96-8, has adopted a safety standard for human exposure to RF electromagnetic energy emitted by FCC-certified equipment. When used with approved Cisco Aironet antennas, Cisco Aironet products meet the uncontrolled environmental limits found in OET-65 and ANSI C95.1, 1991. Proper operation of this radio device according to the instructions in this publication results in user exposure substantially below the FCC recommended limits.

Safety Precautions

For your safety, and to help you achieve a good installation, read and follow these safety precautions. They might save your life.

- If you are installing an antenna for the first time, for your own safety as well as others', seek professional assistance. Your Cisco sales representative can explain which mounting method to use for the size and type of antenna you are about to install.
- Select your installation site with safety as well as performance in mind. Electric power lines and phone lines look alike. For your safety, assume that any overhead line can kill you.
- Call your electric power company. Tell them your plans and ask them to come look at your proposed installation. This is a small inconvenience considering your life is at stake.
- Plan your installation carefully and completely before you begin. Successfully raising a mast or tower is largely a matter of coordination. Each person should be assigned to a specific task and should know what to do and when to do it. One person should be in charge of the operation to issue instructions and watch for signs of trouble.
- When installing an antenna, remember:
 - Do not use a metal ladder.
 - Do not work on a wet or windy day.
 - Do dress properly—shoes with rubber soles and heels, rubber gloves, long-sleeved shirt or jacket.
- If the assembly starts to drop, get away from it and let it fall. Remember that the antenna, mast, cable, and metal guy wires are all excellent conductors of electrical current. Even the slightest touch of any of these parts to a power line completes an electrical path through the antenna and the installer: **you!**

- If any part of an antenna system should come in contact with a power line, do not touch it or try to remove it yourself. Call your local power company. They will remove it safely.
- If an accident should occur with the power lines, call for qualified emergency help immediately.

Installation Instructions

See the appropriate quick start guide or hardware installation guide for instructions on installing Cisco Wireless Controllers and APs.



To meet regulatory restrictions, all external antenna configurations must be installed by experts.

Personnel installing the Cisco WLCs and APs must understand wireless techniques and grounding methods. APs with internal antennas can be installed by an experienced IT professional.

The Cisco WLC must be installed by a network administrator or qualified IT professional, and the proper country code must be selected. After the installation, access to the Cisco WLC should be password protected by the installer to maintain compliance with regulatory requirements and ensure proper unit functionality.

Service and Support

Troubleshooting

| Step 1 | For the most up-to-date, detailed troubleshooting information, see the Cisco TAC website at: |
|--------|--|
| | http://www.cisco.com/c/en/us/support/index.html |
| Step 2 | Choose Product Support > Wireless . |
| Step 3 | Choose your product and click Troubleshooting to find information about the problem you are experiencing. |

Related Documentation

For more information about the Cisco WLCs, lightweight access points, and mesh access points, see these documents:

- The quick start guide or installation guide for your particular Cisco WLC or access point
- Cisco Wireless Controller Configuration Guide
- Cisco Wireless Controller Command Reference
- Cisco Wireless Controller System Message Guide

You can access these documents at http://www.cisco.com/c/en/us/support/wireless/wireless-lan-controller-software/tsd-products-support-s eries-home.html

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, submitting a service request, and gathering additional information, see *What's New in Cisco Product Documentation* at: http://www.cisco.com/c/en/us/td/docs/general/whatsnew/whatsnew.html.

Subscribe to *What's New in Cisco Product Documentation*, which lists all new and revised Cisco technical documentation, as an RSS feed and deliver content directly to your desktop using a reader application. The RSS feeds are a free service.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2015 Cisco Systems, Inc. All rights reserved.

