



Voice Over Wireless LAN (VoWLAN) Troubleshooting Checklist

Published: June 4, 2010

Revised: June 4, 2010

Voice Over Wireless LAN (VoWLAN) Troubleshooting Checklist

The following is a checklist that is recommended when troubleshooting a Voice Over Wireless LAN (VoWLAN). It also defines best practices and additional options that may need to be taken into consideration.

Table 1-1 VoWLAN checklist

Recommendation	Best Practice	May Consider	Done
Verify an AP can be seen from the phone at -67 dBm or better in all areas to be covered. You also need to verify that the AP sees the phone at -67 dBm or better in all areas as well.	X		
Ensure that the SNR is always 25 dB or higher in all areas to provide coverage.	X		
Verify that channel utilization is under 50%.	X		
Configure voice WLAN to use the 802.11a band.		X	
If using EAP authentication, ensure that fast roaming is supported such as CCKM.	X		
WMM should be allowed or required for the voice WLAN.	X		
Voice WLAN should be marked with Platinum QoS.	X		
Platinum QoS profile should have the 802.1p bits set to 6.	X		



Americas Headquarters:
Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

Table 1-1 VoWLAN checklist (continued)

Recommendation	Best Practice	May Consider	Done
Verify the switch ports used to connect to the controller are set to trust CoS and ports to APs and uplinks are set to trust DSCP.	X		
Verify that Call Admission Control is enabled globally for the radios.	X		
Verify that Load-based CAC is enabled under Call Admission Control.	X		
Ensure that Load Based CAC (7920 AP CAC) under the WLAN is enabled for the voice WLAN if the network has a mix of 7920 and 792xG Series wireless IP phones.	X		
Ensure that Client Based CAC (7920 Client CAC) under the WLAN is disabled for the voice WLAN.	X		
Verify that the EDCA profile on the controller is set to Voice Optimized.	X		
Verify that Low Latency MAC is disabled.	X		
Verify that the 12 Mbps data rate is enabled (default PHY rate of the phone).	X		
If using 802.11b/g disable the 1, 2, 5.5, 6, and 9 Mbps data rates if possible.	X		
If using 802.11a disable the 6 and 9 Mbps data rates if possible.	X		
Verify coverage is designed for 24 Mbps to maximize throughput. Optionally disable 36-54 Mbps.		X	
Optionally disable 36-54Mbps			
Verify that Aggressive Load Balancing is disabled.		X	
Disabled ARP unicast if running a pre-4.2 image on the controller.	X		
Verify that DTPC is enabled so that the client and AP match tx power levels.	X		
Verify the Beacon interval is set to 100 ms.	X		
A DTIM of 2 is recommended.	X		
Ensure DHCP required is not enabled for the voice WLAN.		X	
Ensure that Aironet IE is enabled for the voice WLAN.	X		
Verify that Client MFP is set to Optional or Disabled.	X		
Session timeout for the WLAN should not be too short (300 seconds or more).	X		
Verify that peer-to-peer blocking is disabled.	X		
If using TKIP encryption, disable the hold down timer on the voice WLAN to prevent MIC errors from disrupting voice.	X		

Table 1-1 VoWLAN checklist (continued)

Recommendation	Best Practice	May Consider	Done
Verify that the radio of the AP has multiple antennas and that diversity is enabled.	X		
Ensure controllers are configured for Symmetric Mobility if phones will be roaming between controllers.		X	
Validate the virtual interface address is the same across all controllers in the same mobility group.	X		
Validate that the mobility status shows as UP between all controllers in the same mobility group.	X		
Enable Traffic Stream Metrics collection on the controller.	X		
DCA Channel Sensitivity set to High to reduce chance of channel changes during business hours.	X		

CCDE, CCENT, CCSI, Cisco Eos, Cisco Explorer, Cisco HealthPresence, Cisco IronPort, the Cisco logo, Cisco Nurse Connect, Cisco Pulse, Cisco SensorBase, Cisco StackPower, Cisco StadiumVision, Cisco TelePresence, Cisco TrustSec, Cisco Unified Computing System, Cisco WebEx, DCE, Flip Channels, Flip for Good, Flip Mino, Flipshare (Design), Flip Ultra, Flip Video, Flip Video (Design), Instant Broadband, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn, Cisco Capital, Cisco Capital (Design), Cisco:Financed (Stylized), Cisco Store, Flip Gift Card, and One Million Acts of Green are service marks; and Access Registrar, Aironet, AllTouch, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Lumin, Cisco Nexus, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, Continuum, EtherFast, EtherSwitch, Event Center, Explorer, Follow Me Browsing, GainMaker, iLYNX, IOS, iPhone, IronPort, the IronPort logo, Laser Link, LightStream, Linksys, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, PCNow, PIX, PowerKEY, PowerPanels, PowerTV, PowerTV (Design), PowerVu, Prisma, ProConnect, ROSA, SenderBase, SMARTnet, Spectrum Expert, StackWise, WebEx, and the WebEx logo are registered trademarks of Cisco and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1002R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2010 Cisco Systems, Inc. All rights reserved.

 Printed in the USA on recycled paper containing 10% postconsumer waste.