


# Cisco IOS Real-time Transport

## Protocol(RTP) Denial of Service(DoS) Vulnerability



Cisco Bug ID : Cisco-SA-20110610-CVE-2011-1631

[CVE-2011-1631](#)

Published : 2011-06-10 22:07

Version : 1.0 : Final

CVSS Score : 4.3

Workarounds : No Workarounds available

Cisco Bug ID :

**Denial of Service (DoS) Vulnerability in Cisco IOS Real-time Transport Protocol (RTP) Version 1.0**

**Medium**

Cisco

IOS Real-time Transport Protocol (RTP) Denial of Service (DoS) Vulnerability

The vulnerability exists in the RTP protocol implementation in Cisco IOS. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) by sending a specially crafted RTP packet to the target device. The vulnerability is caused by a buffer overflow in the RTP packet processing code.

The vulnerability is caused by a buffer overflow in the RTP packet processing code. The vulnerability exists in the RTP protocol implementation in Cisco IOS.

The vulnerability exists in the RTP protocol implementation in Cisco IOS. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) by sending a specially crafted RTP packet to the target device. The vulnerability is caused by a buffer overflow in the RTP packet processing code.

The vulnerability exists in the RTP protocol implementation in Cisco IOS. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) by sending a specially crafted RTP packet to the target device. The vulnerability is caused by a buffer overflow in the RTP packet processing code.

The vulnerability exists in the RTP protocol implementation in Cisco IOS. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) by sending a specially crafted RTP packet to the target device. The vulnerability is caused by a buffer overflow in the RTP packet processing code.

**CVSS Score: 4.3**

Cisco Bug ID

[CSCsy52459](#) i1/4^ç™»éCE²ãf!ãf!4ã, ¶i1/4%õã ®è,, tã1/4±æ€Sã,'çç°èªã—ã¾ã—ãÿã€,

è,, †ã1/4±æ€§ã®ã,ã, <è£1/2ã" <

9.4.14ã, ^ã, Šã%õã®DSPwareãf•ã, jãf!ãfã, |ã, §ã, çãfãf!ã, ãfšãf³ã, 'ã«ã, €12.4(15)Txã, ^ã, Šã%õã® IOSã, 1/2ãf•ãf^ã, |ã, §ã, çãfãf!ã, ãfšãf³ã®CEã1/2±éÿã, 'ã—ã'ã¾ã™ã€, Cisco IOSã, 1/2ãf•ãf^ã, |ã, §ã, çã®æœ€èè'ã®ãfãf!ã, ãfšãf³ã®šã-ã€ã'ã®è,, tã1/4±æ€Sã, 'ã«ã

è,, †ã1/4±æ€§ã, 'ã«ã, "ãšã,,ãªã,,ã"ã"ã®CEçç°èªã•ã, CEãÿè£1/2ã" <

ã»-ã®ã,ã,1ã,³è£1/2ã"ã«ãšã,,ã|ã"ã®ã, çãf%õãfã, ðã, ¶ãfãã®ã1/2±éÿã, 'ã—ã'ã,

### ã>žéç-

é©ã^†ãªã, 1/2ãf•ãf^ã, |ã, §ã, çã, çãfãfã—ãf†ãf!ãf^ã, 'é©ç"ã™ã, <ã"ã"ã, 'æŽ"ã¥"ã—ã¾ã™ã, ãf—ãfãf^ã, ¾ãf«ã®CEã, è|ãªã'ã^ã-ã®RTPã†|ç†ã®ç,, jãš1ãCE-ã, 'æœœè"Žãšã®ã¾ã¾ã é†è|ãªã,ã,1ãf†ãfã, 'ççèè-ã™ã, <ã"ã"ã, 'æŽ"ã¥"ã—ã¾ã¾ã™ã€,

### ã;®æ£æ, ^ãçã, 1/2ãf•ãf^ã, |ã, §ã, ç

æœ%õãš1ãªã¥ç'„ã, 'çµã, "ãšã,,ã, <ã,ã,1ã,³ã®ãšã®çæš-ã-ã®Ciscoã®Software Centerã,ã,%õã, çãfãfã—ãf†ãf!ãf^ã, 'ã...¥æ%õããšã®ã¾ã¾ã™ã€,ã¥ç'„ã, 'çµã, "ãšã,,ãªã Technical Assistance Center(TAC)ã«1-800-553-2447ã¾ã¾ãÿã-1-408-526-7209ãšé€çµjã™ã,ã«ã®[tac@cisco.com](mailto:tac@cisco.com)ã«é»ããfjãf!ãf^ãšã, çãfãfã—ã, °ãf-ãf!ãf%õã, 'ã...¥

### ã, æ£ã^©ç"ã°<ã¾ã"ã"ã...-ã1/4ç™°èj"

Cisco Product Security Incident Response Team i1/4^PSIRT i1/4%õã-ã®æœ-ã, çãf%õãfã, ðã, ¶ãfãã«è"~è1/4%õã•ã, CEã|ã,,ã, <è,, tã1/4±æ€Sã®

### URL

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/Cisco-SA-20110610-CVE-2011-1631>

### æ"1è",ã±¥æ'

ãfãf!ã, ãfšãf³	èª-æŽ	ã, »ã, -ã, ãfšãf³	ã,1ãf†ãf!ã, çã,1	æ-¥ã»
1.0	ã^çç%õã^ãfãf³ãf!ã,1	é©ç"ãª-	Final	2011ã1'6æœ^10æ-¥

å^©ç"è!ç´,,

æœ-ã,çãf%ãfã,ã,ã,ã,ãfãç,,iàçè"¼ã®ã,,ã®ããã-ãã|ã"æãã¾ãã-ãã|ãŠã,Šã  
æœ-ã,çãf%ãfã,ã,ã,ãfãã®æf...å±ãŠã,ã³ãfã³ã,ã®ã½çç"ã«é-çã™ã,«è²-ã»ã®ã,ã  
ã¾ãŸã€ã,ã,ã,ãæœ-ãf%ã,ãfãfãfãfã®å†...å®¹ã,ã^ãŠããã-ã«å%ãæ'ã-ã  
æœ-ã,çãf%ãfã,ã,ã,ãfãã®è"~èç°å†...å®¹ã«é-çã-ãã|æf...å±é...ãçjã® URL  
ã,çœç•ãã-ã€ããçãçãã«çè¼%ã,,æ,,è"³ã,ã-½ãã-ãŸã'ã^ã€ã½"ç¾ãÇç®çç  
ã"ã®ãf%ã,ãfãfãfãfã®æf...å±ããã,ã,ã,ã,ã,ãè½å"ã®,ãfãf%ãf!ãf¼ã,ã,ã¾è±jã

## 翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。