

Cisco Firepower Management

Center (FMC) Web Interface - Remote Code Execution (RCE) Vulnerability



Cisco Security Advisory ID : cisco-sa-

[CVE-2017-](#)

20170906-firepower-2

[12221](#)

Published : 2017-09-06 16:00

Version : 1.0 : Final

CVSS Score : [5.4](#)

Workarounds : No workarounds available

Cisco Bug ID : [CSCvc38983](#)

Remote Code Execution (RCE) vulnerability in Cisco Firepower Management Center (FMC) Web Interface allows an attacker to execute arbitrary code on the target device.

Summary

Cisco Firepower Management

Center (FMC) Web Interface - Remote Code Execution (RCE) Vulnerability

The vulnerability is located in the `WebInterface` component of the `Firepower Management Center` software.

The vulnerability is caused by a buffer overflow in the `WebInterface` component.

The vulnerability is caused by a buffer overflow in the `WebInterface` component.

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20170906-firepower-2>

Technical Details

The vulnerability is located in the `WebInterface` component.

The vulnerability is caused by a buffer overflow in the `WebInterface` component.

The vulnerability is caused by a buffer overflow in the `WebInterface` component.

The vulnerability is caused by a buffer overflow in the `WebInterface` component.

The vulnerability is caused by a buffer overflow in the `WebInterface` component.

The vulnerability is caused by a buffer overflow in the `WebInterface` component.

ã>žéç-

ã"ãè,,†ã±æ€šã«ã¼ã†|ã™ã,ã>žéç-ã-ã,ã,šã¼ã>ã,"ã€,

ä;®æ£æ, ^ãçã,½ãf•ãf^ã, |ã,šã,ç

ä;®æ£æ, ^ãçã,½ãf•ãf^ã, |ã,šã,ç

ãfãfãf¼ã,¹ã®è³ç°ã«ãªã,,ã|ã-ã€æœ-ã,çãf%ããfã,ªã,¶ãfãã,šéfã® Cisco Bug ID ã,ã,ç...šããããããã,,ã€,

ã,½ãf•ãf^ã,ã,šã,çã®ã,çãffãf-ã,°ãf-ãf¼ããf%ãã,æœœè"Žã™ã,«és>ã«ã-ã€[ã,ã,¹ã,³ã®ã,»ã,ãf Security Advisories and Alerts[¼%]

ãfšãf¼ã,ãšã...¥æ%ãšããã,ã,ã,¹ã,³è£½ã"ã®ã,çãf%ããfã,ªã,¶ãfãã,ã®šæœÿçš,,ã«ã,çã,½ãfããf¼ã,ãfããf³ã,çç°èãã-ã|ããããããã,,ã€,

ã,,ãšã,çã®ãã'ã^ã,,ã€ã,çãffãf-ã,°ãf-ãf¼ããf%ãã™ã,ãfããfã,ªã,¹ã«ããã^ããfãfãfçã Technical Assistance

Center[¼TAC[¼%ã,,ã-ãããã-ãç'ç,,ã-ã|ã,,ã,ãfããfãfãfãã,¹ãf-ããfã,ªãfãf¼ãã<

ä,æ£ã^ç""ã°<ã¼ã"ã...-ã¼ç™°èj"

Cisco Product Security Incident Response

Team[¼PSIRT[¼%ã-ã€æœ-ã,çãf%ããfã,ªã,¶ãfãã«è"~è¼%ãã,çã|ã,,ã,«è,,†ã±æ€šã<

ã†°ã... ,

æœ-è,,†ã±æ€šã-ã€ã,ã,¹ã,³ã†...éfãšã®ã,»ã,ãfããfãfã,£ãfã,¹ãf^ã«ã,^ã£ã|ç™°è|ãã,çã¼ã-ãÿã€,

URL

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20170906-firepower-2>

æ"¹è",ã±¥æ'

| ããf¼ã,ãfšãf³ | è-æ~Ž | ã,»ã,-ã,ãfšãf³ | ã,¹ãfããf¼ã,çã,¹ | æ-¥ã~ |
|--------------|-------------------------|----------------|-----------------|----------------------|
| 1.0 | ã^ã>žã...-é-ãfããfãf¼ã,¹ | - | Final | 2017 ã¹' 9 æœ^ 6 æ-¥ |

ã^ç"è|ç' ,,

翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。