

Cisco Aironet 1560/2800/3800 WPA2-PSK Weak IV Collision Resistance

802.11

«Cisco Aironet 1560/2800/3800 WPA2-PSK Weak IV Collision Resistance



Severity: High
Published: 2017-11-01
Last updated: 2017-11-02
Type: Vulnerability
CVSS Score: 7.4
Workarounds: None available
Cisco ID: CSCve12189

[CVE-2017-12273](#)

This vulnerability has been assigned a CVSS score of 7.4.

Affected Products:

Cisco Aironet 1560/2800/3800 wireless access points (WAPs) running Cisco IOS Software, version 15.0(2)S1 or earlier, are affected by this vulnerability. The affected models include the Cisco Aironet 1560 Series, Cisco Aironet 2800 Series, and Cisco Aironet 3800 Series.

Impact:

This vulnerability allows an attacker to perform a man-in-the-middle attack on WPA2-PSK protected wireless networks. An attacker can capture and modify wireless traffic, potentially leading to sensitive information disclosure, session hijacking, or other malicious activities. The exploit leverages a weakness in the IEEE 802.11 standard regarding the handling of weak IV collisions during the four-way handshake process.

ā♦“ā♦®è,,†å½±æ€§ā♦«å¬¾å†! ā♦™ä,«ä,½äf·äf~ä,|ä,§ä,ç
ä,çäffäf—äf‡äf½äf~ä,~ä€♦ä♦™ä♦§ä♦«ä,·ä,¹ä,³ä♦«ä,‰oäfåäfåäf½ä,¹ä♦·ä,Œä♦|ä♦,,ä♦¾ä♦™ä€,
ä♦“ä♦®è,,†å½±æ€§ä♦«å¬¾å†! ā♦™ä,«å›é♦¿ç-ä,~ä♦,ä,šä♦¾ä♦>ä,“ä€,

<https://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20171101-aironet1>

è©²å¹½“è£¹½å“◆?

è,,†å¼±æ€§ã®ã,ã,«è£½å“?

„Lightweight AP Mobility Express

ã,¤ãf;ãf¼ã,ã?®ã?,,ã?šã,(Eã?ã,'å®Ýè;|Eã?—ã? |ã?,,ã,ã,è~~ã,·ã,¹ã,³èF½å“?ã?«å½éÝ;ã?—

- Aironet 1560 ª,·äf^aäf^{l/4}ä,º ä,çä,¬ä,»ä,¹ äf♦ä,¤äf³äf[~]
 - Aironet 2800 ä,äf^aäf^{l/4}ä,º ä,çä,¬ä,»ä,¹ äf♦ä,¤äf³äf[~]
 - Aironet 3800 ä,·äf^aäf^{l/4}ä,º ä,çä,¬ä,»ä,¹ äf♦ä,¤äf³äf[~]

æ³·: Cisco Aironet 1560 æ·ƒªƒ½æ·° æ·¢æ·-æ·»æ·¹ æ·ƒ◆æ·¤æƒ³æƒ·
æƒ‡æƒ◆æ·¤æ·¹æ·«æ·¤æ◆„æ·!æ·-æ·€◆æƒªæƒ·æƒ½æ·¹ 8.3.112.0
æ·¥é™◆æ·§æ·µæƒ◆æƒ½æƒ·æ·•æ·Œæ◆|æ·„æ·¾æ·™æ·€,

ã,½ãf•ãf^ã,|ã,§ã,c ãf♦ãf¼ã,ãf§ãf³ã,'å^¤å^¥ã♦—ã♦|ã,<ã♦•ã♦,,

Cisco Aironet 1100 Series Wireless Access Points

Webā, αf^3 , $f^{1/4}$, f^\bullet , \S , α^1 , ϵ , \tilde{f} , \circ , αf^3

Webā,¤äf³ä,çäf%äf•ä,§ä,¤ä,¹ä♦«ä½¿ç”™ä,¤ä♦Ýä,¤ä♦«ä€♦ ç®¡ç♦† >

ä, å, ï, ö, ü, ÿ, ð, ç

ā,čāffāf—āſtāf¼āſtā, 'é◊,æŠzā◊—ā€◊æ¬jā◊«āfšāf¼ā, ā◊®ā, Šā◊§ç◊¾ā, ◊ā, Ěā, <āf^aāf^aāf¹¼ā

CLI æ,’æ½ç”æ?™æ,æ?Ýæ,æ?æ?«æ€æ? show version

ã,³ãfžãf³ãf%oã,’ç™oè;Œ—ã€œæ¬|ã«ã,³ãfžãf³ãf%o å‡ºåŠãœ® Image

„**äf•ä, £äf^{1/4}äf«äf%oä, 'å®Öè; (Eä♦™ä, < AP ä♦®å€¤ä, 'å♦, ç...§ä♦—ä♦ | ä, ä♦•ä♦ „ä€,**

æ¬;ã♦®ä¾⁴ã♦~ã,½ãf•ãf^ã,|ã,šã,c ãf♦ãf¼ã,ãffsãf³ 8.3.102.0

ã,’å®ÿè;Œã♦™ã,<ãf‡ãf♦ã,¤ã,¹ã♦®ã♦ÿã,♦ã♦®ã,³ãfžãf³ãf%oã♦®å‡ºåŠ›ã,’ç¤ºã♦—ã♦ÿã,,ã♦®ã

<#root>

AP# show version

.

cisco AIR-AP3802E-B-K9 ARMv7 Processor rev 1 (v7l) with 1030528/668540K bytes of memory.

Processor board ID RFDPP1BS497

AP Running Image :

8.3.102.0

Primary Boot Image : 8.3.102.0

.

.

.

è,,†å¼±æ€§ã,’å♦«ã,“ã♦§ã♦,,ã♦ªã♦,,ã♦“ã♦~ã♦Œç¢°èªã♦ã♦

ã»—ã♦®ã,·ã,¹ã,³è£½å“ã♦«ã♦§ã♦,,ã♦|ã€♦ã♦“ã♦®ã,çãf%oãf♦ã,¤ã,¶ãfªã♦®å½±éÿçã,’å♦—ã

ã,·ã,¹ã,³ã♦~ã€♦ã♦“ã♦®è,,†å¼±æ€§ã♦Œ Cisco Aironet 1800 ã,·ãfªãf¼ã,º ã,cã,~ã,»ã,¹
ãf♦ã,¤ãf³ãf^ã♦³/4ã♦ÿã♦~ Cisco IOS

ã,½ãf•ãf^ã,|ã,šã,cã,’å®ÿè;Œã♦—ã♦|ã♦,,ã,¤ã,‰oã,tã,< Aironet ã,cã,~ã,»ã,¹
ãf♦ã,¤ãf³ãf^ã♦«å½±éÿçã,’ä,žã♦~ã♦ªã♦,,ã♦“ã♦~ã,’ç¢°èªã♦—ã♦³/4ã♦—ã♦ÿã€,

è©³ç`°

ã»ã,ãf¥ãfªãf†ã,£ã³/4µ®³ã♦®ç—•è·í

å›žé♦¿ç-

ã♦“ã♦®è,,†å¼±æ€§ã♦«å~¾å‡|ã♦™ã,<å›žé♦¿ç—ã♦~ã,§ã♦³/4ã♦»ã,“ã€,

ã¿®æ£æ,~ã♦¿ã,½ãf•ãf^ã,|ã,šã,c

ã,·ã,¹ã,³ã♦~ã♦“ã♦®ã,çãf%oãf♦ã,¤ã,¶ãfªã♦“è~è¼‰oã♦•ã,Œã♦ÿè,,†å¼±æ€§ã♦«å~¾å‡|ã♦™ã,<ç„í
ã,cãffãf—ãf‡ãf¼ãf^ã,’æ♦ã♦æ³/4ã♦—ã♦|ã♦,,ã♦³/4ã♦™ã€,

ã♦§ã®çæ§~ã♦Œã,¤ãf³ã,¹ãf^ãf¼ãf«ã♦—ã♦ÿã,§ã,µãf♦ãf¼ãf^ã,’å♦—ã♦’ã♦ÿã,§ã,§ã,¤ã,¤ã®ã

ãf♦ãf¼ã,ãf§ãf³ã♦~ãf•ã,£ãf¼ãf♦ãf£

ã»ãffãf^ã♦«å~¾ã♦—ã♦|ã♦®ã,ã♦¿ã♦~ã♦ªã,§ã♦³/4ã♦™ã€,

ä ◊ ◊ ä ◊ ® ä, ^ ä ◊ t ä ◊ ^ ä, ½ ä f • ä f ^ ä, | ä, § ä, ç

ã,çäffäf—ã,ºäf¬äf¼äf‰oã,‘ä,¤äf³ä,‘äf°äf«ä€♦äf€ä,‘äf³äfäf¼äf‰oã♦™ä,‘ä€♦ä€♦¾ä♦Ýä♦—ä€♦äf©ä,¤ä,‘äf³ä,‘ä♦®æ♦é ...ä♦«å¾“ä♦tä♦“ä♦”ä♦«å♦Œæ,,♦ä♦—ä♦Ýä♦“ä♦”ä♦«ä♦”ä,Šä♦¾ä,

<http://www.cisco.com/en/US/docs/general/warranty/English/EU1KEN.html>

„**Ý**ä€**Š**å®**C**æ**S**~**ã****CE**ä,½äf•äf~ä,|**ã**,**š**ä,**c**ä,’äfëä,|**ã**f³äfäf%4äf%0oä**Š**ä[?]**?**ä,**<**a**®**ä**~**ä€**ä**,
é€šå,,ä€**ä****”**ä,**CE**ä**~**ä»¥å%0o**è**³¼å»...¥ä**—**ä**Ý**ä,½äf•äf~ä,|**ã**,**š**ä,**c**ä**®**äfjäf³äftäfšäf³ä,
ä,**c**äffäf—ä,**°**äf~äf%4äf%0oä**Š**ä**™**ä€, **ç**,**„**ä**®**ä,**»**ä,äf¥äf~äftä,f ä,½äf•äf~ä,|**ã**,**š**ä,**c**
ä,**c**äffäf—äf#äf%4äf~ä**«**ä,^ä**£**ä**?**|ä€**ä****Š**å®**C**æ**S**~ä**?****«**æ~°ä**—**ä**„**ä,½äf•äf~ä,|**ã**,**š**ä,**c**
äf@ä,**¤**ä,**»**äf³ä,1ä€**è****½**äS ä,½äf•äf~ä,|**ã**,**š**ä,**c**äf•ä,£äf%4äf**äf**£
ä,**»**äffäf~ä**€****ä****¾**ä**?****Ý**ä**~**äfjä,äf£äf%4 äf~äf~ä,äfšäf³
ä,**c**äffäf—ä,**°**äf~äf%4äf%0oä**«****å**³¼ä**™**ä,**<**æ[~]**©**é**™****?****ã****CE**ä[~]ä,**ž**ä**•**ä,**CE**ä,**<**ä**”**ä**~**ä**?****ã****~**ä**?****ã**,**Š**ä**¾**ä**?**

ã,½ãf•ãf^ã,|ã,§ã,cã®ã,Cãffãf—ã,°ãf¬ãf¼ãf‰ã,'æœèŽã™ã,<éš>ã«ã?—ã€?Cisco Security
[Advisories and Alerts](#)

ãfšāf¹/4ã, ã~~ø~~Šå...¥æ‰o<ã~~ø~~Šã~~ø~~ã~~ø~~ã, ¹ã, ³è£½å“~~ø~~ã~~ø~~®ã, cãf%
ã, ½ãf²ãf¥ãf¹/4ã, ·ãf§ãf³ã, 'cç°è^a~~ø~~ã~~ø~~—ã~~ø~~ | ã~~ø~~ã~~ø~~ã~~ø~~ ã~~ø~~•ã~~ø~~, „ã,

ã„ãšã, Æã®å`å^ã,, ã€ã, çãffãf—ã, °ãf¬ãf¼ãf%oã™ã, <ãf‡ãfã, ã, ¹ã««å‡å`å^ã‡ãfjãfçã
ä, æ~žã‡äç, ¹ã«ã‡ã, „ã‡|ã‡~ã€Cisco Technical Assistance
Centerï¼^TACIï¼%oã,, ã‡—ã‡ã‡~å¥'ç„ã‡—ã‡|ã‡, „ã, <ãfjãf³ãftãfSãf³ã, ¹
ãf—ãfãfã, ããf€ãf¼ã«ã‡Šå•ã‡, å‡^ã, ã‡>ã‡ã‡ã‡ ã‡•ã‡, „ã€,

ä,ã,f¹¼äf“ä,¹å¥‘ç‘,,ã,’ä◊”å^©ç”“ä◊§ä◊^ä◊,,ä◊Šå®çæ§~

http://www.cisco.com/en/US/support/tsd_cisco_worldwide_contacts.html

ä; ®æ£æ, ^ã♦? ; ãƒªãƒªãƒ½ã, 1

ã, «ã, ¹ã, ãfžãf¹/4ã — ã€ ã ã “ã ã ®ã, »ã, — ã, ·ãf§ãf³ã ã ®èi .. ã «æ² ã ã Fã ã | ã€ ã é ã ©å ^ã ã a ãf^aãf^aãf¹/4ã, æœ—ã, çãf%oãf ã, ã, ¶ã, ¶ãf^aã — ã» ¥ã, <ã ®ã, çãf%oãf ã, ã, ¶ã, ¶ãf^aã, 'å ã «ã, €ã, ³ãf—ã, — ã, ·ãf§ãf³ã ®ã, €éf .. ã, ¹½ãf^aãf¹/4ã, ·ãf§ãf³ã, 'çç°è^a ã — ã? | ã? ? ã? ã? ã? • ã? ?, „ã,

- [cisco-sa-20171101-aironet1](#): Cisco Aironet 1560 2800 ãšã, ^ãš 3800 ã, ·ãfãšf¼ã, °ã, çã, ~ã, »ã, ¹ ãfãšã, þãf³ãf^ãf—ãf©ãffãf^ãf•ã, ©ãf¼ãf ãšã® 802.11 ã«ãšã, ¹ã, µãf¼ãf^ã, ¹ã | .. å®³i¼^DoSi¼‰ã®è,, †å¼±æ€§

- [cisco-sa-20171101-aironet2](#): Cisco Aironet 1560ã€“2800ã€“3800 ã·ãƒ„ãƒ½ã, ° ã,çã,¬ã,»ã,¹ ãf♦ã,¤ãƒ³ãf^ ãf—ãf©ãffãf^ãf•ã,©ãf½ãf ã♦ãsã♦® Extensible Authentication Protocol ã♦«ã♦ãsã♦’ã,«ã,µãf½ãf”ã,¹ã | ° å®³i¼^DoSi¼‰ã♦®è,,†å½±æ€§
- [cisco-sa-20171101-wlc1](#): ã,·ã,¹ã,³ ãf~ã,¤ãf¤ãf~ã,¹ LAN ã,³ãf³ãf^ãfãf½ãf©ã♦ãsã♦®ã,·ãf³ãf—ãf«ãf♦ãffãf^ãf~ãf½ã,¬ç®¡ç♦†ãf—ãfãf~ã,³ãf«ãfjãfçãf^ãf³ãf½ã,¬ã♦«ã♦ãsã♦’ã,«ã,µãf½ãf”ã,¹ã | ° å®³i¼^DoSi¼‰ã♦®è,,†å½±æ€§
- [cisco-sa-20171101-wlc2](#): ã,·ã,¹ã,³ ãf~ã,¤ãf¤ãf~ã,¹ LAN ã,³ãf³ãf^ãfãf½ãf©ã♦ãsã♦® 802.11v Basic Service Set ç§»èjŒç®¡ç♦†ã♦«ã♦ãsã♦’ã,«ã,µãf½ãf”ã,¹ã | ° å®³i¼^DoSi¼‰ã♦®è,,†å½±æ€§

æ¬jã♦®èj ° ã♦ãsã♦¬ã€♦å·|ã♦®å^—ã♦«ã,·ã,¹ã,³

ã,½ãf•ãf~ã,|ã,§ã,çã♦®ãfãfãf½ã,¹ã,’ç¤°ã♦—ã♦|ã♦,ã♦¾ã♦™ã€,

ã,å¤®ã♦®å^—ã♦¬ã€♦ã♦”ã♦®è,,†å½±æ€§ã♦®ä¿®æ£ã♦Œå♦«ã♦¾ã,Œã♦Ýæœ€å^ã♦ã♦®æŽ”å
å♦¾ã♦®å^—ã♦¬ã€♦ã♦”ã♦®ã,çãf‰ãf♦ã,¤ã,¶ãf¤é,†ã♦ãsè^æ~žã♦—ã♦|ã♦,ã,«ã♦™ã♦¹ã♦|ã♦

Cisco Aironet 1560ã€“2800ã€“3800 ã,çã,¬ã,»ã,¹ ãf♦ã,¤ãƒ³ãf^	ã♦“ã♦®è,,†å½±æ€§ã♦®ã♦Ýã,♦ã♦®æŽ”å¥”ã♦•ã,Œã,«ã¿®æ£æ,^ã♦
Prior to 8.0	è©²å½“ã♦^ã♦—
8.0	è©²å½“ã♦^ã♦—
8.1	è©²å½“ã♦^ã♦—
8.2	8.2.166.0
8.3	8.3.133.0
8.4	8.4.100.0
8.5	8.5.105.0

ã,♦æ£å^©ç””ã°<ã¾ã♦”å...¬å½ç™øèj”

Cisco Product Security Incident Response

Teamï¼^PSIRTï¼‰ã♦ãsã♦¬ã€♦æœ¬ã,çãf‰ãf♦ã,¤ã,¶ãf¤ã♦«è ° ~è½‰ã♦•ã,Œã♦|ã♦,ã,«è,,†å½±æ€§

å‡ºå...,

æœ¬è,,†å½±æ€§ã♦¬ã€♦ã,·ã,¹ã,³å...éf”ã♦ãsã♦®ã,»ã,ãf¥ãf¤ãftã,F
ãftã,¹ãf~ã♦«ã,^ã♦£ã♦|ç™øè|<ã♦•ã,Œã♦¾ã♦—ã♦Ýã€,

URL

<https://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20171101-aironet1>

æ”¹è”,å±¥æ‘

â€”

Version	Description
1.1	ãf"ãf"ãf¼ã,¹ 8.2 ã“ 8.3 ã“-ã€-ã“Så®çæ§~ã“Rå•♦é Œã“å“¾å‡ ã“™ã,<ã“Yã,♦ã“«å†♦ã“ãf"ãf“ãf%oã“•ã,Œãæž“å¥“ãf"ãf¼ã,¹ã“Œæ‘æ-°ã“•ã,Œã“¾ã“—ã“Yã€,
1.0	å^♦å›žå...¬é-<ãf"ãf"ãf¼ã,¹

å^©ç”“è|♦ç‘,

æœ¬ã,çãf%oãf♦ã,¤ã,¶ãf"ã“ç„jä;♦è“¼ã“Rã,,ã“®ã““ã“—ã“|ã“"æ♦♦æ¾»ã“—ã“|ã“Sã,Sã€æœ¬ã,çãf%oãf♦ã,¤ã,¶ãf"ã“®æf...å±ã“Sã,^ã“³ãf"ãf³ã,¬ã“®ä½ç““ã“«é-çã“™ã,<è²¬ä»»ã“®ä,€ã“¾ã“Yã€♦ã,·ã,¹ã,³ã“æœ¬ãf%oã,ãf¥ãf|ãf³ãf^ã“®å†...å®¹ã,’äº^å“Sã““ã“—ã“«å¤%oæ‘ã“—ã“æœ¬ã,çãf%oãf♦ã,¤ã,¶ãf"ã“®è“~è;°å†...å®¹ã“«é-çã“—ã“|æf...å±é...♦äç|ã“® URL
ã,’çœ♦ç·¥ã“—ã€♦å♦~ç<-ã“®è»çè¼%oã,,æ,,♦è“³ã,’æ-½ã“—ã“Yã’å“^ã€♦å½“ç¤¾ã“Œç®|ç?ã““ã“®ãf%oã,ãf¥ãf|ãf³ãf^ã“®æf...å±ã“~ã€♦ã,·ã,¹ã,³è£½å“♦ã“®ã,“ãf³ãf%oãf!ãf¼ã,¶ã,’å“¾è±|ã“

翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。