

Cisco Aironet 1810 1830 1850 ³ ₁ Point-to-Point Tunneling Protocol (PPTP) Denial of Service (DoS) ³ ₁



Severity: High
Product: Cisco Aironet 1810 1830 1850
Version: PPTP 1.0
CVSS: 8.6
Workarounds: No workarounds available
Cisco ID: CSCv73890

[CVE-2018-0234](#)

Summary: A Denial of Service (DoS) vulnerability exists in Cisco Aironet 1810 1830 1850 routers running PPTP 1.0. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) on the affected devices.

Impact: Denial of Service (DoS)

Cisco 1810 1830 1850 routers running PPTP 1.0 are vulnerable to a Denial of Service (DoS) attack. The vulnerability is caused by a buffer overflow in the PPTP implementation.

The vulnerability is caused by a buffer overflow in the PPTP implementation. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) on the affected devices.

The vulnerability is caused by a buffer overflow in the PPTP implementation. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) on the affected devices.

The vulnerability is caused by a buffer overflow in the PPTP implementation. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) on the affected devices.

The vulnerability is caused by a buffer overflow in the PPTP implementation. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) on the affected devices.

The vulnerability is caused by a buffer overflow in the PPTP implementation. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) on the affected devices.

The vulnerability is caused by a buffer overflow in the PPTP implementation. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) on the affected devices.

The vulnerability is caused by a buffer overflow in the PPTP implementation. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) on the affected devices.

The vulnerability is caused by a buffer overflow in the PPTP implementation. An attacker can exploit this vulnerability to cause a Denial of Service (DoS) on the affected devices.

DoS çŠ¶æ...ã«é™¥ã, cá 'á^ãÇã,ã,Šã¼ã™ã€,

ã"ã®è,,†á¼±æ€šã«ã¼á†|ã™ã,ã,½ãf•ãf^ã,|ã,šã,ç

ã,çãffãf—ãfã¼ãf^ã™ãšã«ã,ã,¹ã,³ã«ã,%ããfããf¼ã,¹ã•ã,Çã|ã,,ã¼ã™ã€,ã"ã®è,,†á¼±æ€šã«ã¼á†|ã™ã,ã,žéç-ã-ã,ã,Šã¼ã™ã,ã,"ã€,

ã"ã®ã,çãf%ãã,ã,¶ã,¶ãã-ã€æ-ã®ãfããf³ã,-ã,^ã,Šçç°èªãšããã¼ã™ã€,
<https://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20180502-ap-ptp>

è©²á¹/²‘è£¹/²á“

è,,†á¼±æ€šã®ã,ã,«è£¹/²á“

ã"ã®è,,†á¼±æ€šã™ãCisco Mobility Expressã,½ãf•ãf^ã,|ã,šã,çãfããf¼ã,¹

8.4.100.0ã€8.5.103.0ã€ã¼ãÝã 8.5.105.0

ã,'ã®ÿè;Çã—ã€ãfžã,¹ã,çãf¼ãã¼"ã±žãã¼ãÝã-ã,¹ã,çãfããf%ãã,çããããã®ã,çã,-ã,»ã

ãfã,ããf³ãf^ã-ã-ã|æš«æ^ã•ã,Çã|ã,,ã,« Cisco Aironet

1810ã€1830ã€ãšã,^ã³ 1850ã,ãfããf¼ã,°ã,çã,-ã,»ã,¹

ãfã,ããf³ãf^ã«ã¼±éÿã,ã,žã^ã¼ã™ã€,

ã,½ãf•ãf^ã,¹ã,šã,çãfããf¼ã,¹ã®ã^ã^¥

Cisco Mobility Express

ã,³ãf³ãf^ããf¼ãããŠã,^ã³é-çé€£ä»~ã'ã,%ãã,Çã|ã,,ã,ã,çã,-ã,»ã,¹

ãfã,ããf³ãf^ãšã®ÿè;Çã•ã,Çã|ã,,ã,« Cisco Mobility Expressã,½ãf•ãf^ã,|ã,šã,ç

ãfããfããf¼ã,¹ã™ãç®;ç®†è€...ãÇã,³ãf³ãf^ããf¼ããã® Web

ã,ããf³ã,çãf¼ããf•ã,šã,ãã,¹ã¼ãÝã-ã,çã,-ã,»ã,¹ãfã,ããf³ãf^ã® CLI

ã,'ã¼çç""ã-ã|çç°èªãšããã¼ã™ã€,

ã,³ãf³ãf^ããf¼ããã® Web

ã,ããf³ã,çãf¼ããf•ã,šã,ãã,¹ã,'ã¼çç""ã™ã,ã'ã^ã-ã€æ-ã,'ã®ÿè;Çã—ã¼ã™ã€,

- 1.ãf-ããã,¹ã,¶ã,'ã¼çç""ã-ã|ã€Web
ã,ããf³ã,çãf¼ããf•ã,šã,ãã,¹ã«ãfã,°ã,ããf³ã-ã¼ã™ã€,
2. [ç®;ç®†i¼^Managementi¼%] > [ã,½ãf•ãf^ã,|ã,šã,çã,çãffãf—ãfã¼ãf^i¼^Software Updatei¼%]ã,'é,æšžã-ã¼ã™ã€,
- 3.ãfšããf¼ã,ã,šçf"ã«è;ç®ã•ã,Çã,ããfããfããf¼ã,¹ç°ãã,ã'ã,ç...šã-ã¼ã™ã€,

ã,çã,-ã,»ã,¹ãfã,ããf³ãf^ã® CLIã,'ã¼çç""ã™ã,ã'ã^ã-ã€Telnetã¼ãÝã-SSH

ã,'ã¼çç""ã-ã|ã,çã,-ã,»ã,¹ãfã,ããf³ãf^ã«ãfã,°ã,ããf³ã-ã€show version

ã,³ãfžãããf%ãã,'ã®ÿè;Çã—ã|ããã®ã^ãšã,ã'ã,ç...šã-ã¼ã™ã€,

æ-ãã«ã€Cisco Mobility Express Software Release 8.3.111.0ã,'ã®ÿè;Çã™ã,«

ã, çäffäf—äffäff¼äff^ã, 'æ ä¾ã—ã | ä, „ã¾ã™ã€,
ãŠå@çæš~ã@Eã, ðäff³ã, 'äff^äff¼äff«ã—ãYã, Šã, µäffäff¼äff^ã, 'ã—ãäYã, Šãšããã, <ã@ã
äffäff¼ã, äffšäff³ã äff•ã, £äff¼äffäff£
ã, »äffäff^ã«ã¾ã—ã | ä@ãäã äff³ã, Šã¾ã™ã€,
ããã@ã, ^ãtäãªã, ½äff•äff^ã, | ä, šã, ç
ã, çäffäf—ã, °äff-äff¼äff%ã, 'ã, ðäff³ã, 'äff^äff¼äff«ã€äff€ä, | äff³äffäff¼äff%ã™ã, <ã€äã¾ãYã-ã€ä
äff@ã, ðã, »äff³ã, 'ã@æ;é ...ã«ã¾ãtäã“ã äff³ã«ã@Eæ,, äã—ãYã“ã äff³ã, Šã¾ã¾ã
<https://www.cisco.com/c/en/us/products/end-user-license-agreement.html>

ã¾ãYã€ãŠå@çæš~ã@Eã, ½äff•äff^ã, | ä, šã, çã, 'äff€ã, | äff³äffäff¼äff%ãšããã, <ã@ã-ã€ä,
éçšã, ä€ã“ã, @Eã-ã»¥ã%ãè¾ã...¥ã—ãYã, ½äff•äff^ã, | ä, šã, çã@äff;äff³äffäffšäff³ã, '1
ã, çäffäf—ã, °äff-äff¼äff%ãšã™ã€, ç,, ä, Yã@ã, »ã, äff¥äffäfftä, £ã, ½äff•äff^ã, | ä, šã, ç
ã, çäffäf—äffäff¼äff^ã«ã, ^ã£ã | ä€ããŠå@çæš~ã«æ-°ã—ã, „ã, ½äff•äff^ã, | ä, šã, ç
äff@ã, ðã, »äff³ã, 'ã€è½ãŠã, ½äff•äff^ã, | ä, šã, ç äff•ã, £äff¼äffäff£
ã, »äffäff^ãã¾ãYã-äff;ã, äff£äff¼ äff³ã, äffšäff³
ã, çäffäf—ã, °äff-äff¼äff%ã«ã¾ã™ã, <æ“@é™ã@Eã»ã, Žã•ã, @Eã, <ã“ã-ã-ã, ä, Šã¾ã¾ã

ã, ½äff•äff^ã, | ä, šã, çã@ã, çäffäf—ã, °äff-äff¼äff%ã, 'ææœèŽã™ã, <és>ã«ã-ã€ä [Cisco Security](#)
[Advisories and Alerts](#)
[äffäff¼ã](#), äšã...¥æ%ãšããã, <ã, •ã, 'ã, ³è£½ã”ã@ã, çäff%ãäffã, ðã, ¶äff³ã, 'ã@šæœYçš, ä«ã, ç
ã, ½äff³äff¥äff¼ã, äffšäff³ã, 'ççèªã—ã | äããããããã, ä€,

ã, äšã, @Eã@ã 'ã^ã, ä€ã, çäffäf—ã, °äff-äff¼äff%ã™ã, äffäffã, ðã, 'ã«ãããtäªäff;äffçã
ä, æ~Žãªç, 'ã«ãããã, äã | ä-ã€ä Cisco Technical Assistance
Centeri¼^TACi¼%ã, ä—ããã-ã¥ç', ä—ã | ä, „ã, <äff;äff³äffäffšäff³ã, '1
äff—äffäffã, ðäff€äff¼ã«ãŠå@çæš~ã, ä^ã, äã>ãããããã, ä€,

ã, µäff¼äff“ã, 'ã¥ç', „ã, 'ã”ã^ç””ãšãªãã, „ãŠå@çæš~
ã, .ã, 'ã, ³ããã, %ãç'æŽ¥è¾ã...¥ã—ãYã@Eã, .ã, 'ã, ³ã@ã, µäff¼äff“ã, 'ã¥ç', „ã, 'ã”ã^ç””ã, „ãYã
äff™äff³äff€äff¼ã<ã, %ãè¾ã...¥ã—ãYã@Eãä@æ£æ, ^ãäã, ½äff•äff^ã, | ä, šã, çã, 'è¾ã...¥ã...^ã<ã, %ã
Technical Assistance
Centeri¼^TACi¼%ã«é£çµ;ã—ã | ä, çäffäf—ã, °äff-äff¼äff%ã, 'ã...¥æ%ã—ã | äããããããã
<https://www.cisco.com/c/en/us/support/web/tsd-cisco-worldwide-contacts.html>

ç,, ä, Yã, çäffäf—ã, °äff-äff¼äff%ã@ã¾ãè±;è£½ã”ãšããã, ä, <ã“ã-ã-ã, è¼æ~Žã—ã | ä, „ãYã
URL ä, 'ã”ã”æ,, äããããããã, ä€,

ä;@æ£æ, ^ãäãäff³äff¼ã, '1

ã, <ã, 'ã, çäffäff¼ã-ã€äããã@ã, »ã, -ã, äffšäff³ã@è;”ã«æ²ãä£ä | ä€äéç@ã^täªäff³äff¼ã, '1

ä, æ£â^©ç''' ä°<ä¾<ã " å...-å¼ç™°èj''

Cisco Product Security Incident Response

Teami¼^PSIRTi¼%õ ðšã ð-ã€ ðæœ-ã, çãf%õãf ðã, ðã, ¶ãfã ð«è''è¼%õã ð•ã, ÇEã ð |ã ð,,ã, <è,, tå¼±æ€

å±°å...,

ã, .ã, 1ã, 3ã ð-ã€ ðã ð"ã ð®è,, tå¼±æ€šã, 'å ±å'šã ð-ã ð |ã ð,,ã ðÿã ðã ð,,ã ðÿ CableCom
Networking ð® Simon Lockhart æ° ðã ð«æ,, ÿè-ðã ð,,ã ðÿã ð-ã ð¾ã ð™ã€,

URL

<https://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20180502-ap-ntp>

æ''1è'', å±Yæ'

â€''

Version	Description	Section	Status	æ-Yã»~
1.0	å^ ð>žå...-é-<ãfããfãf¼ã, 1		Final	2018 å1' 5 æœ^ 2 æ-Y

å^©ç'''è!ç',,,

æœ-ã, çãf%õãf ðã, ðã, ¶ãfã ð-ç,, jã ç è''¼ã ð®ã,,ã ð®ã ð-ã ð-ã ð |ã ð"æ ð ð¾ã>ã ð-ã ð |ã ðšã, šã€
æœ-ã, çãf%õãf ðã, ðã, ¶ãfã ð®æf...å ±ã ðšã, ^ã ð³ãfããf³ã, -ã ð®ã¼çç'''ã ð«é-çã ð™ã, <è²-ã»»ã ð®ã, €
ã ð¾ã ðÿã€ ðã, .ã, 1ã, 3ã ð-æœ-ãf%õã,ãfããfãf³ã ð®å t...å®1ã, 'å^å'šã ðªã ð-ã ð«å¼%õæ'ã ð-ã ð
æœ-ã, çãf%õãf ðã, ðã, ¶ãfã ð®è''è:°å t...å®1ã ð«é-çã ð-ã ð |æf...å ±é... ðã ç jã ð® URL
ã, çœ ðç•¥ã ð-ã€ ðå ð~ç<-ã ð®è»çè¼%õã,,,æ,, ðè''³ã, 'æ-½ã ð-ã ðÿã 'å ð^ã€ ðå¼"ç¾¾ã ðÇç®|ç ð
ã ð"ã ð®ãf%õã,ãfããfãf³ãf^ã ð®æf...å ±ã ð-ã€ ðã, .ã, 1ã, 3è£½å" ðã ð®ã, ''ãf³ãf%õãf |ãf¼ã, ¶ã, 'å³¼è±jã

翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。