

RV130W: Latam/RV130W/Default Inbound Access Rule Policy

Date Identified

May 25, 2017

Date Resolved

N/A

Products Affected

RV130W	1.0.3.22

Problem Description

If an Allow Access Control List (ACL) has been configured to allow traffic from a specific host or network, and then a Block ACL is configured, the Block ACL will deny traffic that is supposed to be permitted.

Current Status

Beta software version 1.0.3.25 fixed this issue and the public firmware will be published in the next official firmware release of RV130W.