



## Caveats

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The “Open Caveats” sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.
- The “Resolved Caveats” sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.



**Note** The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- [Resolved Caveats - Cisco IOS XE 17.13.1, on page 1](#)
- [Open Caveats - Cisco IOS XE 17.13.1, on page 2](#)
- [Cisco Bug Search Tool, on page 2](#)

## Resolved Caveats - Cisco IOS XE 17.13.1

Identifier	Headline
<a href="#">CSCwf14167</a>	RSP3: uea_mgr memory leak on ARP probes
<a href="#">CSCwf27439</a>	IMD timer value update for ISSU process
<a href="#">CSCwf90667</a>	IMA8Z:frequent reloads of IM due to high temp- FAN speed mismatch
<a href="#">CSCwf42164</a>	No snmp trap link-status get re-added after IM reload
<a href="#">CSCwe82657</a>	VIN P2/0, VOUT P2/2, VIN P4/0 & VOUT P4/2 alarms upon SSO
<a href="#">CSCwf77276</a>	Memory leak seen on chunk module when BDI routed network traffic flow along with mac move
<a href="#">CSCwf49426</a>	PAIS alarm get reported after IM OIR.

Identifier	Headline
<a href="#">CSCwf77316</a>	RSP3: MPLS incorrect label programmed with scenarios of double implicit-null
<a href="#">CSCwf69937</a>	The portchannel does not come up on adding recommended configs till we reload the router
<a href="#">CSCwf18367</a>	RSP3 : uea_mgr RIFID leak/consumption for Multicast routes
<a href="#">CSCwf07736</a>	cem interface counters momentarily report error when x21 xconnect is cleared and re-established
<a href="#">CSCwh42209</a>	RSS memory increment continuously seen uea_mgr process upon system event
<a href="#">CSCwf54249</a>	With CPG, STS1e configuration is giving %ERROR: Standby doesn't support this command
<a href="#">CSCwf86864</a>	CEM traffic flow is dropped in one direction due to DEI bit set from 4202
<a href="#">CSCwf37941</a>	ACL config under serial interface makes dut crash during unconfig
<a href="#">CSCwh30217</a>	NCS4200-3GMS: With rate of OC12 we see "threshold sf-ber 3" getting added under sh run

## Open Caveats - Cisco IOS XE 17.13.1

Identifier	Headline
<a href="#">CSCwh85621</a>	Layer 2 CEF interface is unavailable.
<a href="#">CSCwh80239</a>	IP SLA multicast configuration is not working.

## Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at <http://www.cisco.com/web/applicat/cbsshelp/help.html>