The bridge to possible

End-of-Sale and End-of-Life Announcement for the Cisco Application Policy Infrastructure Controller (APIC-L2 and APIC-M2) and Cisco Application Policy Infrastructure Software (2.x and 12.x)

Contents

Overview

EOL12963 - Amended

Cisco announces the end-of-sale and end-of life dates for the Cisco Application Policy Infrastructure Controller (APIC-L2 and APIC-M2) and Cisco Application Policy Infrastructure Software (2.x and 12.x). The last day to order the affected product(s) is June 20, 2019. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1.   End-of-life milestones and dates for the Cisco Application Policy Infrastructure Controller (APIC-L2 and APIC-M2) and Cisco Application Policy Infrastructure Software (2.x and 12.x)

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	March 21, 2019
End-of-Sale Date: HW, OS SW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 20, 2019
Last Ship Date: HW, OS SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	September 18, 2019
End of SW Maintenance Releases Date: HW, OS SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	June 19, 2021
End of Vulnerability/Security Support: HW	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	June 19, 2022
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	June 19, 2020
End of New Service Attachment Date: HW, OS SW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	June 19, 2020
End of Service Contract Renewal Date: HW, OS SW	The last date to extend or renew a service contract for the product.	September 15, 2023

Milestone	Definition	Date
Last Date of Support: HW, OS SW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	June 30, 2024

HW = Hardware   OS SW = Operating System Software   App. SW = Application Software

Product part numbers

Table 2.   Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
APIC-A03-D600GA2	2.5" 600GB, 10K RPM, SAS 6Gb	There is currently no replacement product available for this product.	–	–
APIC-CLUSTER-L2	APIC Cluster - Large Configurations (> 1000 Edge Ports)	APIC-CLUSTER-L3	APIC Cluster - Large Configurations (> 1200 Edge Ports)	–
APIC-CLUSTER-M2	APIC Cluster - Medium Configurations (Up to 1000 Edge Ports)	APIC-CLUSTER-M3	APIC Cluster - Medium Configurations (Up to 1200 Edge Ports)	–
APIC-CPU-E52609D	1.90 GHz E5-2609 v3/85W 6C/15MB Cache/DDR4 1600MHz	There is currently no replacement product available for this product.	–	–
APIC-CPU-E52620D	2.40 GHz E5-2620 v3/85W 6C/15MB Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	–	–
APIC-CPU-E52630D	^2.40 GHz E5-2630 v3/85W 8C/20MB Cache/DDR4 1866MHz	There is currently no replacement product available for this product.	–	–
APIC-HD12TB10K12G	1.2 TB 6G SAS 10K rpm SFF HDD	There is currently no replacement product available for this product.	–	–
APIC-HD600G10K12G	600GB 12G SAS 10K RPM SFF HDD	There is currently no replacement product available for this product.	–	–
APIC-HD600G10K12G=	^600GB 12G SAS 10K RPM SFF HDD	There is currently no replacement product available for this product.	–	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
APIC-L2	APIC Appliance – Large Configuration(> 1000 EdgePorts)	APIC-L3	APIC Appliance - Lage Configuration(> 1200 EdgePorts)	–
APIC-L2=	APIC Appliance For Large Configurations (> 1000 Edge Ports)	APIC-L3=	APIC Appliance - Lage Configuration(> 1200 EdgePorts)	–
APIC-M2	APIC Appliance – Medium Configuration(Upto 1000 EdgePorts)	APIC-M3	APIC Appliance – Medium Configuration(Upto 1200 EdgePorts)	–
APIC-M2=	APIC Appliance For Medium Configurations (Up to 1000 Ports)	APIC-M3=	APIC Appliance - Medium Configuration(Upto 1200 EdgePorts)	–
APIC-MR-1X162RU-A	16GB DDR4-2133-MHz RDIMM/PC4-17000/dual rank/x4/1.2v	There is currently no replacement product available for this product.	–	–
APIC-MR-1X322RV-A	32GB DDR4-2400-MHz RDIMM/PC4-19200/dual rank/x4/1.2v	There is currently no replacement product available for this product.	–	–
APIC-MRAID12G	Avila Cisco 12G SAS Modular Raid Controller (Raid 0/1)	There is currently no replacement product available for this product.	–	–
APIC-PCIE-C10T-02	Cisco VIC 1225T Dual Port 10GBaseT CNA	There is currently no replacement product available for this product.	–	–
APIC-PCIE-C10T-02=	Cisco VIC 1225T Dual Port 10GBaseT CNA: SPARE	There is currently no replacement product available for this product.	–	–
APIC-PCIE-CSC-02	Cisco VIC 1225 Dual Port 10Gb SFP+ CNA	There is currently no replacement product available for this product.	–	–
APIC-PCIE-CSC-02=	Cisco VIC 1225 Dual Port 10Gb SFP+ CNA: SPARE	There is currently no replacement product available for this product.	–	–
APIC-PCIE-IRJ45	Intel i350 Quad Port 1Gb Adapter	There is currently no replacement product available for this product.	–	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
APIC-PCIE-IRJ45=	Intel i350 Quad Port 1Gb Adapter	There is currently no replacement product available for this product.	–	–
APIC-PSU-BLKP1U	Power Supply Blanking Panel for C220 M4 servers	There is currently no replacement product available for this product.	–	–
APIC-SD120GBKS4-EV	120 GB 2.5 inch Enterprise Value 6G SATA SSD	There is currently no replacement product available for this product.	–	–
APIC-SD200G12S3	^200GB 2.5 inch Enterprise performance 6G SATA SSD(3 FWPD)	There is currently no replacement product available for this product.	–	–
APIC-SD200G12S3-EP	200GB 2.5 inch Enterprise performance 6G SATA SSD	There is currently no replacement product available for this product.	–	–
APIC-SD240GBKS4-EV	240 GB 2.5 inch Enterprise Value 6G SATA SSD	There is currently no replacement product available for this product.	–	–
APIC-SD240GM1X-EV	240GB 2.5 inch Enterprise Value 6G SATA SSD	There is currently no replacement product available for this product.	–	–
APIC-SD240GM1X-EV=	^240GB 2.5 inch Enterprise Value 6G SATA SSD	There is currently no replacement product available for this product.	–	–
APIC-SD400GSAS3-EP	400GB 2.5 inch Enterprise performance 12G SAS SSD	There is currently no replacement product available for this product.	–	–
APIC-SERVER-L2	APIC Appliance - Large Configurations (> 1000 Edge Ports)	There is currently no replacement product available for this product.	–	–
APIC-SERVER-L2=	APIC Appliance - Large Config. (> 1000 Edge Ports) SPARE	There is currently no replacement product available for this product.	–	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
APIC-SERVER-M2	APIC Appliance – Medium Configuration (Upto 1000 Edge Ports)	There is currently no replacement product available for this product.	–	–
APIC-SERVER-M2=	APIC Appliance – Medium (Upto 1000 Edge Ports) SPARE	There is currently no replacement product available for this product.	–	–
APIC-SIM-C10T-02=	Cisco VIC 1225T Dual Port 10GBaseT CNA: SPARE for APIC SIM	There is currently no replacement product available for this product.	–	–
APIC-SIM-CSC-02=	Cisco VIC 1225 Dual Port 10Gb SFP+ CNA: SPARE for APIC SIM	There is currently no replacement product available for this product.	–	–
APIC-SIM-S2	APIC Simulator	There is currently no replacement product available for this product.	–	–
APIC-SIM-S2=	APIC Simulator Small	There is currently no replacement product available for this product.	–	–
APIC-TPM2-001	Trusted Platform Module	There is currently no replacement product available for this product.	–	–
APIC-DK9-2.0	^APIC Base Software Release 2.0	APIC-DK9-3.2	APIC Base Software Release 3.2	–
APIC-DK9-2.0=	APIC Base Software Release 2.0	APIC-DK9-3.2=	APIC Base Software Release 3.2	–
APIC-DK9-2.1	^APIC Base Software Release 2.1	APIC-DK9-3.2	APIC Base Software Release 3.2	–
APIC-DK9-2.1=	APIC Base Software Release 2.1	APIC-DK9-3.2=	APIC Base Software Release 3.2	–
APIC-DK9-2.2	APIC Base Software Release 2.2	APIC-DK9-3.2	APIC Base Software Release 3.2	–
APIC-DK9-2.2=	APIC Base Software Release 2.1	APIC-DK9-3.2=	APIC Base Software Release 3.2	–
APIC-DK9-2.3	APIC Base Software Release 2.3	APIC-DK9-3.2	APIC Base Software Release 3.2	–
APIC-DK9-2.3=	APIC Base Software Release 2.3	APIC-DK9-3.2=	APIC Base Software Release 3.2	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
ACI-N9KDK9-12.0	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 12.0	ACI-N9KDK9-13.2	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 13.2	–
ACI-N9KDK9-12.0=	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 12.0	ACI-N9KDK9-13.2=	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 13.2	–
ACI-N9KDK9-12.1	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 12.1	ACI-N9KDK9-13.2	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 13.2	–
ACI-N9KDK9-12.1=	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 12.1	ACI-N9KDK9-13.2=	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 13.2	–
ACI-N9KDK9-12.2	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 12.2	ACI-N9KDK9-13.2	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 13.2	–
ACI-N9KDK9-12.2=	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 12.2	ACI-N9KDK9-13.2=	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 13.2	–
ACI-N9KDK9-12.3	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 12.3	ACI-N9KDK9-13.2	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 13.2	–
ACI-N9KDK9-12.3=	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 12.3	ACI-N9KDK9-13.2=	Nexus 9500 or 9300 ACI Base Software NX-OS Rel 13.2	–
APIC-SIM-DK9-2.0	^APIC Simulator Base Software Release 2.0	There is currently no replacement product available for this product.	–	–
APIC-SIM-DK9-2.0=	APIC Simulator Base Software Release 2.0	There is currently no replacement product available for this product.	–	–
APIC-SIM-DK9-2.1	^APIC Simulator Base Software Release 2.1	There is currently no replacement product available for this product.	–	–
APIC-SIM-DK9-2.1=	APIC Simulator Base Software Release 2.1	There is currently no replacement product available for this product.	–	–

Product migration options

Customers are encouraged to migrate to the latest APIC controllers (APIC-M3 and APIC-L3). Information about this product can be found at: https://www.cisco.com/c/en/us/products/collateral/cloud-systems-management/application-policy-infrastructure-controller-apic/datasheet-c78-739715.html.

Customers are encouraged to migrate to the latest APIC and ACI releases. Information about this product can be found at: https://www.cisco.com/c/en/us/products/collateral/cloud-systems-management/application-policy-infrastructure-controller-apic/datasheet-c78-732414.html.

The latest releases for APIC and ACI switch software are located here: https://www.cisco.com/c/en/us/support/cloud-systems-management/application-policy-infrastructure-controller-apic/tsd-products-support-series-home.html.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at: https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco Application Policy Infrastructure Controller (APIC-L2 and APIC-M2) through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: https://www.cisco.com/go/eos.

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to: https://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to: https://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: https://www.cisco.com/cisco/support/notifications.html.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.