End-of-Sale and End-of-Life Announcement for the Cisco 801 ISDN Router and Cisco 805 Serial Router

EOL5473

Cisco Systems® announces the end-of-sale and end-of life dates for the Cisco 801 ISDN Router and Cisco 805 Serial Router. The last day to order the Cisco 801 ISDN Router and Cisco 805 Serial Router is July 16, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin.

Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco 801 ISDN Router and Cisco 805 Serial Router. Table 2 lists the product part numbers affected by this announcement.

Table 1.   End-of-Life Milestones and Dates for the Cisco 801 ISDN Router and Cisco 805 Serial Router

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	January 15, 2007
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 16, 2007
Last Ship Date: **HW, OS SW**	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 14, 2007
End of SW Maintenance Releases Date: **OS SW**	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	July 15, 2008
End of Routine Failure Analysis Date: **HW**	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	July 15, 2008
End of New Service Attachment Date: **HW, OS SW**	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	July 15, 2008
End of Service Contract Renewal Date: **HW, OS SW**	The last date to extend or renew a service contract for the product.	October 11, 2011
Last Date of Support: **HW, OS SW**	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	July 14, 2012

HW = Hardware
OS SW = Operating System Software
App. SW = Application Software

Table 2.   Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
CISCO801	ISDN/Ethernet Router	CISCO876-SEC-I-K9	Cisco 876 Security Bundle with Advanced Enterprise features
CISCO801-1CAPI	ISDN/Ethernet Router with one-user CAPI	CISCO876-SEC-I-K9	Cisco 876 Security Bundle with Advanced Enterprise features
CISCO801-20PK	ISDN/Ethernet Router	CISCO876-SEC-I-K9	Cisco 876 Security Bundle with Advanced Enterprise features
CISCO801-RF	CISCO801 REFURBISHED	CISCO876-SEC-I-K9	Cisco 876 Security Bundle with Advanced Enterprise features
CISCO805	Cisco 805 Ethernet/Serial Router	CISCO1841-SEC/K9	1841 Security Bundle,Adv.Security,64FL/256DR
CISCO805-20PK-232	CISCO805 with RS232 Network Cable	CISCO1841-SEC/K9	1841 Security Bundle,Adv.Security,64FL/256DR
CISCO805-20PK-V35	Cisco 805 with V.35 Network Cable	CISCO1841-SEC/K9	1841 Security Bundle,Adv.Security,64FL/256DR
CISCO805-BUNDLE	Special805LA Bundle	CISCO1841-SEC/K9	1841 Security Bundle,Adv.Security,64FL/256DR
CISCO805-RF	CISCO805 REFURBISHED	CISCO1841-SEC/K9	1841 Security Bundle,Adv.Security,64FL/256DR

Product Migration Options

Cisco 801 customers are encouraged to migrate to the Cisco 876 Integrated Services Router, and Cisco 805 customers are encouraged to migrate to the Cisco 1841 Integrated Services Router. Information about the Cisco 876 products can be found at: http://www.cisco.com/en/US/products/ps6201/index.html. Information about the Cisco 1841 products can be found at: http://www.cisco.com/en/US/products/ps5875/index.html.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: http://www.cisco.com/go/tradein/. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to: http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_program_description. html

For More Information

For more information about the Cisco 876 Series and Cisco 1841 Series, visit the Integrated Services Router web site at http://www.cisco.com/en/US/prod/collateral/routers/product_promotion0900aecd8017150a.html, or, contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice