End-of-Sale and End-of-Life Announcement for the Cisco Select Unified Computing System and Hyperflex Accessories

Contents

Overview

EOL13858 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco Select Unified Computing System and Hyperflex Accessories. The last day to order the affected product(s) is October 10, 2021. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1.   End-of-life milestones and dates for the Cisco Select Unified Computing System and Hyperflex Accessories

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	April 12, 2021
End-of-Sale Date Accessory	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 10, 2021
Last Ship Date Accessory	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 9, 2022

Product part numbers

Table 2.   Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
C880-10G-SFPMOD=	10G LAN SFP+ module	There is currently no replacement product available for this product.	–	–
C880-128GB-DDR4R	Cisco C880 M5 128GB DDR4 RDIMM v5	There is currently no replacement product available for this product.	–	–
C880-128GB-DDR4R=	Cisco C880 M5 128GB DDR4 RDIMM v5	There is currently no replacement product available for this product.	–	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
C880-3TBR-48X64	3T Memory Kit 48x64G RDIMM, C880 M5	There is currently no replacement product available for this product.	–	–
C880-64GB-DDR4R	OEM 64GB DDR4 RDIMM, C880 M5	There is currently no replacement product available for this product.	–	–
C880-64GB-DDR4R=	OEM 64GB DDR4 RDIMM, C880 M5	There is currently no replacement product available for this product.	–	–
C880-6T-HANA-J-M5=	C880 M5 v5 8S 6TB 128GB DIMMs and Platinum 8180M	There is currently no replacement product available for this product.	–	–
C880-M4-CHASSIS=	Spare Chassis for C880 M4	There is currently no replacement product available for this product.	–	–
C880-M5-CHASSIS=	Spare Chassis for C880 M5	There is currently no replacement product available for this product.	–	–
C880-MEM-MEZZ2-HW	Cisco C880 M4 Memory Expansion Board HW	There is currently no replacement product available for this product.	–	–
C880-MEM-MEZZ2-HW=	Cisco C880 M4 Memory Expansion Board HW	There is currently no replacement product available for this product.	–	–
C880-SASI-RC-HW	Cisco C880 M4 SAS Internal RAID Controller HW	There is currently no replacement product available for this product.	–	–
C880-SASI-RC-HW=	Cisco C880 M4 SAS Internal RAID Controller HW	There is currently no replacement product available for this product.	–	–
HX-B-NVMEHW-H800	800GB 2.5in U.2 HGST SN200 NVMe High Perf. High Endurance	There is currently no replacement product available for this product.	–	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
HX-B-NVMEHW-H800=	800GB 2.5in U.2 HGST SN200 NVMe High Perf. High Endurance	There is currently no replacement product available for this product.	–	–
HX-F-H16003	Cisco HHHL AIC 1.6T HGST SN260 NVMe Extreme Perf High Endrnc	There is currently no replacement product available for this product.	–	–
HX-F-H16003=	Cisco HHHL AIC 1.6T HGST SN260 NVMe Extreme Perf High Endrnc	There is currently no replacement product available for this product.	–	–
HX-HD6T7KLEM	-VOID	There is currently no replacement product available for this product.	–	–
HX-ML-X32G2RS-H	32GB DDR4-2666-MHz LRDIMM/PC4-21300/dual rank/x4/1.2v	HX-ML-X64G4RS-H	64GB DDR4-2666-MHz LRDIMM/PC4-21300/quad rank/x4/1.2v	–
HX-ML-X64G4RS-H	64GB DDR4-2666-MHz LRDIMM/PC4-21300/quad rank/x4/1.2v	There is currently no replacement product available for this product.	–	–
HX-ML-X64G4RSHM	64GB DDR4-2666-MHz LRDIMM/quad rank/x4/1.2v. Micron only	There is currently no replacement product available for this product.	–	–
HX-MR-128G8RS-H	128GB DDR4-2666-MHz TSV-RDIMM/PC4-21300/octal rank/x4/1.2v	There is currently no replacement product available for this product.	–	–
HX-MR-X16G1RS-H	16GB DDR4-2666-MHz RDIMM/PC4-21300/single rank/x4/1.2v	HX-MR-X32G2RS-H	32GB DDR4-2666-MHz RDIMM/PC4-21300/dual rank/x4/1.2v	–
HX-MR-X32G2RS-H	32GB DDR4-2666-MHz RDIMM/PC4-21300/dual rank/x4/1.2v	There is currently no replacement product available for this product.	–	–
HX-MR-X32G2RSHM	32GB DDR4-2666-MHz RDIMM/dual rank/x4/1.2v. Micron only	There is currently no replacement product available for this product.	–	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
HX-MR-X64G4RS-H	64GB DDR4-2666-MHz TSV-RDIMM/PC4-21300/quad rank/x4/1.2v	HX-MR-128G8RS-H	128GB DDR4-2666-MHz TSV-RDIMM/PC4-21300/octal rank/x4/1.2v	–
HX-NVME-H32003	Cisco HHHL AIC 3.2T HGST SN260 NVMe Extreme Perf High Endrnc	There is currently no replacement product available for this product.	–	–
HX-NVME-H32003=	Cisco HHHL AIC 3.2T HGST SN260 NVMe Extreme Perf High Endrnc	There is currently no replacement product available for this product.	–	–
HX-NVME-H38401	Cisco HHHL 3.8T HGST SN260 NVMe Extreme Perf Value Enderance	There is currently no replacement product available for this product.	–	–
HX-NVME-H38401=	Cisco HHHL 3.8T HGST SN260 NVMe Extreme Perf Value Enderance	There is currently no replacement product available for this product.	–	–
HX-NVME-H64003	Cisco HHHL AIC 6.4T HGST SN260 NVMe Extreme Perf High Endrnc	There is currently no replacement product available for this product.	–	–
HX-NVME-H64003=	Cisco HHHL AIC 6.4T HGST SN260 NVMe Extreme Perf High Endrnc	There is currently no replacement product available for this product.	–	–
HX-NVME-H76801	Cisco HHHL 7.7T HGST SN260 NVMe Extreme Perf Value Enderance	There is currently no replacement product available for this product.	–	–
HX-NVME-H76801=	Cisco HHHL 7.7T HGST SN260 NVMe Extreme Perf Value Enderance	There is currently no replacement product available for this product.	–	–
HX-NVMEHW-H3800	3.8TB 2.5in U.2 HGST SN200 NVMe High Perf. Value Endurance	There is currently no replacement product available for this product.	–	–
HX-NVMEHW-H3800=	3.8TB 2.5in U.2 HGST SN200 NVMe High Perf. Value Endurance	There is currently no replacement product available for this product.	–	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
HX-NVMEHW-H800	800GB 2.5in U.2 HGST SN200 NVMe High Perf. High Endurance	There is currently no replacement product available for this product.	–	–
HX-NVMEHW-H800=	800GB 2.5in U.2 HGST SN200 NVMe High Perf. High Endurance	There is currently no replacement product available for this product.	–	–
HX-NVMEHW-H960	960GB 2.5in U.2 HGST SN200 NVMe High Perf. Value Endurance	There is currently no replacement product available for this product.	–	–
HX-NVMEHW-H960=	960GB 2.5in U.2 HGST SN200 NVMe High Perf. Value Endurance	There is currently no replacement product available for this product.	–	–
HX-NVMEHY-H800	800GB 3.5in LFF HGST SN200 NVMe High Perf. High Endurance	There is currently no replacement product available for this product.	–	–
HX-NVMEHY-H800=	800GB 3.5in LFF HGST SN200 NVMe High Perf. High Endurance	There is currently no replacement product available for this product.	–	–
HX-SD120GBE1NK9	VOID	There is currently no replacement product available for this product.	–	–
HX-SD120GBE1NK9=	VOID	There is currently no replacement product available for this product.	–	–
HX-SD800G63X-EP	VOID	There is currently no replacement product available for this product.	–	–
HX-SD800G63X-EP=	VOID	There is currently no replacement product available for this product.	–	–
HX-SP-M16G1-RSH	SP HX 16GB DDR4-2666-MHz RDIMM/PC4-21300/single rank/x4/1.2v	There is currently no replacement product available for this product.	–	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
HX-SP-M32G2-RSH	SP HX 32GB DDR4-2666-MHz RDIMM/PC4-21300/dual rank/x4/1.2v	There is currently no replacement product available for this product.	-	-
HX-V340CBL-240M5	VOID; Not Used	There is currently no replacement product available for this product.	-	-
HX-V340CBL-240M5=	VOID; Not Used	There is currently no replacement product available for this product.	-	-
RACK2-CBLMGT-004	VOID	There is currently no replacement product available for this product.	-	-
UCS-CPU-5218	Void; Not Used	There is currently no replacement product available for this product.	-	-
UCS-CPU-5218=	Void; Not Used	There is currently no replacement product available for this product.	-	-
UCS-CPU-6230	Void; Not Used	There is currently no replacement product available for this product.	-	-
UCS-CPU-6230=	Void; Not Used	There is currently no replacement product available for this product.	-	-
UCS-CPU-6244	Void; Not Used	There is currently no replacement product available for this product.	-	-
UCS-CPU-6244=	Void; Not Used	There is currently no replacement product available for this product.	-	-
UCS-CPU-6248	VOID; Not Used	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS–CPU–6248=	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS–CPU–6254	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS–CPU–6254=	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS–CPU–8260	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS–CPU–8260=	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS–CPU–8268	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS–CPU–8268=	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS–CPU–8276	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS–CPU–8276=	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS–CPU–8276L	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS–CPU–8276L=	VOID; Not Used	There is currently no replacement product available for this product.	–	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-CPU-8276M	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS-CPU-8276M=	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS-CPU-8280	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS-CPU-8280=	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS-CPU-8280L	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS-CPU-8280L=	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS-CPU-8280M	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS-CPU-8280M=	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS-ML-128G8RS-H	128GB DDR4-2666-MHz LRDIMM/PC4-21300/octal rank/x4/1.2v	There is currently no replacement product available for this product.	–	–
UCS-ML-X32G2RS-H	32GB DDR4-2666-MHz LRDIMM/PC4-21300/dual rank/x4/1.2v	UCS-ML-X64G4RS-H	64GB DDR4-2666-MHz LRDIMM/PC4-21300/quad rank/x4/1.2v	–
UCS-ML-X32G2RSHM	32GB DDR4-2666-MHz LRDIMM/dual rank/x4/1.2v. Micron only	UCS-ML-X64G4RSHM	64GB DDR4-2666-MHz LRDIMM/quad rank/x4/1.2v. Micron only	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-ML-X32G4RS-H	Void-to be obsoleted	There is currently no replacement product available for this product.	–	–
UCS-ML-X64G4RS-H	64GB DDR4-2666-MHz LRDIMM/PC4-21300/quad rank/x4/1.2v	There is currently no replacement product available for this product.	–	–
UCS-ML-X64G4RSHM	64GB DDR4-2666-MHz LRDIMM/quad rank/x4/1.2v. Micron only	There is currently no replacement product available for this product.	–	–
UCS-ML-X64G4RSHS	64GB DDR4-2666-MHz LRDIMM/quad rank/x4/1.2v. Samsung only	There is currently no replacement product available for this product.	–	–
UCS-MR-128G8RS-H	128GB DDR4-2666-MHz TSV-RDIMM/PC4-21300/octal rank/x4/1.2v	There is currently no replacement product available for this product.	–	–
UCS-MR-X16G1RS-H	16GB DDR4-2666-MHz RDIMM/PC4-21300/single rank/x4/1.2v	UCS-MR-X32G2RS-H	32GB DDR4-2666-MHz RDIMM/PC4-21300/dual rank/x4/1.2v	–
UCS-MR-X16G1RSHM	16GB DDR4-2666-MHz RDIMM/single rank/x4/1.2v. Micron only	There is currently no replacement product available for this product.	–	–
UCS-MR-X32G2RS-H	32GB DDR4-2666-MHz RDIMM/PC4-21300/dual rank/x4/1.2v	There is currently no replacement product available for this product.	–	–
UCS-MR-X32G2RSHM	32GB DDR4-2666-MHz RDIMM/dual rank/x4/1.2v. Micron only	There is currently no replacement product available for this product.	–	–
UCS-MR-X32G2RSHS	32GB DDR4-2666-MHz RDIMM/dual rank/x4/1.2v. Samsung only	There is currently no replacement product available for this product.	–	–
UCS-MR-X64G4RS-H	64GB DDR4-2666-MHz TSV-RDIMM/PC4-21300/quad rank/x4/1.2v	UCS-MR-128G8RS-H	128GB DDR4-2666-MHz TSV-RDIMM/PC4-21300/octal rank/x4/1.2v	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-S3260-EX8T=	Void; Not Used	There is currently no replacement product available for this product.	–	–
UCS-S3260-NVM48	Cisco UCS S3260 800G NVMe SSD for M5 Node(SN 200)	There is currently no replacement product available for this product.	–	–
UCS-S3260-NVM48=	Cisco UCS S3260 800G NVMe SSD for M5 Node(SN 200)	There is currently no replacement product available for this product.	–	–
UCS-S3348-HBAM5	UCS S3348 Pass through Controller (IT) based on LSI	There is currently no replacement product available for this product.	–	–
UCS-S3348-HBAM5=	UCS S3348 Pass through Controller (IT) based on LSI	There is currently no replacement product available for this product.	–	–
UCS-S3348-RAIDM5	UCS S3348 Raid Controller based on LSI	There is currently no replacement product available for this product.	–	–
UCS-S3348-RAIDM5=	UCS S3348 Raid Controller based on LSI	There is currently no replacement product available for this product.	–	–
UCS-S3X48-FAN	UCS S3X48 Chassis Fan	There is currently no replacement product available for this product.	–	–
UCS-S3X48-FAN=	UCS S3X48 Chassis Fan	There is currently no replacement product available for this product.	–	–
UCS-S3X48-SNM5-HS	UCS SX348 M5 Heatsink	There is currently no replacement product available for this product.	–	–
UCS-S3X48-SNM5-HS=	UCS SX348 M5 Heatsink	There is currently no replacement product available for this product.	–	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-SP-C480-8HDD01	UCS SP C480 M5 Drive Module for 8x HDD	There is currently no replacement product available for this product.	–	–
UCS-SP-M16G1-RSH	SP 16GB DDR4-2666-MHz RDIMM/PC4-21300/singlerank/x4/1.2v	There is currently no replacement product available for this product.	–	–
UCS-SP-M16G2-RSH	SP 16GB DDR4-2666-MHz RDIMM/PC4-21300/dual rank/x4/1.2v	There is currently no replacement product available for this product.	–	–
UCS-SP-M32G2-RSH	SP 32GB DDR4-2666-MHz RDIMM/PC4-21300/dual rank/x4/1.2v	There is currently no replacement product available for this product.	–	–
UCS-SX348-CMC	UCS Sx348 CMC Module	There is currently no replacement product available for this product.	–	–
UCS-SX348-CMC=	UCS Sx348 CMC Module	There is currently no replacement product available for this product.	–	–
UCS-V340CBL-240M5	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCS-V340CBL-240M5=	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCSB-NVMEHW-H3800	3.8TB 2.5in U.2 HGST SN200 NVMe High Perf. Value Endurance	There is currently no replacement product available for this product.	–	–
UCSB-NVMEHW-H3800=	3.8TB 2.5in U.2 HGST SN200 NVMe High Perf. Value Endurance	There is currently no replacement product available for this product.	–	–
UCSB-NVMEHW-H800	800GB 2.5in U.2 HGST SN200 NVMe High Perf. High Endurance	There is currently no replacement product available for this product.	–	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCSB-NVMEHW-H800=	800GB 2.5in U.2 HGST SN200 NVMe High Perf. High Endurance	There is currently no replacement product available for this product.	-	-
UCSC-F-H16003	Cisco HHHL AIC 1.6T HGST SN260 NVMe Extreme Perf High Endrnc	There is currently no replacement product available for this product.	-	-
UCSC-F-H16003=	Cisco HHHL AIC 1.6T HGST SN260 NVMe Extreme Perf High Endrnc	There is currently no replacement product available for this product.	-	-
UCSC-NVME-H32003	Cisco HHHL AIC 3.2T HGST SN260 NVMe Extreme Perf High Endrnc	There is currently no replacement product available for this product.	-	-
UCSC-NVME-H32003=	Cisco HHHL AIC 3.2T HGST SN260 NVMe Extreme Perf High Endrnc	There is currently no replacement product available for this product.	-	-
UCSC-NVME-H38401	Cisco HHHL 3.8T HGST SN260 NVMe Extreme Perf Value Enderance	There is currently no replacement product available for this product.	-	-
UCSC-NVME-H38401=	Cisco HHHL 3.8T HGST SN260 NVMe Extreme Perf Value Enderance	There is currently no replacement product available for this product.	-	-
UCSC-NVME-H64003	Cisco HHHL AIC 6.4T HGST SN260 NVMe Extreme Perf High Endrnc	There is currently no replacement product available for this product.	-	-
UCSC-NVME-H64003=	Cisco HHHL AIC 6.4T HGST SN260 NVMe Extreme Perf High Endrnc	There is currently no replacement product available for this product.	-	-
UCSC-NVME-H76801	Cisco HHHL 7.7T HGST SN260 NVMe Extreme Perf Value Enderance	There is currently no replacement product available for this product.	-	-
UCSC-NVME-H76801=	Cisco HHHL 7.7T HGST SN260 NVMe Extreme Perf Value Enderance	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCSC-NVMEHW-H3800	3.8TB 2.5in U.2 HGST SN200 NVMe High Perf. Value Endurance	There is currently no replacement product available for this product.	–	–
UCSC-NVMEHW-H3800=	3.8TB 2.5in U.2 HGST SN200 NVMe High Perf. Value Endurance	There is currently no replacement product available for this product.	–	–
UCSC-NVMEHW-H800	800GB 2.5in U.2 HGST SN200 NVMe High Perf. High Endurance	There is currently no replacement product available for this product.	–	–
UCSC-NVMEHW-H800=	800GB 2.5in U.2 HGST SN200 NVMe High Perf. High Endurance	There is currently no replacement product available for this product.	–	–
UCSC-NVMEHW-H960	960GB 2.5in U.2 HGST SN200 NVMe High Perf. Value Endurance	There is currently no replacement product available for this product.	–	–
UCSC-NVMEHW-H960=	960GB 2.5in U.2 HGST SN200 NVMe High Perf. Value Endurance	There is currently no replacement product available for this product.	–	–
UCSC-NVMEHY-H800	800GB 3.5in LFF HGST SN200 NVMe High Perf. High Endurance	There is currently no replacement product available for this product.	–	–
UCSC-NVMEHY-H800=	800GB 3.5in LFF HGST SN200 NVMe High Perf. High Endurance	There is currently no replacement product available for this product.	–	–
UCSC-OCP-QS100GF	Void; not used	There is currently no replacement product available for this product.	–	–
UCSC-OCP-QS100GF=	Void; not used	There is currently no replacement product available for this product.	–	–
UCSC-PCIE-MD25GF	VOID; Not Used	There is currently no replacement product available for this product.	–	–

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCSC–PCIE–MD25GF=	VOID; Not Used	There is currently no replacement product available for this product.	–	–
UCSC–PCIF–01F=	Full height PCIe filler for C-Series	There is currently no replacement product available for this product.	–	–

Product migration options

Service prices for Cisco products are subject to change after the product End–of–Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For more information

For more information about the Cisco End–of–Life Policy, go to: https://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to: https://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end–of–life/end–of–sale information, go to: https://www.cisco.com/cisco/support/notifications.html.

Any authorized translation issued by Cisco Systems or affiliates of this end–of–life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.