Cisco public



Cisco announces a change in product part numbers for the Cisco Spark/Webex Board 70

Contents

| Overview | 3 |
|---------------------------|---|
| End-of-life milestones | 3 |
| Product part numbers | 4 |
| Product migration options | 4 |
| For more information | 5 |

Overview

EOL12827 - Amended

Cisco announces a change in product part numbers for the Cisco Spark/Webex Board 70. This is a product part number change only announcement. Customers will experience no change in functionality when using the new product part numbers. The new product part numbers are designed to simplify the customer ordering process. The last day to order the affected product using the current product part numbers is February 11, 2019. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until otherwise specified in the end-of-life announcement for the new product part numbers. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco Spark/Webex Board 70

| Milestone | Definition | Date |
|----------------------------------|---|-------------------|
| End-of-Life Announcement Date | The date the document that announces the end of sale and end of life of a product is distributed to the general public. | November 12, 2018 |
| End-of-Sale Date : HW | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date. | February 11, 2019 |
| Last Ship Date : HW | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time. | May 12, 2019 |
| Last Date of Support : HW | The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete. | May 31, 2027 |

HW = Hardware OS SW = Operating System Software

App. SW = Application Software

Product part numbers

 Table 2.
 Product part numbers affected by this announcement

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|------------------------------------|---|---------------------------------|----------------------------------|------------------------|
| CS-BOARD70-K9 | Cisco Spark Board 70 | CS-BOARD70S-G-K9 | Cisco Webex Board 70S (GPL) | - |
| CS-BOARD70= | Cisco Spark Board 70 - Spare unit without accessories | CS-BOARD70S= | Cisco Webex Board 70S - Spare | - |
| SPARK-BOARD70 | Cisco Spark Board 70 - unit | CS-BOARD70S | Cisco Webex Board 70S - unit | - |
| SPARK-BOARD70-K9 | Cisco Spark Board 70 | CS-BOARD70S-M-K9 | ^Cisco Webex Board 70S (MSRP) | - |
| SPARK-BOARD70= | Cisco Spark Board 70 - Spare | CS-BOARD70S= | Cisco Webex Board 70S - Spare | - |

Product migration options

This is a product part number change only. Customers will experience no change in functionality when using the new product IDs. The new product IDs are designed to simplify the ordering process.

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to: https://www.cisco.com/c/en/us/products/eos-eol-policy.html.

For more information about the Cisco Product Warranties, go to: https://www.cisco.com/c/en/us/products/warranty-listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: https://cway.cisco.com/mynotifications.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at https://www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-741602-01 01/22