

# End-of-Sale and End-of-Life Announcement for the Cisco 829 Industrial Integrated Services Routers

---

# Contents

Overview	3
End-of-life milestones	3
Product Part Numbers	4
Product Migration Options	11
For More Information	11

## Overview

### EOL14833

Cisco announces the End-of-sale and end-of-life dates for the Cisco 829 Industrial Integrated Services Routers. The last day to order the affected product(s) is March 1, 2023. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

## End-of-life milestones

**Table 1.** End-of-life milestones and dates for the Cisco 829 Industrial Integrated Services Routers

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	August 31, 2022
<b>End-of-Sale Date: HW</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	March 1, 2023
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 30, 2023
<b>End of SW Maintenance Releases Date: HW</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	February 29, 2024
<b>End of Vulnerability/Security Support: HW</b>	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	February 28, 2026
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	February 29, 2024
<b>End of New Service Attachment Date: HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	February 29, 2024
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	May 27, 2027
<b>Last Date of Support: HW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	February 29, 2028

HW = Hardware OS SW = Operating System Software App. SW = Application Software

## Product Part Numbers

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>IR829-2LTE-EA-AK9</b>	829 Industrial ISR, 4G/LTE multimode Canada, 802.11n FCC	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: Non PoE IR1831-K9 + WP-WIFI6-A
<b>IR829-2LTE-EA-AK9</b>	829 Industrial ISR, 4G/LTE multimode Canada, 802.11n FCC	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: IR1833-K9 + WP-WIFI6-A
<b>IR829-2LTE-EA-AK9</b>	829 Industrial ISR, 4G/LTE multimode Canada, 802.11n FCC	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: IR1835-K9 + WP-WIFI6-A
<b>IR829-2LTE-EA-BK9</b>	829 Industrial ISR, LTE multimode US, 802.11n FCC	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: IR1831-K9 + WP-WIFI6-B
<b>IR829-2LTE-EA-BK9</b>	829 Industrial ISR, LTE multimode US, 802.11n FCC	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: IR1833-K9 + WP-WIFI6-B
<b>IR829-2LTE-EA-BK9</b>	829 Industrial ISR, LTE multimode US, 802.11n FCC	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: IR1835-K9 + WP-WIFI6-B
<b>IR829-2LTE-EA-EK9</b>	829 Industrial ISR, Dual 4G/LTE multimode, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: IR1831-K9 + WP-WIFI6-E
<b>IR829-2LTE-EA-EK9</b>	829 Industrial ISR, Dual 4G/LTE multimode, 802.11n ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: IR1833-K9 + WP-WIFI6-E
<b>IR829-2LTE-EA-EK9</b>	829 Industrial ISR, Dual 4G/LTE multimode, 802.11n ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: IR1835-K9 + WP-WIFI6-E
<b>IR829-LTE-EA-BK9</b>	829 Industrial ISR, LTE US,WiFi,FCC	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: (Non PoE IR1821-K9 + WP-WIFI6-B
<b>IR829-LTE-EA-BK9</b>	829 Industrial ISR, LTE US,WiFi,FCC	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: (Non PoE IR1831-K9 + WP-WIFI6-B
<b>IR829-LTE-EA-BK9</b>	829 Industrial ISR, LTE US,WiFi,FCC	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: (Non PoE IR1833-K9 + WP-WIFI6-B
<b>IR829-LTE-EA-BK9</b>	829 Industrial ISR, LTE US,WiFi,FCC	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: (Non PoE IR1835-K9 + WP-WIFI6-B

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>IR829B-2LTE-EA-AK9</b>	829 Industrial ISR, 4G/LTE multimode Canada, 802.11n FCC	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: IR1831-K9 + WP-WIFI6-A
<b>IR829B-2LTE-EA-BK9</b>	829 Industrial ISR, LTE multimode US, 802.11n FCC	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: IR1831-K9 + WP-WIFI6-B
<b>IR829B-2LTE-EA-EK9</b>	829 Industrial ISR, Dual 4G/LTE multimode, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: IR1831-K9 + WP-WIFI6-E
<b>IR829B-2LTE-EA-RK9</b>	829 Industrial ISR, Dual 4G/LTE multimode, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: IR1831-K9 + WP-WIFI6-R
<b>IR829B-LTE-EA-AK9</b>	829 Industrial ISR, LTE Canada, WiFi, FCC	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: IR1821-K9 + WP-WIFI6-A
<b>IR829B-LTE-EA-AK9</b>	829 Industrial ISR, LTE Canada, WiFi, FCC	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: IR1831-K9 + WP-WIFI6-A
<b>IR829-LTE-EA-EK9</b>	829 Industrial ISR, LTE, WiFi, ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: IR1821-K9 + WP-WIFI6-E
<b>IR829-LTE-EA-EK9</b>	829 Industrial ISR, LTE, WiFi, ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: IR1831-K9 + WP-WIFI6-E
<b>IR829B-LTE-EA-RK9</b>	829 Industrial ISR, LTE, WiFi, ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: IR1821-K9 + WP-WIFI6-R
<b>IR829B-LTE-EA-RK9</b>	829 Industrial ISR, LTE, WiFi, ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: IR1831-K9 + WP-WIFI6-R
<b>IR829-LTE-LA-ZK9</b>	829 Industrial ISR, LTE, WiFi, SFP, ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: IR1821-K9 + WP-WIFI6-Z
<b>IR829-LTE-LA-ZK9</b>	829 Industrial ISR, LTE, WiFi, SFP, ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: IR1831-K9 + WP-WIFI6-Z
<b>IR829GW-LTE-LA-CK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: Non PoE: IR1821-K9 + WP-WIFI6-C
<b>IR829GW-LTE-LA-CK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: Non PoE: IR1831-K9 + WP-WIFI6-C

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>IR829GW-LTE-LA-CK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: PoE: IR1833-K9 + WP-WIFI6-C
<b>IR829GW-LTE-LA-CK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: PoE: IR1835-K9 + WP-WIFI6-C
<b>IR829M-LTE-EA-BK9</b>	IR829 Industrial ISR, LTE US,WiFi,POE,SSD connector,FCC	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: IR1833-K9 + WP-WIFI6-B
<b>IR829M-LTE-EA-BK9</b>	IR829 Industrial ISR, LTE US,WiFi,POE,SSD connector,FCC	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: IR1835-K9 + WP-WIFI6-B
<b>IR829M-LTE-EA-EK9</b>	829 Industrial ISR, LTE, WiFi, POE, SSD connector, ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: IR1833-K9 + WP-WIFI6-E
<b>IR829M-LTE-EA-EK9</b>	829 Industrial ISR, LTE, WiFi, POE, SSD connector, ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: IR1835-K9 + WP-WIFI6-E
<b>IR829M-LTE-EA-RK9</b>	829 Industrial ISR, LTE, WiFi, POE, SSD slot, ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: IR1833-K9 + WP-WIFI6-R
<b>IR829M-LTE-EA-RK9</b>	829 Industrial ISR, LTE, WiFi, POE, SSD slot, ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: IR1835-K9 + WP-WIFI6-R
<b>IR829M-LTE-LA-ZK9</b>	829 Industrial ISR, LTE, POE, SSD connector, WiFi, SFP, ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: IR1833-K9 + WP-WIFI6-Z
<b>IR829M-LTE-LA-ZK9</b>	829 Industrial ISR, LTE, POE, SSD connector, WiFi, SFP, ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: IR1835-K9 + WP-WIFI6-Z
<b>IR829GW-LTE-LA-DK9</b>	829 Industrial ISR, 4G/LTE multimode India, 802.11n ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: Non PoE: IR1821-K9 + WP-WIFI6-D
<b>IR829GW-LTE-LA-DK9</b>	829 Industrial ISR, 4G/LTE multimode India, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: Non PoE: IR1831-K9 + WP-WIFI6-D
<b>IR829GW-LTE-LA-DK9</b>	829 Industrial ISR, 4G/LTE multimode India, 802.11n ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: PoE: IR1833-K9 + WP-WIFI6-D
<b>IR829GW-LTE-LA-DK9</b>	829 Industrial ISR, 4G/LTE multimode India, 802.11n ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: PoE: IR1835-K9 + WP-WIFI6-D

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>IR829GW-LTE-LA-FK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: Non PoE: IR1821-K9 + WP-WIFI6-F
<b>IR829GW-LTE-LA-FK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: Non PoE: IR1831-K9 + WP-WIFI6-F
<b>IR829GW-LTE-LA-FK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Router	Replacement PID: PoE: IR1833-K9 + WP-WIFI6-F
<b>IR829GW-LTE-LA-FK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: PoE: IR1835-K9 + WP-WIFI6-F
<b>IR829GW-LTE-LA-HK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: Non PoE: IR1821-K9 + WP-WIFI6-H
<b>IR829GW-LTE-LA-HK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: Non PoE: IR1831-K9 + WP-WIFI6-H
<b>IR829GW-LTE-LA-HK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Router	Replacement PID: PoE: IR1833-K9 + WP-WIFI6-H
<b>IR829GW-LTE-LA-HK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: PoE: IR1835-K9 + WP-WIFI6-H
<b>IR829GW-LTE-LA-KK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: Non PoE: IR1821-K9 + WP-WIFI6-K
<b>IR829GW-LTE-LA-KK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: Non PoE: IR1831-K9 + WP-WIFI6-K
<b>IR829GW-LTE-LA-KK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Router	Replacement PID: PoE: IR1833-K9 + WP-WIFI6-K
<b>IR829GW-LTE-LA-KK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: PoE: IR1835-K9 + WP-WIFI6-K
<b>IR829GW-LTE-LA-LK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: Non PoE: IR1821-K9 + WP-WIFI6-L
<b>IR829GW-LTE-LA-LK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: Non PoE: IR1831-K9 + WP-WIFI6-L

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>IR829GW-LTE-LA-LK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: PoE: IR1833-K9 + WP-WIFI6-L
<b>IR829GW-LTE-LA-LK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: PoE: IR1835-K9 + WP-WIFI6-L
<b>IR829GW-LTE-LA-NK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: Non PoE: IR1821-K9 + WP-WIFI6-N
<b>IR829GW-LTE-LA-NK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: Non PoE: IR1831-K9 + WP-WIFI6-N
<b>IR829GW-LTE-LA-NK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: PoE: IR1833-K9 + WP-WIFI6-N
<b>IR829GW-LTE-LA-NK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: PoE: IR1835-K9 + WP-WIFI6-N
<b>IR829GW-LTE-LA-QK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: Non PoE: IR1821-K9 + WP-WIFI6-Q
<b>IR829GW-LTE-LA-QK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: Non PoE: IR1831-K9 + WP-WIFI6-Q
<b>IR829GW-LTE-LA-QK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: PoE: IR1833-K9 + WP-WIFI6-Q
<b>IR829GW-LTE-LA-QK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: PoE: IR1835-K9 + WP-WIFI6-Q
<b>IR829GW-LTE-LA-SK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: Non PoE: IR1821-K9 + WP-WIFI6-S
<b>IR829GW-LTE-LA-SK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: Non PoE: IR1831-K9 + WP-WIFI6-S
<b>IR829GW-LTE-LA-SK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: PoE: IR1833-K9 + WP-WIFI6-S
<b>IR829GW-LTE-LA-SK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: PoE: IR1835-K9 + WP-WIFI6-S



End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>IR829GW-LTE-LA-TK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: Non PoE: IR1821-K9 + WP-WIFI6-T
<b>IR829GW-LTE-LA-TK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: Non PoE: IR1831-K9 + WP-WIFI6-T
<b>IR829GW-LTE-LA-TK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Router	Replacement PID: PoE: IR1833-K9 + WP-WIFI6-T
<b>IR829GW-LTE-LA-TK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: PoE: IR1835-K9 + WP-WIFI6-T
<b>IR829GW-LTE-LA-ZK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: Non PoE: IR1821-K9 + WP-WIFI6-Z
<b>IR829GW-LTE-LA-ZK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: Non PoE: IR1831-K9 + WP-WIFI6-Z
<b>IR829GW-LTE-LA-ZK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Router	Replacement PID: PoE: IR1833-K9 + WP-WIFI6-Z
<b>IR829GW-LTE-LA-ZK9</b>	829 Industrial ISR, 4G/LTE multimode Global, 802.11n ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: PoE: IR1835-K9 + WP-WIFI6-Z
<b>IR829GW-LTE-NA-AK9</b>	829 Industrial ISR, 4G/LTE multimode ATT/Canada, 802.11n FCC	IR1821-K9	Cisco Catalyst IR1821 Rugged Series Router	Replacement PID: Non PoE: IR1821-K9 + WP-WIFI6-A
<b>IR829GW-LTE-NA-AK9</b>	829 Industrial ISR, 4G/LTE multimode ATT/Canada, 802.11n FCC	IR1831-K9	Cisco Catalyst IR1831 Rugged Series Router	Replacement PID: Non PoE: IR1831-K9 + WP-WIFI6-A
<b>IR829GW-LTE-NA-AK9</b>	829 Industrial ISR, 4G/LTE multimode ATT/Canada, 802.11n FCC	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Router	Replacement PID: PoE: IR1833-K9 + WP-WIFI6-A
<b>IR829GW-LTE-NA-AK9</b>	829 Industrial ISR, 4G/LTE multimode ATT/Canada, 802.11n FCC	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: PoE: IR1835-K9 + WP-WIFI6-A
<b>IR829M-2LTE-EA-AK9</b>	829 Industrial ISR, Dual LTE Canada, WiFi, POE, SSD Connector, FCC	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Router	Replacement PID: IR1833-K9 + WP-WIFI6-A

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>IR829M-2LTE-EA-AK9</b>	829 Industrial ISR,Dual LTE Canada,WiFi,POE,SSD Connector,FCC	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: IR1835-K9 + WP-WIFI6-A
<b>IR829M-2LTE-EA-BK9</b>	829 Industrial ISR, Dual LTE US,WiFi,POE,SSD connector,FCC	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: IR1833-K9 + WP-WIFI6-B
<b>IR829M-2LTE-EA-BK9</b>	829 Industrial ISR, Dual LTE US,WiFi,POE,SSD connector,FCC	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: IR1835-K9 + WP-WIFI6-B
<b>IR829M-2LTE-EA-EK9</b>	829 Industrial ISR, Dual LTE, WiFi, POE, SSD connector, ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: IR1833-K9 + WP-WIFI6-E
<b>IR829M-2LTE-EA-EK9</b>	829 Industrial ISR, Dual LTE, WiFi, POE, SSD connector, ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: IR1835-K9 + WP-WIFI6-E
<b>IR829M-2LTE-EA-RK9</b>	829 Industrial ISR, Dual LTE, WiFi, POE, SSD slot, ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: IR1833-K9 + WP-WIFI6-R
<b>IR829M-2LTE-EA-RK9</b>	829 Industrial ISR, Dual LTE, WiFi, POE, SSD slot, ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: IR1835-K9 + WP-WIFI6-R
<b>IR829M-2LTE-LA-ZK9</b>	IR829, Dual LTE, POE, SSD connector, WiFi, SFP, ETSI	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: IR1833-K9 + WP-WIFI6-Z
<b>IR829M-2LTE-LA-ZK9</b>	IR829, Dual LTE, POE, SSD connector, WiFi, SFP, ETSI	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: IR1835-K9 + WP-WIFI6-Z
<b>IR829M-LTE-EA-AK9</b>	829 Industrial ISR, LTE Canada,WiFi,POE,SSD Connector,FCC	IR1833-K9	Cisco Catalyst IR1833 Rugged Series Route	Replacement PID: IR1833-K9 + WP-WIFI6-A
<b>IR829M-LTE-EA-AK9</b>	829 Industrial ISR, LTE Canada,WiFi,POE,SSD Connector,FCC	IR1835-K9	Cisco Catalyst IR1835 Rugged Series Router	Replacement PID: IR1835-K9 + WP-WIFI6-A

---

## Product Migration Options

Customers are encouraged to migrate to the Cisco Catalyst IR1800 Rugged Series Routers. Information about Cisco Catalyst IR1800 Series can be found here:

<https://www.cisco.com/site/us/en/products/networking/industrial-routers-gateways/catalyst-ir1800-rugged-series/index.html>

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

[https://www.cisco.com/web/partners/incentives\\_and\\_promotions/tmp.html](https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html).

Customers may be able to continue to purchase the Cisco 829 Industrial Integrated Services Routers through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <https://www.cisco.com/go/eos>

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[https://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For More Information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>

For more information about the Cisco Product Warranties, go to:

<https://www.cisco.com/c/en/us/products/warranty-listing.html>

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

---

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)