ılıılı cısco

End-of-Sale and End-of-Life Announcement for the Cisco UCS Intel Xeon Processor E7/E5 v3 Series Spare

EOL12299 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco UCS Intel Xeon Processor E7/E5 v3 Series Spare. The last day to order the affected product(s) is February 9, 2019. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	February 9, 2018
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	February 9, 2019
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 11, 2019
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	February 9, 2020
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	February 9, 2020
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	May 10, 2023
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	February 29, 2024

Table 1. End-of-Life Milestones and Dates for the Cisco UCS Intel Xeon Processor E7/E5 v3 Series Spare

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
UCS-CPU-E5-4610D=	1.70 GHz E5-4610 v3/105W 10C/25MB Cache/DDR4 1600MHz
UCS-CPU-E5-4620D=	2.00 GHz E5-4620 v3/105W 10C/25MB Cache/DDR4 1866MHz
UCS-CPU-E5-4627D=	2.60 GHz E5-4627 v3/135W 10C/25MB Cache/DDR4 2133MHz
UCS-CPU-E5-4640D=	1.90 GHz E5-4640 v3/105W 12C/30MB Cache/DDR4 1866MHz

End-of-Sale Product Part Number	Product Description
UCS-CPU-E5-4650D=	2.10 GHz E5-4650 v3/105W 12C/30MB Cache/DDR4 2133MHz
UCS-CPU-E5-4655D=	2.90 GHz E5-4655 v3/135W 6C/30MB Cache/DDR4 2133MHz
UCS-CPU-E5-4660D=	2.10 GHz E5-4660 v3/120W 14C/35MB Cache/DDR4 2133MHz
UCS-CPU-E5-4667D=	2.00 GHz E5-4667 v3/135W 16C/40MB Cache/DDR4 2133MHz
UCS-CPU-E5-4669D=	2.10 GHz E5-4669 v3/135W 18C/45MB Cache/DDR4 2133MHz
UCS-CPU-E52609D=	1.90 GHz E5-2609 v3/85W 6C/15MB Cache/DDR4 1600MHz
UCS-CPU-E52620D=	2.40 GHz E5-2620 v3/85W 6C/15MB Cache/DDR4 1866MHz
UCS-CPU-E52623D=	3.00 GHz E5-2623 v3/105W 4C/10MB Cache/DDR4 1866MHz
UCS-CPU-E52630D=	2.40 GHz E5-2630 v3/85W 8C/20MB Cache/DDR4 1866MHz
UCS-CPU-E52630LD=	1.80 GHz E5-2630L v3/55W 8C/20MB Cache/DDR4 1866MHz
UCS-CPU-E52637D=	3.50 GHz E5-2637 v3/135W 4C/15MB Cache/DDR4 2133MHz
UCS-CPU-E52640D=	2.60 GHz E5-2640 v3/90W 8C/20MB Cache/DDR4 1866MHz
UCS-CPU-E52643D=	3.40 GHz E5-2643 v3/135W 6C/20MB Cache/DDR4 2133MHz
UCS-CPU-E52650D=	2.30 GHz E5-2650 v3/105W 10C/25MB Cache/DDR4 2133MHz
UCS-CPU-E52650LD=	1.80 GHz E5-2650L v3/65W 12C/30MB Cache/DDR4 2133MHz
UCS-CPU-E52658D=	2.20 GHz E5-2658 v3/105W 12C/30MB Cache/DDR4 2133MHz
UCS-CPU-E52660D=	2.60 GHz E5-2660 v3/105W 10C/25MB Cache/DDR4 2133MHz
UCS-CPU-E52667D=	3.20 GHz E5-2667 v3/135W 8C/20MB Cache/DDR4 2133MHz
UCS-CPU-E52670D=	2.30 GHz E5-2670 v3/120W 12C/30MB Cache/DDR4 2133MHz
UCS-CPU-E52680D=	2.50 GHz E5-2680 v3/120W 12C/30MB Cache/DDR4 2133MHz
UCS-CPU-E52683D=	2.00 GHz E5-2683 v3/120W 14C/35MB Cache/DDR4 2133MHz
UCS-CPU-E52690D=	2.60 GHz E5-2690 v3/135W 12C/30MB Cache/DDR4 2133MHz
UCS-CPU-E52695D=	2.30 GHz E5-2695 v3/120W 14C/35MB Cache/DDR4 2133MHz
UCS-CPU-E52697D=	2.60 GHz E5-2697 v3/145W 14C/35MB Cache/DDR4 2133MHz
UCS-CPU-E52698D=	2.30 GHz E5-2698 v3/135W 16C/40MB Cache/DDR4 2133MHz
UCS-CPU-E52699D=	2.30 GHz E5-2699 v3/145W 18C/45MB Cache/DDR4 2133MHz
UCS-CPU-E74809D=	2.0GHz E7-4809 v3/115W/8 cores/20M
UCS-CPU-E74820D=	1.9GHz E7-4820 v3/ 115W/10 cores/25M
UCS-CPU-E74830D=	2.1GHz E7-4830 v3/115W/12C/30M
UCS-CPU-E74850D=	2.2GHz E7-4850 v3/115W/14C/35M
UCS-CPU-E78860D=	2.2GHz E7-8860 v3/140W/16C/40M
UCS-CPU-E78867D=	2.5GHz E7-8867 v3/165W/16C/45M
UCS-CPU-E78870D=	2.1GHz E7-8870 v3/140W/18C/45M
UCS-CPU-E78880D=	2.3GHz E7-8880 v3/150W/18C/45M
UCS-CPU-E78880LD=	2.0GHz E7-8880L v3/115W/18C/45M
UCS-CPU-E78890D=	2.5GHz E7-8890 v3/165W/18C/45M Cache
UCS-CPU-E78891D=	2.8GHz E7-8891 v3/165W/10C/45M
UCS-CPU-E78893D=	3.2GHz E7-8893 v3/140W/4C/45M

Product Migration Options

There is no replacement available for the Cisco UCS Intel Xeon Processor E7/E5 v3 Series Spare at this time.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at:

https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco UCS Intel Xeon Processor E7/E5 v3 Series Spare through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <u>https://www.cisco.com/go/eos</u>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to: <u>https://www.cisco.com/en/US/products/products_end-of-life_policy.html</u>.

For more information about the Cisco Product Warranties, go to: <u>https://www.cisco.com/en/US/products/prod_warranties_listing.html</u>.

To subscribe to receive end-of-life/end-of-sale information, go to: https://www.cisco.com/cisco/support/notifications.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: <u>https://www.cisco.com/web/feeds/products/end_of_life_rss.xml</u>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at https://www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA