



End-of-Sale and End-of-Life Announcement for the Select Cisco UCS Server Accessories (Memory, RAID, Mezzanine Card, Adapter, Power Supply)

EOL8900—Amended

Cisco announces the end-of-sale and end-of life dates for the Select Cisco UCS Server Accessories (Memory, RAID, Mezzanine Card, Adapter, Power Supply). The last day to order the affected product(s) is March 8, 2013. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1. End-of-Life Milestones and Dates for the Select Cisco UCS Server Accessories (Memory, RAID, Mezzanine Card, Adapter, Power Supply)

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	December 7, 2012
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	March 8, 2013
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	June 6, 2013
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	March 8, 2014
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	March 8, 2014
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	June 3, 2017
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	March 31, 2018

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
N20-AI0102	Cisco UCS CNA M61KR-I Intel Converged Network Adapter	N20-AC0002	UCS M81KR Virtual Interface Card/PCIe/2-port 10Gb	—
N20-AI0102=	Cisco UCS CNA M61KR-I Intel Converged Network Adapter	N20-AC0002=	UCS M81KR Virtual Interface Card/PCIe/2-port 10Gb	—
N20-PAC5-2500W	2500W AC power supply unit for UCS 5108	UCSB-PSU-2500ACPL	2500W Platinum AC Hot Plug Power Supply for UCS 5108 Chassis	—
N20-PAC5-2500W=	2500W AC power supply unit for UCS 5108	UCSB-PSU-2500ACPL=	2500W Platinum AC Hot Plug Power Supply for UCS 5108 Chassis	—
N2XX-ABPCI02	Broadcom 57711 Dual Port 10GbE NIC w/TOE iSCSI	There is currently no replacement product available for this product.		
N2XX-ABPCI02=	Broadcom 57711 Dual Port 10GbE NIC w/TOE iSCSI	There is currently no replacement product available for this product.		
N2XX-ACPCI01	Cisco UCS P81E Virtual Interface Card/ 2-port 10Gbps	UCSC-PCIE-CSC-02	Cisco VIC 1225 Dual Port 10Gb SFP+ CNA	—
N2XX-AEPCI01	Emulex OneConnect OCe10102-F CNA 2 port 10Gb	There is currently no replacement product available for this product.		
N2XX-AEPCI01=	Emulex OneConnect OCe10102-F CNA 2 port 10Gb	There is currently no replacement product available for this product.		
N2XX-AIPCI02	Intel Quad port GbE Controller (E1G44ETG1P20)	There is currently no replacement product available for this product.		
N2XX-AMPCI01	Mellanox ConnectX-2 EN with dual 10GbE SFP+ ports	There is currently no replacement product available for this product.		
N2XX-AMPCI01=	Mellanox ConnectX-2 EN with dual 10GbE SFP+ ports	There is currently no replacement product available for this product.		
N2XX-AQPCI01	Qlogic QLE 8152-CNA 2port 10Gb SFP+ Copper	There is currently no replacement product available for this product.		
R210-SASXPAND	SAS Pass-Thru Expander (srvr requiring 8 HDDs) - C210	There is currently no replacement product available for this product.		
R210-SASXTDR	SAS Extender (servers requiring 8 HDDs) for UCS C210 M1	There is currently no replacement product available for this product.		
R210-SASXTDR=	SAS Extender (servers requiring 8 HDDs) for UCS C210 M1	There is currently no replacement product available for this product.		
R250-PL003	LSI SAS30813E-R - SAS/SATA RAID 0/1 PCIe Card	See the Product Migration Options section below for detailed information on replacing this product.		
R2X0-ML002	LSI 1064E (4-port SAS 3.0G RAID 0, 1, 1E) Mezz Card	There is currently no replacement product available for this product.		
R2X0-ML002=	LSI 1064E (4-port SAS) Mezz Card w/ 1-SAS Cable - C200 ONLY	There is currently no replacement product available for this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
R2XX-PL002	LSI MegaRAID SAS 8708EM2	There is currently no replacement product available for this product.		
R2XX-PL002=	LSI MegaRAID SAS 8708EM2 w/256MB WC and 1-SAS Cable for C200	There is currently no replacement product available for this product.		
UCS-MR-1X162RX-A	16GB DDR3-1333-MHz RDIMM/PC3-10600/dual rank/1.35v	UCS-MR-1X162RY-A	16GB DDR3-1600-MHz RDIMM/PC3-12800/dual rank/1.35v	—
UCS-MR-1X162RX-A=	16GB DDR3-1333-MHz RDIMM/PC3-10600/dual rank/1.35v	UCS-MR-1X162RY-A=	16GB DDR3-1600-MHz RDIMM/PC3-12800/dual rank/1.35v	—

Product Migration Options

Customers are encouraged to migrate to the replacement products noted in Table 2 where applicable. Information about these products can be found at: <http://www.cisco.com/en/US/products/ps10265/index.html>.

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html

For More Information

For more information about the Cisco UCS Server Memory, RAID, and Power Supply, visit <http://www.cisco.com/en/US/products/ps10265/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cisco/support/notifications.html>

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA

C51-722151-01 03/13

© 2013 Cisco and/or its affiliates. All rights reserved. This document is Cisco Public.

Page 4 of 4