

# End-of-Sale and End-of-Life Announcement for the Cisco Select Unified Computing System and Hyperflex Accessories



# Contents

- Overview 3
- End-of-life milestones 3
- Product part numbers 3
- Product migration options 7
- For more information 8

## Overview

### EOL14614 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco Select Unified Computing System and Hyperflex Accessories. The last day to order the affected product(s) is April 13, 2022. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

## End-of-life milestones

**Table 1.** End-of-life milestones and dates for the Cisco Select Unified Computing System and Hyperflex Accessories

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	January 12, 2022
<b>End-of-Sale Date Accessory</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 13, 2022
<b>Last Ship Date Accessory</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	April 13, 2022

## Product part numbers

**Table 2.** Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-GPU-RTX6000</b>	QUADRO RTX 6000, PASSIVE, 250W TGP, 24GB	HX-GPU-A40	TESLA A40 RTX, PASSIVE, 300W, 48GB	-
<b>HX-GPU-RTX6000=</b>	QUADRO RTX 6000, PASSIVE, 250W TGP, 24GB	HX-GPU-A40=	TESLA A40 RTX, PASSIVE, 300W, 48GB	-
<b>HX-GPU-RTX8000</b>	QUADRO RTX 8000, PASSIVE, 250W TGP, 48GB	HX-GPU-A40	TESLA A40 RTX, PASSIVE, 300W, 48GB	-
<b>HX-GPU-RTX8000=</b>	QUADRO RTX 8000, PASSIVE, 250W TGP, 48GB	HX-GPU-A40=	TESLA A40 RTX, PASSIVE, 300W, 48GB	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-HD10T7KL4KN</b>	10 TB 12G SAS 7.2K RPM LFF HDD (4K)	There is currently no replacement product available for this product.	-	-
<b>HX-HD10T7KL4KN=</b>	10 TB 12G SAS 7.2K RPM LFF HDD (4K)	There is currently no replacement product available for this product.	-	-
<b>HX-HD1T7KL12N</b>	1TB 12G SAS 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>HX-HD1T7KL12N=</b>	1TB 12G SAS 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>HX-HD1T7KL6GN</b>	1TB 6G SATA 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>HX-HD1T7KL6GN=</b>	1TB 6G SATA 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>HX-HD2T7KL6GN</b>	2 TB 6G SATA 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>HX-HD2T7KL6GN=</b>	2 TB 6G SATA 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>HX-HD4T7KL6GN</b>	4TB 6G SATA 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>HX-HD4T7KL6GN=</b>	4TB 6G SATA 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>HX-HD6T7KL6GN</b>	6TB 6G SATA 7.2K RPM LFF HDD (512e)	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-HD6T7KL6GN=</b>	6TB 6G SATA 7.2K RPM LFF HDD (512e)	There is currently no replacement product available for this product.	-	-
<b>HX-SP-M16-RVA</b>	16GB DDR4-2400-MHz RDIMM/PC4-19200/single rank/x4/1.2v	There is currently no replacement product available for this product.	-	-
<b>HX-SP-M32-RVA</b>	32GB DDR4-2400-MHz RDIMM/PC4-19200/dual rank/x4/1.2v	There is currently no replacement product available for this product.	-	-
<b>UCS-AMDCBL-C480M5</b>	C480M5 AMD 7150X2 Cable	There is currently no replacement product available for this product.	-	-
<b>UCS-AMDCBL-C480M5=</b>	C480M5 AMD 7150X2 Cable	There is currently no replacement product available for this product.	-	-
<b>UCS-BR-M32-RVA</b>	Brazil mem	There is currently no replacement product available for this product.	-	-
<b>UCS-HD10T7KL4KN</b>	10 TB 12G SAS 7.2K RPM LFF HDD (4K)	There is currently no replacement product available for this product.	-	-
<b>UCS-HD10T7KL4KN=</b>	10 TB 12G SAS 7.2K RPM LFF HDD (4K)	There is currently no replacement product available for this product.	-	-
<b>UCS-HD1T7KL12N</b>	1TB 12G SAS 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>UCS-HD1T7KL12N=</b>	1TB 12G SAS 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>UCS-HD1T7KL6GN</b>	1TB 6G SATA 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>UCS-HD1T7KL6GN=</b>	1TB 6G SATA 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>UCS-HD2T7KL6GN</b>	2 TB 6G SATA 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>UCS-HD2T7KL6GN=</b>	2 TB 6G SATA 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>UCS-HD4T7KL6GN</b>	4TB 6G SATA 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>UCS-HD4T7KL6GN=</b>	4TB 6G SATA 7.2K RPM LFF HDD	There is currently no replacement product available for this product.	-	-
<b>UCS-HD6T7KL6GN</b>	6TB 6G SATA 7.2K RPM LFF HDD (512e)	There is currently no replacement product available for this product.	-	-
<b>UCS-HD6T7KL6GN=</b>	6TB 6G SATA 7.2K RPM LFF HDD (512e)	There is currently no replacement product available for this product.	-	-
<b>UCS-SP-M16-RVA</b>	16GB DDR4-2400-MHz RDIMM/PC4-19200/single rank/x4/1.2v	There is currently no replacement product available for this product.	-	-
<b>UCS-SP-M32-RVA</b>	32GB DDR4-2400-MHz RDIMM/PC4-19200/dual rank/x4/1.2v	There is currently no replacement product available for this product.	-	-
<b>UCSC-C3X60-10TB</b>	UCSC C3X60 10TB 4Kn for Top-Load	There is currently no replacement product available for this product.	-	-
<b>UCSC-C3X60-10TB=</b>	UCSC C3X60 10TB 4Kn for Top-Load	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>UCSC-C3X60-10TBRR</b>	UCSC C3X60 10TB 4Kn Drives for Rear-Load	There is currently no replacement product available for this product.	-	-
<b>UCSC-C3X60-10TBRR=</b>	UCSC C3X60 10TB 4Kn Drives for Rear-Load	There is currently no replacement product available for this product.	-	-
<b>UCSC-GPU-RTX6000</b>	QUADRO RTX 6000, PASSIVE, 250W TGP, 24GB	UCSC-GPU-A40	TESLA A40 RTX, PASSIVE, 300W, 48GB	-
<b>UCSC-GPU-RTX6000=</b>	QUADRO RTX 6000, PASSIVE, 250W TGP, 24GB	UCSC-GPU-A40=	TESLA A40 RTX, PASSIVE, 300W, 48GB	-
<b>UCSC-GPU-RTX8000</b>	QUADRO RTX 8000, PASSIVE, 250W TGP, 48GB	UCSC-GPU-A40	TESLA A40 RTX, PASSIVE, 300W, 48GB	-
<b>UCSC-GPU-RTX8000=</b>	QUADRO RTX 8000, PASSIVE, 250W TGP, 48GB	UCSC-GPU-A40=	TESLA A40 RTX, PASSIVE, 300W, 48GB	-
<b>UCSC-V340CBL=</b>	CABLE v340 GPU with two 8-pin Power Connectors	There is currently no replacement product available for this product.	-	-

## Product migration options

Cisco goes through a very rigorous process to ensure that customers receive support. However in rare occasions, due to component supplier limitations, there may be a need for customer to migrate to a part that is an upgrade of something comparable or better than what they previously bought. This may require customer to upgrade to a different Software and OS version or even the closest generation of an equivalent server that may be currently shipping at the time.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[https://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

---

## For more information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to: <https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)