



PRODUCT BULLETIN, NO. 2391

CISCO CATALYST 4003 CHASSIS, SUPERVISOR ENGINE I, SUPERVISOR ENGINE III, CISCO IOS SOFTWARE RELEASE 12.1(12C)EW, AND ASSOCIATED BUNDLES

| | |
|-------------------------------------|------------------|
| Addendum Date | May 3, 2004 |
| Effective Date | May 3, 2004 |
| Original Bulletin Announcement Date | January 26, 2004 |
| Original Bulletin Information | PB2391 |

Cisco Systems® announces the end of life of the Cisco® Catalyst® 4003 chassis (WS-C4003-S1), Cisco Catalyst 4000 Supervisor Engine I (WS-X4012), Cisco Catalyst 4000/4500 Supervisor Engine III (WS-X4014), Cisco IOS® Software Release 12.1(12c)EW, and associated bundles. The end-of-life milestones, definitions, and dates are separated in to two sections: Table 1a and 2a.

The end-of-life Cisco Catalyst product bundles that contain DC power supplies (Table 2a) have been extended 9 months. Table 2b lists the affected product IDs. For all other end-of-sale Cisco Catalyst 4000/4500 products in this product bulletin, please refer to Tables 1a and 1b.

Cisco Catalyst 4003 and Cisco Catalyst 4000 Supervisor Engine I customers are encouraged to migrate to the Cisco Catalyst4503 with Supervisor Engine II-Plus, which provides nonblocking Layer 2 switching, basic Layer 3 routing, comprehensive Layer 3-4 security, and QoS at up to 64 Gbps and 48 Mpps.

Cisco Catalyst 4000/4500 Supervisor Engine III customers are encouraged to migrate to the Cisco Catalyst 4000/4500 Supervisor Engine IV, which includes the same features and functions as the Supervisor Engine III, plus additional enhancements at a lower price.

Cisco IOS Software Release 12.1(12c)EW customers are encouraged to migrate to Cisco IOS Software Release 12.2(25)EWA2 or later. These releases support additional hardware and software features.

For more information about the Cisco Catalyst 4503, Supervisor Engine II-Plus, and Supervisor Engine IV, go to:

<http://www.cisco.com/en/US/products/hw/switches/ps4324/index.html>

Table 1a. End-of-Life Milestones and Dates including the Cisco Catalyst 4003, Catalyst 4000 Supervisor Engine I, Catalyst 4000/4500 Supervisor Engine III, and Cisco IOS Software Release 12.1(12c)EW. Please see Table 1b for the complete list of products.

| Milestone | Definition | Date |
|---|---|--------------------|
| End-of-Life Announcement Date | The date the end of sale and end of life of a product is announced to the general public. | January 26, 2004 |
| End-of-Sale Date | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date | July 26, 2004 |
| Last Shipment Date | The last-possible date that Cisco and/or its contract manufacturers will ship the affected product. | September 30, 2004 |
| End of Software Maintenance Releases Date | The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software. | July 26, 2005 |

| Milestone | Definition | Date |
|--------------------------------------|---|---------------|
| End of Routine Failure Analysis Date | The last possible date a routine failure analysis may be performed to determine the cause of product failure or defect. | July 26, 2005 |
| End of New Service Attachment Date | For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract. | July 26, 2005 |
| End of Service Contract Renewal Date | The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support. | July 26, 2008 |
| Last Date of Support | The last date to receive service and support for the product. After this date, all support services for the product are unavailable and the product becomes obsolete. | July 26, 2009 |

Table 1b. Product Part Numbers Associated to Table 1a

| End-of-Sale Product Part Number | Product Description |
|---------------------------------|--|
| WS-X4012= | Catalyst 4000 Supervisor Engine I, Console (DB-25)/Mgt. (RJ-45) (Spare) |
| WS-X4014 | Catalyst 4000/4500 Supervisor Engine III (2 GE), Console (RJ45) |
| WS-X4014= | Catalyst 4000/4500 Supervisor Engine III (2 GE), Console (RJ45) (Spare) |
| WS-C4003-S1 | Catalyst 4000 Chassis (3-slot), Supervisor Engine1 AC P/S, Fan Tray |
| WS-C4003-S1-82 | Catalyst 4003 Chassis, AC P/S, Supervisor Engine I, 80 10/100 FE + 2 GE |
| WS-C4003= | Catalyst 4000 Chassis (3-slot), Single AC Power Supply (Spare) |
| WS-C4006-S3* | Catalyst 4000 Chassis (6-slot), Supervisor Engine III with 2 GE, 2 AC P/S, Fans |
| S4KL3-12112EW | Cisco IOS Software Basic Layer 3 Catalyst 4000/4500 Supervisor Engine III and Supervisor Engine IV (RIP, St. Routes, IPX, AppleTalk) |
| S4KL3-12112EW= | Cisco IOS BASIC L3 Cat4000 SUP III/IV (RIP, St. Routes, IPX, AppleTalk) |
| S4KL3E-12112EW | Cisco IOS ENHANCED L3 Cat4000 SUP III/IV (OSPF, IGRP, EIGRP) |
| S4KL3E-12112EW= | Cisco IOS ENHANCED L3 Cat4000 SUP III/IV (OSPF, IGRP, EIGRP) |

* Cisco is not announcing end of sale for the Cisco Catalyst 4006 Switch as part of this bulletin. This bulletin pertains only to the Catalyst 4006 bundle that includes Cisco Catalyst 4000/4500 Supervisor Engine III.

Table 2a. End-of-Life Milestones and Dates for WS-C4003-S1-DC and WS-C4006-S3-DC. Please refer to Table 2b for more information on the related products.

| Milestone | Definition | Date |
|---|---|------------------|
| End-of-Life Announcement Date | The date the end of sale and end of life of a product is announced to the general public. | January 26, 2004 |
| End-of-Sale Date | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date. | May 3, 2005 |
| Last Shipment Date | The last-possible date that Cisco and/or its contract manufacturers will ship the affected product. | August 3, 2005 |
| End of Software Maintenance Releases Date | The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software. | May 3, 2006 |

| Milestone | Definition | Date |
|--------------------------------------|---|-------------|
| End of Routine Failure Analysis Date | The last possible date a routine failure analysis may be performed to determine the cause of product failure or defect. | May 3, 2006 |
| End of New Service Attachment Date | For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract. | May 3, 2006 |
| End of Service Contract Renewal Date | The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support. | May 3, 2009 |
| Last Date of Support | The last date to receive service and support for the product. After this date, all support services for the product are unavailable and the product becomes obsolete. | May 3, 2010 |

Table 2b. Product Part Numbers Associated to Table 2a

| End-of-Sale Product Part Number | Product Description |
|---------------------------------|---|
| WS-C4003-S1-DC | Catalyst 4000 Chassis (3-slot), Supervisor Engine I, 1 DC P/S, Fans |
| WS-C4006-S3-DC | Catalyst 4000 Chassis (6-slot), Supervisor Engine III with 2 GE, 2 DC P/S, Fans |

PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco Catalyst 4003 chassis with Catalyst 4000 Supervisor Engine I is the Cisco Catalyst 4503 with Supervisor Engine II-Plus.

For a list of benefits of the Cisco Catalyst 4503, please visit:

http://www.cisco.com/en/US/products/hw/switches/ps4324/products_data_sheet0900aecd8017a0c5.html

Table 3 provides information for migrating from the Cisco Catalyst 4003 chassis with Supervisor Engine I.

Table 3. Cisco Catalyst 4003 Chassis and Catalyst 4000 Supervisor Engine I Replacement Products

| End of Sale Product Part Number | Deployed With | Replacement Product Numbers |
|---------------------------------|---|---|
| WS-C4003-S1 | Cisco Catalyst 4000 and Catalyst 4500 series line cards | <ul style="list-style-type: none"> WS-C4503, WS-C4506, or WS-C4507R WS-X4013+ or WS-X4515 PWR-C45-1000AC |
| WS-C4003-S1-DC | Cisco Catalyst 4000 and Catalyst 4500 series line cards | <ul style="list-style-type: none"> WS-C4503, WS-C4506, or WS-C4507R WS-X4013+ or WS-X4515 PWR-C45-1400DC-P |

The recommended replacement for the Cisco Catalyst 4000/4500 Supervisor Engine III is the Cisco Catalyst 4000/4500 Supervisor Engine IV. The Catalyst 4000/4500 Supervisor Engine IV is compatible with all Catalyst 4500 Series chassis, power supplies, and existing Catalyst 4000 Series line cards.

For a list of benefits of the Cisco Catalyst 4000/4500 Supervisor Engine IV, go to:

http://www.cisco.com/en/US/prod/collateral/switches/ps5718/ps4324/product_data_sheet0900aecd8035cf2b.html

Table 4 provides information for migrating from the Cisco Catalyst 4000/4500 Supervisor Engine III.

Table 4. Cisco Catalyst 4000/4500 Supervisor Engine III Replacement Products

| End of Sale Product Part Number | Deployed with | Replacement Product Numbers |
|---------------------------------|--|-----------------------------|
| WS-X4014 | Cisco Catalyst 4503, 4506, or 4006 chassis | WS-X4515 |

The recommended replacement for Cisco IOS Software Release 12.1(12c)EW is Cisco IOS Software Release 12.2(25)EWA2 or later. These releases support additional hardware and software features.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>

The Cisco TMP application requires that all users have a Cisco.com user ID.

ADDITIONAL INFORMATION

For more information about Cisco products, contact your Cisco account manager or Cisco Channel Partner. For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life or end-of-sale information go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel
Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) 205389.G_ETMG_CC_8.05

