

CSCvc53327: RV32x does not provide an IP address when host name includes spaces

Summary

RV32x does not provide an IP address when host name of the DHCP client includes spaces. RV32x does not currently support spaces and special characters in the host name field.

Date Identified

December 16, 2016

Date Resolved

N/A

Products Affected

RV320	1.3.2.02
RV325	1.3.2.02

Next Steps

Check the characters and length of your device host name. If it contains special characters or spaces, you can temporarily remove them from the host name for the device to receive an IP address from the RV32x. A router firmware that would accept special characters and spaces is currently in progress.