

# Configuración y resolución de problemas de señalización E1 R2 para llamadas de datos

## Contenido

[Introducción](#)  
[Prerequisites](#)  
[Requirements](#)  
[Componentes Utilizados](#)  
[Convenciones](#)  
[Antecedentes](#)  
[Configurar](#)  
[Diagrama de la red](#)  
[Configuraciones](#)  
[Verificación](#)  
[Troubleshoot](#)  
[Comandos para resolución de problemas](#)  
[Información Relacionada](#)

## [Introducción](#)

Este documento suministra un ejemplo de configuración y técnicas de troubleshooting para la señalización E1 R2 para las llamadas de datos.

## [Prerequisites](#)

### [Requirements](#)

Antes de intentar esta configuración, se recomienda leer el documento [E1 R2 Signaling Theory](#). Para obtener información sobre la señalización E1 R2 para aplicaciones de voz, refiérase al documento [Configuración y Troubleshooting de Señalización E1 R2](#).

## [Componentes Utilizados](#)

Esta configuración fue desarrollada y probada utilizando las versiones de software y hardware indicadas a continuación. Esta configuración muestra una configuración de laboratorio adosada entre un router Cisco 3640 y un servidor de acceso Cisco AS5300.

- El AS5300 simula al cliente y ejecuta la versión 12.2(3) del software del IOS® de Cisco.
  - El 3640 actúa como servidor y ejecuta la versión 12.1(10) del software del IOS de Cisco.
- The information in this document was created from the devices in a specific lab environment. All of the devices used in this document started with a cleared (default) configuration. If your network is

live, make sure that you understand the potential impact of any command.

## Convenciones

Para obtener más información sobre las convenciones del documento, consulte [Convenciones de Consejos Técnicos de Cisco](#).

## Antecedentes

La señalización E1 R2 permite a un servidor de acceso universal de Cisco comunicarse con los troncos de la oficina central que también utilizan la señalización E1 R2. La señalización R2 es un estándar de señalización internacional común a las redes E1 canalizadas. No hay un único estándar para la señalización R2. La recomendación Q.400-Q.490 de la ITU-T define la R2, pero varios países implementan la R2 de maneras completamente diferentes.

Cisco Systems hace frente a este desafío al admitir muchas implementaciones localizadas de señalización R2 en su software Cisco IOS. La localización personalizada de R2 significa que la señalización R2 es compatible con una amplia gama de países y regiones geográficas. Cisco es compatible continuamente con las variantes de señalización E1 R2 en nuevos países.

**Nota:** Sólo los módulos de agregación de canales ISDN (MICA) y módem digital Nextport admiten la funcionalidad R2. No se proporciona soporte R2 para módems Microcom o aplicaciones que no son de módem.

## Configurar

En esta sección encontrará la información para configurar las funciones descritas en este documento. Esta configuración es válida para los siguientes escenarios:

- Conexiones de marcado del módem sobre E1 R2
- Conexiones adosadas E1 R2
- Conexiones E1 R2 entre el router de Cisco


**Nota:** La configuración del controlador E1 es la misma para las llamadas de datos o de voz. La única diferencia es:

- Para las llamadas de datos, debe configurar los módems para aceptar las llamadas.
- Para las llamadas de voz, debe configurar los puertos de voz para aceptar las llamadas.

**Nota:** Para encontrar información adicional sobre los comandos usados en este documento, utilice la [Command Lookup Tool](#) (sólo clientes registrados) .

## Diagrama de la red

Este documento utiliza la instalación de red que se muestra en el siguiente diagrama.



## Configuraciones

La configuración de E1 R2 para llamadas de datos implica dos pasos generales:

- Configuración de E1 R2
- Configuración de módems y problemas relacionados

La configuración E1 R2 se basa en la información obtenida de la compañía telefónica. Refiérase al documento [Configuración y Troubleshooting de Señalización E1 R2](#) para obtener información adicional sobre la configuración específica E1 R2.

La configuración del módem es similar a la de cualquier servidor de acceso con, por ejemplo, una línea PRI.

<b>Mónica (as5300)</b>
<pre>Monica#show running-config  controller E1 1 !---- E1 R2 configuration framing NO-CRC4 clock source line secondary 1 ds0-group 1 timeslots 1-15,17-31 type r2-digital r2-compelled cas-custom 1 country easteurope use-defaults interface Async60 !---- Interface configuration for outgoing call no ip address encapsulation ppp dialer in-band dialer rotary-group 3 async mode dedicated ppp authentication chap line 60 !-- - Line configuration for outgoing call modem InOut modem dialout controller e1 1 !---- Specify that e1 1 is used for outgoing call transport input all autoselect during- login autoselect ppp</pre>
<b>angela (3640)</b>
<pre>angela#show running-config interface Ethernet0/0  ip address 10.200.20.2 255.255.255.0 controller E1 2/0 !---- E1 R2 configuration framing NO-CRC4 ds0-group 1 timeslots 1-15,17-31 type r2-digital r2-compelled cas- custom 1 country easteurope use-defaults interface Group-Async1 ip unnumbered Ethernet0/0 encapsulation ppp async mode interactive peer default ip address pool DIAL_POOL ppp authentication chap group-range 97 114 !</pre>

```
ip local pool DIAL_POOL 105.41.30.101 105.41.30.132 line  
97 114 !---- Line configuration for incoming calls modem  
InOut autocmd ppp transport input all autoselect  
during-login autoselect ppp
```

## Verificación

Actualmente, no hay un procedimiento de verificación disponible para esta configuración.

## Troubleshoot

En esta sección encontrará información que puede utilizar para solucionar problemas de configuración.

Para obtener más información sobre la resolución de problemas de fallas de E1 R2, refiérase a [Configuración y Troubleshooting de Señalización E1 R2](#).

### Comandos para resolución de problemas

La herramienta [Output Interpreter](#) (sólo para clientes registrados) permite utilizar algunos comandos “show” y ver un análisis del resultado de estos comandos.

**Nota:** Antes de ejecutar **comandos debug**, consulte [Información Importante sobre Comandos Debug](#).

- **show controllers e1** - muestra el estado del controlador que es específico del hardware del controlador. Para obtener detalles, consulte [Comprensión del Comando show controllers e1](#).
- **show diag**: en el Cisco 3600, muestra información de hardware para el router, verifica si se reconoce todo el hardware.
- **debug modem csm**: depura el Módulo de conmutación de llamadas (CSM) utilizado para conectar llamadas en el módem.
- **debug cas**: proporciona seguimientos en tiempo real del estado del bit de señalización CAS.
- **debug modem** - muestra la actividad de línea del módem en un servidor de acceso.
- **show modem version** - muestra información de versión sobre el firmware del módem, el controlador y el código DSP.

```
angela#show modem version  
Slot 3:MICA-6DM Firmware, Source - flashow :/mica-modem-pw.2.7.3.0.bin  
CP ver 2730 - 5/23/2001, CheckSum BCCEB316.  
SP ver 2730 - 5/23/2001.  
MICA 0: HW Version 2.1, Serial Number 21094004.
```

```
angela#show diag  
Slot 2:  
CE1 (Balanced) Port adapter, 1 port  
Port adapter is analyzed  
Port adapter insertion time unknown  
EEPROM contents at hardware discovery:  
Hardware revision 1.1 Board revision A0  
Serial number 11359839 Part number 800-01234-04  
Test history 0x0 RMA number 00-00-00  
EEPROM format version 1
```

```
EEPROM contents (hex):
0x20: 01 2A 01 01 00 AD 56 5F 50 04 D2 04 00 00 00 00
0x30: 50 00 00 00 98 11 24 00 FF FF FF FF FF FF FF FF
```

```
angela#show controllers e1 2/0
E1 2/0 is up.
Applique type is Channelized E1 - balanced
Far End Block Errors Detected
No alarms detected.
Framing is NO-CRC4, Line Code is HDB3, Clock Source is Line.
Data in current interval (34 seconds elapsed):
0 Line Code Violations, 0 Path Code Violations
0 Slip Secs, 0 Fr Loss Secs, 0 Line Err Secs, 0 Degraded Mins
0 Errorred Secs, 0 Bursty Err Secs, 0 Severely Err Secs, 0 Unavail
Secs
```

Robbed bit signals state:

	timeslots	rxA	rxB	rxC	rxD	txA	txB	txC	txD
1		1	0	0	1	1	0	0	1
2		1	0	0	1	1	0	0	1
3		1	0	0	1	1	0	0	1
4		1	0	0	1	1	0	0	1
5		1	0	0	1	1	0	0	1
6		1	0	0	1	1	0	0	1
7		1	0	0	1	1	0	0	1
8		1	0	0	1	1	0	0	1
9		1	0	0	1	1	0	0	1
10		1	0	0	1	1	0	0	1
11		1	0	0	1	1	0	0	1
12		1	0	0	1	1	0	0	1
13		1	0	0	1	1	0	0	1
14		1	0	0	1	1	0	0	1
15		1	0	0	1	1	0	0	1
17		1	0	0	1	1	0	0	1
18		1	0	0	1	1	0	0	1
19		1	0	0	1	1	0	0	1
20		1	0	0	1	1	0	0	1
21		1	0	0	1	1	0	0	1
22		1	0	0	1	1	0	0	1
23		1	0	0	1	1	0	0	1
24		1	0	0	1	1	0	0	1
25		1	0	0	1	1	0	0	1
26		1	0	0	1	1	0	0	1
27		1	0	0	1	1	0	0	1
28		1	0	0	1	1	0	0	1
29		1	0	0	1	1	0	0	1
30		1	0	0	1	1	0	0	1
31		1	0	0	1	1	0	0	1

El cliente está marcando 789 interpretaciones necesarias en las depuraciones del servidor.

```
monica#2.2.2.1 2060
Trying 2.2.2.1, 2060 ... Open
at
OK
atdt789
```

Para comprender mejor este resultado de debug, consulte el documento [E1 R2 Signaling Theory](#).

```
angela#show debug
General OS:
    Modem control/process activation debugging is on
```

CAS:  
 Channel Associated Signaling debugging is on  
 CSM Modem Management:  
 Modem Management Call Switching Module debugging is on

angela#  
Oct 29 15:59:46.591: Modem 255/255 CSM: received EVENT\_CALL\_DIAL\_IN with call\_id 0006  
Oct 29 15:59:46.591: src 2/0/25 dest 255/0/255 cause 768  
Oct 29 15:59:46.591: CSM: Next free modem = 3/6; statbits = 80010020  
Oct 29 15:59:46.591: Modem 3/6 CSM: modem is allocated, modems free=17  
Oct 29 15:59:46.591: Modem 3/6 CSM: (CSM\_PROC\_IDLE)<--DSX0\_CALL  
Oct 29 15:59:46.595: Modem 3/6 Mica: configured for Answer mode,  
with Lower R2 signaling, 0x0 tone detection.  
Oct 29 15:59:46.707: Modem 3/6 CSM: received EVENT\_START\_RX\_TONE with call\_id 0006  
Oct 29 15:59:46.707: src 2/0/25 dest 3/0/6 cause 0  
Oct 29 15:59:46.707: Modem 3/6 CSM: (CSM\_PROC\_IC\_CAS\_CHANNEL\_LOCKED)<--DSX0\_START\_RX\_TONE  
Oct 29 15:59:46.707: Modem 3/6 CSM: (CSM\_PROC\_IC\_CAS\_CHANNEL\_LOCKED)<--CSM\_EVENT\_MODEM\_SETUP  
Oct 29 15:59:46.711: R2 Incoming Modem(3/6): DSX (E1 2/0:25):  
STATE: R2\_IN\_IDLE R2 Got Event R2\_START  
Oct 29 15:59:46.715: Modem 3/6 Mica: in modem state CALL\_SETUP  
Oct 29 15:59:46.883: Modem 3/6 CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--MODEM\_DIGITS\_COLLECTED  
!--- We can see number 7 Oct 29 15:59:46.887: R2 Incoming Modem(3/6): DSX (E1 2/0:25):  
STATE: R2\_IN\_COLLECT\_DNIS R2 Got Event 7 Oct 29 15:59:46.887: Modem 3/6 Mica: dialing number '1'  
!--- MICA sends 1 (which means send next digit) Oct 29 15:59:46.887: Modem 3/6 Mica: Detected  
dial digit '7' Oct 29 15:59:46.959: Modem 3/6 CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--  
MODEM\_DIGITS\_GENERATED Oct 29 15:59:47.011: Modem 3/6 CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--  
MODEM\_DIGITS\_COLLECTED Oct 29 15:59:47.011: R2 Incoming Modem(3/6): DSX (E1 2/0:25): STATE:  
R2\_IN\_COLLECT\_DNIS R2 Got Event R2\_TONE\_OFF Oct 29 15:59:47.011: Modem 3/6 Mica: dialing number  
'#' Oct 29 15:59:47.011: Modem 3/6 Mica: Detected dial digit '#' Oct 29 15:59:47.099: Modem 3/6  
CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--MODEM\_DIGITS\_GENERATED Oct 29 15:59:47.163: Modem 3/6  
CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--MODEM\_DIGITS\_COLLECTED !!-- We can see number 8 Oct 29  
15:59:47.163: R2 Incoming Modem(3/6): DSX (E1 2/0:25): STATE: R2\_IN\_COLLECT\_DNIS R2 Got Event 8  
Oct 29 15:59:47.163: Modem 3/6 Mica: dialing number '1' !!-- MICA sends 1 (which means send next  
digit) Oct 29 15:59:47.163: Modem 3/6 Mica: Detected dial digit '8' Oct 29 15:59:47.235: Modem  
3/6 CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--MODEM\_DIGITS\_GENERATED Oct 29 15:59:47.299: Modem 3/6  
CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--MODEM\_DIGITS\_COLLECTED Oct 29 15:59:47.299: R2 Incoming  
Modem(3/6): DSX (E1 2/0:25): STATE: R2\_IN\_COLLECT\_DNIS R2 Got Event R2\_TONE\_OFF Oct 29  
15:59:47.299: Modem 3/6 Mica: dialing number '#' Oct 29 15:59:47.299: Modem 3/6 Mica: Detected  
dial digit '#' Oct 29 15:59:47.375: Modem 3/6 CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--  
MODEM\_DIGITS\_GENERATED Oct 29 15:59:47.427: Modem 3/6 CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--  
MODEM\_DIGITS\_COLLECTED Oct 29 15:59:47.427: R2 Incoming Modem(3/6): DSX (E1 2/0:25):  
STATE: R2\_IN\_COLLECT\_DNIS R2 Got Event 9 Oct 29 15:59:47.427: Modem 3/6 Mica: dialing number '1'  
!--- MICA sends 1 (which means send next digit) Oct 29 15:59:47.427: Modem 3/6 Mica: Detected  
dial digit '9' Oct 29 15:59:47.499: Modem 3/6 CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--  
MODEM\_DIGITS\_GENERATED Oct 29 15:59:47.551: Modem 3/6 CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--  
MODEM\_DIGITS\_COLLECTED Oct 29 15:59:47.551: R2 Incoming Modem(3/6): DSX (E1 2/0:25):  
STATE: R2\_IN\_COLLECT\_DNIS R2 Got Event R2\_TONE\_OFF Oct 29 15:59:47.551: Modem 3/6 Mica: dialing  
number '#' Oct 29 15:59:47.551: Modem 3/6 Mica: Detected dial digit '#' Oct 29 15:59:47.639:  
Modem 3/6 CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--MODEM\_DIGITS\_GENERATED !!-- NORMAL TIMEOUT--> 3  
seconds Oct 29 16:00:02.426: R2 Incoming Modem(3/6): DSX (E1 2/0:25): STATE: R2\_IN\_COLLECT\_DNIS  
R2 Got Event R2\_TONE\_TIMER !!-- MICA sends 3 (which means ADDRESS COMPLETE) Oct 29 16:00:02.426:  
Modem 3/6 Mica: dialing number '3#' Oct 29 16:00:02.654: Modem 3/6  
CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--MODEM\_DIGITS\_GENERATED Oct 29 16:00:02.678: Modem 3/6  
CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--MODEM\_DIGITS\_COLLECTED !!-- We can see number 1 after we  
send 3 Oct 29 16:00:02.678: R2 Incoming Modem(3/6): DSX (E1 2/0:25): STATE: R2\_IN\_CATEGORY R2 Got  
Event 1 Oct 29 16:00:02.682: r2\_comp\_category:R2\_ALERTING !!-- MICA sends 3 (which means ADDRESS  
COMPLETE) Oct 29 16:00:02.682: Modem 3/6 Mica: dialing number '6' Oct 29 16:00:02.682: Modem 3/6  
Mica: Detected dial digit '1' Oct 29 16:00:02.834: Modem 3/6  
CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--MODEM\_DIGITS\_COLLECTED Oct 29 16:00:02.834: R2 Incoming  
Modem(3/6): DSX (E1 2/0:25): STATE: R2\_IN\_COMPLETE R2 Got Event R2\_TONE\_OFF Oct 29 16:00:02.834:  
Modem 3/6 CSM: Pending digit generation for # Oct 29 16:00:02.834: Modem 3/6 Mica: Detected dial  
digit '#' Oct 29 16:00:02.854: Modem 3/6 CSM: (CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--  
MODEM\_DIGITS\_GENERATED Oct 29 16:00:02.854: Modem 3/6 Mica: dialing number '#' Oct 29

16:00:02.854: Modem 3/6 CSM: Generate 1 pending digit(s) # Oct 29 16:00:02.918: Modem 3/6  
 CSM:(CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--MODEM\_DIGITS\_GENERATED Oct 29 16:00:03.834: R2 Incoming  
 Modem(3/6): DSX (E1 2/0:25): STATE:R2\_IN\_WAIT\_GUARD R2 Got Event R2\_TONE\_TIMER Oct 29  
 16:00:03.834: R2\_IN\_IDLE:2 r2\_in\_connect called Oct 29 16:00:03.834: Modem 3/6  
 CSM:(CSM\_PROC\_IC\_CAS\_COLLECT\_DIGITS)<--ADDR\_INFO\_COLLECTED Oct 29 16:00:03.842: Modem 3/6 CSM:  
 received EVENT\_CHANNEL\_CONNECTED with call\_id 0006 Oct 29 16:00:03.842: src 2/0/25 dest 3/0/6  
 cause 0 Oct 29 16:00:03.842: Modem 3/6 CSM:(CSM\_PROC\_IC\_CAS\_ANSWER\_CALL)<--DSX0\_CONNECTED Oct 29  
 16:00:04.926: Modem 3/6 Mica: in modem state CONNECT Oct 29 16:00:12.290: Modem 3/6 Mica: in  
 modem state LINK Oct 29 16:00:21.278: Modem 3/6 Mica: in modem state TRAINUP Oct 29  
 16:00:23.002: Modem 3/6 Mica: in modem state EC\_NEGOTIATING Oct 29 16:00:23.170: Modem 3/6  
 CSM:(CSM\_PROC\_CAS\_WAIT\_FOR\_CARRIER)<--MODEM\_CONNECTED Oct 29 16:00:23.170: Modem 3/6 Mica: in  
 modem state STEADY Oct 29 16:00:23.194: Modem 3/6 Mica: CONNECT at 33600/33600 (Tx/Rx), V34+,  
 LAPM, V42bis Oct 29 16:00:23.446: TTY103: DSR came up Oct 29 16:00:23.446: tty103: Modem: IDLE->(unknown)  
 Oct 29 16:00:23.446: TTY103: Autoselect started Oct 29 16:00:23.446: TTY103: create  
 timer type 0, 120 seconds ----- monica#**show debug**  
 General OS:  
     Modem control/process activation debugging is on  
 CAS:  
     Channel Associated Signaling debugging is on  
 Modem Management:  
     Modem Management Call Switching Module debugging is on  
  
 monica#  
 Oct 29 15:59:46.540: Mica Modem(1/59): Rcvd Dial String(T789)  
 Oct 29 15:59:46.540: Mica Modem(1/59): Dropped character T  
 Oct 29 15:59:46.540: Mica Modem(1/59): Dial String to be processed (789)  
 Oct 29 15:59:46.540: Mica Modem(1/59): End of Dial String  
 Oct 29 15:59:46.540: CSM\_PROC\_IDLE: CSM\_EVENT\_MODEM\_OFFHOOK at slot 1, port 59  
 Oct 29 15:59:46.540: csm\_get\_signaling\_channel csm\_call\_info->bchan\_num 0xFFFFFFFF  
 Oct 29 15:59:46.540: csm\_get\_signaling\_channel dchan\_index=24952,next\_index=0,  
 dchan\_info=0x62269D0C  
 Oct 29 15:59:46.540: csm\_get\_signaling\_channel csm\_call\_info->bchan\_num 0xFFFFFFFF  
 Oct 29 15:59:46.540: csm\_get\_signaling\_channel dchan\_index=0,next\_index=1,  
 dchan\_info=0x61D37574  
 Oct 29 15:59:46.540: CSM\_RX\_CAS\_EVENT\_FROM\_NEAT:(8007):  
 EVENT\_CHANNEL\_LOCK at slot 1 port 59 on ctrlr 1 chan 25  
 Oct 29 15:59:46.544: CSM\_PROC\_OC4\_DIALING:  
 CSM\_EVENT\_DSX0\_BCHAN\_ASSIGNED at slot 1, port 59  
 Oct 29 15:59:46.544: csm\_connect\_pri\_vdev:  
 TS allocated at bp\_stream 1, bp\_Ch 9, vdev\_common 0x61B7BBAC 1/59  
 Oct 29 15:59:46.544: Mica Modem(1/59): Configure(0x1 = 0x1)  
 Oct 29 15:59:46.544: Mica Modem(1/59): Configure(0x23 = 0x4)  
 Oct 29 15:59:46.544: Mica Modem(1/59): Call Setup  
 Oct 29 15:59:46.544: from Trunk(0): (1/25): Tx SEIZURE (ABCD=0001)  
 Oct 29 15:59:46.616: Mica Modem(1/59): State Transition to Call Setup  
 Oct 29 15:59:46.712: from Trunk(0): (1/25): Rx SEIZURE\_ACK (ABCD=1101)  
 Oct 29 15:59:46.752: CSM\_RX\_CAS\_EVENT\_FROM\_NEAT:(8007):  
 EVENT\_START\_TX\_TONE at slot 1 and port 59  
 Oct 29 15:59:46.752: CSM\_PROC\_OC4\_DIALING:  
 CSM\_EVENT\_DSX0\_START\_TX\_TONE at slot 1, port 59  
 Oct 29 15:59:46.752: R2 Outgoing Modem(1/59): DSX (E1 1:25):  
 STATE: R2\_OUT\_IDLE R2 Got Event R2\_START  
 Oct 29 15:59:46.752: Mica Modem(1/59): Generate digits:called\_party\_num=# len=1  
 Oct 29 15:59:46.752: Mica Modem(1/59): Will Generate digits:called\_party\_num=7 len=1  
 Oct 29 15:59:46.824: Mica Modem(1/59): Rcvd Digits Generated  
 Oct 29 15:59:46.824: Mica Modem(1/59): Generate digits  
 Oct 29 15:59:46.900: Mica Modem(1/59): Rcvd Digits Generated  
 Oct 29 15:59:46.944: Mica Modem(1/59): Rcvd Digit detected(1)  
 Oct 29 15:59:46.944: R2 Outgoing Modem(1/59): DSX (E1 1:25):  
 STATE: R2\_OUT\_PROCESS\_A R2 Got Event 1  
 Oct 29 15:59:46.944: Mica Modem(1/59): Generate digits:called\_party\_num=# len=1  
 Oct 29 15:59:47.020: Mica Modem(1/59): Rcvd Digits Generated  
 Oct 29 15:59:47.108: Mica Modem(1/59): Rcvd Digit detected(#)  
 Oct 29 15:59:47.108: R2 Outgoing Modem(1/59): DSX (E1 1:25):

```

STATE: R2_OUT_PROCESS_A R2 Got Event R2_TONE_OFF
Oct 29 15:59:47.108: Mica Modem(1/59): Generate digits:called_party_num=8 len=1
Oct 29 15:59:47.184: Mica Modem(1/59): Rcvd Digits Generated
Oct 29 15:59:47.228: Mica Modem(1/59): Rcvd Digit detected(1)
Oct 29 15:59:47.228: R2 Outgoing Modem(1/59): DSX (E1 1:25):
STATE: R2_OUT_PROCESS_A R2 Got Event 1
Oct 29 15:59:47.228: Mica Modem(1/59): Generate digits:called_party_num=# len=1
Oct 29 15:59:47.304: Mica Modem(1/59): Rcvd Digits Generated
Oct 29 15:59:47.380: Mica Modem(1/59): Rcvd Digit detected(#)
Oct 29 15:59:47.380: R2 Outgoing Modem(1/59): DSX (E1 1:25):
STATE: R2_OUT_PROCESS_A R2 Got Event R2_TONE_OFF
Oct 29 15:59:47.380: Mica Modem(1/59): Generate digits:called_party_num=9 len=1
Oct 29 15:59:47.440: Mica Modem(1/59): Rcvd Digits Generated
Oct 29 15:59:47.484: Mica Modem(1/59): Rcvd Digit detected(1)
Oct 29 15:59:47.484: R2 Outgoing Modem(1/59): DSX (E1 1:25):
STATE: R2_OUT_PROCESS_A R2 Got Event 1
Oct 29 15:59:47.484: Mica Modem(1/59): Generate digits:called_party_num=# len=1
Oct 29 15:59:47.560: Mica Modem(1/59): Rcvd Digits Generated
Oct 29 15:59:47.636: Mica Modem(1/59): Rcvd Digit detected(#)
Oct 29 15:59:47.636: R2 Outgoing Modem(1/59): DSX (E1 1:25):
STATE: R2_OUT_PROCESS_A R2 Got Event R2_TONE_OFF
Oct 29 16:00:02.521: Mica Modem(1/59): Rcvd Digit detected(3)
Oct 29 16:00:02.521: R2 Outgoing Modem(1/59): DSX (E1 1:25):
STATE: R2_OUT_PROCESS_A R2 Got Event 3
Oct 29 16:00:02.521: Mica Modem(1/59): Generate digits:called_party_num=# len=1
Oct 29 16:00:02.593: Mica Modem(1/59): Rcvd Digits Generated
Oct 29 16:00:02.641: Mica Modem(1/59): Rcvd Digit detected(#)
Oct 29 16:00:02.641: R2 Outgoing Modem(1/59): DSX (E1 1:25):
STATE: R2_OUT_PROCESS_B R2 Got Event R2_TONE_OFF
Oct 29 16:00:02.641: Mica Modem(1/59): Generate digits:called_party_num=1 len=1
Oct 29 16:00:02.713: Mica Modem(1/59): Rcvd Digits Generated
Oct 29 16:00:02.745: Mica Modem(1/59): Rcvd Digit detected(6)
Oct 29 16:00:02.745: R2 Outgoing Modem(1/59): DSX (E1 1:25):
STATE: R2_OUT_PROCESS_B R2 Got Event 6
Oct 29 16:00:02.745: Mica Modem(1/59): Generate digits:called_party_num=# len=1
Oct 29 16:00:02.745: CSM_PROC_OC4_DIALING:
CSM_EVENT_ADDR_INFO_COLLECTED at slot 1, port 59
Oct 29 16:00:02.821: Mica Modem(1/59): Rcvd Digits Generated
Oct 29 16:00:02.925: Mica Modem(1/59): Rcvd Digit detected(#)
Oct 29 16:00:02.925: R2 Outgoing Modem(1/59): DSX (E1 1:25):
STATE: R2_OUT_IDLE R2 Got Event R2_TONE_OFF
Oct 29 16:00:03.845: from Trunk(0): (1/25): Rx ANSWERED (ABCD=0101)
Oct 29 16:00:03.885: CSM_RX_CAS_EVENT_FROM_NEAT:(8007):
EVENT_CHANNEL_CONNECTED at slot 1 and port 59
Oct 29 16:00:03.885: CSM_PROC_OC5_WAIT_FOR_CARRIER:
CSM_EVENT_DSX0_CONNECTED at slot 1, port 59
Oct 29 16:00:03.885: Mica Modem(1/59): Link Initiate
Oct 29 16:00:03.917: Mica Modem(1/59): State Transition to Connect
Oct 29 16:00:06.709: Mica Modem(1/59): State Transition to unknown
Oct 29 16:00:12.497: Mica Modem(1/59): State Transition to Link
Oct 29 16:00:15.197: Mica Modem(1/59): State Transition to unknown
Oct 29 16:00:17.241: Mica Modem(1/59): State Transition to unknown
Oct 29 16:00:21.385: Mica Modem(1/59): State Transition to Trainup
Oct 29 16:00:23.061: Mica Modem(1/59): State Transition to EC Negotiating
Oct 29 16:00:23.245: Mica Modem(1/59): State Transition to Steady State

```

## Información Relacionada

- [Teoría de la señalización E1 R2](#)
- [Configuración y resolución de problemas de la señalización E1 R2](#)
- [Personalización de los enlaces E1 R2 con el comando cas-custom](#)

- [Señalización E1 R2 para los servidores de acceso Cisco AS5300 y Cisco AS5200](#)
- [Señalización E1 R2 para los routers de las series 3620 y 3640 de Cisco](#)
- [Señalización E1 R2 para el Cisco AS5800](#)
- [Página de Soporte de la Tecnología de Marcación y Acceso](#)
- [Soporte Técnico - Cisco Systems](#)