ASR 1000 Box-to-Box NAT 고가용성 컨피그레이션 예

목차

소개

사전 요구 사항

요구 사항

사용되는 구성 요소

구성

B2BHA 장애 조치 트리거

최소 구성

기본 L2/L3 연결을 사용하는 네트워크 다이어그램

다음을 확인합니다.

확인 명령 및 예상 출력

유용한 명령

문제 해결

소개

이 문서에서는 Cisco IOS®-XE 디바이스에서 Box-to-Box-NAT High Availability(B2B NAT HA)의 컨피그레이션과 ASR(Aggregation Services Router) 100 제품군에 초점을 두고 설명합니다.

B2B NAT HA는 ASR 1000 제품군 라우터 간에 ZBFW(Zone-Based Firewall), NAT(Network Address Translation), VPN, SBC(Session Border Controller) 등과 같은 애플리케이션의 고가용성을 실현하는 방법입니다.이 문서에서는 검증과 함께 Cisco ASR 1000 플랫폼에서 B2B NAT HA를 구성하는 방법에 대해 설명합니다.

사전 요구 사항

요구 사항

다음 주제에 대한 지식을 보유하고 있으면 유용합니다.

- ASR 1000 플랫폼 아키텍처 개요
- 고가용성 및 NAT 기술에 대한 기본 지식

사용되는 구성 요소

이 문서의 정보는 Cisco IOS 버전 XE 3.10 이상 릴리스가 포함된 ASR 1000 제품군을 기반으로 합니다.B2B NAT HA는 Cisco IOS-XE Release 3.5 이상에서 지원됩니다.

이 문서의 정보는 특정 랩 환경의 디바이스를 토대로 작성되었습니다.이 문서에 사용된 모든 디바이스는 초기화된(기본) 컨피그레이션으로 시작되었습니다.현재 네트워크가 작동 중인 경우, 모든 명령어의 잠재적인 영향을 미리 숙지하시기 바랍니다.

구성

B2BHA 장애 조치 트리거

일반적인 장애 조치 트리거 중 일부는 다음과 같습니다.

- 활성 상태의 전력 손실/다시 로드(충돌 포함)
- ESP(Embedded Service Processor) 다시 로드(계획된 또는 계획되지 않은).
- RG(Redundancy Group)에 대한 제어 인터페이스가 종료/링크다운되었습니다.
- RG용 데이터 인터페이스가 종료/링크다운되었습니다.
- 추적된 개체 실패(IP 서비스 수준 계약).
- 프로토콜 keep-alive 오류입니다.
- 활성 상태의 런타임 우선순위는 구성된 임계값의 우선순위보다 낮습니다.
- 활성 상태의 런타임 우선 순위는 대기 시간 우선 순위 아래로 내려갑니다.

최소 구성

이 섹션에서는 토폴로지 정보와 함께 B2B NAT HA를 구성하는 방법에 대해 설명합니다.

B2 BHA 구축에는 다음과 같은 세 가지 토폴로지가 있을 수 있습니다.

- LAN-LAN
- LAN-WAN
- LAN 메시

참고:평균 이중화 패킷 크기는 256바이트입니다.

기본 L2/L3 연결을 사용하는 네트워크 다이어그램


기본 L2/L3 연결

구성은 두 가지 주요 부분으로 나눌 수 있습니다.하나는 RG, 이중화 프로토콜, 타이머, 제어 및 데이터 인터페이스를 활성화하는 기본 컨피그레이션입니다.두 번째 부분은 실제 데이터/트래픽 인터페이스 및 RG와의 연결과 관련이 있습니다.

이 예에서는 LAN 172.16.1.4에서 원엔드 서버 192.168.5.5을 사용하여 ASR에서 B2B NAT HA를 얻으려고 시도합니다. 이러한 구성은 현재 고정 NAT 컨피그레이션으로 준비됩니다.

ip nat pool POOL1 200.200.200.200.200.200.200.200 netmask 255.255.252 ip nat inside source list NAT pool POOL1 redundancy 1 mapping-id 252 $\,$

Extended IP access list NAT
10 permit ip host 172.16.1.4 host 192.168.5.5



ASR-1 ASR-2

redundancy mode none application redundancy group 1 name TEST preempt priority 150

control GigabitEthernet0/0/2

protocol 1 data GigabitEthernet0/0/3 redundancy mode none application redundancy group 1 name TEST preempt priority 50 control GigabitEthernet0/0/2

protocol 1

data GigabitEthernet0/0/3

두 ASR은 모두 ISP에서 제공한 공용 IP 주소에 연결할 수 있어야 합니다.

ASR-1#ping 200.200.200.200

Type escape sequence to abort. Sending 5, 100-byte ICMP Echos to 200.200.200, timeout is 2 seconds:

Success rate is 100 percent (5/5), round-trip min/avg/max = 1/1/1 ms

ASR-2#ping 200.200.200.200

Type escape sequence to abort.

Sending 5, 100-byte ICMP Echos to 200.200.200, timeout is 2 seconds:

LAN 연결 인터페이스는 디스트리뷰션 스위치에 연결되며, 이는 호스트에 연결됩니다.

ASR-1#show run int GigabitEthernet0/0/0

interface GigabitEthernet0/0/0
 ip address 172.16.1.2 255.255.255.248
 ip nat inside
 negotiation auto
 cdp enable
 redundancy rii 100
 redundancy group 1 ip 172.16.1.5
 exclusive decrement 100
end

ASR-2#show run int GigabitEthernet0/0/0

interface GigabitEthernet0/0/0
 ip address 172.16.1.3 255.255.255.248
 ip nat inside
 negotiation auto
 cdp enable
 redundancy rii 100
 redundancy group 1 ip 172.16.1.5
 exclusive decrement 100
end

ISP 연결 인터페이스에는 다음 컨피그레이션이 있습니다.

ASR-1#show run int gi0/0/1

interface GigabitEthernet0/0/1
 ip address 192.168.3.2 255.255.255.252
 ip nat outside
 negotiation auto
 cdp enable
 redundancy rii 101
 redundancy asymmetric-routing enable
 redundancy group 1 decrement 20
end

ASR-2#show run int gi0/0/1

interface GigabitEthernet0/0/1
 ip address 192.168.4.2 255.255.255.252
 ip nat outside
 negotiation auto
 cdp enable
 redundancy rii 101
 redundancy asymmetric-routing enable
 redundancy group 1 decrement 20
end

ASR 간의 데이터 및 제어 인터페이스는 이 섹션에 표시된 대로 구성되었습니다.

제어 인터페이스

ASR-1#show run int gi0/0/2

interface GigabitEthernet0/0/2
description CONTROL-INTERFACE
ip address 10.10.10.1 255.255.255.252
negotiation auto
cdp enable
end

ASR-2#show run int gi0/0/2

interface GigabitEthernet0/0/2
description CONTROL INTERFACE
ip address 10.10.10.2 255.255.255
negotiation auto
cdp enable
end

데이터 인터페이스

ASR-1#show run int gi0/0/3

interface GigabitEthernet0/0/3
description DATA INTERFACE
encapsulation dot1Q 10
ip address 10.11.11.1 255.255.255
end

ASR-2#show run int gi0/0/3

interface GigabitEthernet0/0/3
description DATA INTERFACE
encapsulation dot1Q 10
ip address 10.11.11.2 255.255.255
end

참고:

- 데이터 인터페이스나 제어 인터페이스로 구성된 인터페이스에서 RII(Redundant Interface Identifier)를 구성하지 않아야 합니다.
- 액티브 디바이스와 스탠바이 디바이스 모두에서 RII 및 비대칭 라우팅을 구성해야 합니다.
- 가상 IP 주소가 구성된 인터페이스에서는 비대칭 라우팅을 활성화할 수 없습니다.

다음을 확인합니다.

확인 명령 및 예상 출력

<u>Cisco CLI Analyzer(등록된</u> 고객만 해당)는 특정 **show** 명령을 지원합니다.**show** 명령 출력의 분석을 보려면 Cisco CLI Analyzer를 사용합니다.

ASR-1#show redundancy application group

Group ID	Group Name	State
1	TEST	ACTIVE

ASR-2#show redundancy application group

 Group ID
 Group Name
 State

 ---- ----

 1
 TEST
 STANDBY

ASR-1#show redundancy application group 1

Group ID:1
Group Name:TEST

Administrative State: No Shutdown Aggregate operational state: Up

My Role: ACTIVE
Peer Role: STANDBY
Peer Presence: Yes
Peer Comm: Yes

Peer Progression Started: Yes

RF Domain: btob-one RF state: ACTIVE

Peer RF state: STANDBY HOT

ASR-2#show redundancy application group 1

Group ID:1
Group Name:TEST

Administrative State: No Shutdown Aggregate operational state: Up

My Role: STANDBY
Peer Role: ACTIVE
Peer Presence: Yes
Peer Comm: Yes

Peer Progression Started: Yes

RF Domain: btob-one

RF state: STANDBY HOT Peer RF state: ACTIVE

ASR-1#show ip nat translations

Pro	Inside global	Inside local	Outside local	Outside global		
	200.200.200.200	172.16.1.4				
icmp	200.200.200.200:98	172.16.1.4:98	192.168.5.5:98	192.168.5.5:98		
Total number of translations: 2						

ASR-2#show ip nat translations

Pro	Inside global	Inside local	Outside local	Outside global
	200.200.200.200	172.16.1.4		
icmp	200.200.200.200:98	172.16.1.4:98	192.168.5.5:98	192.168.5.5:98

ASR-1#show redundancy application protocol group 1

```
RG Protocol RG 1
-----
  Role: Active
  Negotiation: Enabled
  Priority: 150
  Protocol state: Active
  Ctrl Intf(s) state: Up
  Active Peer: Local
  Standby Peer: address 10.10.10.2, priority 50, intf Gi0/0/2
  Log counters:
      role change to active: 7
      role change to standby: 7
      disable events: rg down state 7, rg shut 0
      ctrl intf events: up 7, down 8, admin_down 7
      reload events: local request 0, peer request 0
RG Media Context for RG 1
_____
  Ctx State: Active
  Protocol ID: 1
  Media type: Default
  Control Interface: GigabitEthernet0/0/2
      Current Hello timer: 3000
  Configured Hello timer: 3000, Hold timer: 9000
  Peer Hello timer: 3000, Peer Hold timer: 9000
  Stats:
      Pkts 386597, Bytes 23969014, HA Seq 0, Seq Number 386597, Pkt Loss 0
      Authentication not configured
      Authentication Failure: 0
      Reload Peer: TX 0, RX 0
      Resign: TX 0, RX 1
  Standby Peer: Present. Hold Timer: 9000
      Pkts 386589, Bytes 13144026, HA Seq 0, Seq Number 1503658, Pkt Loss 0
ASR-2#show redundancy application protocol group 1
RG Protocol RG 1
-----
  Role: Standby
  Negotiation: Enabled
  Priority: 50
  Protocol state: Standby-hot
  Ctrl Intf(s) state: Up
  Active Peer: address 10.10.10.1, priority 150, intf Gi0/0/2
  Standby Peer: Local
  Log counters:
      role change to active: 8
      role change to standby: 16009
      disable events: rg down state 1, rg shut 0
      ctrl intf events: up 9, down 10, admin_down 1
      reload events: local request 15999, peer request 2
RG Media Context for RG 1
-----
  Ctx State: Standby
  Protocol ID: 1
  Media type: Default
  Control Interface: GigabitEthernet0/0/2
      Current Hello timer: 3000
```

Configured Hello timer: 3000, Hold timer: 9000

```
Peer Hello timer: 3000, Peer Hold timer: 9000
  Stats:
     Pkts 1503674, Bytes 93227788, HA Seq 0, Seq Number 1503674, Pkt Loss 0
     Authentication not configured
     Authentication Failure: 0
     Reload Peer: TX 2, RX 2
     Resign: TX 8, RX 7
  Active Peer: Present. Hold Timer: 9000
     Pkts 386603, Bytes 13144502, HA Seq 0, Seq Number 386613, Pkt Loss 0
ASR-1#show platform hardware qfp active system rg 1
Redundancy Group 1
  State: RG_ACTIVE
  Bulksync: NO BULKSYNC REQ
  Transport:
     SYNC_B2B LISTEN
        cp hdl 0x01013e8d dp hdl 0x03010006, platfm hdl 0x0000fa35
     L3_IPV4
         src addr 10.11.11.1 dest addr 10.11.11.2
     L4_UDP_RELIABLE
         src port 19510 dest port 3497
     AR transport not available
  Stats:
     RG Request:
        CREATE 0
UPDATE 32
                   32048
                   0
        DELETE
     RG State:
        RG_PREINIT 0
         RG_INIT
         RG_STANDBY
                       21
         RG_ACTIVE 32020
     RG Transport Request:
          NA
         OPEN 160
CLOSE 0
                     16014
     RG Transport Status:
        CONN_ESTB 7
         CONN_FAIL
         TRANS_DOWN 0
         TRANS_DOWN_GRACEFUL 8
     Bulksync:
         Request
Success
         Fail
                      0
ASR-1#show platform hardware qfp active system rg 1 stats
  trans index: 00000006 Trans Type: 00000001 RG 1
  ha_control_state 0x5
  pending ack 00000000
  keepalive_timeout 00000100
  rx_seq_flags 0x8000000
  rx_seq_num 0x2c0d4a44
             0xb4965908
  tx_seq
  tx_ack_tail 0xb4965908
  tx_seq_flags 0x700003ff
  tx 000000000580126
  rx 000000000580089
  retx 0000000000000000
  rx dropped 0000000000000000
```

```
ack dropped 00000000 oob pkts dropped 00000000 send dropped 00000000 rx_control_msgs 00580090 tx control_msgs 00580078 for_us_hits 01160217 sync_alloc_failures 00000000 status_notifications 00000001 sync_msgs_received 00580093 sync_msgs_sent 00580133 for_us_udp_checksum_drops 000000000 acks sent 00580089 rcvd 00580126 nacks sent 000000000 rcvd 000000000
```

유용한 명령

- 활성 상태의 RG는 EXEC 모드에서 **이중화 애플리케이션** reload group <rg-number> self 명령을 사용하여 다시 로드됩니다.
- 이중화 컨피그레이션 모드에서 다음 CLI 명령을 사용하여 활성 상태의 RG가 종료됩니다.

ISR1(config-red-app)#group 1
ISR1(config-red-app-grp)#shutdown

문제 해결

현재 이 컨피그레이션에 사용할 수 있는 특정 문제 해결 정보가 없습니다.