



## Caveats

---

- [Cisco Bug Search Tool](#), on page 1
- [Open Caveats in Cisco IOS XE Cupertino 17.9.x](#), on page 1
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.5](#), on page 2
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.4a](#), on page 2
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.4](#), on page 2
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.3](#), on page 3
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.2](#), on page 3
- [Resolved Caveats in Cisco IOS XE Cupertino 17.9.1](#), on page 3

## Cisco Bug Search Tool

The Cisco [Bug Search Tool](#) (BST) allows partners and customers to search for software bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. The BST is designed to improve the effectiveness in network risk management and device troubleshooting. The tool has a provision to filter bugs based on credentials to provide external and internal bug views for the search input.

To view the details of a caveat, click on the identifier.

## Open Caveats in Cisco IOS XE Cupertino 17.9.x

Identifier	Headline
<a href="#">CSCwe17454</a>	C9500 PWR-C4-950WAC-R power supply x is not responding and responding soon
<a href="#">CSCwe20100</a>	[C9500] SFPs not in 'show inventory' after boot on 17.3.5 or 17.6.3
<a href="#">CSCwi57770</a>	Interface is not coming up when use FINISAR SFP-10G-SR on 9500-40X switch

## Resolved Caveats in Cisco IOS XE Cupertino 17.9.5

Identifier	Applicable Models	Headline
<a href="#">CSCwh55164</a>	C9500	Cat9k: ICMP TTL expired error incorrectly forwarded via global table instead of VRF
<a href="#">CSCwi01706</a>	C9500H	GLC-TE link-down on interop between C9606R [LC-48YL] -- C3560x [Fa0, 100M speed] with AN enabl -day1
<a href="#">CSCwf87624</a>	C9500X	Observing LED Status as Green after removing Fan tray for 9500X
<a href="#">CSCwh55170</a>	C9500X	9500X: Incorrect details are showing for Fantray in <b>show firmwar ver all</b> output upon OIR ofFT1
<a href="#">CSCwe95691</a>	C9500	PnP   Cat9k sends DHCP Discover with IP Source address 192.168.1.1 instead of 0.0.0.0
<a href="#">CSCwi10405</a>	C9500	[NEAT] CISP installs a static MAC address entry pointing to a wrong interface

## Resolved Caveats in Cisco IOS XE Cupertino 17.9.4a

Identifier	Applicable Models	Headline
<a href="#">CSCwh87343</a>	All Models	Cisco IOS XE Software Web UI Privilege Escalation Vulnerability For more information, see Security Advisory: <a href="#">cisco-sa-iosxe-webui-privesc-j22SaA4z</a> .

## Resolved Caveats in Cisco IOS XE Cupertino 17.9.4

Identifier	Applicable Models	Headline
<a href="#">CSCwe33886</a>	C9500	17.9 install oper DB queries returning errors on DB queries to xpath install-oper-hist
<a href="#">CSCwe36743</a>	C9500	Segmentation Fault - Crash - SSH - When Changing AAA Group Configs
<a href="#">CSCwe96441</a>	C9500H	Outgoing Flow control is not available on Cat platforms but it can be configured on cat9500HP
<a href="#">CSCwe44308</a>	C9500H	9500H: entSensorValueTimeStamp & entSensorValueUpdateRate values not refreshing after a read issue

## Resolved Caveats in Cisco IOS XE Cupertino 17.9.3

Identifier	Applicable Models	Headline
<a href="#">CSCwb53649</a>	All models	100G: Wrong output for DOM values through snmpwalk
<a href="#">CSCwd51319</a>	9500	9500: EntSensor shows wrong values after switchover

## Resolved Caveats in Cisco IOS XE Cupertino 17.9.2

Identifier	Applicable Models	Headline
<a href="#">CSCwb91153</a>	Catalyst 9500 High Performance	fed_main_event memory leak @ htm_xml_parse_htm_section while running "show sdm.."

## Resolved Caveats in Cisco IOS XE Cupertino 17.9.1

There are no resolved caveats in this release.

