

# End-of-Sale and End-of-Life Announcement for the Cisco Select HX Accessories

---

# Contents

Overview	3
End-of-life milestones	3
Product part numbers	3
Product migration options	27
For more information	27

## Overview

### EOL15065 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco Select HX Accessories. The last day to order the affected product(s) is October 30, 2023. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

## End-of-life milestones

**Table 1.** End-of-life milestones and dates for the Cisco Select HX Accessories

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	May 1, 2023
<b>End-of-Sale Date Accessory</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 30, 2023
<b>Last Ship Date Accessory</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 28, 2024

HW = Hardware      OS SW = Operating System Software      App. SW = Application Software

## Product part numbers

**Table 2.** Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-9400-8E</b>	Cisco 12G 9400-8e 12G SAS HBA for external JBOD attach	There is currently no replacement product available for this product.	-	-
<b>HX-9400-8E=</b>	Cisco 12G 9400-8e 12G SAS HBA for external JBOD attach	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-B-MRAID12G-HE</b>	Cisco FlexStorage 12G SAS RAID contr w/2GB FBWC/drive bays	There is currently no replacement product available for this product.	-	-
<b>HX-B-MRAID12G-HE=</b>	Cisco FlexStorage 12G SAS RAID contr w/2GB FBWC/drive bays	There is currently no replacement product available for this product.	-	-
<b>HX-B-VIC-M83-8P</b>	Cisco UCS VIC 1380 mezzanine adapter for blade servers	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-B-VIC-M83-8P=</b>	Cisco UCS VIC 1380 mezzanine adapter for blade servers	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-BZL-EX-M5</b>	Optional bezel for UCS C480 M5 rack server	There is currently no replacement product available for this product.	-	-
<b>HX-BZL-EX-M5=</b>	Optional bezel for UCS C480 M5 rack server	There is currently no replacement product available for this product.	-	-
<b>HX-C240SD-EXT</b>	UCS C240SD M5 Extender Kit	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-C480-8AUX</b>	UCS C480 M5 Auxiliary Drive Module for 8x rear drives	There is currently no replacement product available for this product.	-	-
<b>HX-C480-8AUX=</b>	UCS C480 M5 Auxiliary Drive Module for 8x rear drives	There is currently no replacement product available for this product.	-	-
<b>HX-C480-8HDD</b>	UCS C480 M5 Drive Module for 8x HDD	There is currently no replacement product available for this product.	-	-
<b>HX-C480-8HDD=</b>	UCS C480 M5 Drive Module for 8x HDD	There is currently no replacement product available for this product.	-	-
<b>HX-C480-8NVME</b>	UCS C480 M5 Drive Module for 8x NVMe Drives	There is currently no replacement product available for this product.	-	-
<b>HX-C480-8NVME=</b>	UCS C480 M5 Drive Module for 8x NVMe Drives	There is currently no replacement product available for this product.	-	-
<b>HX-C480-DVD</b>	UCS C480 M5 Optional DVD drive	There is currently no replacement product available for this product.	-	-
<b>HX-C480-DVD=</b>	UCS C480 M5 Optional DVD drive	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-C480-INT-SW</b>	UCS C480 Safety Intrusion Switch	There is currently no replacement product available for this product.	-	-
<b>HX-C480-INT-SW=</b>	UCS C480 Safety Intrusion Switch	There is currently no replacement product available for this product.	-	-
<b>HX-CMA-4U-M5</b>	Cable Management Arm for UCS C480 M4	There is currently no replacement product available for this product.	-	-
<b>HX-CMA-4U-M5=</b>	Cable Management Arm for UCS C480 M4	There is currently no replacement product available for this product.	-	-
<b>HX-CMAF-M4</b>	Reversible CMA for C220 M4 friction & ball bearing rail kits	There is currently no replacement product available for this product.	-	-
<b>HX-CMAF-M4=</b>	Reversible CMA for C220 & C240 M4 & M5 rack servers	There is currently no replacement product available for this product.	-	-
<b>HX-CPU-I3204</b>	Intel 3204 1.9GHz/85W 6C/8.25MB DDR4 2133MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-CPU-I3204=</b>	Intel 3204 1.9GHz/85W 6C/8.25MB DDR4 2133MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I3206R</b>	Intel 3206R 1.9GHz/85W 8C/11MB DDR4 2133MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I3206R=</b>	Intel 3206R 1.9GHz/85W 8C/11MB DDR4 2133MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4208</b>	Intel 4208 2.1GHz/85W 8C/11MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4208=</b>	Intel 4208 2.1GHz/85W 8C/11MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-CPU-I4210</b>	Intel 4210 2.2GHz/85W 10C/13.75MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4210=</b>	Intel 4210 2.2GHz/85W 10C/13.75MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4210R</b>	Intel 4210R 2.4GHz/100W 10C/13.75MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4210R=</b>	Intel 4210R 2.4GHz/100W 10C/13.75MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4214</b>	Intel 4214 2.2GHz/85W 12C/16.5MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-



End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-CPU-I4214=</b>	Intel 4214 2.2GHz/85W 12C/16.5MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4214R</b>	Intel 4214R 2.4GHz/100W 12C/16.50MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4214R=</b>	Intel 4214R 2.4GHz/100W 12C/16.50MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4214Y</b>	Intel 4214Y SS 2.2GHz/85W 12/10/8C 13.75MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4214Y=</b>	Intel 4214Y SS 2.2GHz/85W 12/10/8C 13.75MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-CPU-I4215</b>	Intel 4215 2.5GHz/85W 8C/11MB DCP/DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4215=</b>	Intel 4215 2.5GHz/85W 8C/11MB DCP/DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4215R</b>	Intel 4215R 3.2GHz/130W 8C/11MB DCP DDR4 1TB 2400 MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4215R=</b>	Intel 4215R 3.2GHz/130W 8C/11MB DCP DDR4 1TB 2400 MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I4216</b>	Intel 4216 2.1GHz/100W 16C/22MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-CPU-I4216=</b>	Intel 4216 2.1GHz/100W 16C/22MB DDR4 2400MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I5218N</b>	Intel 5218N 2.3GHz/105W 16C/22MB DCP DDR4 2666MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I5218N=</b>	Intel 5218N 2.3GHz/105W 16C/22MB DCP DDR4 2666MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I5218R</b>	Intel 5218R 2.1GHz/125W 20C/27.5MB DDR4 2667MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I5218R=</b>	Intel 5218R 2.1GHz/125W 20C/27.5MB DDR4 2667MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-CPU-I5218T</b>	Intel 5218T 2.1GHz/105W 16C/22MB DDR4 2667MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I5218T=</b>	Intel 5218T 2.1GHz/105W 16C/22MB DDR4 2667MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I5220R</b>	Intel 5220R 2.2GHz/150W 24C/35.75MB DDR4 2667MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I5220R=</b>	Intel 5220R 2.2GHz/150W 24C/35.75MB DDR4 2667MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6226R</b>	Intel 6226R 2.9GHz/150W 16C/22MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-CPU-I6226R=</b>	Intel 6226R 2.9GHz/150W 16C/22MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6230N=</b>	Intel 6230N 2.3GHz/125W 20C/27.50MB DCP DDR4 2933 MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6230R</b>	Intel 6230R 2.1GHz/150W 26C/35.75MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6230R=</b>	Intel 6230R 2.1GHz/150W 26C/35.75MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6238R</b>	Intel 6238R 2.2GHz/165W 28C/38.5MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-CPU-I6238R=</b>	Intel 6238R 2.2GHz/165W 28C/38.5MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6238T</b>	Intel 6238T 1.9GHz/125W 22C/30.25MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6238T=</b>	Intel 6238T 1.9GHz/125W 22C/30.25MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6240R</b>	Intel 6240R 2.4GHz/165W 24C/35.75MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6240R=</b>	Intel 6240R 2.4GHz/165W 24C/35.75MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-CPU-I6242R</b>	Intel 6242R 3.1GHz/205W 20C/35.75MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6242R=</b>	Intel 6242R 3.1GHz/205W 20C/35.75MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6246=</b>	3.3GHz/165W 6246 12C/24.75MB DCP DDR4 2TB 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6246R</b>	Intel 6246R 3.4GHz/205W 16C/35.75MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6246R=</b>	Intel 6246R 3.4GHz/205W 16C/35.75MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-CPU-I6248R</b>	Intel 6248R 3GHz/205W 24C/35.75MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6248R=</b>	Intel 6248R 3GHz/205W 24C/35.75MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6250</b>	Intel 6250 3.9GHz/185W 8C/35.75MB PMM DDR4 1TB 2933 MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6250=</b>	Intel 6250 3.9GHz/185W 8C/35.75MB PMM DDR4 1TB 2933 MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6252N</b>	Intel 6252N 2.3GHz/150W 24C/35.75MB DCP DDR4 2933 MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-



End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-CPU-I6252N=</b>	Intel 6252N 2.3GHz/150W 24C/35.75MB DCP DDR4 2933 MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6256</b>	Intel 6256 3.6GHz/205W 12C/33MB PMM DDR4 1TB 2933 MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6256=</b>	Intel 6256 3.6GHz/205W 12C/33MB PMM DDR4 1TB 2933 MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6258R</b>	Intel 6258R 2.7GHz/205W 28C/38.5MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-CPU-I6258R=</b>	Intel 6258R 2.7GHz/205W 28C/38.5MB DDR4 2933MHz	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-DVD-C240M5</b>	Media Drive (DVD) for C240 M5 Servers (8 HDD version only)	There is currently no replacement product available for this product.	-	-
<b>HX-DVD-C240M5=</b>	Media Drive (DVD) for C240 M5 Servers (8 HDD version only)	There is currently no replacement product available for this product.	-	-
<b>HX-INT-SW01</b>	C220 M5 and C240 M5 Chassis Intrusion Switch	There is currently no replacement product available for this product.	-	-
<b>HX-INT-SW01=</b>	C220 M5 and C240 M5 Chassis Intrusion Switch	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-MLOM-C100-04</b>	Cisco UCS VIC 1497 Dual Port 100G QSFP28 CNA mLOM	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-MLOM-C100-04=</b>	Cisco UCS VIC 1497 Dual Port 100G QSFP28 CNA mLOM	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-MLOM-C25Q-04</b>	Cisco UCS VIC 1457 Quad Port 10/25G SFP28 CNA MLOM	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-MLOM-C25Q-04=</b>	Cisco UCS VIC 1457 Quad Port 10/25G SFP28 CNA MLOM	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-MLOM-C40Q-03</b>	Cisco VIC 1387 Dual Port 40Gb QSFP CNA MLOM	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-MLOM-C40Q-03=</b>	Cisco VIC 1387 Dual Port 40Gb QSFP CNA MLOM	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-MLOM-IRJ45</b>	Intel i350 quad-port MLOM NIC	See the Product Migration Options section below for detailed information on replacing this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-MLOM-IRJ45=</b>	Intel i350 quad-port MLOM NIC	There is currently no replacement product available for this product.	-	-
<b>HX-MRAID1GB-KIT</b>	SAS RAID KIT for C220M5L	There is currently no replacement product available for this product.	-	-
<b>HX-MRAID1GB-KIT=</b>	SAS RAID KIT for C220M5L	There is currently no replacement product available for this product.	-	-
<b>HX-MSD-32G</b>	32GB Micro SD Card for UCS M5 servers	There is currently no replacement product available for this product.	-	-
<b>HX-MSD-32G=</b>	32GB Micro SD Card for UCS M5 servers	There is currently no replacement product available for this product.	-	-
<b>HX-NVME-SC</b>	PCIe NVME Switch Module	There is currently no replacement product available for this product.	-	-
<b>HX-NVME-SC=</b>	PCIe NVME Switch Module	There is currently no replacement product available for this product.	-	-
<b>HX-PCI-1-C240M5</b>	Riser 1 incl 3 PCIe slots (x8, x16, x8)	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-PCI-1-C240M5=</b>	Riser 1 incl 3 PCIe slots (x8, x16, x8); slot 3 req CPU2	There is currently no replacement product available for this product.	-	-
<b>HX-PCI-1B-240M5</b>	Riser 1B incl 3 PCIe slots (x8, x8, x8); all slots from CPU1	There is currently no replacement product available for this product.	-	-
<b>HX-PCI-1B-240M5=</b>	Riser 1B incl 3 PCIe slots (x8, x8, x8); all slots from CPU1	There is currently no replacement product available for this product.	-	-
<b>HX-PCI-2A-240M5</b>	Riser 2A incl 3 PCIe slots (x8, x16, x16) supports GPU	There is currently no replacement product available for this product.	-	-
<b>HX-PCI-2A-240M5=</b>	Riser 2A incl 3 PCIe slots (x8, x16, x16) supports GPU	There is currently no replacement product available for this product.	-	-
<b>HX-PCI-2B-240M5</b>	Riser 2B incl 3PCleslots(x8,x16,x8)+2NVMe(1cnctr)supportsGPU	There is currently no replacement product available for this product.	-	-
<b>HX-PCI-2B-240M5=</b>	Riser 2B incl 3PCleslots(x8,x16,x8) supports GPU+rear NVMe	There is currently no replacement product available for this product.	-	-
<b>HX-PCI-2C-240M5</b>	Riser 2C incll 3 PCIe slots (3 x8) supports front+rear NVMe	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-PCI-2C-240M5=</b>	Riser 2C incll 3 PCIe slots (3 x8) supports front+rear NVMe	There is currently no replacement product available for this product.	-	-
<b>HX-PCIE-C40Q-03</b>	Cisco VIC 1385 Dual Port 40Gb QSFP+ CNA w/RDMA	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-PCIE-C40Q-03=</b>	Cisco VIC 1385 Dual Port 40Gb QSFP+ CNA w/RDMA, HH bracket	See the Product Migration Options section below for detailed information on replacing this product.	-	-
<b>HX-R1-A100-M5</b>	Riser1 3PCIe slots(x8, x16, x8) For A100	There is currently no replacement product available for this product.	-	-
<b>HX-R1-A100-M5=</b>	Riser1 3PCIe slots(x8, x16, x8) For A100	There is currently no replacement product available for this product.	-	-
<b>HX-R2A-A100-M5</b>	Riser2A 3PCIe slots (x8, x16, x16) For A100	There is currently no replacement product available for this product.	-	-
<b>HX-R2A-A100-M5=</b>	Riser2A 3PCIe slots (x8, x16, x16) For A100	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-R2B-A100-M5</b>	Riser2B 3PCIe slot(x8,x16,x8)spprt GPU+NVMe, For A100	There is currently no replacement product available for this product.	-	-
<b>HX-R2B-A100-M5=</b>	Riser2B 3PCIe slot(x8,x16,x8)spprt GPU+NVMe, For A100	There is currently no replacement product available for this product.	-	-
<b>HX-RAID-M5</b>	Cisco 12G Modular RAID controller with 2GB cache	There is currently no replacement product available for this product.	-	-
<b>HX-RAID-M5=</b>	Cisco 12G Modular RAID controller with 2GB cache	There is currently no replacement product available for this product.	-	-
<b>HX-RAID-M5HD</b>	Cisco 12G Modular RAID controller with 4GB cache	There is currently no replacement product available for this product.	-	-
<b>HX-RAID-M5HD=</b>	Cisco 12G Modular RAID controller with 4GB cache	There is currently no replacement product available for this product.	-	-
<b>HX-RAILB-M4</b>	Ball Bearing Rail Kit for C220 M4 and C240 M4 rack servers	There is currently no replacement product available for this product.	-	-
<b>HX-RAILB-M4=</b>	Ball Bearing Rail Kit for C220 & C240 M4 & M5 rack servers	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-RAILF-M4</b>	Friction Rail Kit for C220 M4 rack servers	There is currently no replacement product available for this product.	-	-
<b>HX-RAILF-M4=</b>	Friction Rail Kit for C220 M4 and M5 rack servers	There is currently no replacement product available for this product.	-	-
<b>HX-RAILS-M5</b>	Ball Bearing Rail Kit for C240M5 SD Rack Server	There is currently no replacement product available for this product.	-	-
<b>HX-RAILS-M5=</b>	Ball Bearing Rail Kit for C240M5 SD Rack Server	There is currently no replacement product available for this product.	-	-
<b>HX-RIS-1-240M5</b>	Riser 1 3PCIe slots (x8, x16, x8); slot 3 req CPU2, For T4	There is currently no replacement product available for this product.	-	-
<b>HX-RIS-1-240M5=</b>	Riser 1 3PCIe slots (x8, x16, x8); slot 3 req CPU2, For T4	There is currently no replacement product available for this product.	-	-
<b>HX-RIS-1B-240M5</b>	Riser 1B 3PCIe slots (x8, x8, x8); all from CPU1, For T4	There is currently no replacement product available for this product.	-	-
<b>HX-RIS-1B-240M5=</b>	Riser 1B 3PCIe slots (x8, x8, x8); all from CPU1, For T4	There is currently no replacement product available for this product.	-	-



End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-RIS-2A-240M5</b>	Riser 2A 3PCIe slots (x8, x16, x16) supports GPU, For T4	There is currently no replacement product available for this product.	-	-
<b>HX-RIS-2B-240M5</b>	Riser 2B 3PCIe slot(x8,x16,x8) supports GPU+rear NVMe, For T4	There is currently no replacement product available for this product.	-	-
<b>HX-RIS-2C-240M5</b>	Riser 2C 3PCIe slots (3 x8) supports front+rear NVMe, For T4	There is currently no replacement product available for this product.	-	-
<b>HX-RIS-2C-240M5=</b>	Riser 2C 3PCIe slots (3 x8) supports front+rear NVMe, For T4	There is currently no replacement product available for this product.	-	-
<b>HX-RS2E-240M5SD</b>	Riser 2E 1x16 PCIe slot, 2x Drive slots, no microSD	There is currently no replacement product available for this product.	-	-
<b>HX-RS2E-240M5SD=</b>	Riser 2E 1x16 PCIe slot, 2x Drive slots, no microSD	There is currently no replacement product available for this product.	-	-
<b>HX-SAS-M5</b>	Cisco 12G Modular SAS HBA (max 16 drives)	There is currently no replacement product available for this product.	-	-
<b>HX-SAS-M5=</b>	Cisco 12G Modular SAS HBA (max 16 drives)	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-SAS-M5HD</b>	Cisco 12G Modular SAS HBA for up to 26 drives	There is currently no replacement product available for this product.	-	-
<b>HX-SAS-M5HD=</b>	Cisco 12G Modular SAS HBA for up to 26 drives	There is currently no replacement product available for this product.	-	-
<b>HX-SAS9460-8I</b>	Cisco 12G 9460-8i Raid controller with 2GB cache	There is currently no replacement product available for this product.	-	-
<b>HX-SAS9460-8I=</b>	Cisco 12G 9460-8i Raid controller with 2GB cache	There is currently no replacement product available for this product.	-	-
<b>HX-CPU-I8260Y</b>	Intel 8260Y SS 2.4GHz/165W 24/20/16C 35.75MB 3DX DDR4 2933	There is currently no replacement product available for this product.	-	-
<b>HX-CPU-I8260Y=</b>	Intel 8260Y SS 2.4GHz/165W 24/20/16C 35.75MB 3DX DDR4 2933	There is currently no replacement product available for this product.	-	-

---

## Product migration options

Many of these component PIDs are only applicable with the server platforms being discontinued. For the appropriate components to use with the new or replacements servers, refer to the appropriate data sheets of M6 servers for guidance. <https://www.cisco.com/c/en/us/products/hyperconverged-infrastructure/hyperflex-hx-series/datasheet-listing.html>

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[https://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For more information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to: <https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)