



End-of-Sale and End-of-Life Announcement for the Cisco UCS M4 based hardware appliances for: Stealthwatch Flow Collector, Flow Sensor, UDP Director, Management Console

EOL12928

Cisco announces the end-of-sale and end-of-life dates for the Cisco UCS M4 based hardware appliances for: Stealthwatch Flow Collector, Flow Sensor, UDP Director, Management Console. The last day to order the affected product(s) is June 30, 2019. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1. End-of-Life Milestones and Dates for the Cisco UCS M4 based hardware appliances for: Stealthwatch Flow Collector, Flow Sensor, UDP Director, Management Console

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	March 30, 2019
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 30, 2019
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	September 28, 2019
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	June 29, 2020
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	June 29, 2020
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	September 25, 2023
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	June 30, 2024

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
ST-10G-NIC-2FI	Cisco Stealthwatch X520 Dual Port 10G Base-SFP+ NIC	There is currently no replacement product available for this product.	-	-
ST-10G-NIC-4FI	Cisco Stealthwatch Accelerated 4x10G SFP+ NIC	There is currently no replacement product available for this product.	-	-
ST-1G-NIC-2FI	Cisco Stealthwatch i350 Dual Port 1G Fiber NIC with SX SFP's	There is currently no replacement product available for this product.	-	-
ST-1G-NIC-4CU	Cisco Stealthwatch i350 Quad Port 1G Copper NIC	There is currently no replacement product available for this product.	-	-
ST-CPU-E52609E	Cisco Stealthwatch CPU 1.70 GHz E52609 v4 - Cache 8C/20MB	There is currently no replacement product available for this product.	-	-
ST-CPU-E52650E	Cisco Stealthwatch CPU 2.20 GHz E52650 v4 - Cache 12C/30MB	There is currently no replacement product available for this product.	-	-
ST-CPU-E52680D	Cisco Stealthwatch CPU 2.50 GHz E52680 v3 - Cache 12C/30MB	There is currently no replacement product available for this product.	-	-
ST-CPU-E52680E	Cisco Stealthwatch CPU 2.40 GHz E52680 v4 - Cache 14C/35MB	There is currently no replacement product available for this product.	-	-
ST-CPU-E52695D	Cisco Stealthwatch CPU 2.30 GHz E52695 v3 - Cache 14C/35MB	There is currently no replacement product available for this product.	-	-
ST-CPU-E52695E	Cisco Stealthwatch CPU 2.10 GHz E52695 v4 - Cache 18C/45MB	There is currently no replacement product available for this product.	-	-
ST-FC-PCI-1B-240M4	Cisco Stealthwatch Right PCIe Riser Board (3 x8) 6 PCI Slots	There is currently no replacement product available for this product.	-	-
ST-FC4200-CHAS-K9	Cisco Stealthwatch Flow Collector 4200 - RMA	There is currently no replacement product available for this product.	-	-
ST-FC4200-K9	Cisco Stealthwatch Flow Collector 4200	ST-FC4210-K9	Cisco Stealthwatch Flow Collector 4210	-
ST-FC5200-K9	Cisco Stealthwatch Flow Collector 5200	ST-FC5210-K9	Cisco Stealthwatch Flow Collector 5210	-
ST-FC5200D-CHAS-K9	Cisco Stealthwatch Flow Collector 5200 - Database - RMA	There is currently no replacement product available for this product.	-	-
ST-FC5200E-CHAS-K9	Cisco Stealthwatch Flow Collector 5200 - Engine - RMA	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
ST-FS1200-CHAS-K9	Cisco Stealthwatch Flow Sensor 1200 - RMA	There is currently no replacement product available for this product.	-	-
ST-FS1200-K9	Cisco Stealthwatch Flow Sensor 1200	ST-FS1210-K9	Cisco Stealthwatch Flow Sensor 1210	-
ST-FS2200-CHAS-K9	Cisco Stealthwatch Flow Sensor 2200 - RMA	There is currently no replacement product available for this product.	-	-
ST-FS2200-K9	Cisco Stealthwatch Flow Sensor 2200	ST-FS3210-K9	Cisco Stealthwatch Flow Sensor 3210	-
ST-FS3200-CHAS-K9	Cisco Stealthwatch Flow Sensor 3200 - RMA	There is currently no replacement product available for this product.	-	-
ST-FS3200-K9	Cisco Stealthwatch Flow Sensor 3200	ST-FS3210-K9	Cisco Stealthwatch Flow Sensor 3210	-
ST-FS4200-CHAS-K9	Cisco Stealthwatch Flow Sensor 4200 - RMA	There is currently no replacement product available for this product.	-	-
ST-FS4200-K9	Cisco Stealthwatch Flow Sensor 4200	ST-FS4210-K9	Cisco Stealthwatch Flow Sensor 4210	-
ST-HDD-1.2TB	Cisco Stealthwatch 1.2 TB 12G SAS 10K RPM SFF HDD	There is currently no replacement product available for this product.	-	-
ST-HDD-1.2TB=	Cisco Stealthwatch 1.2 TB 12G SAS 10K RPM SFF HDD	There is currently no replacement product available for this product.	-	-
ST-HDD-300GB	Cisco Stealthwatch 300 GB 12G SAS 10K RPM SFF HDD	There is currently no replacement product available for this product.	-	-
ST-HDD-300GB=	Cisco Stealthwatch 300 GB 12G SAS 10K RPM SFF HDD	There is currently no replacement product available for this product.	-	-
ST-MEM-1X081RV-A	Cisco Stealthwatch 8 GB DDR4-2400 MHz RDIMM/PC4-19200	There is currently no replacement product available for this product.	-	-
ST-MEM-1X161RV-A	Cisco Stealthwatch 16GB DDR4-2400 MHz RDIMM/PC4-19200	There is currently no replacement product available for this product.	-	-
ST-MEM-1X322RV-A	Cisco Stealthwatch 32GB DDR4-2400 MHz RDIMM/PC4-19200	There is currently no replacement product available for this product.	-	-
ST-MRAID12G	Cisco Stealthwatch 12G SAS Modular Raid Controller	There is currently no replacement product available for this product.	-	-
ST-MRAID12G-2GB	Cisco Stealthwatch 12Gbps SAS 2GB FBWC Cache module	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
ST-MRAID12G-4GB	Cisco Stealthwatch 12Gbps SAS 4GB FBWC Cache module	There is currently no replacement product available for this product.	-	-
ST-PWR-AC-1200W	Cisco Stealthwatch AC Power Supply 1200W	There is currently no replacement product available for this product.	-	-
ST-PWR-AC-1200W=	Cisco Stealthwatch AC Power Supply 1200W	There is currently no replacement product available for this product.	-	-
ST-PWR-AC-770W	Cisco Stealthwatch AC Power Supply 770W	There is currently no replacement product available for this product.	-	-
ST-PWR-AC-770W=	Cisco Stealthwatch AC Power Supply 770W	There is currently no replacement product available for this product.	-	-
ST-SMC2200-CHAS-K9	Cisco Stealthwatch Management Console 2200 - RMA	There is currently no replacement product available for this product.	-	-
ST-SMC2200-K9	Cisco Stealthwatch Management Console 2200	ST-SMC2210-K9	Cisco Stealthwatch Management Console 2210	-
ST-UDP2200-CHAS-K9	Cisco Stealthwatch UDP Director 2200 - RMA	There is currently no replacement product available for this product.	-	-
ST-UDP2200-K9	Cisco Stealthwatch UDP Director 2200	ST-UDP2210-K9	Cisco Stealthwatch UDP Director 2210	-

Product Migration Options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco UCS M4 based hardware appliances for: Stealthwatch Flow Collector, Flow Sensor, UDP Director, Management Console through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <https://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to:

https://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to:

https://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<https://www.cisco.com/cisco/support/notifications.html>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)