



# End-of-Sale and End-of-Life Announcement for the Cisco Select Unified Computing System and Hyperflex Accessories



# Contents

Overview	3
End-of-life milestones	3
Product part numbers	3
Product migration options	6
For more information	7

## Overview

### EOL14419

Cisco announces the end-of-sale and end-of life dates for the Cisco Select Unified Computing System and Hyperflex Accessories. The last day to order the affected product(s) is September 16, 2021 . Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

## End-of-life milestones

**Table 1.** End-of-life milestones and dates for the Cisco Select Unified Computing System and Hyperflex Accessories

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	June 17, 2021
<b>End-of-Sale Date Accessory</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	September 16, 2021
<b>Last Ship Date Accessory</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	September 16, 2021

## Product part numbers

**Table 2.** Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>HX-SD400GBCNK9</b>	400GB Enterprise performance SAS LFF SSD (10X FWPD, SED)	There is currently no replacement product available for this product.	-	-
<b>HX-SD400GBCNK9=</b>	400GB Enterprise performance SAS LFF SSD (10X FWPD, SED)	There is currently no replacement product available for this product.	-	-
<b>UCS-SD400GBCNK9</b>	400GB Enterprise performance SAS LFF SSD (10X FWPD, SED)	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>UCS-SD400GBCNK9=</b>	400GB Enterprise performance SAS LFF SSD (10X FWPD, SED)	There is currently no replacement product available for this product.	-	-
<b>UCSC-FAN-C460-M4=</b>	Fan Module for UCS C460 M4	There is currently no replacement product available for this product.	-	-
<b>UCSC-FAN-C460-M4</b>	Fan Module for UCS C460 M4	There is currently no replacement product available for this product.	-	-
<b>UCS-SD800GBCNK9</b>	800GB Enterprise performance SAS LFF SSD (10X FWPD, SED)	There is currently no replacement product available for this product.	-	-
<b>UCS-SD800GBCNK9=</b>	800GB Enterprise performance SAS LFF SSD (10X FWPD, SED)	There is currently no replacement product available for this product.	-	-
<b>UCS-SD800GBHMK9</b>	800GB Enterprise performance SAS SSD (10X FWPD, SED)	There is currently no replacement product available for this product.	-	-
<b>UCS-SD800GBHMK9=</b>	800GB Enterprise performance SAS SSD (10X FWPD, SED)	There is currently no replacement product available for this product.	-	-
<b>UCS-RAID9361CV-8I</b>	MegaRAID 9361CV with 8 internal SAS/SATA ports with Supercap	There is currently no replacement product available for this product.	-	-
<b>UCS-RAID9361CV-8I=</b>	MegaRAID 9361CV with 8 internal SAS/SATA ports with Supercap	There is currently no replacement product available for this product.	-	-
<b>UCS-240CBLMR16</b>	C240 M4 (2) RAID controller cables for 16 HD backplane	There is currently no replacement product available for this product.	-	-
<b>UCS-240CBLMR16=</b>	C240 M4 (2) RAID controller cables for 16 HD backplane	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>UCS-240CBLMR12</b>	C240 M4 (2) RAID controller cables for 12 HD backplane	There is currently no replacement product available for this product.	-	-
<b>UCS-240CBLMR12=</b>	C240 M4 (2) RAID controller cables for 12 HD backplane	There is currently no replacement product available for this product.	-	-
<b>UCSC-EARS-C220M4=</b>	C220 M4 rack ears kit	There is currently no replacement product available for this product.	-	-
<b>HX-SD800GBCNK9</b>	800GB Enterprise performance SAS LFF SSD (10X FWPD, SED)	There is currently no replacement product available for this product.	-	-
<b>HX-SD800GBCNK9=</b>	800GB Enterprise performance SAS LFF SSD (10X FWPD, SED)	There is currently no replacement product available for this product.	-	-
<b>HX-SD800GBHMK9</b>	800GB Enterprise performance SAS SSD (10X FWPD, SED)	There is currently no replacement product available for this product.	-	-
<b>HX-SD800GBHMK9=</b>	800GB Enterprise performance SAS SSD (10X FWPD, SED)	There is currently no replacement product available for this product.	-	-
<b>UCSC-BZL-EX-M5ML</b>	Optional Bezel for UCS C480 M5ML rack server	There is currently no replacement product available for this product.	-	-
<b>UCSC-BZL-EX-M5ML=</b>	Optional Bezel for UCS C480 M5ML rack server	There is currently no replacement product available for this product.	-	-
<b>UCS-S3260-TSD38K9</b>	UCS S3260 3.8TB(1X) SED Top Load K9	There is currently no replacement product available for this product.	-	-
<b>UCS-S3260-TSD38K9=</b>	VOID	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>UCSC-GPU-V100-32</b>	NVIDIA TESLA, VOLTA 100 PCIE 32GB, 250W	UCSC-GPU-A100	TESLA A100, PASSIVE, 250W, 40GB	-
<b>UCSC-GPU-V100-32=</b>	NVIDIA TESLA, VOLTA 100 PCIE 32GB, 250W	UCSC-GPU-A100=	TESLA A100, PASSIVE, 250W, 40GB	-
<b>HX-GPU-V100-32</b>	NVIDIA TESLA, VOLTA 100 PCIE 32GB, 250W	HX-GPU-A100	TESLA A100, PASSIVE, 250W, 40GB	-
<b>HX-GPU-V100-32=</b>	NVIDIA TESLA, VOLTA 100 PCIE 32GB, 250W	HX-GPU-A100=	TESLA A100, PASSIVE, 250W, 40GB	-
<b>UCS-480ML-G-GAP=</b>	Service Only: Gap Pad Kit for a GPU on C480 ML M5	There is currently no replacement product available for this product.	-	-
<b>UCS-480ML-G-HS-F=</b>	Service Only: Heat Sink for a Front GPU on C480 ML M5	There is currently no replacement product available for this product.	-	-
<b>UCS-480ML-G-HS-R=</b>	Service Only: Heat Sink for a Rear GPU on C480 ML M5	There is currently no replacement product available for this product.	-	-
<b>UCS-480ML-G-INST=</b>	Service Only: GPU Installation Fixture Kit on C480 ML M5	There is currently no replacement product available for this product.	-	-
<b>UCSC-GPUV100SXM32=</b>	NVIDIA TESLA, VOLTA SXM2 32GB, 300W	There is currently no replacement product available for this product.	-	-
<b>UCSC-GPUV100SXM32</b>	NVIDIA TESLA, VOLTA SXM2 16GB, 300W	There is currently no replacement product available for this product.	-	-

## Product migration options

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[https://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

---

## For more information

For more information about the Cisco End-of-Life Policy, go to:

[https://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](https://www.cisco.com/en/US/products/products_end-of-life_policy.html).

For more information about the Cisco Product Warranties, go to:

[https://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](https://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to:

<https://www.cisco.com/cisco/support/notifications.html>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)