

End-of-Sale and End-of-Life Announcement for the Cisco Nexus C93180YC-FX and C93108TC-FX Fixed Switches

Contents

Overview	3
End-of-life milestones	3
Product part numbers	4
Product migration options	6
For more information	6

Overview

EOL15110 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco Nexus C93180YC-FX and C93108TC-FX Fixed Switches. The last day to order the affected product(s) is July 31, 2024. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco Nexus C93180YC-FX and C93108TC-FX Fixed Switches

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	August 1, 2023
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 31, 2024
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 30, 2024
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	July 31, 2027
End of Vulnerability/Security Support: HW	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	July 31, 2029
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	July 31, 2025
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	July 31, 2025
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	October 29, 2028
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	July 31, 2029

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Product part numbers

Table 2. Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
N9K-C93108-FX-B24C	2xNexus 93108TC-FX w/ 8x 100G Optics	There is currently no replacement product available for this product.	-	-
N9K-C93108TC-FX	Nexus 9300 with 48p 10G-T, 6p 100G QSFP28	N9K-C93108TC-FX3P	Nexus 9300 48x 100M/1/2.5/5/10GT, 6x 100G Switch	-
N9K-C93108TC-FX-24	Nexus 9300-FX w/ 24p 100M/1/10GT & 6p 40/100G	N9K-C93108TC-FX3H	Nexus 9300 24x 100M/1/2.5/5/10GT, 6x 100G Switch	-
N9K-C93108TC-FX-B	Nexus 93108TC-FX bundle PID	There is currently no replacement product available for this product.	-	-
N9K-C93108TC-FX24=	Nexus 9300-FX 24x100M/1/10GT & 6x100G,Spare(no Acc/PSU/fan)	N9K-C93108TC-FX3H=	Nexus 9300 24x 100M/1/2.5/5/10GT, 6x 100G Switch	-
N9K-C93108TC-FX=	Nexus 9300 with 48p 10G-T, 6p 100G QSFP28	N9K-C93108TC-FX3P=	Nexus 9300 N9K-C93108TC-FXP Spare (no fan/PSU/acc)	-
N9K-C93108TCFXB18Q	2 Nexus 93108TC-FX with 8 QSFP-40G-SR-BD	There is currently no replacement product available for this product.	-	-
N9K-C93180-FX-B24C	2xNexus 93180YC-FX w/ 8x 100G Optics	There is currently no replacement product available for this product.	-	-
N9K-C93180YC-FX	Nexus 9300 with 48p 1/10/25G, 6p 40/100G, MACsec	N9K-C93180YC-FX3	Nexus 9300 48p 1/10/25G, 6p 40/100G, MACsec,SyncE	-
N9K-C93180YC-FX-24	Nexus 9300-FX w/24p 1/10/25G & 6p 40/100G	N9K-C93180YC-FX3H	Nexus 9300 24p 1/10/25G, 6p 40/100G, MACsec,SyncE	-
N9K-C93180YC-FX-A	Nexus 9300 w/ 48p 1/10/25G, 6p 40/100G for Archforce	There is currently no replacement product available for this product.	-	-
N9K-C93180YC-FX-B	Nexus 93180YC-FX bundle PID	There is currently no replacement	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
		product available for this product.		
N9K-C93180YC-FX-H	N9K-C93180YC-FX Smartplay bundle - 48p 1/10/25G, 6p 40/100G	There is currently no replacement product available for this product.	-	-
N9K-C93180YC-FX24=	Nexus 9300-FX w/24p 1/10/25G & 6p 100G;Spare(no Acc/PSU/fan)	N9K-C93180YC-FX3H=	Nexus 9300 24p 1/10/25G, 6p 40/100G, MACsec,SyncE	-
N9K-C93180YC-FX=	Nexus 9K w/ 48p 1/10/25G, 6p 40/100G Spare (No Acc/PSU/fan)	N9K-C93180YC-FX3=	Nexus 9300 48p 1/10/25G, 6p 40/100G, MACsec,SyncE	-
N9K-C93180YC-FXB2S	Limited availability, 2x Nexus 93180YC-FX	There is currently no replacement product available for this product.	-	-
N9K-C93180YCFXB18Q	2 Nexus 93180YC-FX with 8 QSFP-40G-SR-BD	There is currently no replacement product available for this product.	-	-
N9KC93180YCFX24-H	HX SP Nexus 9K FX w/ 24p 10/25G & 6p 100G, Upg avl	There is currently no replacement product available for this product.	-	-
N9KC93180YCFX24-H=	HX SP Nexus 9K FX w/ 24p 10/25G & 6p 100G, Upg avl	There is currently no replacement product available for this product.	-	-

Product migration options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco Nexus C93180YC-FX and C93108TC-FX Fixed Switches through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <https://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to: <https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)