

End-of-Sale and End-of-Life Announcement for the Cisco Prisma II Long Reach Multi Wavelength (LRMW) Transmitters - 8 dBm

EOL10690

Cisco announces the end-of-sale and end-of-life dates for the Cisco Prisma II Long Reach Multi Wavelength (LRMW) Transmitters - 8 dBm. The last day to order the affected product(s) is May 7, 2016. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions.

Table 1. End-of-Life Milestones and Dates for the Cisco Prisma II Long Reach Multi Wavelength (LRMW) Transmitters – 8 dBm

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	November 7, 2015
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 7, 2016
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 5, 2016
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	May 7, 2017
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 7, 2017
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	August 2, 2020
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	May 31, 2021

HW = Hardware OS SW = Operating System Software App. SW = Application Software

 Table 2.
 Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4044130	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 1	4043191	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 1	-
4044131	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 2	4043192	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 2	-
4044132	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 3	4043193	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 3	-
4044133	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 4	4043194	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 4	-
4044134	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 5	4043195	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 5	-
4044135	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 6	4043196	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 6	-
4044136	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 7	4043197	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 7	-
4044137	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 8	4043198	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 8	-
4044138	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 9	4043199	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 9	-
4044139	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 10	4043200	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 10	-
4044140	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 11	4043201	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 11	-
4044141	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 12	4043202	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 12	-
4044142	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 13	4043203	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 13	-
4044143	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 14	4043204	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 14	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4044144	P2-15TXM-08-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 15	4043205	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 15	-
4044145	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 8dBm, 1GHz, SA, CH 16	4043206	P2-15TXM-12-EM-IWDM- SA-CH1-1WD) 1550DWDM, 12dBm, 1GHz, SA, CH 16	-

Product Migration Options

Customers are encouraged to migrate to the Cisco Prisma II Long Reach Multi Wavelength (LRMW) Transmitters - 12 dBm. Information about this product can be found at:

http://www.cisco.com/c/en/us/products/collateral/video/prisma-ii/datasheet-c78-728786.html.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives and promotions/tmp.html.

Customers may be able to continue to purchase the Cisco Prisma II Long Reach Multi Wavelength (LRMW) Transmitters - 8 dBm through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: http://www.cisco.com/go/eos.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more Information about the Cisco Prisma II Long Reach Multi Wavelength (LRMW) Transmitters - 12 dBm, visit http://www.cisco.com/c/en/us/products/collateral/video/prisma-ii/datasheet-c78-728786.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html.

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-736210-00 11/15