

End-of-Sale and End-of-Life Announcement for the Cisco 5x20U Broadband Processing Engine for the Cisco uBR10012 Universal Broadband Router

EOL6197

Cisco® announces the end-of-sale and end-of-life dates for the Cisco 5x20U Broadband Processing Engine for the Cisco uBR10012 Universal Broadband Router. The last day to order the affected product(s) is March 14, 2008. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Customers are encouraged to migrate to the Cisco 5x20H Broadband Processing Engine for the Cisco uBR10012 platform. Information about this product can be found at: http://www.cisco.com/en/US/prod/collateral/video/ps8806/ps5684/ps2209/product_data_sheet0900_aecd8058fc36.html. The Cisco 5x20H BPE is a performance-enhanced update of the Cisco 5x20U BPE with incremental memory and processor capacity

Table 1. End-of-Life Milestones and Dates for the Cisco 5x20U Broadband Processing Engine for the Cisco uBR10012 Universal Broadband Router

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	September 14, 2007
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	March 14, 2008
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	June 12, 2008
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	March 14, 2009
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	March 14, 2009
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	June 9, 2012
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	March 13, 2013

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
UBR10-MC5X20U-D	uBR10K Universal Card, 5DS w/upx, 20US, Spec An, Dense	UBR10-MC5X20H-D	uBR10K High-Performance Card, 5DS w/upx, 20US, Spec An
UBR10-MC5X20U-D=	uBR10K Universal Card, 5DS w/upx, 20US, Spec An, Dense	UBR10-MC5X20H-D=	uBR10K High-Performance Card, 5DS w/upx, 20US, Spec An

Product Migration Options

The recommended replacement for the Cisco 5x20U Broadband Processing Engine is the Cisco 5x20H Broadband Processing Engine for the Cisco uBR10012 platform. The Cisco 5x20H BPE is designed with more advanced processor and incremental memory to provide better packet-processing performance.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through the Cisco Certified Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to: <http://cisco.com/go/remarketing>.

For More Information

For more information about the the Cisco 5x20H Broadband Processing Engine for the Cisco uBR10012 Universal Broadband Router, visit http://www.cisco.com/en/US/prod/collateral/video/ps8806/ps5684/ps2209/product_data_sheet0900aecd8058fc36.html or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Europe Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: +31 0 800 020 0791
Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0708R)