



Release Notes for Cisco 8000 Series Routers, IOS XR Release 7.11.2

[Cisco 8100, 8200, 8600, and 8800 Series Routers](#) 2

[What's New in Cisco IOS XR Release 7.11.2](#) 2

[Release 7.11.2 Packages](#) 2

[Caveats](#) 3

[Determine Software Version](#) 3

[Determine Firmware Support](#) 3

[Important Notes](#) 12

[Related Documentation](#) 13

Revised: June 19, 2024

Cisco 8100, 8200, 8600, and 8800 Series Routers



Note Cisco IOS XR Release 7.11.2 is an Extended Maintenance Release of [Cisco IOS XR Release 7.11.1](#) for Cisco 8000 Series routers. For more details on the Cisco IOS XR release model and associated support, see [Guidelines for Cisco IOS XR Software](#).

What's New in Cisco IOS XR Release 7.11.2

Cisco IOS XR Release 7.11.2 is a maintenance release for Cisco 8000 Series routers. There are no new software features or hardware introduced in this release.

For more details on the Cisco IOS XR release model and associated support, see [Software Lifecycle Support Statement - IOS XR](#).

Release 7.11.2 Packages

The Cisco IOS XR software is composed of a base image (ISO) that provides the XR infrastructure. The ISO image is made up of a set of packages (also called RPMs). These packages are of three types:

- A mandatory package that is included in the ISO
- An optional package that is included in the ISO
- An optional package that is not included in the ISO

Visit the [Cisco Software Download](#) page to download the Cisco IOS XR software images.

To determine the Cisco IOS XR Software packages installed on your router, log in to the router and enter the **show install active** command:

```
RP/0/RP0/CPU0# show install active summary
Active Packages:   XR: 209   All: 1551
Label:             7.11.2
Software Hash:     acbdd5b12cf9d1d9bc7ffaae16b13a0e41930e68ded64496f5da2a447ec78b21
```

```
Optional Packages                                     Version
-----
xr-8000-l2mcast                                       7.11.2v1.0.0-1
xr-8000-mcast                                          7.11.2v1.0.0-1
xr-8000-netflow                                       7.11.2v1.0.0-1
xr-bgp                                                 7.11.2v1.0.0-1
xr-ipsla                                              7.11.2v1.0.0-1
xr-is-is                                              7.11.2v1.0.0-1
xr-lldp                                               7.11.2v1.0.0-1
xr-mcast                                              7.11.2v1.0.0-1
xr-mps-oam                                            7.11.2v1.0.0-1
xr-netflow                                            7.11.2v1.0.0-1
xr-ops-script-repo                                   7.11.2v1.0.0-1
xr-ospf                                               7.11.2v1.0.0-1
xr-perf-meas                                         7.11.2v1.0.0-1
```

```
xr-perfmgmt
xr-track
```

```
7.11.2v1.0.0-1
7.11.2v1.0.0-1
```

To know about all the RPMs installed including XR, OS and other components use the **show install active all** command.

The software modularity approach provides a flexible model that allows you to install a subset of IOS XR packages on devices based on your individual requirements. All critical components are modularized as packages so that you can select the features that you want to run on your router.



Note The above show command output displays mandatory packages that are installed on the router. To view the optional and bug fix RPM packages, first install the package and use the **show install active summary** command.

Caveats

Table 1: Cisco 8000 Series Router Specific Bugs

Bug ID	Headline
CSCwj39497	the show yang operational fails with error ERR: MDCLI Suggestor ctx Initialization failed !!
CSCwj35617	After upgrading the 88-LC0-34H14FH LC in D8 was reset.

Determine Software Version

Log in to the router and enter the **show version** command:

```
RP/0/RP0/CPU0# show version
Cisco IOS XR Software, Version 7.11.2 LNT
Copyright (c) 2013-2024 by Cisco Systems, Inc.
```

```
Build Information:
  Built By      : sajshah
  Built On     : Fri Mar 29 22:06:56 UTC 2024
  Build Host   : iox-ucs-055
  Workspace    : /auto/srcarchive11/prod/7.11.2/8000/ws/
  Version      : 7.11.2
  Label       : 7.11.2
```

```
cisco 8000 (Intel(R) Xeon(R) CPU D-1530 @ 2.40GHz)
cisco 8201-SYS (Intel(R) Xeon(R) CPU D-1530 @ 2.40GHz) processor with 32GB of memory
R2-sherman uptime is 11 hours, 41 minutes
Cisco 8201 1RU System with 24x400GE QSFP56-DD & 12x100GE QSFP28
```

Determine Firmware Support

Log in to the router and enter **show fpd package** command:

Cisco 8100 Series Router

RP/0/RP0/CPU0# show fpd package

```

=====
                        Field Programmable Device Package
=====

```

Card Type	FPD Description	Req Reload	SW Ver	Min Req SW Ver	Min Req Board Ver
8101-32FH	Bios	YES	1.15	1.15	0.0
	BiosGolden	YES	1.15	1.13	0.0
	IoFpga	YES	1.10	1.10	0.35
	IoFpgaGolden	YES	1.10	1.02	0.35
	PowerCpld	YES	1.17	1.17	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.89	1.89	0.35
	x86FpgaGolden	YES	1.89	1.06	0.35
	x86TamFw	YES	6.16	6.16	0.0
	x86TamFwGolden	YES	6.16	6.05	0.0
8101-32FH-O	Bios	YES	0.241	0.241	0.0
	BiosGolden	YES	0.241	0.218	0.0
	IoFpga	YES	1.10	1.10	0.35
	IoFpgaGolden	YES	1.10	1.02	0.35
	PowerCpld	YES	1.17	1.17	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.89	1.89	0.35
	x86FpgaGolden	YES	1.89	1.06	0.35
	x86TamFw	YES	6.16	6.16	0.0
	x86TamFwGolden	YES	6.16	6.05	0.0
8201-24H8FH	Bios	YES	1.15	1.15	0.0
	BiosGolden	YES	1.15	0.13	0.0
	IoFpga	YES	1.10	1.10	0.35
	IoFpgaGolden	YES	1.10	1.02	0.35
	PowerCpld	YES	1.17	1.17	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.89	1.89	0.35
	x86FpgaGolden	YES	1.89	1.06	0.35
	x86TamFw	YES	6.16	6.16	0.0
	x86TamFwGolden	YES	6.16	6.05	0.0
8201-24H8FH-O	Bios	YES	0.241	0.241	0.0
	BiosGolden	YES	0.241	0.218	0.0
	IoFpga	YES	1.10	1.10	0.35
	IoFpgaGolden	YES	1.10	1.02	0.35
	PowerCpld	YES	1.17	1.17	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.89	1.89	0.35
	x86FpgaGolden	YES	1.89	1.06	0.35
	x86TamFw	YES	6.16	6.16	0.0

	x86TamFwGolden	YES	6.16	6.05	0.0

8201-32FH	Bios	YES	1.15	1.15	0.0
	BiosGolden	YES	1.15	0.13	0.0
	IoFpga	YES	1.10	1.10	0.35
	IoFpgaGolden	YES	1.10	1.02	0.35
	PowerCpld	YES	1.17	1.17	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.89	1.89	0.35
	x86FpgaGolden	YES	1.89	1.06	0.35
	x86TamFw	YES	6.16	6.16	0.0
	x86TamFwGolden	YES	6.16	6.05	0.0

8201-32FH-O	Bios	YES	0.241	0.241	0.0
	BiosGolden	YES	0.241	0.218	0.0
	IoFpga	YES	1.10	1.10	0.35
	IoFpgaGolden	YES	1.10	1.02	0.35
	PowerCpld	YES	1.17	1.17	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.89	1.89	0.35
	x86FpgaGolden	YES	1.89	1.06	0.35
	x86TamFw	YES	6.16	6.16	0.0
	x86TamFwGolden	YES	6.16	6.05	0.0

PSU1.4KW-ACPE	DT-PrimMCU	NO	3.01	3.01	0.0
	DT-SecMCU	NO	2.02	2.02	0.0
	QC-PrimMCU	NO	1.00	1.00	0.0
	QC-SecMCU	NO	1.00	1.00	0.0

PSU1.4KW-ACPI	DT-PrimMCU	NO	3.01	3.01	0.0
	DT-SecMCU	NO	2.02	2.02	0.0
	QC-PrimMCU	NO	1.00	1.00	0.0
	QC-SecMCU	NO	1.00	1.00	0.0

PSU2KW-ACPE	PO-PrimMCU	NO	1.03	1.03	0.0
	PO-SecMCU	NO	1.06	1.06	0.0
	QC-PrimMCU	NO	1.01	1.01	0.0
	QC-SecMCU	NO	1.04	1.04	0.0

PSU2KW-ACPI	PO-PrimMCU	NO	1.03	1.03	0.0
	PO-SecMCU	NO	1.08	1.08	0.0
	QC-PrimMCU	NO	1.01	1.01	0.0
	QC-SecMCU	NO	3.02	3.01	0.0

PSU2KW-DCPE	PO-PrimMCU	NO	1.07	1.07	0.0

PSU2KW-DCPI	PO-PrimMCU	NO	1.07	1.07	0.0

PSU2KW-HVPI	PO-PrimMCU	NO	1.09	1.09	0.0

Cisco 8200 Series Router

RP/0/RP0/CPU0# show fpd package

```

=====
                          Field Programmable Device Package
=====

```

	Req	SW	Min Req	Min Req
--	-----	----	---------	---------

Card Type	FPD Description	Reload	Ver	SW Ver	Board Ver
8201	Bios	YES	1.29	1.29	0.0
	BiosGolden	YES	1.29	1.15	0.0
	IoFpga	YES	1.11	1.11	0.1
	IoFpgaGolden	YES	1.11	0.48	0.1
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.06	1.06	0.0
	x86FpgaGolden	YES	1.06	0.48	0.0
	x86TamFw	YES	5.13	5.13	0.0
	x86TamFwGolden	YES	5.13	5.05	0.0
8201-ON	Bios	YES	1.208	1.208	0.0
	BiosGolden	YES	1.208	1.207	0.0
	IoFpga	YES	1.11	1.11	0.1
	IoFpgaGolden	YES	1.11	0.48	0.1
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.06	1.06	0.0
	x86FpgaGolden	YES	1.06	0.48	0.0
	x86TamFw	YES	5.13	5.13	0.0
	x86TamFwGolden	YES	5.13	5.05	0.0
8201-SYS	Bios	YES	1.29	1.29	0.0
	BiosGolden	YES	1.29	1.15	0.0
	IoFpga	YES	1.11	1.11	0.1
	IoFpgaGolden	YES	1.11	0.48	0.1
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.06	1.06	0.0
	x86FpgaGolden	YES	1.06	0.48	0.0
	x86TamFw	YES	5.13	5.13	0.0
	x86TamFwGolden	YES	5.13	5.05	0.0
8201-SYS-ON	Bios	YES	1.208	1.208	0.0
	BiosGolden	YES	1.208	1.207	0.0
	IoFpga	YES	1.11	1.11	0.1
	IoFpgaGolden	YES	1.11	0.48	0.1
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.06	1.06	0.0
	x86FpgaGolden	YES	1.06	0.48	0.0
	x86TamFw	YES	5.13	5.13	0.0
	x86TamFwGolden	YES	5.13	5.05	0.0
PSU1.4KW-ACPE	DT-PrimMCU	NO	3.01	3.01	0.0
	DT-SecMCU	NO	2.02	2.02	0.0
	QC-PrimMCU	NO	1.00	1.00	0.0
	QC-SecMCU	NO	1.00	1.00	0.0
PSU1.4KW-ACPI	DT-PrimMCU	NO	3.01	3.01	0.0
	DT-SecMCU	NO	2.02	2.02	0.0
	QC-PrimMCU	NO	1.00	1.00	0.0
	QC-SecMCU	NO	1.00	1.00	0.0

PSU2KW-ACPE	PO-PrimMCU	NO	1.03	1.03	0.0
	PO-SecMCU	NO	1.06	1.06	0.0
	QC-PrimMCU	NO	1.01	1.01	0.0
	QC-SecMCU	NO	1.04	1.04	0.0
PSU2KW-ACPI	PO-PrimMCU	NO	1.03	1.03	0.0
	PO-SecMCU	NO	1.08	1.08	0.0
	QC-PrimMCU	NO	1.01	1.01	0.0
	QC-SecMCU	NO	3.02	3.01	0.0
PSU2KW-DCPE	PO-PrimMCU	NO	1.07	1.07	0.0
PSU2KW-DCPI	PO-PrimMCU	NO	1.07	1.07	0.0
PSU2KW-HVPI	PO-PrimMCU	NO	1.09	1.09	0.0
	PO-SecMCU	NO	1.10	1.10	0.0

Cisco 8600 Series Router

RP/0/RP0/CPU0# show fpd package

```

=====
                        Field Programmable Device Package
=====

```

Card Type	FPD Description	Req Reload	SW Ver	Min Req SW Ver	Min Req Board Ver
86-3.2KW-AC	EM-LogicMCU	NO	0.10	0.10	0.0
	EM-PrimMCU	NO	0.02	0.02	0.0
	EM-SecMCU	NO	0.02	0.02	0.0
86-3.2KW-DC	EM-LogicMCU	NO	0.11	0.11	0.0
	EM-PrimMCU	NO	0.04	0.04	0.0
	EM-SecMCU	NO	0.04	0.04	0.0
86-MPA-14H2FH-M	IoFpga	YES	1.02	1.02	0.1
	IoFpgaGolden	NO	1.02	1.00	0.1
86-MPA-24Z-M	IoFpga	YES	1.02	1.02	0.1
	IoFpgaGolden	NO	1.02	1.00	0.1
86-MPA-4FH-M	IoFpga	YES	1.02	1.02	0.1
	IoFpgaGolden	NO	1.02	1.00	0.1
8608-FS [FB]	IoFpga	NO	1.11	1.11	0.2
	IoFpgaGolden	NO	1.11	1.00	0.2
8608-RP	Bios	YES	1.09	1.09	0.0
	BiosGolden	YES	1.09	1.01	0.0
	IoFpga	YES	1.10	1.10	0.0
	IoFpgaGolden	NO	1.10	1.01	0.0
	SsdMicron7300M2	YES	2.60	2.60	0.0
	SsdMicron7450M2	YES	11.00	11.00	0.0
	x86Fpga	YES	1.07	1.07	0.0
	x86FpgaGolden	YES	1.07	1.07	0.0
	x86TamFw	YES	7.12	7.12	0.0
x86TamFwGolden	YES	7.12	7.12	0.0	
8608-SC0-128	IoFpga	YES	1.01	1.01	0.0
	IoFpgaGolden	YES	1.01	1.01	0.0
8608-SC0-128 [FB]	IoFpga	NO	1.11	1.11	0.2
	IoFpgaGolden	NO	1.11	1.00	0.2

```
-----
```

PSU4.3KW-HVPI	DT-LogicMCU	NO	8.04	1.04	0.0
	DT-PrimMCU	NO	8.02	1.02	0.0
	DT-SecMCU	NO	8.02	1.02	0.0

Cisco 8800 Series Router

RP/0/RP0/CPU0# show fpd package

```
=====
```

Field Programmable Device Package					
Card Type	FPD Description	Req Reload	SW Ver	Min Req SW Ver	Min Req Board Ver

88-LC0-34H14FH	Bios	YES	1.15	1.15	0.0
	BiosGolden	YES	1.15	0.13	0.0
	EthSwitch	YES	1.05	1.05	0.0
	EthSwitchGolden	YES	1.05	0.07	0.0
	IoFpga	YES	1.09	1.09	0.1
	IoFpgaGolden	YES	1.09	1.01	0.1
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	0.91	0.91	0.1
	x86FpgaGolden	YES	0.91	0.78	0.1
	x86TamFw	YES	6.13	6.13	0.1
	x86TamFwGolden	YES	6.13	6.10	0.1

88-LC0-34H14FH-O	Bios	YES	0.241	0.241	0.0
	BiosGolden	YES	0.241	0.218	0.0
	EthSwitch	YES	1.05	1.05	0.0
	EthSwitchGolden	YES	1.05	0.07	0.0
	IoFpga	YES	1.09	1.09	0.1
	IoFpgaGolden	YES	1.09	1.01	0.1
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	0.91	0.91	0.1
	x86FpgaGolden	YES	0.91	0.78	0.1
	x86TamFw	YES	6.13	6.13	0.1
	x86TamFwGolden	YES	6.13	6.10	0.1

88-LC0-36FH	Bios	YES	1.15	1.15	0.0
	BiosGolden	YES	1.15	0.13	0.0
	EthSwitch	YES	1.05	1.05	0.0
	EthSwitchGolden	YES	1.05	0.07	0.0
	IoFpga	YES	1.14	1.14	0.1
	IoFpgaGolden	YES	1.14	1.00	0.1
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.48	1.48	0.1
	x86FpgaGolden	YES	1.48	1.04	0.1
	x86TamFw	YES	6.18	6.18	0.1
	x86TamFwGolden	YES	6.18	6.05	0.1

88-LC0-36FH-M	Bios	YES	1.15	1.15	0.0
	BiosGolden	YES	1.15	0.13	0.0
	EthSwitch	YES	1.05	1.05	0.0

	EthSwitchGolden	YES	1.05	0.07	0.0
	IoFpga	YES	1.14	1.14	0.1
	IoFpgaGolden	YES	1.14	1.00	0.1
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.48	1.48	0.1
	x86FpgaGolden	YES	1.48	1.04	0.1
	x86TamFw	YES	6.18	6.18	0.1
	x86TamFwGolden	YES	6.18	6.05	0.1

88-LC0-36FH-MO	Bios	YES	0.241	0.241	0.0
	BiosGolden	YES	0.241	0.218	0.0
	EthSwitch	YES	1.05	1.05	0.0
	EthSwitchGolden	YES	1.05	0.07	0.0
	IoFpga	YES	1.14	1.14	0.1
	IoFpgaGolden	YES	1.14	1.00	0.1
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.48	1.48	0.1
	x86FpgaGolden	YES	1.48	1.04	0.1
	x86TamFw	YES	6.18	6.18	0.1
	x86TamFwGolden	YES	6.18	6.05	0.1

88-LC0-36FH-O	Bios	YES	0.241	0.241	0.0
	BiosGolden	YES	0.241	0.218	0.0
	EthSwitch	YES	1.05	1.05	0.0
	EthSwitchGolden	YES	1.05	0.07	0.0
	IoFpga	YES	1.14	1.14	0.1
	IoFpgaGolden	YES	1.14	1.00	0.1
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.48	1.48	0.1
	x86FpgaGolden	YES	1.48	1.04	0.1
	x86TamFw	YES	6.18	6.18	0.1
	x86TamFwGolden	YES	6.18	6.05	0.1

8800-LC-36FH	Bios	YES	1.29	1.29	0.0
	BiosGolden	YES	1.29	1.15	0.0
	EthSwitch	YES	1.05	1.05	0.0
	EthSwitchGolden	YES	1.05	0.07	0.0
	IoFpga	YES	1.39	1.39	0.0
	IoFpgaGolden	YES	1.39	0.08	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.56	1.56	0.0
	x86FpgaGolden	YES	1.56	0.33	0.0
	x86TamFw	YES	5.17	5.17	0.0
	x86TamFwGolden	YES	5.17	5.05	0.0

8800-LC-36FH-O	Bios	YES	1.208	1.208	0.0
	BiosGolden	YES	1.208	1.207	0.0
	EthSwitch	YES	1.05	1.05	0.0
	EthSwitchGolden	YES	1.05	0.07	0.0
	IoFpga	YES	1.39	1.39	0.0
	IoFpgaGolden	YES	1.39	0.08	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0

	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.56	1.56	0.0
	x86FpgaGolden	YES	1.56	0.33	0.0
	x86TamFw	YES	5.17	5.17	0.0
	x86TamFwGolden	YES	5.17	5.05	0.0

8800-LC-48H	Bios	YES	1.29	1.29	0.0
	BiosGolden	YES	1.29	1.15	0.0
	EthSwitch	YES	1.05	1.05	0.0
	EthSwitchGolden	YES	1.05	0.07	0.0
	IoFpga	YES	1.39	1.39	0.0
	IoFpgaGolden	YES	1.39	0.08	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.56	1.56	0.0
	x86FpgaGolden	YES	1.56	0.33	0.0
	x86TamFw	YES	5.17	5.17	0.0
	x86TamFwGolden	YES	5.17	5.05	0.0

8800-LC-48H-O	Bios	YES	1.208	1.208	0.0
	BiosGolden	YES	1.208	1.207	0.0
	EthSwitch	YES	1.05	1.05	0.0
	EthSwitchGolden	YES	1.05	0.07	0.0
	IoFpga	YES	1.39	1.39	0.0
	IoFpgaGolden	YES	1.39	0.08	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	x86Fpga	YES	1.56	1.56	0.0
	x86FpgaGolden	YES	1.56	0.33	0.0
	x86TamFw	YES	5.17	5.17	0.0
	x86TamFwGolden	YES	5.17	5.05	0.0

8800-RP	Bios	YES	1.29	1.29	0.0
	BiosGolden	YES	1.29	1.15	0.0
	EthSwitch	YES	1.03	1.03	0.0
	EthSwitchGolden	YES	1.03	0.07	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	TimingFpga	YES	1.02	1.02	0.0
	TimingFpgaGolden	YES	1.02	0.11	0.0
	x86Fpga	YES	1.38	1.38	0.0
	x86FpgaGolden	YES	1.38	0.24	0.0
	x86TamFw	YES	5.17	5.17	0.0
	x86TamFwGolden	YES	5.17	5.05	0.0

8800-RP-E	Bios	YES	1.29	1.29	0.0
	BiosGolden	YES	1.29	1.15	0.0
	EthSwitch	YES	1.03	1.03	0.0
	EthSwitchGolden	YES	1.03	0.07	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	TimingFpga	YES	1.02	1.02	0.0
	TimingFpgaGolden	YES	1.02	0.11	0.0
	x86Fpga	YES	1.38	1.38	0.0

	x86FpgaGolden	YES	1.38	0.24	0.0
	x86TamFw	YES	5.17	5.17	0.0
	x86TamFwGolden	YES	5.17	5.05	0.0

8800-RP-O	Bios	YES	1.208	1.208	0.0
	BiosGolden	YES	1.208	1.207	0.0
	EthSwitch	YES	1.03	1.03	0.0
	EthSwitchGolden	YES	1.03	0.07	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	TimingFpga	YES	1.02	1.02	0.0
	TimingFpgaGolden	YES	1.02	0.11	0.0
	x86Fpga	YES	1.38	1.38	0.0
	x86FpgaGolden	YES	1.38	0.24	0.0
	x86TamFw	YES	5.17	5.17	0.0
	x86TamFwGolden	YES	5.17	5.05	0.0

8800-RP2	Bios	YES	1.09	1.09	0.3
	BiosGolden	YES	1.09	1.07	0.3
	EthSwitch	YES	1.03	1.03	0.0
	EthSwitchGolden	YES	1.03	0.07	0.0
	PcieSwitch	YES	120.14	120.14	0.7
	SsdMicron7300M2	YES	2.60	2.60	0.0
	SsdMicron7450M2	YES	11.00	11.00	0.0
	TimingFpga	YES	1.01	1.01	0.0
	TimingFpgaGolden	YES	1.01	1.00	0.0
	x86Fpga	YES	1.11	1.11	0.6
	x86FpgaGolden	YES	1.11	1.02	0.6
	x86TamFw	YES	7.17	7.17	0.6
	x86TamFwGolden	YES	7.17	7.13	0.6

8800-RP2-O	Bios	YES	1.00	1.00	0.3
	BiosGolden	YES	1.00	1.00	0.3
	EthSwitch	YES	1.03	1.03	0.0
	EthSwitchGolden	YES	1.03	0.07	0.0
	SsdIntelS3520	YES	1.21	1.21	0.0
	SsdIntelS4510	YES	11.32	11.32	0.0
	SsdMicron5100	YES	7.01	7.01	0.0
	SsdMicron5300	YES	0.01	0.01	0.0
	TimingFpga	YES	1.01	1.01	0.0
	TimingFpgaGolden	YES	1.01	1.00	0.0
	x86Fpga	YES	0.128	0.128	0.3
	x86FpgaGolden	YES	0.128	0.128	0.3
	x86TamFw	YES	7.12	7.12	0.3
	x86TamFwGolden	YES	7.12	7.12	0.3

8804-FAN	FtFpga	NO	1.00	1.00	0.0
	FtFpgaGolden	NO	1.00	0.16	0.0

8804-FC0	IoFpga	YES	1.00	1.00	0.0
	IoFpgaGolden	YES	1.00	0.16	0.0

8808-FAN	FtFpga	NO	1.00	1.00	0.0
	FtFpgaGolden	NO	1.00	0.16	0.0

8808-FC	IoFpga	YES	1.02	1.02	0.0
	IoFpgaGolden	YES	1.02	0.05	0.0

8808-FC0	IoFpga	YES	1.00	1.00	0.0
	IoFpgaGolden	YES	1.00	0.16	0.0

8808-FC1-G	IoFpga	YES	1.05	1.05	0.0

	IoFpgaGolden	YES	1.05	1.01	0.0
8812-FAN	FtFpga	NO	1.00	1.00	0.0
	FtFpgaGolden	NO	1.00	0.16	0.0
8812-FC	IoFpga	YES	1.02	1.02	0.0
	IoFpgaGolden	YES	1.02	0.05	0.0
	Retimer	YES	3.00	3.00	0.0
8818-FAN	FtFpga	NO	1.00	1.00	0.0
	FtFpgaGolden	NO	1.00	0.16	0.0
8818-FC	IoFpga	YES	1.02	1.02	0.0
	IoFpgaGolden	YES	1.02	0.05	0.0
	Retimer	YES	3.00	3.00	0.0
8818-FCO	IoFpga	YES	1.00	1.00	0.0
	IoFpgaGolden	YES	1.00	0.16	0.0
	Retimer	YES	3.00	3.00	0.0
PSU-4.8KW-DC100	PO-PrimMCU	NO	51.85	51.85	0.0
	PO-SecMCU	NO	51.85	51.85	0.0
PSU6.3KW-20A-HV	DT-LogicMCU	NO	1.00	1.00	0.0
	DT-PrimMCU	NO	1.00	1.00	0.0
	DT-SecMCU	NO	1.00	1.00	0.0
PSU6.3KW-HV	AB-LogicMCU	NO	3.08	3.08	0.0
	AB-PrimMCU	NO	3.08	3.08	0.0
	AB-SecMCU	NO	3.06	3.06	0.0
	DT-LogicMCU	NO	4.11	4.11	0.0
	DT-PrimMCU	NO	4.01	4.01	0.0
	DT-SecMCU	NO	4.00	4.00	0.0
PWR-4.4KW-DC-V3	DT-LogicMCU	NO	3.02	3.02	0.0
	DT-Prim1MCU	NO	3.01	3.01	0.0
	DT-Prim2MCU	NO	3.01	3.01	0.0
	DT-Sec1MCU	NO	3.01	3.01	0.0
	DT-Sec2MCU	NO	3.01	3.01	0.0

Important Notes

- The warning message that the smart licensing evaluation period has expired is displayed in the console every hour. There is, however, no functionality impact on the device. The issue is seen on routers that don't have the Flexible Consumption licensing model enabled. To stop the repetitive messaging, register the device with the smart licensing server and enable the Flexible Consumption model. Later load a new registration token.

To register the device with the smart licensing server, see the [Registering and Activating Your Router](#).

Supported Transceiver Modules

To determine the transceivers that Cisco hardware device supports, refer to the [Transceiver Module Group \(TMG\) Compatibility Matrix](#) tool.

Production Software Maintenance Updates (SMUs)

A production SMU is a SMU that is formally requested, developed, tested, and released. Production SMUs are intended for use in a live network environment and are formally supported by the Cisco TAC and the relevant development teams. Software bugs identified through software recommendations or Bug Search Tools are not a basis for production SMU requests.

For information on production SMU types, refer the [Production SMU Types](#) section of the *IOS XR Software Maintenance Updates (SMUs)* guide.

Supported Transceiver Modules

To determine the transceivers that Cisco hardware device supports, refer to the [Transceiver Module Group \(TMG\) Compatibility Matrix](#) tool.

Cisco IOS XR Error messages

To view, search, compare, and download Cisco IOS XR Error Messages, refer to the [Cisco IOS XR Error messages](#) tool.

Cisco IOS XR MIBs

To determine the MIBs supported by platform and release, refer to the [Cisco IOS XR MIBs](#) tool.

Related Documentation

The most current Cisco 8000 router documentation is located at the following URL:

<https://www.cisco.com/c/en/us/td/docs/iosxr/8000-series-routers.html>



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA 95134-1706
USA

Asia Pacific Headquarters
CiscoSystems(USA)Pte.Ltd.
Singapore

Europe Headquarters
CiscoSystemsInternationalBV
Amsterdam,TheNetherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.