



August 2021

- [What's New in this Release, on page 1](#)
- [What's Changed in this Release, on page 1](#)
- [Issues, on page 2](#)

What's New in this Release

Partner Dashboard


A new app type called **Single Tenant Cloud** is introduced in the Cisco Spaces - Partner Dashboard. We recommend the **Single Tenant Cloud** app when a partner wants to have one deployment per customer.

What's Changed in this Release

Dashboard

The following enhancements are made to the **Digitization Stats** section in the home page of the Cisco Spaces Dashboard:

- The **Visitors** counter is removed from the **Digitization Stats** section.
- You can now view the **Digitization Stats** section as a single row.
- You can now click or hover your cursor on any counter to view the tooltip with the corresponding information, as shown in the following image:



Issues

Issues describe unexpected behavior in the Cisco Spaces application. The Resolved Issues and Open Issues sections list the issues in this release.

The following information is provided for each issue:

- **Identifier:** Each issue is assigned a unique identifier (ID) with a pattern of CSCxxNNNNN, where *x* is any letter (a-z) and *N* is any number (0-9). These IDs are frequently referenced in Cisco documentation, such as Security Advisories, Field Notices, and other Cisco support documents. Cisco Technical Assistance Center (TAC) engineers or other Cisco staff can also provide you with the ID for a specific issue.
- **Description:** A description of what is observed when the issue occurs.

This section contains the following topics:

Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST) is a gateway to the Cisco bug-tracking system, which maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. The BST provides you with detailed defect information about your products and software.

Open Issues

This section lists the open issues in this release of Cisco Spaces.

Table 1: Cisco Spaces Open Issues

Issue Identifier	Issue Description
CSCvu98859	Telemetry such as Button Click and Movement data gets reset to 18+ hours when applying new configuration
CSCvv16880	During gateway deployment workflow, the AP is sometimes erroneously categorized as <code>needs config</code> mode due to timing issues.

Resolved Issues

There are no resolved issues in this release of Cisco Spaces.