

# uBR10012ルータのMC3GX60Vラインカード間のライセンスのリホスト

## 内容

[概要](#)

[使用するコンポーネント](#)

[要件](#)

[手順](#)

[ステップ 1: デバイス資格情報の取得](#)

[ステップ 2: ライセンスポータルでのライセンス転送の要求](#)

[ステップ2.1ライセンス転送の送信元を指定する](#)

[ステップ2.2ライセンス転送のターゲットの指定](#)

[ステップ2.3ライセンス転送用の許可チケットの生成](#)

[ステップ 3: ソースLCのライセンスを取り消す](#)

[ステップ 4: ライセンスポータルでターゲットLCの新しいライセンスを取得](#)

[ステップ 4.1: リホスト情報を入力します](#)

[ステップ 4.2: ターゲットLCのライセンスファイルの生成](#)

[ステップ 5: ターゲットLCに新しいライセンスをインストールします。](#)

[ステップ 5.1: CMTSへのライセンスファイルのコピー](#)

[ステップ 5.2: ターゲットLCに新しいライセンスをインストールする前に、現在のライセンスステータスを確認します](#)

[ステップ 5.3: ターゲットLCへの新しいライセンスのインストール](#)

[ステップ 5.4: インストール後のライセンスステータスを確認します](#)

uBR10022(LC)2DS x 2 US8/172x608/0 16)

Shawn Dashuai Zhang & Andy Lau

Cisco uBR10012

MC3GC60V

[Cisco.com](https://www.cisco.com)

<https://slexui.cloudapps.cisco.com/SWIFT/LicensingUI/Quickstart#>

8/18/0

1LC

2

3LC

4LC

5LC

# 1

LC 8/181\_cred.txtdisk0 more

ubr10012-1#show license udi

SlotID	PID	SN	UDI
7/0	UBR-MC20X20V	CAT1441E0L2	UBR-MC20X20V:CAT1441E0L2
7/1	UBR-MC20X20V	CAT1441E0KH	UBR-MC20X20V:CAT1441E0KH
8/0	UBR-MC3GX60V	CAT1616E015	UBR-MC3GX60V:CAT1616E015

```

8/1 UBR-MC3GX60V CAT1435E0TZ UBR-MC3GX60V:CAT1435E0TZ ubr10012-1#license save credential
disk0:81_cred.txt subslot 8/1 Device credential saved ..... to disk0:81_cred.txt ubr10012-1#more
disk0:81_cred.txt <?xml version="1.0" encoding="UTF-8"?><CISCO_WT_ARTIFACTS
version="1.0"><CISCO_WT_REHOST_ARTIFACT version="1.0"><HEADER><ARTIFACT_TYPE>Device
Credentials</ARTIFACT_TYPE><ARTIFACT_VERSION>1.0</ARTIFACT_VERSION><TRANSACTION_ID>T and I trans
id</TRANSACTION_ID><UDI><PID>UBR-
MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Device</SOURCE><CREATE_DATE>2013-07-
04T13:25:25.307Z</CREATE_DATE><ARTIFACT_INFO>T and art
info</ARTIFACT_INFO></HEADER><CONTENT><DECIPHER_INFO
encoding="BASE64">AAEAAGAOAA4AhQEBgABlBM8UMnw+NZxYfVWqIFuiUq7aqRoKmf06/hOkQuoe706yxkteiCMZrEE592
0+SxD6TTEHBqlf9YHxgv6yguQ9hM+JXLASZRPh5i jSyTfHc0eATvmwltlxEv17kMmI jpxMlZ7/tKd4AAAAAAAAAAAAAAAA
AAAAAAAAAAAAAAAAA=</DECIPHER_INFO><CORE_DATA><CIPHER_DATA
encoding="BASE64">AAEAAGAPAA8DhAAPABAN/lbTrMxBGdHYqWuzbUD5rFvGVudf1BuINdnRkIPaksB00Vs96Zw5U5tYt
xK0nixv11z1UTtvJhxyK2r+lHG1UcZhn4ZPLIYWcJTMSPqANPEI6rE324hkaT+NveeQxVdVAp+uGu3/CKesJbfA3x0qyqM
cevT2mUfC2aZY2lLbga9mv8dhNlSUTKN0uDGPChaHNw+VKXfLh0Y/rGurwVb63UsRKOIglef5Iw5bDHmZ6y2RiJy+VR7LvBZ
MZialAouROg7XiRwFjqGOMsahKrkTF+aMFBNBdHiOgZAYP7QnaiKNwsFHnU0Wky1EzqbCBYce6CBrMMWDWLE30z68j/5roXl
m2cUHYEJAmGUBmCHreBeEa44SHyQkTKQ1pv2213nhKv4PZ5cL5JIQs6xZMY6mcNj1f0uuUXIKswWrRj7TOGnQJCSB+cP9POu
JIz8cQrXopc1P+McA/TdNv9K0usJOnUJZVCc2ZvS2B6XaLdAGssGbL0W3dlqyKpcushbLZ6s1F7h0vuQ4N56pScxO+PiE4VF
rz4G1U9JfWgt/G1hF359yNtaBBikxml37A5uwoDT5cMfLpJLJ48kWSi/9qunQ2mvmxxgRit+tmY3SxQtcx2GgmiPGNVTX8W1
hheolDMRiLNYxmfrMP9vK27rcpsS4fEN2bK0hkaPDMfQDzx+/MsNS/38vSrHWkWRoe9xM0cAybyYJgX7jr4hYed0F0g6QD+9U
vm8Ski0UMbMCAAZJHZJcgaC8BGvhZvbnDVPBoHq1+8P1t129YSFCg8GfJ1XHAmTqRB+kxZihVcRmD5eG6o70s2h/kt9ozteq
jMVraDEURxFY4SSr7Wym1Oa0e7WAP0rrCBUNMV18bkNW22Ju5OeytNGHvKz9mjDFeFqMzegHrQJSQeMQD0h+UrRlS9qzpls8
5FL1sb6J7S1HvGMFdkTq3ITuqcmxMdgukZLP3prfWYc5ZamtZ256B/ZdGiNowePzbvaFwWUAyWqsLYDBrPmT80Bfm4SVekA6
ZSyexnkJevGipqW0QOm9ATZqplm60Lfwl0NpNTBVvv3Izin8M7h4SnAsRq59Kw5E4RgsraIgyhtbDbEn6109MegKb/hwErF
l054l4zDSfPdWUeiBrGziv9/D9fik6NZ2/v1vOePYZTRehZlUkOJpleZwi8l7qRKZtBcHLXonc95q01w==</CIPHER_DATA>
</CORE_DATA><SIGNATURE_INFO
encoding="BASE64">AAEAAGALAAAsAVAECAQnYWA7F1UKowplFYRGINxVEf2ThwAAAAAAAAAAAAAAAAABImmNxd3wI3ESvX6T
CYfl8ffm9kRCY+zaQAc3ley0iCVh5/4qa2t4Ns1iS+icrxrw==</SIGNATURE_INFO></CONTENT></CISCO_WT_REHOST_A
RTIFACT></CISCO_WT_ARTIFACTS> ubr10012-1#

```

# 2

# Product License Registration

Help Settings

Show: All Licenses for Yuen Tak Lau

PAKs or Tokens Licenses Devices Transactions History

Get Licenses	Move Licenses	Add Devices	Download Licenses	Email Selected Licenses	Export to CSV	Show Filters
Device	Family	Features	Quantity			
<input type="checkbox"/> UDI Product ID:UBR-MC3GX60V UDI Serial Number:	UBR MC20x20/3G60/PRE5/3GSPA	DS_License	123			
		US_License	35			
		US_License	20			
<input type="checkbox"/> UDI Product ID:UBR-MC20X20V UDI Serial Number:		DS_License	20			
		DS_License	+1 120			
<input type="checkbox"/> UDI Product ID:C891FW-E-K9 UDI Serial Number:	800 Fixed	MEM-8XX-512U1GB	1			
		advipservices	1			

- Download License...
- Email License...
- Rehost license...
- Rehost license from failed device(RMA)...
- Get device information...

CCO[(Add Devices)]CCO

### Initiate a Rehost

On this page, you can transfer specific licenses from one device to another that were previously registered with your Cisco.com profile or by others in your organization.

1. Specify License Source 2. Specify Target & Options 3. Review

#### Source Device Selection

Select the product type: Device Credential

Credentials:


```
/hwErFI054Iz4DSfPdWUeiBrGziv9/D9fiK6NZ2
/v1vOePYZTRehZIUkJleZWl8i7qRKZiBcHLXonc95qO1w==</CIPHER_DATA>
</CORE_DATA><SIGNATURE_INFO
encoding="BASE64">AAEAAGALAAAsAVAECAQnwYWA7F1UKowplFYRGInxVEf2ThwAA
AAAAAAAAAAAAABImmNxd3wI3ESvX6TCYfl8ffm9kRCY+zaQAc3leY0iCVh5/4qa2t4Ns1i
S+icrxw==</SIGNATURE_INFO></CONTENT></CISCO_WT_REHOST_ARTIFACT>
</CISCO_WT_ARTIFACTS>
```

OK Cancel

Web

## 2.1

2




[Next]

## 2.2

[Quantity to Assign]

8/172DSX60US2DSx2US8/070DSx58US8/1



[Next]

## 2.3

## Initiate a Rehost



On this page, you can transfer specific licenses from one device to another that were previously registered with your Cisco.com profile or by others in your organization. [How do I ...](#)

✓ 1. Specify License Source   ✓ 2. Specify Target & Options   **3. Review**

	Serial Number	Product ID
1 Source	CAT1435E0TZ	UBR-MC3GX60V
Target	CAT1616E015	UBR-MC3GX60V

	Sku Name	Quantity
1.1	SWLIC-MC3GX60V-DS	2
1.2	SWLIC-MC3GX60V-US	2

Your License Key will be emailed within the hour to these email addresses and connected with the specified end user.

\* Send To:

\* End User:

\* License Agreement:  I agree with the Terms of the License [View License Agreement...](#)

[Submit]

TFTPCMTS

```
ubr10012-1#copy tftp://10.66.94.155/CAT1435E0TZ_20130704171351238.lic disk0:
```

```
Destination filename [CAT1435E0TZ_20130704171351238.lic]?
```

```
Accessing tftp://10.66.94.155/CAT1435E0TZ_20130704171351238.lic...
```

```
Loading CAT1435E0TZ_20130704171351238.lic from 10.66.94.155 (via GigabitEthernet1/1/0): !
```

```
[OK - 8872 bytes]
```

# 3LC

Cisco IOS

license revoke

60

(disk0:rt)

```
ubr10012-1#license revoke disk0:CAT1435E0TZ_20130704171351238.lic disk0:rt Following Permanent license(s) will be revoked from this device Feature Name: DS_License : Count = 72 Feature Name: US_License : Count = 60 Following Permanent license(s) will be installed on this device Feature Name: US_License : Count = 58 Feature Name: DS_License : Count = 70 Following Extension license(s) will be installed on this device Feature Name: US_License : Count = 60 Feature Name: DS_License : Count = 72 PLEASE READ THE FOLLOWING TERMS CAREFULLY. INSTALLING THE LICENSE OR LICENSE KEY PROVIDED FOR ANY CISCO PRODUCT FEATURE OR USING SUCH PRODUCT FEATURE CONSTITUTES YOUR FULL ACCEPTANCE OF THE FOLLOWING TERMS. YOU MUST NOT PROCEED FURTHER IF YOU ARE NOT WILLING TO BE BOUND BY ALL THE TERMS SET FORTH HEREIN. You hereby acknowledge and agree that the product feature license is terminable and that the product feature enabled by such license may be shut down or terminated by Cisco after expiration of the applicable term of the license (e.g., 30-day trial period). Cisco reserves the right to terminate or shut down any such product feature electronically or by any other means available. While alerts or such messages may be provided,
```

it is your sole responsibility to monitor your terminable usage of any product feature enabled by the license and to ensure that your systems and networks are prepared for the shut down of the product feature. You acknowledge and agree that Cisco will not have any liability whatsoever for any damages, including, but not limited to, direct, indirect, special, or consequential damages related to any product feature being shutdown or terminated. By clicking the "accept" button or typing "yes" you are indicating you have read and agree to be bound by all the terms provided herein. ACCEPT? (yes/[no]): yes Rehost ticket saved ..... to disk0:rt ubr10012-1#show license detail subslot 8/1 Index: 1 Feature: DS\_License Version: 1.0 License Type: Evaluation License State: Active, In Use Evaluation total period: 8 weeks 4 days Evaluation period left: 8 weeks 3 days Expiry date: Sep 02 2013 06:41:34 License Count: 72/72/0 (Active/In-use/Violation) License Priority: High Store Index: 3 Store Name: Primary License Storage Index: 2 Feature: DS\_License Version: 1.0 License Type: Permanent License State: Inactive License Count: 70/0/0 (Active/In-use/Violation) License Priority: Medium Store Index: 1 Store Name: Primary License Storage Index: 3 Feature: DS\_License Version: 1.0 License Type: Evaluation License State: Inactive Evaluation total period: 8 weeks 4 days Evaluation period left: 1 week 2 days License Count: 72/0/0 (Active/In-use/Violation) License Priority: Low Store Index: 1 Store Name: Evaluation License Storage Index: 4 Feature: US\_License Version: 1.0 License Type: Evaluation License State: Active, In Use --More-- % RPC failed to slot 17 Evaluation total period: 4 days Evaluation period left: 8 weeks 3 days Expiry date: Sep 02 2013 06:46:34 License Count: 60/60/0 (Active/In-use/Violation) License Priority: High Store Index: 2 Store Name: Primary License Storage Index: 5 Feature: US\_License Version: 1.0 License Type: Permanent License State: Inactive License Count: 58/0/0 (Active/In-use/Violation) License Priority: Medium Store Index: 0 Store Name: Primary License Storage Index: 6 Feature: US\_License Version: 1.0 License Type: Evaluation License State: Inactive Evaluation total period: 8 weeks 4 days Evaluation period left: 8 weeks 4 days License Count: 60/0/0 (Active/In-use/Violation) License Priority: Low Store Index: 0 Store Name: Evaluation License Storage ubr10012-1#

## 4LC

[Devices] > [Move licenses] > [Complete secure rehost...] UDI

PAKs or Tokens		Licenses	Devices	Transactions History
Get Licenses ▼	Move Licenses ▼	Add Devices	Download Licenses	
<input type="checkbox"/>	Device	Rehost selected licenses...	nily	
<input type="checkbox"/>	UDI Serial	Rehost from failed device(RMA)...	GW-10 DS384	
	UDI Product	<b>Complete secure rehost...</b>		
		Share licenses... >		

```
ubr10012-1#more disk0:rt <?xml version="1.0" encoding="UTF-8"?><CISCO_WT_ARTIFACTS
version="1.0"><CISCO_WT_REHOST_ARTIFACT version="1.0"><HEADER><ARTIFACT_TYPE>Rehost
Artifact</ARTIFACT_TYPE><ARTIFACT_VERSION>1.0</ARTIFACT_VERSION><TRANSACTION_ID>00DD93AAAC</TRAN
SACTION_ID><UDI><PID>UBR-
MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Device</SOURCE><CREATE_DATE>2013-07-
04T13:41:34.151Z</CREATE_DATE><CISCO_REHOST_CHANGES><CISCO_REHOST_ADD><CISCO_WT_LICENSE
version="1.0"><FEATURE_NAME>US_License</FEATURE_NAME><FEATURE_VERSION>1.0</FEATURE_VERSION><UDI>
<PID>UBR-MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Cisco HQ</SOURCE><CREATE_DATE>2013-07-
05T00:13:44.000Z</CREATE_DATE><LICENSE_LINE_HASH
hashAlgo="SHA1">v/mLxNULGRGMRuR/vu09b2IRd2w=</LICENSE_LINE_HASH><TYPE>EXTENSION</TYPE><EXPIRATIO
N><DAYS>60</DAYS></EXPIRATION><EULA>YES</EULA><COUNT>60</COUNT></CISCO_WT_LICENSE></CISCO_REHOST
```

\_ADD><CISCO\_REHOST\_ADD><CISCO\_WT\_LICENSE  
version="1.0"><FEATURE\_NAME>DS\_License</FEATURE\_NAME><FEATURE\_VERSION>1.0</FEATURE\_VERSION><UDI>  
<PID>UBR-MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Cisco HQ</SOURCE><CREATE\_DATE>2013-07-  
05T00:13:44.000Z</CREATE\_DATE><LICENSE\_LINE\_HASH  
hashAlgo="SHA1">vXiItxKb5jUhxKsJvOsdobszcyg=</LICENSE\_LINE\_HASH><TYPE>EXTENSION</TYPE><EXPIRATIO  
N><DAYS>60</DAYS></EXPIRATION><EULA>YES</EULA><COUNT>72</COUNT></CISCO\_WT\_LICENSE></CISCO\_REHOST  
\_ADD><CISCO\_REHOST\_REMOVE><CISCO\_WT\_LICENSE  
version="1.0"><FEATURE\_NAME>DS\_License</FEATURE\_NAME><FEATURE\_VERSION>1.0</FEATURE\_VERSION><UDI>  
<PID>UBR-MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Cisco HQ</SOURCE><CREATE\_DATE>2010-11-  
25T07:51:48.000Z</CREATE\_DATE><LICENSE\_LINE\_HASH  
hashAlgo="SHA1">GG9LxrdlVjD0ihBN8FxbiV+y4f0=</LICENSE\_LINE\_HASH><TYPE>PERMANENT</TYPE><COUNT>72<  
</COUNT></CISCO\_WT\_LICENSE></CISCO\_REHOST\_REMOVE><CISCO\_REHOST\_REMOVE><CISCO\_WT\_LICENSE  
version="1.0"><FEATURE\_NAME>US\_License</FEATURE\_NAME><FEATURE\_VERSION>1.0</FEATURE\_VERSION><UDI>  
<PID>UBR-MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Cisco HQ</SOURCE><CREATE\_DATE>2010-11-  
25T07:52:01.000Z</CREATE\_DATE><LICENSE\_LINE\_HASH  
hashAlgo="SHA1">djuYPaGEO/YcP/jdZdLBIbpERW8=</LICENSE\_LINE\_HASH><TYPE>PERMANENT</TYPE><COUNT>60<  
</COUNT></CISCO\_WT\_LICENSE></CISCO\_REHOST\_REMOVE><CISCO\_REHOST\_ADD><CISCO\_WT\_LICENSE  
version="1.0"><FEATURE\_NAME>US\_License</FEATURE\_NAME><FEATURE\_VERSION>1.0</FEATURE\_VERSION><UDI>  
<PID>UBR-MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Cisco HQ</SOURCE><CREATE\_DATE>2013-07-  
05T00:13:44.000Z</CREATE\_DATE><LICENSE\_LINE\_HASH  
hashAlgo="SHA1">Zl6GLxkzY5soZX+lff80dXud70Q=</LICENSE\_LINE\_HASH><TYPE>PERMANENT</TYPE><COUNT>58<  
</COUNT></CISCO\_WT\_LICENSE></CISCO\_REHOST\_ADD><CISCO\_REHOST\_ADD><CISCO\_WT\_LICENSE  
version="1.0"><FEATURE\_NAME>DS\_License</FEATURE\_NAME><FEATURE\_VERSION>1.0</FEATURE\_VERSION><UDI>  
<PID>UBR-MC3GX60V</PID><SN>CAT1435E0TZ</SN></UDI><SOURCE>Cisco HQ</SOURCE><CREATE\_DATE>2013-07-  
05T00:13:44.000Z</CREATE\_DATE><LICENSE\_LINE\_HASH  
hashAlgo="SHA1">/>6XdchgOaVgYv9HFcdUtsuzqMDY=</LICENSE\_LINE\_HASH><TYPE>PERMANENT</TYPE><COUNT>70<  
</COUNT></CISCO\_WT\_LICENSE></CISCO\_REHOST\_ADD></CISCO\_REHOST\_CHANGES></HEADER><CONTENT><DECIPHER\_  
INFO  
encoding="BASE64">AAEAAGAOAA4AhQEBgABlBmH/Q5r7IwMdRbAS/JAFyDQEKGwQkgLtrFwFdZalclKxv3eZF/WVGvcBUBC  
WkYMB5ULk/RAA0BkVdecbCoHbpe2LNaTVbI1zBAKW/B6iPNqIwIbGzfUTNsFkV3hKtVPBayWiG4boAAAAAAAAAAAAAAAAA  
AAAAAAAAAAAAAAAAA=</DECIPHER\_INFO><CORE\_DATA><CIPHER\_DATA  
encoding="BASE64">AAEAAGAPAA8RtAAPABAanu6WfSp4fjmEfsILXTPN3nG/7QCtE2Saa+L9N3qAiqCF5QTlorKYqN8NTk  
BZnYdSoDs003+n0Ek9c5kzTzxnbtK2Qw+qtbtAgS4L5ZwgM1WC5v8+muTuyAFefMglgXuG6rsoosn+7vkvaf02Au2I+wLvvg  
Tl9BYVMxrZixyk+aZYWL32z6GHF2P013xXLQk+nPovyB9Hy7/o8xBaVDZ+zYb2hUIB8osfvyqyJP0S4u9V4UWr22z2Vx1s  
+GBw528i/tf3xB1+c3DtAWQfcAaPk5WPuB+KEYbJvhs/uSXqxWaQpDKxvQow5Im5+js4od5/WhtkOcq+OBLEXDGG7euBR+ra  
azeP+7ULUN+zSY5yCNOe0wfJv1c4n/bQaAAX8a38+KzKndJL8cI7LkyUgNxiv1KugcaQYjaDstiWxanQ7ok87eVNMCTsck2Gq  
Uxfow4n1KWYDTW6ZOA3LzXwF+9uJZNzSTifbFrwE5r1sylnPGbtLD0AmHpfKPAzTuXadjrJoMLNwc+w52TK25dHhrRqWn4Pc  
fwj5ceOhovPa6+XtsiTP+x/63xRf+OBi5iihoCBAUm+mhn6xy2uHDIiPKLaeY/no7E6Cyh7QS9gP9wFyGyBYJVq7n7qmGJG  
ctdDZkTl9Q34RUDycvvrtrQnyf3nbOL3Nox5PxY7zOmxP2LldJ7A3+EsXFE06aw/c4Y9Ggb1glGfb6IAM9/HZwZ4fYWWvC  
LoZDl1lCiBTVWlFwIGX49WTZqp9A//EMyOxcmEbbPEBIyifID19fRvJecVK8q39MsDY+V1R/li12idGJfTiU1hLUQnoPYRIp  
fpdSo4P5T+QxT6GIBSstXy55D1WLtEalclw18o9h6XLlnUySTMZBmHMH1MzevOgKRTaXJfMlHbTKiU1lNboVDbUKclc0PPEy  
ely9XX19Z0LlTYNazAe4wbnxouDbsQ99WuxYpPr8TcrD+ab8vKX3DUFxu+pyznPVzcymlTlkw2ZtsFzK4VjqU3xHBaZhhz2R  
bdQckwlnkBB9+9e4eZ6wVOC29pVZBrBA8mh6Bt7H3dwj1LJNMpdegeZTgnr7+dHbATppbVeFfZe06wJ1jmM/EzRs/7/1mA01  
uXUd6WUSjsyzUTIEyFTmVwfb1un9uyMzoSzQbCerCz3vHQdi/dy8iQbXwGyJPKhjHhbBjiKN6+p1UXHZRGvr0r09v/kIdTLn  
fkBFgXPOoCRIUmbUZ/ULimzibTf0PfqwQ98r42dQwXgN4UPybKoR6/pQcPX287GVsB/5zpIvWR9544B+1Dvo+cCeuVA/60W  
J3UFVqoCA9YNM6b+B6A4mZvBT78S+j+r+prnFMBzhnyD90yOOpY5JocOEJfkdMsvDT78G+acfeqzRm76Ny4N4YbKVI4kUA06  
PS0fqRsvK1hHUAu00yluVnqaD3OX/SH8C97HCN1hmXUyDZ9ZfabAq49jairvba7fLHyHFY56RaQUhJCK08v70CXyy+3zVWF9  
Ce6YmAAjeTqVIE4Q6hZqXQbvLOUbl+YHoSVaUIfQ3LaJDi9phIrDlfpL9bYaCDDDCgarbj8Xh/CT+6qit1bXikoVSMlJ/xHD  
EP9FFbL9oQQq0U90I4J6Hqcn/f0SD4wjiS86Rz6+EE6kNNG00FhVxQZQsZfABsHy6PFXF4sH2lr333ILEiAxLypwUiANfkTU  
ulf94rpdMKubQbPtjah1BnS1tCka3ANK5XOmDcmJ379K119zHs+s4B+I6/Dbb4kvZKUA++UPyzu/AxhlXOXGodRI419lvjtD  
+rr3/kIJo0FkX3blsx5qIdxgNsZmAG3ijUIxcMqMEnsJ7+/1zV7GCGfM9002E9BFqCvLzat0MKRKPu2aWM+LpOXvr9ybWjn0  
Y4hIDR/3tnAYFo85ZAHtDOOdyEHMaqx38fZuFHQ0vGKA+XZzhZy2qDG1SsAzN39VlDsDThkbgm5hM9seUHLvWin9QEsFzpe  
bI6ENWIEz8vhlYwtfJZ5v/8KeBydSeTvYr9lr0+02zSNfdrMmguldG104ZQ60358AnR7EBtN57WAYCrNJswyFySKSKQtHiZh  
KVLXMxiboxDwJcVquT8sLjk60iRtPtoboTRVHNCDBTardMonhHiy5ZY6DIKhg7DN/lnoOAPwNY8K4BZHTPyzb3P9BGg+tAiyt  
Tzm0ulz/ktAweled7IU311RvS7wR3Wvxh7WTwiQG8e4fj+FioTz90XBnBabl+7V53KHbcgXRC4w3wJmH804Gwe2UDVuyARFE  
6uSbeZvf3FQitViC03h/gnGcvWtV6ghsOzwm7spxz2VNORK1KZRn+FmDPrTPBJeu6YN+VAFXvc27fJ/10phJiRdomUW/VJgG  
YGXZxC0wAZom9Mdht4W/nSsupcZQRoiOB4EPP06jn6Ij5iNowSjGDFQ0rIz9wTe06qvI33uunyq/jih8+g7qqwpzXncc70  
gQ2hAO2Kynp4GjX5aUALbxs00diMjT2JUAH2aMoi7ZAqE9izk8wyYpEzWdsD1GALfIedJEfQvUDFFewZDxEA4+JxhHT0ybuK  
j8KCZKMTtojhIOG6UgMuyR0rwlo/YAC3RSjVDCYieW2MpirnFJDS5TbQ6ua8YbVpjdJn+b4wTfsl29fV/mSPj3mZQCSf9k7M+  
72Jy2b29Bqz/G0ZJB6+7+hXQRYVzB8Xcis9bnPBWmt3JSKugotK65dqUTVoE9c+kPkmZ/haUkST6FukqiZRE4mJYmgbJJyXM  
YcHJkv5HrUaJ8xfeB8+gJT40gbhaV2X6W2Yl22vVeV+epGPxU8VzBdQcltDoE6TU5YPqV8Pb7J/7ZKHF+QkcC1q91ZKCV7ob  
9H4xvuBKsSGHS0HkI3/gzgrkM8fvaxWDC3RJK7C1iqd84Y17DxToCSmaFWymKaoRvK+iYxslE6k4FdKrvObLvdDiM+jZTcfuW  
BD389nBuGmiDfVwIf5/DPuTjPxbppPrCjCZzwwUJf1K+ZjNj09HLonYomtP49T45+0uFBfd8w63rgTtx39N3iteJkEievSR  
hkyB4zil/g160B9ssb/OYEMJoc+BIjuxLExyIon14qN/xlB2Vm7AcFH6uOagaT/qTm+xsEe5OZDivuv4cr2zKdbQUiVXky1k



bfZGJdC0R41kh2eOeWYMKbHI9UipZ3mEgknBm+ZE6AUwYlRbZP3JrxUfNoXI73zIkCVZidzBYPVeKcBhXTRWnbXXqxz4kKn0  
TOigchAdyhOgfsElsGWCtRBreXHP3qT5syFSA7pydhTspK3BLMiWSuRZw9uH0bMJF8LURvnJD4hI1D1hLmFP4TD0v5bo2Mj  
CgQmUSKamfBulXdB/OVawWrmdqXU/W4JIQUt96JNICl4BIZXtM2e8zWaziw4g83F8ND7v3fIFrvaReQL7K7Q+pZn7BbIPNG6  
A5pMSJ79zChz+Da8JxZ5hxPhxjzt+SpXZ3Tz0SLP49B6WL6dtiOcbIh854eKEDQRHwztDUMMtaYfdIBsureERzmUDLXHT73V  
/+PIFMEkxwv6dDsr81qbsOyMT47DcCrcJwEvxxWDS2Px3OyuzA79FepsIvmKoudhm8Ik4zXuJfbDNdf00uV/P001EQASUiuT  
pllm/1/YQ/3fdOnxtm823/n+FXksa4GX0ji+9qr7GmsEDo/sxPql0p4Ha+epmoYmiTKAJW7i9r+XLMTdpMXKriVgKIx6qydB  
C5TGcKomeaAKVULkvHvCF801/NyUdaSVg2cMcm7wWWarOrwHcJF7Wy/KccbXocgirYjgzXlU2REza+RRln+xy802IQDDaNBk  
7ED6W1Dy9MKPknJc6vTJ+kflbap0ag+CmOGdGesgWJVRIMEk7UBJagChpP+eLPTmk6s7du9WLMVegBRMqIttqHhVodZt01J  
Q1HGZFdvrgndd0V4kqDB0p28C0Y+Jci/V09waVfWHXsowL0hFXerFRYNNRvToXIdXug3uwKgVsl7QIkDwz3cKDbOCbbzR0V1  
/YdewkOBWYbqxZ6d1eGCKmYnXk2KJhkxz1QkkEw5JLvpYIPcR70iLVWr/nEH+CtWCG0fRiWVRPduCXU2Hrmq7hBv2c9+Fi6  
V2TmWXHxrMBS3CflzTo06V1bLOpt1G75b76D/ntzaCbco30/UtGkRvOZhj3pwUd/oj4exSQ9SJrpashlYmGL9nAVzOMoI3  
p34LoyL3Yl65zEEDuGQcsVd0ESxHf+81+7Pws9Y6+p5V70+vi10Jp4ia0BOgtDb2gic/gpxeKqCIyK6qaRwJ6kIJRoFuaoVb  
xBizL4Xmb818bBmM/zQDonWOZFHvjtYukuqKdnbf20o2CY+Sf6HV3IMcrTOMLL9xdeJbHZjHC7Y/PU7w4JOT6boDHFHv5Y  
q2je90Dn5HzU/3wrXpvmLwbixVSDhphcdCEvKE8zUZuM0YHnn5uGn0YECiiQX4r2i7dBy7elocqeMfEMQLV0s0jt0tZgO/  
Is/J8hXJHv8xkRCSzVUYJBTRDb22vmpv5rbR805KQ8sBfxvILHbXQaj8Clu9Th6nRKbcEqGsDR1BQ941m4/aMyZe891tqe11  
uuJuIs7qXf00GKTBl+SliWw0kzjI5z8vRobFTNGzifo/7qRCjad2+xf3dyR4zswJ28GZcUee1ni3DWX/devKhPi4F1a+fTv1  
EquDrkrYZdTAAXvGBjJqWPZCK/32X1GTlWcBv9xNqSHY31VME02FFWglK/519RK5WAvB0Oa0oii7QYXiUQ3S5Znp2YUvRy  
e7jGq12zhixzorOD9W1DzGrVLjPfmW1aQ/hhv3SnCLrJ/Z45FLYJzWk6lQDGRan21d6MYnUgzwx033+Zx4K159WgoGapGEfo  
Qn56eolqE5ehaPCCWX09pJt1gTjtRR8e47iEX/fZ7rkYUfWxqBlBYyGP14WTmv1Q7N3VqyT6UIYj2Y028/SCUDKlhhKqPRi  
wvJo3Hnb3jiokILNZnefu5tjFpU5quPV6Y2C1e1LfgUoHUIHTW/ap5XlSbiu3uLl/QpmmFPmFeJjJ3axOAYVo0s7pRmIWRo9  
EvVy7LFEELHnZoSyR2jIV1vx0wCCwB/tLPDDi9twcOERdoMM+WFPCAZZEeBI7LfzZYT6DjCmGbdg2C2wdoVNqENIT2P61nV  
zQIJTEJfLktV7rVWHBaS9CesJxlXlnc1mJU6+lgFm9+a8QhEQvYx/4U4B54EYiXH2P3dxNhQbzemdROIluMj3mF0ZK9zbWn  
PTuEN87JTrQ1+UWxXHKsA/zPGROGjmCdYqIDeVm76HUDkgM7oQ0c4qD88LNKzc0UbkzBwJwTp9xymawjX9AnUe3hOQR1WVN  
Lm9D6p4db5JSasUwBuxbB8obn/YLwB1Fi03bVO/tWSEdy/BWG9w6N2NcX4P+I1mmVk9tOYQv741VbuC9YufbNyOzaFWY6qt  
exCODtmNbvufIPCYznUbAYWeHzUbgwzAbletW6LPwKYpElkRsorXWL4p72NDK49w5kfBsYGwRd5C+/iJvzF9nnh5mBd5bg51  
ZTDiNB/aLd1M7QnkzAKI+42h1wWqBR/nmTfON9cPQY4U8VepkliI2BHoZMW5IeQaRh1D1n0EpIa7hp/yl0Hln1eRJaBxo2Nz  
CY8bQN61KvFXM+3/XC8D/M8bYn4zybUf3NmbQy+ES7p/AwRbwhdEhc3biHpKm0TdAdJalkzaH8rOadqsenLWuWXVnHzIWgWb  
uuUca5hTWfeAz0CuJAZDme+ETTSIhYCFBIZcoMuKfrJvqMdRRLLId6w/1LYCCuAogxNTXzDYqjd79uJjNr/n5Mn/D7jOztWd+  
5POtDC7g1lqh64zok+hKfropP2fuzU9wUkZqahjMG7/A5/IVGhn7y5k6MLx5IZDyRkxkAzYv0lhoGEOjIpmDowkymZVml2kL  
HQOrmmEE+y0TMwu74YyDapxCqguA3MckE6i/PGtpIW9+JhKTWA8tgMr7IrvlSsdLIIiO2UVpa0aadEbnAtZP3y2i9YHCTbuJ  
8kuBlw8t4mJMYe/ayR8EOw1+90</CIPHER\_DATA></CORE\_DATA><SIGNATURE\_INFO  
encoding="BASE64">AAEAAGALAAAsAVAECAQlAYiZn2o1/b/XEYyF3681aOv/kIQAAAAAAAAAAAAAAAAAAE/cnMwLdddnDg807K  
ZDqj7n5UvftxqDacwXmHnecgM3yfHlctTmyWC0lCdm9Mtt8g==</SIGNATURE\_INFO></CONTENT></CISCO\_WT\_REHOST\_A  
RTIFACT></CISCO\_WT\_ARTIFACTS> ubr10012-1#

## 4.1

Safenet

UDIID: <PID>

UDI <SN>

[Rehost Ticket]

[Next]



# Complete Secure Rehost/Transfer



## 1. Enter Rehost Ticket/Key | 2. Review

Select the Product Type:

Enter a Rehost Ticket required to generate the license for the new device.

\* UDI Product ID:

\* UDI Serial Number:

\* Rehost Ticket:

```
<?xml version="1.0" encoding="UTF-8"?><CISCO_WT_ARTIFACTS
version="1.0"><CISCO_WT_REHOST_ARTIFACT version="1.0">
<HEADER><ARTIFACT_TYPE>Device
Credentials</ARTIFACT_TYPE>
<ARTIFACT_VERSION>1.0</ARTIFACT_VERSION>
<TRANSACTION_ID>T and I trans id</TRANSACTION_ID><UDI>
```

Cancel

Next

## 4.2LC

[Get License]

### Upload Rehost Ticket to Finish Rehost

Use this page to complete the final step of the secure license transfer process. [How do I ...](#)



✓ 1. Enter Rehost Ticket/Key

**2. Review**

	Serial Number	Product ID
1 Source	CAT1435E0TZ	UBR-MC3GX60V
Target	CAT1616E015	UBR-MC3GX60V

SKU	Quantity	More Information	Feature
1.1 SWLIC-MC3GX60V-DS	2	1 DS license: Must configure with UBR-MC3GX60V only	DS_License
1.2 SWLIC-MC3GX60V-US	2	1 US license: Must configure with UBR-MC3GX60V only	US_License

Your License Key will be emailed within the hour to these email addresses and connected with the specified end user.

\*Send To:

daszhang@cisco.com



\*End User:

Zhang, Dashuai



\*License Agreement:

I agree with the Terms of the License

[View License Agreement...](#)

Back

Get License

Cancel

# ステップ 5 : ターゲットLCに新しいライセンスをインストール します。

## ステップ 5.1 : CMTSへのライセンスファイルのコピー

電子メールからuBR10Kからアクセス可能なTFTPサーバにライセンスファイルをコピーします。

TFTPサーバからuBR10Kにライセンスファイルをコピーします。

```
ubr10012-1#copy tftp://10.66.94.155/ CAT1616E015_20130704172627009.lic disk0:
```

```
Destination filename [CAT1616E015_20130704172627009.lic]?
```

```
Accessing tftp://10.66.94.155/CAT1616E015_20130704172627009.lic...
```

```
Loading CAT1616E015_20130704172627009.lic from 10.66.94.155 (via GigabitEthernet1/1/0): !
```

```
[OK - 2237 bytes]
```

```
2237 bytes copied in 0.556 secs (4023 bytes/sec)
```

```
ubr10012-1#
```

### 5.2LC

```
8/0
```

```
ubr10012-1#show license detail subslot 8/0
```

```
Index: 1      Feature: DS_License                               Version: 1.0
```

```
License Type: Permanent
```

```
License State: Active, In Use License Count: 60/60/0 (Active/In-use/Violation) License  
Priority: Medium Store Index: 0 Store Name: Primary License Storage Index: 2 Feature: DS_License
```

Version: 1.0 License Type: Evaluation License State: Inactive Evaluation total period: 8 weeks 4 days Evaluation period left: 8 weeks 4 days License Count: 72/0/0 (Active/In-use/Violation) License Priority: None Store Index: 1 Store Name: Evaluation License Storage Index: 3 Feature: US\_License Version: 1.0 License Type: Permanent License State: Active, In Use License Count: 16/16/0 (Active/In-use/Violation) License Priority: Medium Store Index: 1 Store Name: Primary License Storage Index: 4 Feature: US\_License Version: 1.0 License Type: Evaluation License State: Inactive Evaluation total period: 8 weeks 4 days Evaluation period left: 8 weeks 4 days License Count: 60/0/0 (Active/In-use/Violation) License Priority: None Store Index: Name: Evaluation License Storage ubr10012-1#

## 5.3LC

```
ubr10012-1#license install disk0:CAT1616E015_20130704172627009.lic
```

```
Installing licenses from "disk0:CAT1616E015_20130704172627009.lic"
```

```
Installing...Feature:US_License...Successful:Supported
```

```
Installing...Feature:DS_License...Successful:Supported
```

```
2/2 licenses were successfully installed 0/2 licenses were existing licenses 0/2 licenses were failed to install
```

## 5.4

```
2x2show license detail8/062/18
```

```
ubr10012-1#
```

```
show license detail subplot 8/0
```

```
Index: 1 Feature: DS_License
```

```
Version: 1.0
```

```
License Type: Permanent
```

```
License State: Active, In Use License Count: 62/62/0 (Active/In-use/Violation) License Priority: Medium Store Index: 3 Store Name: Primary License Storage Index: 2 Feature: DS_License Version: 1.0 License Type: Permanent License State: Inactive License Count: 60/0/0 (Active/In-use/Violation) License Priority: Medium Store Index: 0 Store Name: Primary License Storage Index: 3 Feature: DS_License Version: 1.0 License Type: Evaluation License State: Inactive Evaluation total period: 8 weeks 4 days Evaluation period left: 8 weeks 4 days License Count: 72/0/0 (Active/In-use/Violation) License Priority: None Store Index: 1 Store Name: Evaluation License Storage Index: 4 Feature: US_License Version: 1.0 License Type: Permanent License State: Active, In Use License Count: 18/18/0 (Active/In-use/Violation) License Priority: Medium Store Index: 2 Store Name: Primary License Storage Index: 5 Feature: US_License Version: 1.0 License Type: Permanent License State: Inactive License Count: 16/0/0 (Active/In-use/Violation) License Priority: Medium Store Index: 1 Store Name: Primary License Storage Index: 6 Feature: US_License Version: 1.0 License Type: Evaluation License State: Inactive Evaluation total period: 8 weeks 4 days Evaluation period left: 8 weeks 4 days License Count: 60/0/0 (Active/In-use/Violation) License Priority: None Store Index: 0 Store Name: Evaluation License Storage ubr10012-1#
```