


Cisco IP Phone

7800, 8800, Session Initiation Protocol (SIP) Denial of Service (DoS)



ID : cisco-sa-20190703-ip-phone-sip-dos
Created : 2019-07-03 16:00
Updated : 2019-07-08 16:16
Version : 1.1 : Final
CVSS : [5.3](#)
Workarounds : No workarounds available
Cisco ID : [CSCvc61672](#)

[CVE-2019-1922](#)

Summary: Cisco IP Phone 7800, 8800, Session Initiation Protocol (SIP) Denial of Service (DoS)

Details

Cisco IP Phone 7800, 8800, Session Initiation Protocol (SIP) Denial of Service (DoS) is a vulnerability in Cisco SIP IP Phone 7800, 8800, Session Initiation Protocol (SIP) Denial of Service (DoS) that allows an attacker to cause a Denial of Service (DoS) by sending a SIP INVITE message with a large payload. The vulnerability is caused by a buffer overflow in the SIP INVITE message processing. The vulnerability is rated as Medium (CVSS 5.3) and there are no workarounds available. The Cisco ID is CSCvc61672.

References

[Cisco Security Advisories and Alerts](#)
[Cisco Security Advisory: Cisco SIP IP Phone 7800, 8800, Session Initiation Protocol \(SIP\) Denial of Service \(DoS\)](#)

ã"ã®è,,tå¼±æ€šã«ã³åå!ã™ã,ãžéç-ã-ã,ã,šã¼ã>ã,"ã€,

ä,æfå^©ç"ä°<ä¼ã"å...-å¼ç™°èj"

Cisco Product Security Incident Response

Teami¼^PSIRTi¼%ã-ã€æœ-ã,çãf%ãfã,ãã,¶ã,¶ãfã«è~è¼%ã•ã,œã|ã,,ã,è,,tå¼±æ€šã

å±°å...,

ã,ã,1ã,³ã-ã€ã"ã®è,,tå¼±æ€šã,å±šã-ã|ã,,ãÿãã,,ãÿxen1thLabsã®Thomas Sabonoæ°ã«æ,,ÿè-ã,,ãÿã-ã¼ã™ã€,

URL

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20190703-ip-phone-sip-dos>

æ"¹è,,å±æ'

ãfã¼ã,ãfšãf³	èª-æž	ã,»ã,-ã,ãfšãf³	ã,¹ãfãf¼ã,çã,¹	
1.1	è²å½"è£½ã"ã®ãfã,¹ãfã<ã,%œUnified IP 8831 Conference Phoneã,å%šé™ã€,	è²å½"è£½ã"ã	Final	2019
1.0	å^åžå...-é-ãfãfãf¼ã,¹	-	Final	2019 æ-Y

å^©ç"è!ç',,

æœ-ã,çãf%ãfã,ãã,¶ã,¶ãfã-ç,,jãçè"¼ã®ã,,ã®ã"ã-ã-ã|ã"æãã¼ã-ã|ãšã,šã€æœ-ã,çãf%ãfã,ãã,¶ã,¶ãfã®æf...å±šãšã,^ã³ãfãf³ã,-ã®å½çç"ã«é-çã™ã,<è²-ã»ã®ã,ã¼ãÿã€ã,ã,¹ã,³ã-æœ-ãf%ã,ãfãfãfãfã®å±šã®¹ã,'ã°ãšããã-ã«ã%œ'ã-ãæœ-ã,çãf%ãfã,ãã,¶ã,¶ãfã®è"~èç°å±šã®¹ã«é-çã-ã|æf...å±é...ãçjã® URLã,çœç•ã-ã€ãççç-ã®è»çè¼%ã,,,æ,,è³ã,'æ-½ã-ãÿã'å^ã€å½"ç³ã¼ãœç®ççã"ã®ãf%ã,ãfãfãfãfãfã®æf...å±šã-ã€ã,ã,¹ã,³è£½ã"ã®ã,"ãfãf%ãfãf¼ã,¶ã,å³è¼±jã

翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。