SG350X, SX550X:스위치에서 XG 포트 설정을 변경할 수 없음

식별된 날짜

2016년 3월 30일

해결된 날짜

해당 없음

영향을 받는 제품

모델	펌웨어 버 전	고정 수 신	
SG350X, SX550X	2.2.0.x	2.3.0.1 30	

문제 설명

XG 포트 설정을 변경하여 협상을 비활성화하고 스위치의 웹 기반 유틸리티를 통해 동시에 속 도를 설정할 수 없습니다.

해결

스위치의 펌웨어를 최신 버전으로 업그레이드합니다.자세한 내용을 보려면 <u>여기</u>를 클릭하십 시오.

해결 방법

어떤 이유로 스위치의 펌웨어를 업그레이드하지 않으려면 다음 해결 방법을 수행할 수 있습니 다.

1단계. 스위치의 웹 기반 유틸리티에 로그인합니다.기본 사용자 이름 및 비밀번호는 cisco/cisco입니다.

참고:이미 비밀번호를 변경하거나 새 계정을 생성한 경우 대신 새 자격 증명을 입력합니다.



2단계. Port Management(포트 관리) > Port Settings(포트 설정)를 선택합니다.



3단계. Port Settings Table(포트 설정 테이블)에서 구성할 포트에 해당하는 라디오 버튼을 클 릭한 다음 Edit(**수정)**를 클릭합니다.

Port Settings Table									
Filte	er: Interface	<i>Type</i> eq	uals to Por						
	Entry No.	Port	Description	Port Type	Operational Status	Port Speed	Duplex Mode	LAG	Protection State
\bigcirc	1	XG1		10G-Copper	Down				Unprotected
	2	XG2		10G-Copper	Up	10G	Full		Unprotected
$\overline{\bigcirc}$	3	XG3		10G-Copper	Up	10G	Full		Unprotected
\bigcirc	4	XG4		10G-Copper	Down				Unprotected
\bigcirc	5	XG5		10G-Copper	Down				Unprotected
\bigcirc	6	XG6		10G-Copper	Down				Unprotected
\bigcirc	7	XG7		10G-Copper	Down				Unprotected
\bigcirc	8	XG8		10G-Copper	Down				Unprotected
\bigcirc	9	XG9		10G-FiberOptics	Down				Unprotected
\bigcirc	10	XG10		10G-FiberOptics	Down				Unprotected
\bigcirc	11	XG11		10G-FiberOptics	Down				Unprotected
\bigcirc	12	XG12		10G-FiberOptics	Down				Unprotected
\bigcirc	13	XG13		10G-FiberOptics	Down				Unprotected
\bigcirc	14	XG14		10G-FiberOptics	Down				Unprotected
\bigcirc	15	XG15		10G-FiberOptics	Down				Unprotected
\bigcirc	16	XG16		10G-FiberOptics	Down				Unprotected
\bigcirc	17	OOB		1000M-Copper	Up	1000M	Full	N/A	N/A
	Copy Sett	ings	Ed	it					

참고:이 예에서는 XG2가 선택됩니다.

4단계. 자동 협상을 비활성화하려면 자동 협상 **사용** 체크박스를 선택 취소한 다음 **적용**을 클 릭합니다.

Auto Negotiation:		Operational Auto Negotiation:	Enabled
Administrative Port Speed:	 100M 1000M 10G 	Operational Port Speed:	10G
Auto Advertisement:	 Max Capability 1000 Full 100 Full 10000 Full 	Operational Advertisement:	Max Capability
Preference Mode:	Slave Master		
Neighbor Advertisement:	100 Full 1000 Full 10000 Full		
Flow Control:	 Enable Disable Auto Negotiation 		
MDI/MDIX:	MDIX MDI • Auto	Operational MDI/MDIX:	MDIX
Protected Port:	Enable		
		Member in LAG:	
Apply Close			

5단계. Administrative Port Speed(관리 포트 속도) 영역에서 포트 속도를 클릭합니다.



참고:이 예에서는 1000M을 선택합니다.

6단계. Apply(적용)를 클릭한 다음 Close(닫기)를 클릭합니다.

Auto Negotiation:	Enable	Operational Auto Negotiation:		
Administrative Port Speed:	 100M 1000M 10G 	Operational Port Speed:		
Auto Advertisement:	Max Capability 1000 Full 100 Full 10000 Full	Operational Advertisement: Unknown		
Preference Mode:	 Slave Master 			
Neighbor Advertisement:	Unknown			
Flow Control:	 Enable Disable Auto Negotiation 			
MDI/MDIX:	MDIX MDI Auto	Operational MDI/MDIX:		
Protected Port:	Enable			
		Member in LAG:		
Apply Close				

7단계. (선택 사항) Save 버튼을 클릭하여 설정을 시작 구성 파일에 저장합니다.

				(⊗ Save	cisco La	anguage:	English	\$
-8T 16-Port 10G Stackable Managed Switch									
Port Settings									
Jumbo Frames: Enable									
Jumbo frames configuration changes will take effect after saving the configuration and rebooting the switch.									
Apply Cancel									
Port Settings Table									
Filte	Filter: Interface Type equals to Port of Unit 1 \$ Go								
	Entry No.	Port	Description	Port Type	Operational Status	Port	Duplex	LAG	Protection
						Speed	Mode		State
\bigcirc	1	XG1		10G-Copper	Down				Unprotected
\bigcirc	2	XG2		10G-Copper	Up	1000M	Full		Unprotected
\bigcirc	3	XG3		10G-Copper	Up	10G	Full		Unprotected
\bigcirc	4	XG4		10G-Copper	Down				Unprotected

이제 자동 협상을 성공적으로 비활성화하고 스위치의 웹 기반 유틸리티를 통해 포트 속도 설 정을 변경해야 합니다.