

了解Catalyst 3K和Catalyst 9000系列交换机中的AVB

目录

[简介](#)

[背景信息](#)

[硬件/软件支持](#)

[AV模拟技术](#)

[AVB IEEE标准](#)

[AVB网络术语](#)

[AVB拓扑](#)

[AVB域](#)

[AVB PTP域](#)

[AVB MSRP域\(QoS\)](#)

[MSRP — 通告注册期间的保留失败](#)

[MSRP — 就绪注册期间的预留失败](#)

[MSRP — 通话者状态](#)

[MSRP — 侦听程序状态](#)

[AVB架构 — QoS流量类](#)

[AVB MVRP域](#)

[AVB流 — 汇总](#)

[AVB组件交互](#)

[排除Cat3k和Cat9k交换机中的AVB故障](#)

[AVB配置](#)

[如何配置AVB](#)

[MSRP自动添加的配置](#)

[不同类型的入口策略](#)

[不同类型的出口策略](#)

[验证AVB是否正常工作](#)

[AVB注意事项](#)

[MSRP注意事项](#)

[QoS 注意事项](#)

[PTP注意事项](#)

[MVRP注意事项](#)

[命令列表](#)

[相关信息](#)

简介

本文档介绍如何在Catalyst 3650、3850、9300和9500平台中配置音频视频桥接(AVB)并对其进行故障排除。

背景信息

音频和视频(AV)设备部署传统上是模拟、单用途、点对点、单向链路。随着部署迁移到数字传输，它们继续保留点对点、单向链路架构。这种专用连接模式在专业和消费类应用中产生了大量难以管理和操作的布线。

为解决此问题，我们确定了多种机制，但所有这些机制都是非标准的、难以操作和部署的，或者成本高昂且缺乏灵活性。迁移到以太网基础设施被视为满足专业AV设备需求的一种手段，同时还可以降低总拥有成本(TCO)并实现新服务的透明集成。但是，部署机制缺乏灵活性和互操作性。

为了加速采用基于以太网的AV并提供更灵活的部署，IEEE制定了IEEE 802.1音频视频桥接(AVB)标准。此标准定义了一种机制，通过这种机制，终端和网络可以整体运行，从而在消费者应用之间实现高质量AV流传输，并通过以太网基础设施实现专业AV部署。

硬件/软件支持

从软件版本Cisco IOS® XE Denali 16.3.x开始，Cat3K平台支持AVB。在Cat9k中，AVB功能在Fuji-16.8.1a中引入。一直以来，都有显著的改进，因此较新的软件版本包括AVB功能的增强功能。

这些平台支持AVB:

	Catalyst 3650/3850	Catalyst 9300	Catalyst 9400	Catalyst 9500
支持的SKU/PID	<ul style="list-style-type: none">• WS-C3650-24PDM• WS-C3650-48FQM• WS-C3650-8X24PD• WS-C3650-8X24UQ• WS-C3650-12X48FD• WS-C3650-12X48UQ• WS-C3650-12X48UR• WS-C3650-12X48UZ• WS-C3850-12x48U• WS-C3850-24XU• WS-C3850-12XS• WS-C3850-16XS• WS-C3850-24XS• WS-C3850-32XS• WS-C3850-48XS	<ul style="list-style-type: none">• 支持所有型号	<ul style="list-style-type: none">• 17.2软件支持 PTPv2/ gPTP• 尚不支持AVB*	<ul style="list-style-type: none">• C9500-24Q• C9500-12Q• C9500-40X• C9500-16X

注意：目前，AVB仅在固定/独立平台上受支持，在堆叠配置中不受支持。对Cat9400等模块化

平台的支持正在规划中。

AV模拟技术

	AVB	但丁	CobraNet
标准	IEEE802.1 (以太网音频/视频)	专有 (IP音频)	专有 (以太网音频)
通道容量	在>=10Gbps网络时的最高信道容量	在1Gbps网络中提供更高的通道容量	在100Mbps网络下信道容量低
时钟同步	IEEE802.1AS gPTP 所有设备 (交换机、AVB终端) 都需要支持gPTP	IEEE1588 支持DANTE的设备需要支持IEEE1588	专有
延迟	<2毫秒	<2毫秒	<5.33毫秒 对于许多应用程序而言高
帧/数据包格式	第2层以太网帧	第3层IP数据包, 但不可路由	第2层以太网帧
配置和安装	简单 (来自不同供应商的控制器软件)	简单 (DANTE的控制器软件)	复杂
许可费	不适用	昂贵	昂贵
网络交换机/路由器	交换机需要支持AVB QoS自动设置 更好的QoS功能	标准交换机 QoS是手动设置的 使用标准IP语音(VoIP)服务质量(QoS)交换机功能	标准交换机 QoS是手动设置的

AVB IEEE标准

IEEE 802.1音频视频网桥(AVB)实际上包含这四个IEEE标准。这意味着, 每当出现AVB问题时, 我们必须考虑每个标准并进行相应的故障排除:

IEEE802.1AS(gPTP)

- 广义精确时间协议(gPTP)。
- 时间敏感型应用第2层设备的计时和同步。

IEEE802.1Qat(MSRP)

- 多流预留协议(MSRP)。
- 用于资源预留的端到端流量准入控制系统。

IEEE802.1Qav(QoS)


- 时间敏感流(FQTS)的转发和队列。
- AV流量调度和整形。

IEEE802.1Qak(MVRP)

- 多个VLAN注册协议。
- 动态配置和共享VLAN信息。

AVB网络术语


- AVB讲话者：AVB流源。
- AVB网桥/交换机。
- AVB侦听程序：AVB流的消费者。
- AVB流：在AVB讲者和收听者之间建立的流。



注意：某些AVB端点可以同时充当AVB讲话者和AVB收听者。


AVB拓扑

AVB域



注意：每台交换机仅支持一个AVB域。

AVB PTP域



注意：gPTP仅支持一个域。

BMCA用于选择每条链路上的主时钟，并最终为整个gPTP域选择祖时钟。祖时钟负责为整个域提供定时和同步。BMCA用于使用通告消息选择每条链路上端口的主状态和从状态。选择作为主时钟的最佳时钟取决于时钟的质量（稳定性）和配置（如gPTP优先级）。它在每个端口上本地运行，以自己的本地数据集与来自相邻设备的通告消息上接收到的数据集进行比较，以确定链路上的最佳时

钟。

- 首选：此端口是路径上的时间源。
- 从属：此端口与处于从属状态的路径上的设备同步。


支持gPTP的交换机通过测量点对点延迟来确定对等体是否也支持gPTP，该延迟是直接连接端口之间的延迟，而无中介交换机。此延迟测量机制使用消息类型Pdelay_Req、Pdelay_Resp和Pdelay_Resp_Follow_Up。根据这些消息交换，将确定端口gPTP功能。一旦建立了主从时钟层次结构，时钟同步过程就会启动。

gPTP基于IEEE1588v2

- 它类似于1588v2中规定的BMCA，在状态机中几乎没有简化
- 没有预主状态(在进入主状态之前)。
- 无外国初等资格期。
- 没有未校准状态(在进入从属状态之前)。

	gPTP	IEEE1588v2
传输	仅L2	L2/L3
系统组合	只有具有时间感知的gPTP设备才可以在网络内	可以同时使用PTP时间感知和时间感知设备
域	仅允许一个	可以是多个
最佳主时钟选择算法	简化状态机	存在预主和未校准状态
设备类型	AVB终端和AVB交换机	普通、边界和透明时钟

AVB MSRP域(QoS)



讲话者声明被转发到可能导致保留的目的MAC地址的输出端口。侦听器声明仅传播到具有关联的讲话者声明的端口（即，基于匹配流ID）。如果任何交换机端口上没有注册的关联讲话者声明，则不会传播收听者声明。

注意：MSRP感知型交换机会自动生成失效注册的取消注册，以终止AVB会话。

MSRP — 通告注册期间的保留失败

AVB架构 — QoS流量类

支持8Q策略。Cat3K/Cat9K不支持每端口入口队列。内部队列经过优化，适用于AVB，为交换机内的SR类流量提供端到端优先处理（低延迟）。

控制流量示例：OAM、信令、网络控制、网间控制

流预留(SR)A类	流预留(SR)B类	Control Traffic	VoIP
最高优先级	第2高优先级		
最坏情况延迟2毫秒	最坏情况延迟50毫秒	COS 6,7	COS 5
COS 3	COS 2		
多媒体	事务数据	批量/清除数据	尽力
COS 4	COS -	COS 1	COS 0

IEEE802.1Qav - QoS入口重新标记

- AVB流数据包使用传入帧的PCP（优先级控制点）分类为SRP流量类。
- 为了保护保留的流，AVB交换机不能允许非AVB参与者端口将尽力而为流量转发到SRP类队列。
- 要实现此保护，必须在所有非AVB参与者端口（SRP域边缘端口）上执行入口重新标记，以将匹配任何SRP类的传入PCP更改为尽力而为的PCP。
- 任何端口的SRP域状态更改（边缘与核心）时，都必须添加或删除此重新标记。

IEEE802.1Qav - QoS出口队列

- SR类流量映射到支持基于信用的流量整形算法的出口优先级队列
- AVB核心端口的每类和每端口出口整形器速率（用于带宽预留）的动态配置
- 对于Cat3k，交换机生成的控制流量（即gPTP、MSRP）在16.3.1版本中处于尽力队列。它们在16.3.2版本及以后的优先级队列中。

AVB架构 — 带宽分配设计

- 最多为SR A类+ SR B类分配75%的带宽。
- SR A类保留高达75%的带宽。
- SR B类保留SR A类未使用的带宽。
- 为AV流按先到先服务的基础分配带宽。
- 基于硬件信用的整形器，以均匀地调度AVB流量。

AVB MVRP域

什么是MVRP?

- 多VLAN注册协议(MVRP)是基于MRP（多注册协议）的应用，支持在VLAN桥接网络中的端口上动态注册和取消注册VLAN。它使用MRP在桥接网络中每个网桥的每个端口上声明要在数据库中注册的属性。MVRP使用的实际属性是VLAN ID。如果站点或已配置的网桥端口不需要接收给定VLAN ID的帧，则会发出（撤消）声明。如果VLAN ID通过MVRP在网桥端口上注册，网桥知道该VLAN ID的帧必须在该网桥端口上传输。
- MVRP允许AVB终端在需要接收给定VLAN ID的帧时进行声明。
- MVRP允许AVB终端在不需要接收给定VLAN ID的帧时撤消声明。

在交换机上启用MVRP时

- 终端的MVRP VLAN声明会触发交换机上的VLAN创建。
- 端口有三种不同的MVRP注册模式：
 - 正常** — VLAN根据设备声明动态注册/取消注册。这是全局启用MVRP时端口的默认模式 (mvrp注册正常)。
 - 固定** — 端口忽略所有MVRP声明。静态配置的VLAN不会由MVRP动态修剪。此模式可以在连接到非MVRP感知 (mvrp注册已修复) 的网络设备的接口上按端口配置。
 - Forbidden - Port**忽略所有传入的MVRP消息并修剪VLAN (mvrp注册禁止)。

注意：VTP必须处于禁用模式或透明模式才能使MVRP工作。


注意：MVRP以双向方式处理声明和注册事件，这意味着如果在其中一台设备上启用此功能，则该域中的终端和相邻网桥也需要具有MVRP感知能力，否则启用MVRP的网桥可以修剪某些VLAN，如果它没有收到声明/注册，这可能导致潜在的连接问题。

交换机上未启用MVRP时

在中继模式下手动配置交换机，允许AVB流使用所有范围的VLAN。


AVB流 — 汇总

1. MSRP初始化gPTP以进行时间同步。
2. MSRP在AVB交换机端口上初始化QoS策略。
3. MSRP信令，包含讲话者和收听者声明以检查资源。保证带宽和上限延迟。
4. QoS (整形器) 是动态调整的。高达75%的带宽分配给SR A类+ SR B类。
5. MSRP添加第2层组播条目。
6. AV流开始流动。



AVB组件交互

AVB ARCHITECTURE – COMPONENTS INTERACTION



排除Cat3k和Cat9k交换机中的AVB故障

AVB配置

如何配置AVB

步骤1.启用AVB功能及其相应的VLAN:

```
Cat3850# configure terminal  
Cat3850(config)# avb  
Cat3850(config)# vlan 2  
Cat3850(config)# end
```

注意：AVB使用的标准VLAN-ID是VLAN 2。在交换机中，可以使用cli avb vlan <vlan-id>为AVB VLAN设置不同的VLAN-ID。此配置用于指定通过MSRP应用AVB特定QoS设置的VLAN。如果需要使用非标准VLAN（默认VLAN 2除外），该VLAN需要在AVB终端设备控制器上设置，以便AVB终端设备向交换机声明AVB所需的正确VLAN，否则，AVB终端设备可以在交换机上配置的VLAN上通告其流。

步骤2.将沿AVB连接路径的交换机接口配置为dot1q中继端口：

```
Cat3850# configure terminal  
Cat3850(config)# interface GigabitEthernet1/0/3  
Cat3850(config-if)# switchport mode trunk  
Cat3850(config-if)# end  
Cat3850#
```

步骤3（可选）。在交换机上启用MVRP以启用动态VLAN传播。

```
Cat3850# configure terminal  
Cat3850(config)# mvrp global  
Cat3850(config)# vtp mode transparent  
Cat3850(config)# mvrp vlan create  
Cat3850(config)# end  
Cat3850#
```

第4步（可选）。调整交换机上的PTP优先级。

```
Cat3850#configure terminal  
Cat3850(config)# ptp priority1 <0-255>  
Cat3850(config)# ptp priority2 <0-255>  
Cat3850(config)# end  
Cat3850#
```

MSRP自动添加的配置

Cisco XE Denali 16.3.2引入了对AVB的分层QoS的支持。AVB分层QoS策略是两级父子策略。AVB父策略将音频、视频流量流(SR-Class A、SR-Class B)和网络控制数据包与标准尽力而为以太网流量(Non-SR)分离，并相应地管理流。

注意：AVB的QoS策略由MSRP自动创建和控制。

注意：最终用户对包含非SR类属性的子策略拥有完全控制权，并且只能修改这些子策略，即

: **policy-map AVB-Output-Child-Policy**和**policy-map AVB-Input-Child-Policy**。AVB HQoS子策略配置即使在重新加载后仍保留。

不同类型的入口策略

SR A类的核心端口和SR B类的边界端口 (这意味着在此端口上 , MSRP仅接收了A类流的通告 , 因此B的所有流量重新标记为COS 0 , 而A类流的标记保留)。

```
interface GigabitEthernet1/0/3
  service-policy input AVB-Input-Policy-Remark-B
  service-policy output AVB-Output-Policy-Gi1/0/3

policy-map AVB-Input-Policy-Remark-B
  class AVB-SR-B-CLASS <<< Parent Policy dynamically generated (not user
  editable)
  set cos 0 (set 0 for boundary & SR class B PCP value for core port)
  class class-default
    service-policy AVB-Input-Child-Policy <<< Child Policy (user editable)
```

SR B类的核心端口和SR A类的边界端口 (这意味着在此端口上 , MSRP仅接收了B类流的通告 , 因此A的所有流量重新标记为COS 0 , 而B类流的标记保留)。

```
interface GigabitEthernet1/0/4
  service-policy input AVB-Input-Policy-Remark-A
  service-policy output AVB-Output-Policy-Gi1/0/4

policy-map AVB-Input-Policy-Remark-A
  class AVB-SR-A-CLASS <<< Parent Policy dynamically generated (not user
  editable)
  set cos 0 (set 0 for boundary & SR class A PCP value for core port)
  class class-default
    service-policy AVB-Input-Child-Policy <<< Child Policy (user editable)
```

SR A类和SR B类的核心端口 (这意味着在此端口上 , MSRP收到了A类和B类流的通告 , 因此保留了两种流类型的入口标记)。

```
interface GigabitEthernet1/0/2
  service-policy input AVB-Input-Policy-Remark-None
  service-policy output AVB-Output-Policy-Gi1/0/2

policy-map AVB-Input-Policy-Remark-None
  class class-default
    service-policy AVB-Input-Child-Policy <<< Child Policy (user editable)
```

SR A类和SR B类的边界端口 (这意味着在此端口上 , MSRP没有收到任何流的通告 , 既无A类流 , 也无B类流 , 因此两种流类型的入口标记都重新标记为COS 0)。

```
interface GigabitEthernet1/0/1
  service-policy input AVB-Input-Policy-Remark-AB
  service-policy output AVB-Output-Policy-Gi1/0/1

policy-map AVB-Input-Policy-Remark-AB
  class AVB-SR-A-CLASS <<< Parent Policy dynamically generated (not user
  editable)
  set cos 0 (set 0 for boundary & SR class A PCP value for core port)
```

```

class AVB-SR-B-CLASS <<< Parent Policy dynamically generated (not user
editable)
set cos 0 (set 0 for boundary & SR class B PCP value for core port)
class class-default
service-policy AVB-Input-Child-Policy <<< Child Policy (user editable)
输入子策略 (用户可编辑)

```

policy-map AVB-Input-Child-Policy

```

class VOIP-DATA-CLASS
  set dscp EF
class MULTIMEDIA-CONF-CLASS
  set dscp AF41
class BULK-DATA-CLASS
  set dscp AF11
class TRANSACTIONAL-DATA-CLASS
  set dscp AF21
class SCAVENGER-DATA-CLASS
  set dscp CS1
class SIGNALING-CLASS
  set dscp CS3
class class-default
  set dscp default

```

不同类型的出口策略

出口策略也由MSRP在端口上动态配置。MSRP可以动态保留最大值。A类和B类端口带宽的75%。其余15%静态保留用于控制管理流量，其余的可按需分配给在AVB-Output-Child-Policy上定义的不同流量类型：

policy-map AVB-Output-Policy-Gix/y/z

```

class AVB-SR-A-CLASS
  priority level 1 (Shaper value based on stream registration)
class AVB-SR-B-CLASS
  priority level 2 (Shaper value based on stream registration)
class CONTROL-MGMT-QUEUE
  priority level 3 percent 15
class class-default
bandwidth remaining percent 100
queue-buffers ratio 80
service-policy AVB-Output-Child-Policy <<< Child Policy (user editable)

```

policy-map AVB-Output-Child-Policy

```

class VOIP-PRIORITY-QUEUE
bandwidth remaining percent 30
queue-buffers ratio 10
class MULTIMEDIA-CONFERENCING-STREAMING-QUEUE
bandwidth remaining percent 15
queue-limit dscp AF41 percent 80
queue-limit dscp AF31 percent 80
queue-limit dscp AF42 percent 90
queue-limit dscp AF32 percent 90
queue-buffers ratio 10
class TRANSACTIONAL-DATA-QUEUE
bandwidth remaining percent 15
queue-limit dscp AF21 percent 80
queue-limit dscp AF22 percent 90
queue-buffers ratio 10
class BULK-SCAVENGER-DATA-QUEUE
bandwidth remaining percent 15

```

```

queue-limit dscp AF11 percent 80
queue-limit dscp AF12 percent 90
queue-limit dscp CS1 percent 80
queue-buffers ratio 15
class class-default
bandwidth remaining percent 25
queue-buffers ratio 25

```

在本示例中，Gi1/0/6是A类SR的核心端口和B类SR的边界端口（这意味着在此端口上，我们仅接收A类流的通告）。分配给AV流的带宽限制为端口总带宽的最大75%。因为在这种情况下，端口会自动协商链路速度为1 Gbps，因此最多75%的带宽(750 Mbps)可保留给A类和B类流。在这个例子中。MSRP动态保留71%用于A类（约701 Mbps），0%用于B类。

但是，当我们检查连接到接口的实际QoS策略时，我们可以注意到，从75%的可保留BW中，有71%被有效分配到A类（优先级1），但实际上，BW的一小部分-1%—也被分配到B类（优先级2）。如预期，15%分配给了control-mgmt流量（优先级3），其余带宽分配给了用户可编辑的出口子策略：

```
show msrp port interface Gi1/0/6
```

```

Port: Gi1/0/6      Admin: admin up      Oper: up
MTU: 1500      Bandwidth: 1000000 Kbit/s      DLY: 0 us      mode: Trunk
gPTP status: Enabled, asCapable
  Residence delay: 20000 ns
  Peer delay: 84 ns (Updated Wed Nov 18 17:35:18.823)
AVB readiness state: Ready
Per-class value          Class-A      Class-B
-----
Tx srClassVID            2            2
Rx srClassVID            2            0
Domain State             Core         Boundary
VLAN STP State           FWD         FWD
Reservable BW (Kbit/s)   750000      0
Reserved BW (Kbit/s)    701504      0
Applied QOS BW (percent) 71           0

```

```
show policy-map interface Gi1/0/6
```

```
Service-policy output: AVB-Output-Policy-Gi1/0/6
```

```
<snip>
```

```

Class-map: AVB-SR-CLASS-A (match-any)
  0 packets
  Match: cos 3
  Priority: 701504 kbps, burst bytes 17537600, <<< 71% of the reservable BW
  Priority Level: 1

```

```

Class-map: AVB-SR-CLASS-B (match-any)
  0 packets
  Match: cos 2
  Priority: 10000 kbps, burst bytes 250000, <<< 1% of the reservable BW
  Priority Level: 2

```

```

Class-map: AVB-CONTROL-MGMT-QUEUE (match-any)
  0 packets
  Match: ip dscp cs2 (16)
    0 packets, 0 bytes
    5 minute rate 0 bps
  Match: ip dscp cs3 (24)

```

```
0 packets, 0 bytes
5 minute rate 0 bps
Match: ip dscp cs6 (48)
0 packets, 0 bytes
5 minute rate 0 bps
Match: ip dscp cs7 (56)
0 packets, 0 bytes
5 minute rate 0 bps
Match: ip precedence 6
0 packets, 0 bytes
5 minute rate 0 bps
Match: ip precedence 7
0 packets, 0 bytes
5 minute rate 0 bps
Match: ip precedence 3
0 packets, 0 bytes
5 minute rate 0 bps
Match: ip precedence 2
0 packets, 0 bytes
5 minute rate 0 bps
Match: cos 6
0 packets, 0 bytes
5 minute rate 0 bps
Match: cos 7
0 packets, 0 bytes
5 minute rate 0 bps
Priority: 15% (150000 kbps), burst bytes 3750000, <<<< 15% of the total BW
Priority Level: 3
```

```
Class-map: class-default (match-any)
0 packets
Match: any
Queueing

(total drops) 0
(bytes output) 81167770686
bandwidth remaining 100% <<< all remaining BW got assigned to child policy
queue-buffers ratio 70

Service-policy : AVB-Output-Child-Policy
<snip>
```

验证AVB是否正常工作

您必须将故障排除分为五个部分：

- 1.我们是否在所有涉及的交换机中正确配置了AVB?
- 2.检查AVB
- 3.检查MSRP(QoS)
- 4.检查gPTP
- 5.检查MVRP

AVB注意事项

<< show avb domain >>

- 每个AVB流 (A类和B类) 的端口数和类型
- 特定类的核心意味着在该端口上收到该SR类的流通告。
- 边界表示该SR类的通告在该端口上未收到。
- **Not asCapable**表示该端口不支持PTP
- 端口可以同时作为两个类的核心。
- PCP = QoS优先级代码点
- VID =用于AVB的VLAN-ID

```
Switch#show avb domain
```

```
AVB Class-A
```

```
Priority Code Point : 3
VLAN                : 2
Core ports          : 2
Boundary ports      : 31
```

```
AVB Class-B
```

```
Priority Code Point : 2
VLAN                : 2
Core ports          : 0
Boundary ports      : 33
```

```
-----
```

Interface	State	Delay	PCP	VID	Information
Te1/0/1	up	300ns			
Class- A	core		3	2	
Class- B	boundary		0	0	

Te1/0/2	up	N/A			Port is not asCapable

Te1/0/3	up	284ns			
Class- A	core		3	2	
Class- B	boundary		0	0	

Te1/0/4	down	N/A			Oper state not up

Te1/0/5	down	N/A			Oper state not up

Te1/0/6	down	N/A			Oper state not up

```
<< show avb stream>
```

- 有关流的相关信息 (流ID、实际带宽、传入和传出接口)。
- 根据连接到该端口的AV终端，端口可以同时为某些流发送和为某些其他流接收。

```
----- show avb stream -----
```

```
Stream ID:      0090.5E15.965A:65434      Incoming Interface:  Te1/0/1
Destination   : 91E0.F000.3470  <<<< AVB works with layer-2 multicast (least-significant bit
of the first octet is on)
Class         : A
Rank          : 1
Bandwidth     : 8192 Kbit/s
```

```
Outgoing Interfaces:
```

```
-----
```

Interface	State	Time of Last Update	Information
-----------	-------	---------------------	-------------


```
-----
0090.5E1A.33E2:65534      0 | 0      0 | 0      0 | 0      0 | 0      1 | 0 <<< Listener
request for the stream, but such stream is not transmitted by any talker
<snip>
```

<< show msrp port bandwidth>

- AV-Streams可使用的75%可保留带宽中，有多少实际分配给了基于MSRP协商的端口（在本例中，SR-A类流仅分配2%）。

```
----- show msrp port bandwidth -----
```

```
-----
```

Ethernet Interface	Capacity (Kbit/s)	Assigned		Available		Reserved	
		A	B	A	B	A	B
Tel1/0/1	1000000	75	0	73	73	2	0
Tel1/0/2	1000000	75	0	75	75	0	0
Tel1/0/3	1000000	75	0	73	73	2	0
Tel1/0/4	1000000	75	0	75	75	0	0

```
-----
```

<< show msrp port interface>

```
Switch# sh msrp port int tel/0/1
Port: Tel1/0/1 Admin: admin up Oper: up
MTU: 1500 Bandwidth: 1000000 Kbit/s DLY: 0 us mode: Trunk
gPTP status: Enabled, asCapable
Residence delay: 20000 ns
Peer delay: 295 ns (Updated Thu Apr 27 16:49:05.574)
AVB readiness state: Ready
Per-class value Class-A Class-B
-----
Tx srClassVID 2 2
Rx srClassVID 2 0
Domain State Core Boundary
VLAN STP State FWD FWD
Reservable BW (Kbit/s) 750000 0
Reserved BW (Kbit/s) 14720 0
Applied QOS BW (percent) 2 0
```

```
Switch# show msrp port interface gi 1/0/40 det
Port: Gi1/0/40 Admin: admin down Oper: down
Intf handle: 0x30 Intf index: 0x30
Location: 1/40, Handle: 0x1001000100000027
MTU: 1500 Bandwidth: 1000000 Kbit/s DLY: 0 us mode: Other
LastRxMAC: 0:90:5E:1A:F5:92
gPTP status: Enabled
AVB readiness state: Oper state not up
Per-class value Class-A Class-B
-----
Tx srClassVID 2 2
Rx srClassVID 2 0
Domain State Boundary Boundary <<< Interface is Down hence Boundary.
VLAN STP State BLK BLK
Reservable BW (Kbit/s) 750000 0
Reserved BW (Kbit/s) 0 0
Applied QOS BW (percent) 0 0
Registered Talker: count 0
Declared Talker: count 0
Registered Listener: count 1
Handle 0x1001000100001F97
```

```
Registered Listener, Listener Fail
Stream: 0090.5E1B.048D:65534, handle 1001000100001F96
Port handle 0x1001000100000027, vlan: 0
MRP: 0/0/60207669/0/0
```

<< show tech msrp>

- 收集所有相关MSRP输出

```
Switch#show tech msrp
```

```
----- show clock -----
```

```
*10:32:56.410 UTC Thu Jun 13 2017
```

```
----- show version -----
```

```
Cisco IOS Software [Denali], Catalyst L3 Switch Software (CAT3K_CAA-UNIVERSALK9-M), Version 16.3.2, RELEASE SOFTWARE (fc4)
```

```
Technical Support: http://www.cisco.com/techsupport
```

```
Copyright (c) 1986-2016 by Cisco Systems, Inc.
```

```
Compiled Tue 08-Nov-16 17:31 by mcpre
```

```
Cisco IOS-XE software, Copyright (c) 2005-2016 by cisco Systems, Inc.
All rights reserved. Certain components of Cisco IOS-XE software are
licensed under the GNU General Public License ("GPL") Version 2.0. The
software code licensed under GPL Version 2.0 is free software that comes
with ABSOLUTELY NO WARRANTY. You can redistribute and/or modify such
GPL code under the terms of GPL Version 2.0. For more details, see the
documentation or "License Notice" file accompanying the IOS-XE software,
or the applicable URL provided on the flyer accompanying the IOS-XE
software.
```

```
<snip>
```

QoS 注意事项

- AVB网络可保证对时间敏感的音频和视频流的带宽和最低限定延迟。
- AVB根据从来话者到收听者的流量的最坏情况延迟目标(优先级代码指向将流量映射到特定流, A类的COS 3和B类的COS 2)将A类和B类定义为时间敏感流。
- 以下列出了两个流的延迟目标: SR-A类 : 2毫秒SR-B类 : 50毫秒

注意 : 每跳最坏情况延迟贡献之和导致SR-A类的总端到端延迟为2毫秒或更小, SR-B类的总端到端延迟为50毫秒或更小。从讲话者到听众的7跳的典型AVB部署满足这些延迟要求。

注意 : 在mGig平台上, 100Mbps或更低的速度不支持gPTP。理由: 100Mbps的速度导致50毫秒以上的抖动。

PTP注意事项

- 检查祖时钟的位置并运行 (请注意, 祖时钟可以是外部设备) :

```
<< show ptp brief>>
```

- 在此输出中主表示此端口是时间源 (主)，而从表示它从另一端接收计时(故障表示未连接任何设备或另一端不支持PTP)。如果交换机上的所有AVB端口都是主端口，则交换机是 Grandmaster时钟。

```
Switch#show ptp brief
Interface                               Domain    PTP State
FortyGigabitEthernet1/1/1              0        FAULTY
FortyGigabitEthernet1/1/2              0        FAULTY
TenGigabitEthernet1/0/1                0        MASTER
TenGigabitEthernet1/0/2                0        MASTER
TenGigabitEthernet1/0/3                0        MASTER
TenGigabitEthernet1/0/4                0        FAULTY
TenGigabitEthernet1/0/5                 0        FAULTY
TenGigabitEthernet1/0/6                 0        FAULTY
TenGigabitEthernet1/0/7                 0        FAULTY
TenGigabitEthernet1/0/8                 0        FAULTY
TenGigabitEthernet1/0/9                 0        FAULTY
<snip>
<< show ptp clock>>
```

- 此输出提供本地PTP信息。

```
Switch#show ptp clock
PTP CLOCK INFO
PTP Device Type: Boundary clock
PTP Device Profile: IEEE 802/1AS Profile
Clock Identity: 0x2C:86:D2:FF:ED:AD:A6:0
Clock Domain: 0
Number of PTP ports: 34
PTP Packet priority: 4
Priority1: 2
Priority2: 2
Clock Quality:
  Class: 248
  Accuracy: Unknown
  Offset (log variance): 16640
Offset From Master(ns): 0
Mean Path Delay(ns): 0
Steps Removed: 0
```

```
<< show ptp parent>>
```

- 提供有关大师级时钟标识的信息：

```
Switch# show ptp parent
PTP PARENT PROPERTIES
Parent Clock:
Parent Clock Identity: 0x2C:86:D2:FF:ED:AD:A6:0
Parent Port Number: 0
Observed Parent Offset (log variance): 16640
Observed Parent Clock Phase Change Rate: N/A

Grandmaster Clock:
Grandmaster Clock Identity: 0x2C:86:D2:FF:ED:AD:A6:0 <<< Local switch is the Grandmaster
Clock of the domain
Grandmaster Clock Quality:
  Class: 248
```

Accuracy: Unknown
Offset (log variance): 16640
Priority1: 2
Priority2: 2

<< show ptp port>

<< show platform software fed switch active ptp interface>

- 这些输出显示详细的PTP端口信息，如邻居传播延迟。
- 首先，检查邻居传播延迟，并且仅当此值在允许范围内时，链路才被提升为支持AVB，其余过程将遵循。否则，链路设置为不为**Capable**状态，AVB将无法工作。
- 根据网络设计/要求，可以手动配置邻居传播延迟：

ptp neighbor-propagation-delay-threshold

Non-Working Port:

```
switch#show ptp port gi1/0/32
PTP PORT DATASET: GigabitEthernet1/0/32
Port identity: clock identity: 0xB0:90:7E:FF:FE:28:3C:0
Port identity: port number: 32
PTP version: 2
Port state: DISABLED
Delay request interval(log mean): 0
Announce receipt time out: 3
Neighbor prop delay(ns): -10900200825022 <<< The is an erroneous reading. Default to 800ns.
Announce interval(log mean): 0
Sync interval(log mean): -3
Delay Mechanism: Peer to Peer
Peer delay request interval(log mean): 0
Sync fault limit: 500000000
```

```
switch# show platform software fed switch active ptp interface gi1/0/32
```

```
Displaying port data for if_id 28
=====
Port Mac Address B0:90:7E:28:3C:20
Port Clock Identity B0:90:7E:FF:FE:28:3C:00
Port number 32
PTP Version 2
domain_value 0
Profile Type: : DOT1AS
dot1as capable: FALSE
sync_recpt_timeout_time_interval 375000000 nanoseconds
sync_interval 125000000 nanoseconds
compute_neighbor_rate_ratio: TRUE
neighbor_rate_ratio 0.999968
compute_neighbor_prop_delay: TRUE
neighbor_prop_delay 9223079830310536030 nanoseconds <<< Error reading
port_enabled: TRUE
ptt_port_enabled: TRUE
current_log_pdelay_req_interval 0
pdelay_req_interval 1000000000 nanoseconds
allowed_pdelay_lost_responses 3
is_measuring_delay : TRUE
neighbor_prop_delay_threshold 800 nanoseconds
Port state: : DISABLED
sync_seq_num 29999
num sync messages transmitted 903660
num followup messages transmitted 903628
num sync messages received 0
```

```
num followup messages received 0
num pdelay requests transmitted 161245
num pdelay responses received 161245
num pdelay followup responses received 161245
num pdelay requests received 161283
num pdelay responses transmitted 161283
num pdelay followup responses transmitted 160704
```

Working Port:

```
switch#show ptp port gil/0/7
PTP PORT DATASET: GigabitEthernet1/0/7
Port identity: clock identity: 0xB0:90:7E:FF:FE:28:3C:0
Port identity: port number: 7
PTP version: 2
PTP port number: 7
PTP slot number: 1
Port state: MASTER
Delay request interval(log mean): 0
Announce receipt time out: 3
Neighbor prop delay(ns): 154
Announce interval(log mean): 0
Sync interval(log mean): -3
Delay Mechanism: Peer to Peer
Peer delay request interval(log mean): -3
Sync fault limit: 500000000
```

```
switch#sh platform software fed switch active ptp interface gil/0/7
Displaying port data for if_id f
```

```
=====
Port Mac Address B0:90:7E:28:3C:07
Port Clock Identity B0:90:7E:FF:FE:28:3C:00
Port number 7
PTP Version 2
domain_value 0
Profile Type: : DOT1AS
dot1as capable: TRUE
sync_recpt_timeout_time_interval 375000000 nanoseconds
sync_interval 125000000 nanoseconds
compute_neighbor_rate_ratio: TRUE
neighbor_rate_ratio 1.000000
compute_neighbor_prop_delay: TRUE
neighbor_prop_delay 146 nanoseconds
port_enabled: TRUE
ptt_port_enabled: TRUE
current_log_pdelay_req_interval -3
pdelay_req_interval 0 nanoseconds
allowed_pdelay_lost_responses 3
is_measuring_delay : TRUE
neighbor_prop_delay_threshold 800 nanoseconds
Port state: : MASTER
sync_seq_num 41619
num sync messages transmitted 2748392
num followup messages transmitted 2748387
num sync messages received 0
num followup messages received 35
num pdelay requests transmitted 2746974
num pdelay responses received 2746927
num pdelay followup responses received 2746926
num pdelay requests received 2746348
num pdelay responses transmitted 2746348
num pdelay followup responses transmitted 2746345
```

MVRP注意事项

- MVRP是可选的。在交换机上手动配置VLAN就足以支持AVB（中继模式下的端口，vlan 2通常用于AVB）。
- 如果在交换机上启用了MVRP，则VTP必须处于禁用或透明模式，MVRP才能工作。

```
!
mvrp global
mvrp vlan create
!
!
<snip>
!! vlan 2
avb
!
!
vtp mode transparent
<< show mvrp interface>
```

- 在本示例中，我们在switch1上手动配置了vlan 17。在此之后，我们开始通过连接到交换机2的Te1/0/2的中继接口Gi1/0/1发送该vlan的MVRP声明：

```
switch1(config)#vlan 17
switch1(config-vlan)#exit
```

```
switch1(config)#interface vlan 17
switch1(config-if)#
```

```
*Nov 10 10:48:40.155: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan17, changed state to up >>> configured vlan with interface.
```

```
switch1(config)#do sh mvrp interface Gi1/0/1
```

```
Port          Status      Registrar State
Gi1/0/1       on          normal
```

```
Port          Join Timeout      Leave Timeout      Leaveall Timeout      Periodic
Gi1/0/1       20                60                1000                  Timeout
100
```

```
Port          Vlans Declared   >>> Switch is sending Declarations for VLAN 17 over Gi1/0/1
Gi1/0/1       1,8,17
```

```
Port          Vlans Registered >>> MVRP Registration available only for VLAN 1 and 8
Gi1/0/1       1,8
```

```
Port          Vlans Registered and in Spanning Tree Forwarding State
Gi1/0/1       1,8
```

```
switch1(config)#do show interfaces trunk
```

```
Port          Mode              Encapsulation      Status              Native vlan
Gi1/0/1       on                802.1q              trunking            1
```

```
Port          Vlans allowed on trunk
Gi1/0/1       1-4094
```

```
Port          Vlans allowed and active in management domain
Gi1/0/1       1-2,8,17,21-33,35-62,64-72,74-82,84-86,88-91,94-95,97-110,112-198,531-544,800-802,900-1000
```

```
Port          Vlans in spanning tree forwarding state and not pruned
Gi1/0/1      1,8 >>> Vlan 17 is Pruned because we have not received any Declaration from the
neighboring device, hence this vlan is not registered in MVRP yet.
```

- 在前面显示的输出中，我们可以看到switch1正在为最近创建的vlan 17发送MVRP声明，但该vlan尚未在该接口的MVRP中注册，因此交换机正在该端口上修剪该VRP。该VLAN的注册事件未在switch1上完成，可能是因为相邻设备switch2没有为该VLAN发送MVRP声明(因为该VLAN在该设备上不存在，或者switch2未运行MVRP)。
- 在本例中，相邻设备switch2已在运行MVRP，但vlan 17的SVI尚未在此创建，因此它未为该vlan发送MVRP声明。在交换机2上为vlan 17创建SVI后，它便开始发送此vlan的声明，并且在交换机1上的MVRP中注册了该vlan

switch2

```
switch2(config)#do show mvrp interface Te1/0/2
```

```
Port          Status      Registrar State
Te1/0/2       on          normal
```

```
Port          Join Timeout      Leave Timeout      Leaveall Timeout      Periodic
Te1/0/2       20                60                1000                  Timeout
100
```

```
Port          Vlans Declared
Te1/0/2       1,8 >>> we are not sending Declarations for vlan 17 to switch1
```

```
Port          Vlans Registered
Te1/0/2       1,8,17 >>> we see the vlan getting registered and hence in forwarding state on this
switch.
```

```
Port          Vlans Registered and in Spanning Tree Forwarding State
Te1/0/2       1,8,17
```

```
switch2(config)#do show interfaces trunk
```

```
Port          Mode          Encapsulation      Status          Native vlan
Te1/0/2       on            802.1q             trunking        1
```

```
Port          Vlans allowed on trunk
Te1/0/2       1-4094
```

```
Port          Vlans allowed and active in management domain
Te1/0/2       1,8,17
```

```
Port          Vlans in spanning tree forwarding state and not pruned
Te1/0/2       1,8,17 >>> vlan 17 is in forwarding state on switch2
```

```
switch2(config)#int vlan 17
```

```
switch2(config-if)#
```

```
*Nov 10 11:32:55.539: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan17, changed state to
up
```

switch1

```
switch1(config)#do sh mvrp interface Gi1/0/1
```

```
Port          Status      Registrar State
Gi1/0/1       on          normal
```

Port	Join Timeout	Leave Timeout	Leaveall Timeout	Periodic Timeout
Gi1/0/1	20	60	1000	100

Port	Vlans Declared
Gi1/0/1	1,8,17

Port	Vlans Registered
Gi1/0/1	1,8,17 >>> vlan 17 is now registered on switch1

Port	Vlans Registered and in Spanning Tree Forwarding State
Gi1/0/1	1,8,17 >>> and in FWD state

```
switch1(config)#do show interfaces trunk
```

Port	Mode	Encapsulation	Status	Native vlan
Gi1/0/1	on	802.1q	trunking	1

Port	Vlans allowed on trunk
Gi1/0/1	1-4094

Port	Vlans allowed and active in management domain
Gi1/0/1	1-2,8,17,21-33,35-62,64-72,74-82,84-86,88-91,94-95,97-110,112-198,531-544,800-802,900-1000

Port	Vlans in spanning tree forwarding state and not pruned
Gi1/0/1	1,8,17 >>> vlan 17 is in FWD state and no longer pruned

提示：如果相邻设备不运行或支持MVRP，则在已运行MVRP的交换机上，可以在不支持MVRP的邻居所连接的端口上配置此线路：*'mvrp注册已修复'*。此配置会忽略该端口上的所有MVRP声明，并且该交换机上静态配置的所有VLAN不会由该接口上的MVRP动态修剪。

命令列表

— AVB验证命令 —

#gptp

```
show ptp brief
show ptp clock
show ptp parent
show ptp port <int_name>
show platform software fed switch active ptp interface <int_name>
```

#avb

```
show avb domain
show avb stream
```

#msrp

```
show msrp streams
show msrp streams brief show msrp streams detail
show msrp streams stream-id <stream-id> show msrp port bandwidth
show msrp port interface <int_name>
show tech msrp #mvrp
show mvrp summary
show mvrp interface <int_name> #QoS
show policy-map interface <int_name>
```

```
show interface <int_name> counter errors show platform hardware fed switch active qos queue
config interface <int_name> show platform hardware fed switch active qos queue stats interface
<int_name>
show platform hardware fed switch active fwd-asic resource tcam utilization
show tech qos
```

!!! Starting from Cisco IOS XE Denali 16.3.2, 'show running-config interface' command does not display any details of the AVB policy attached.

!!! You must use 'show policy-map interface' command to display all the details of the AVB policy attached to that port. #FED QoS

```
show platform software fed switch active qos policy summary
show platform software fed switch active qos policy target interface <int_name>
```

相关信息

- 企业网络的思科音频视频桥接设计和部署 (白皮书)
<https://www.cisco.com/c/dam/en/us/products/collateral/switches/catalyst-3850-series-switches/white-paper-c11-736890.pdf>
- Cat3K交换机上的音频视频桥接
<https://www.cisco.com/c/dam/en/us/products/collateral/switches/q-and-a-c67-737896.pdf>
- AVB产品页面
<https://www.cisco.com/c/en/us/products/switches/avb.html>
- Denali 16.3.x上的AVB配置指南
https://www.cisco.com/c/en/us/td/docs/switches/lan/catalyst3650/software/release/16-3/configuration_guide/b_163 consolidated_3650_cg/b_163 consolidated_3650_cg_chapter_010.html
- Everest 16.6.x上的AVB配置指南
https://www.cisco.com/c/en/us/td/docs/switches/lan/catalyst3850/software/release/16-6/configuration_guide/avb/b_166_avb_3850_cg/b_165_avb_3850_cg_chapter_00.html
- Fuji 16.9.x上的AVB配置指南
https://www.cisco.com/c/en/us/td/docs/switches/lan/catalyst9300/software/release/16-9/configuration_guide/avb/b_169_avb_9300_cg/audio_video_bridging.html
- 直布罗陀16.10.x上的AVB配置指南
https://www.cisco.com/c/en/us/td/docs/switches/lan/catalyst9300/software/release/16-10/configuration_guide/avb/b_1610_avb_9300_cg/audio_video_bridging.html
- Biamp系统 — 在Cisco Catalyst交换机上启用AVB
https://support.biamp.com/Tesira/AVB/Enabling_AVB_on_Cisco_Catalyst_Switches